



The Commonwealth of Massachusetts  
 Executive Office of Health and Human Services  
 Department of Public Health  
 Bureau of Climate and Environmental Health  
 Division of Environmental Health Regulations and Standards  
 5 Randolph Street  
 Canton, MA 02021  
 Phone: 617-624-5757

MAURA T. HEALEY  
 Governor  
 KIMBERLEY DRISCOLL  
 Lieutenant Governor

KATHLEEN E. WALSH  
 Secretary  
 ROBERT GOLDSTEIN, MD, PhD  
 Commissioner  
 Tel: 617-624-6000  
 www.mass.gov/dph

June 18, 2025

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)  
 Kathleen E. Walsh, Secretary, Executive Office of Health and Human Services (electronic copy)  
 Clerk, Massachusetts House of Representatives (electronic copy)  
 Clerk, Massachusetts Senate (electronic copy)  
 John Aponte, Environmental Health and Safety Officer (electronic copy)

Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Massachusetts Treatment Center, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Patrick Wallace  
 Environmental Health Inspector, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)  
 Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)  
 Eric J. Badger, Health Agent, Bridgewater Board of Health (electronic copy)  
 Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)  
 Jeffrey Gonsalves, Superintendent (electronic copy)  
 Sally Desrosiers, Deputy Superintendent (electronic copy)



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards

MAURA T. HEALEY  
Governor  
KIMBERLEY DRISCOLL  
Lieutenant Governor

5 Randolph Street  
Canton, MA 02021  
Phone: 617-624-5757

KATHLEEN E. WALSH  
Secretary  
ROBERT GOLDSTEIN, MD, PhD  
Commissioner  
Tel: 617-624-6000  
[www.mass.gov/dph](http://www.mass.gov/dph)

June 9, 2025

Jeffrey Gonsalves, Superintendent  
Massachusetts Treatment Center  
30 Administration Road  
Bridgewater, MA 02324 (electronic copy)

Re: Facility Inspection – Massachusetts Treatment Center, Bridgewater

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Massachusetts Treatment Center on May 19 and 20, 2025 accompanied by John Aponte, Environmental Health and Safety Officer and Nathan Frasier, Facility Maintenance Director, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 151 total deficiencies: 41 deficiencies under the Required Standards (100 and .200 series), 38 repeat deficiencies under the Required Standards, 30 deficiencies under the Recommended Standards (.300 series), and 42 repeat deficiencies under the Recommended Standards.

### Overview

**Section 1** provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

**Section 2** provides information on areas that EHRS found to be compliant.

**Section 3** documents the areas that EHRS did not inspect.

**Section 4** provides information on submitting a Plan of Correction for the identified deficiencies.

**Section 5** outlines observations and recommendations related to the inspection.

## **SECTION 1: Health and Safety Deficiencies**

### **Front Lobby**

#### **Deficiencies under the Required Standards (.100 and .200 series)**

1 repeat deficiency (indicated by an \*) was found during the inspection:

1. Male Bathroom	105 CMR 451.123*	Maintenance: Trash barrel rotted
------------------	------------------	----------------------------------

#### **Deficiencies under the Recommended Standards (.300 series)**

2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Waiting Area	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged
2. Waiting Area	105 CMR 451.350*	Structural Maintenance: Front entrance not rodent and weathertight

### **Administration Area**

#### **Deficiencies under the Recommended Standards (.300 series)**

1 new deficiency was found during the inspection:

1. Main Area	105 CMR 451.353	Interior Maintenance: Ceiling tiles missing
--------------	-----------------	---

### **Control Area**

#### **Deficiencies under the Recommended Standards (.300 series)**

1 repeat deficiency (indicated by an \*) were found during the inspection:

1. Central Tower	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
------------------	------------------	---

### **Fire Safety Room**

#### **Deficiencies under the Recommended Standards (.300 series)**

3 new deficiencies were found during the inspection:

1. Central Laundry	105 CMR 451.353	Interior Maintenance: Floor paint damaged
2. Central Laundry	105 CMR 451.353	Interior Maintenance: Dryer # 1 out-of-order
3. Central Laundry	105 CMR 451.353	Interior Maintenance: Washing machine # 1 out-of-order

## A Units

### Deficiencies under the Required Standards (.100 and .200 series)

13 new deficiencies and 18 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AM-12 and AM-13
2.	A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # AM-12 and AM-13
3.	A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Floor surface damaged in shower # AM-12 and AM-13
4.	A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Ceiling damaged in shower # AM-12
5.	A1 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # AM-12 and AM-13
6.	A1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Door frame rotted in shower # AG-12 and AG-13
7.	A1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AG-12 and AG-13
8.	A1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # AG-13
9.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # AM-35
10.	A2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # AM-36
11.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Mold on ceiling in shower # AM-36
12.	A2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Mold on ceiling in shower # AM-35
13.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AM-36
14.	A2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Wall epoxy damaged in shower # AM-35
15.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # AM-36
16.	A2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # AM-35
17.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rotted in shower # AM-36
18.	A2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Door frame rotted in shower # AM-35
19.	A2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # AM-35
20.	A2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Shower # AM-36 out-of-order
21.	A2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # AG-36
22.	A2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # AG-36
23.	A2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # AG-35

24. A2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Wall epoxy damaged in shower # AG-35
25. A2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # AG-35

**Deficiencies under the Recommended Standards (.300 series)**

1 new deficiency and 6 repeat deficiencies (indicated by an \*) were found during the inspection:

1. A1 Unit	Common Area	105 CMR 451.350*	Structural Maintenance: Window cracked near stairs
2. A1 Unit	Slop Sink # A1-1	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
3. All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked
4. A1 Unit	Cells	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 1
5. A2 Unit	Common Area	105 CMR 451.353*	Interior Maintenance: Floor epoxy damaged on second level
6. A2 Unit	Common Area	105 CMR 451.353*	Interior Maintenance: Floor paint damaged on handicapped ramp
7. A2 Unit	Cells	105 CMR 451.353	Interior Maintenance: Floor surface damaged in cell # 11

**Health Services Unit**

**Deficiencies under the Recommended Standards (.300 series)**

1 new deficiency was found during the inspection:

1. Room # A1-57		105 CMR 451.353	Interior Maintenance: Floor surface damaged at entrance
-----------------	--	-----------------	---

**B Units**

**Deficiencies under the Required Standards (.100 and .200 series)**

2 new deficiencies and 1 repeat deficiency (indicated by an \*) were found during the inspection:

1. B1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # BG-13
2. B1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Ceiling epoxy damaged in shower # BG-12
3. B2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Ceiling rusted in shower # BG-35

**Deficiencies under the Recommended Standards (.300 series)**

3 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1. B Control		105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained
2. B1 Unit	Common Area	105 CMR 451.353	Interior Maintenance: Floor paint damaged outside 1st floor showers
3. B1 Unit	Common Area	105 CMR 451.350	Structural Maintenance: Ceiling water damaged

4.	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked
5.	B2 Unit	Common Area	105 CMR 451.353*	Interior Maintenance: Wall paint damaged outside shower # BG-35
6.	B2 Unit	Cells	105 CMR 451.353	Interior Maintenance: Wall water damaged in cell # 9

## Food Service Areas

### Deficiencies under the Required Standards (.100 and .200 series)

7 new deficiencies and 5 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Kitchen	Northside Tray Return Area	105 CMR 451.200	Plumbing System; Design, Construction, and Installation: Air gap missing between water supply inlet and the flood level rim of the sink, sink sprayer was hanging below the flood rim (Pf). Standard found in 105 CMR 590; FC 5-202.13.
2.	Kitchen	Ice Machine	105 CMR 451.200	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil/mold observed on interior surfaces of ice machine. Standard found in 105 CMR 590; FC 4-602.11(E)(4)(b). <b>** Corrected On-Site **</b>
3.	Kitchen	Warmer Units	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, warmer # 3 not functioning properly. Standard found in 105 CMR 590; FC 4-501.11(A). <b>** Corrected On-Site **</b>
4.	Kitchen	Oven Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, floor dirty behind ovens. Standard found in 105 CMR 590; FC 6-501.12(A).
5.	Kitchen	Rinse/Dishwashing Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, sprayer head dirty. Standard found in 105 CMR 590; FC 6-501.12(A). <b>** Corrected On-Site **</b>
6.	Kitchen	Rinse/Dishwashing Area	105 CMR 451.200	Maintenance and Operation, Equipment: Inadequate water temperature in the mechanical warewashing machine (Pf). Standard found in 105 CMR 590; FC 4-501.112(A)(2).
7.	Kitchen	Dry Storage	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, floor surface damaged. Standard found in 105 CMR 590; FC 6-501.11.

8.	Kitchen	Dry Storage	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling damaged. Standard found in 105 CMR 590; FC 6-501.11.
9.	Kitchen	Recycling Area	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, recycling carts damaged. Standard found in 105 CMR 590; FC 4-501.11(A).
10.	Kitchen	Recycling Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, recycling carts dirty and moldy. Standard found in 105 CMR 590; FC 6-501.12(A).
11.	Staff Food Service	3-Compartment Sink	105 CMR 451.200*	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, faucet leaking. Standard found in 105 CMR 590; FC 5-202.13.
12.	Staff Food Service	Staff Dining Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling tiles missing. Standard found in 105 CMR 590; FC 6-501.11.

## D Units

### Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies were found during the inspection:

1.	D1 Unit	Common Area	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water dispenser out-of-order
2.	D1 Unit	1st Floor Showers	105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure in shower # DG-12
3.	D2 Unit	Common Area	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water dispenser damaged
4.	D2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Door handle missing on shower # DG-35

### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 5 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	D1 Unit	Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked
2.	D1 Unit	Cells	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in cell # 8
3.	D2 Unit	Utility Closet # D1-10	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
4.	D2 Unit	Utility Closet # D1-10	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

5.	D2 Unit	Cells	105 CMR 451.353*	Interior Maintenance: Ceiling damaged in cell # 21
6.	D2 Unit	Cells	105 CMR 451.353	Interior Maintenance: Wall water damaged in cell # 7
7.	D2 Unit	Cells	105 CMR 451.353	Interior Maintenance: Standing water on floor in cell # 7

#### B.A.U.

##### Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 1 repeat deficiency (indicated by an \*) were found during the inspection:

1.	Main Area	Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # 1
2.	Main Area	Showers	105 CMR 451.123	Maintenance: Shower # 2 out-of-order

##### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Main Area	Cells	105 CMR 451.353*	Interior Maintenance: Light shield damaged in cell # 7
2.	Main Area	Cells	105 CMR 451.353	Interior Maintenance: Walls damaged in cell # 9
3.	Main Area	Cells	105 CMR 451.353	Interior Maintenance: Floor damaged in cell # 7
4.	Main Area	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # 3 and 4

#### Modular Units – South

##### Deficiencies under the Required Standards (.100 and .200 series)

9 new deficiencies and 6 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	South 1	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Door frame rusted at entrance to showers
2.	South 1	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Wall damaged near entrance
3.	South 1	Dorm Hallway	West Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink # 4
4.	South 1	Dorm Hallway	West Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 6
5.	South 1	Dorm Hallway	East Bathroom	105 CMR 451.123*	Maintenance: Mold on ceiling outside showers
6.	South 1	Dorm Hallway	East Bathroom	105 CMR 451.123*	Maintenance: Ceiling paint damaged outside showers
7.	South 1	Dorm Hallway	East Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower # 2 out-of-order

8.	South 1	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover missing in shower # 5
9.	South 1	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink # 6
10.	South 1	Dorm Hallway	East Bathroom	105 CMR 451.123	Maintenance: Wall water damaged near entrance
11.	South 2	Dorm Hallway	Utility Closet	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink
12.	South 2	Dorm Hallway	East Bathroom	105 CMR 451.123*	Maintenance: Caulking dirty in shower # 5
13.	South 2	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 1 out-of-order
14.	South 2	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Door rusted at entrance to shower area
15.	South 2	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Soap scum on floor in shower # 3

### Deficiencies under the Recommended Standards (.300 series)

9 new deficiencies and 14 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm room # 102, 103, 104, 107, and 108
2.	South 1	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room # 101
3.	South 1	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 102
4.	South 1	Dorm Hallway	Dorms	105 CMR 451.344	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 105 and 108
5.	South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in dorm room # 113
6.	South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall water damaged in dorm room # 113
7.	South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Door hardware damaged in dorm room # 109
8.	South 2	Common Area	Back Rooms	105 CMR 451.353	Interior Maintenance: Wall damaged in left side back room
9.	South 2	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in room # 201 and 207
10.	South 2	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 212
11.	South 2	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light flickering in dorm room # 203 and 211
12.	South 2	Dorm Hallway	Dorms	105 CMR 451.344	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 201, 206, 208, 210, and 212

## Modular Units – North

### Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 6 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	North 1	Dorm Hallway	East Bathroom	105 CMR 451.123*	Maintenance: Floor surface left unfinished next to showers
2.	North 1	Dorm Hallway	East Bathroom	105 CMR 451.123	Maintenance: Wall damaged outside showers
3.	North 1	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 5 out-of-order
4.	North 1	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Ceiling dirty outside showers
5.	North 1	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Ceiling paint damaged outside showers
6.	North 2	Dorm Hallway	East Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower # 1 leaking
7.	North 2	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 3 out-of-order
8.	North 2	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Curtain missing at shower # 2
9.	North 2	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Door rusted at entrance to showers
10.	North 2	Dorm Hallway	West Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, sink basin loose at handwash sink # 5

### Deficiencies under the Recommended Standards (.300 series)

7 new deficiencies and 6 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	North 1	Common Area	Old Laundry Area	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
2.	North 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall damaged in dorm room # 157
3.	North 1	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room # 159
4.	North 1	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Floor damaged at entrance to dorm room # 151
5.	North 1	Dorm Hallway	Dorms	105 CMR 451.344	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 157
6.	North 2			105 CMR 451.353	Interior Maintenance: Ceiling water damaged outside entrance
7.	North 2	Common Area	Old Laundry Area	105 CMR 451.353	Interior Maintenance: Floor damaged
8.	North 2	Common Area	Old Laundry Area	105 CMR 451.353	Interior Maintenance: Wall damaged
9.	North 2	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall damaged in dorm room # 254 and 261
10.	North 2	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm room # 260

11. North 2	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room # 258
12. North 2	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 253

### Vehicle Trap / Rear Tower

#### Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1. Bathroom		105 CMR 451.123*	Maintenance: Wall paint damaged
-------------	--	------------------	---------------------------------

#### Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1. Rear Tower		105 CMR 451.353	Interior Maintenance: Floor damaged
---------------	--	-----------------	-------------------------------------

### Community Transition House

#### Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. 1st Floor	Front Porch	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
2. Basement		105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged

### SECTION 2: Areas Found to be in Compliance

EHRIS inspected 178 additional areas of the facility which were found to be in compliance.

### Section 3: Areas EHRIS did not inspect

EHRIS did not inspect 6 areas of the facility because they were either in use, locked, or under construction.

1. Visiting Area	Children's Day Room		Unable to Inspect – Under Construction
2. B Units	B1 Unit	2nd Floor Showers	Unable to Inspect Shower # BM-12 – Under Construction
3. B Units	B2 Unit	2nd Floor Showers	Unable to Inspect Shower # BM-36 – Under Construction
4. B Units	B2 Unit	2nd Floor Showers	Unable to Inspect Shower # BM-35 – In Use
5. B Units	B2 Unit	1st Floor Showers	Unable to Inspect Shower # BG-36 – In Use
6. C Units			Unable to Inspect – Closed

### SECTION 4: Plan of Correction

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects

3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

### **SECTION 5: Observations and Recommendations**

1. The inmate population was 448 at the time of inspection.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Correctional Facilities" [105 CMR 451.000](#) is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Patrick Wallace  
Environmental Health Inspector, EHRS, BCEH



*The Commonwealth of Massachusetts*  
*Executive Office of Public Safety & Security*  
*Department of Correction*  
*Massachusetts Treatment Center*  
*30 Administration Road*  
*Bridgewater, MA 02324*  
*Tel: (508) 279-8100*  
*www.mass.gov/doc*



**MAURA T. HEALEY**  
*Governor*

**TERRENCE M. REIDY**  
*Secretary*

**KIMBERLEY DRISCOLL**  
*Lieutenant Governor*

**SHAWN P. JENKINS**  
*Commissioner*

June 11, 2025


Patrick Wallace, Environmental Health Inspector, CSP, BEH  
Bureau of Environmental Health  
Community Sanitation Program  
5 Randolph Street  
Canton, MA 01583

Dear Inspector Wallace:

I am in receipt of the bi-annual Department of Public Health Inspection, which was held on May 19, and 20, 2025, in accordance with Chapter 11, Section 5 and 20 of the Massachusetts General Laws; Department of Public Health Regulation 105 CMR 451: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

I have enclosed for your review Massachusetts Treatment Center's plan of corrective report. Many of the discrepancies noted have been corrected. Dates of completion have been provided for the discrepancies in need of resolution. Should you have any questions or require any additional information, please do not hesitate to contact my office.

Sincerely,

  
Lisa M. Curto  
Superintendent

cc: Jeffrey Fisher, Assistant Deputy Commissioner, Health Services Division  
Sally Desrosiers, Deputy Superintendent of Operations  
Lynn Lizotte, Deputy Superintendent of Reentry  
Nathan Frazier, Director of Facility Maintenance  
John Aponte, Fire Safety/EHSO Officer  
File

**INSTITUTION NAME:** Massachusetts Treatment Center  
30 Administration Road  
Bridgewater, MA 02324

**SUPERINTENDENT:** Lisa M. Curto, Superintendent

**ENVIRONMENTAL HEALTH OFFICER:** John Aponte, Correction Officer

**INSPECTION DATE:** May 19, 2025, and May 20, 2025

**INSPECTOR:** Patrick Wallace, Environmental Health Inspector, CSP, BEH

---

**FRONT LOBBY**

*Male Bathroom*

105 CMR 451.123*	Maintenance: Trash barrel rotted	Responsible Staff: Maintenance Corrective Action: Replaced barrel Completion Date: 5/22/25
------------------	----------------------------------	--

*Waiting Area*

105 CMR 451.350*	Structural Maintenance: Ceiling water damage	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 8/16/25
105 CMR 451.350*	Structural Maintenance: Front entrance not rodent and weathertight	Responsible Staff: Maintenance Corrective Action: Install weather stripping Completion Date: 8/16/25

**ADMINISTRATION AREA**

*Main Area*

105 CMR 451.353*	Interior Maintenance: Ceiling tiles missing	Responsible Staff: Maintenance Corrective Action: Replace ceiling tiles Completion Date: 9/1/25
------------------	---	---

**CONTROL AREA**

*Central Tower*

105 CMR 451.353*	Interior Maintenance: Floor surface damaged	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 8/20/25
------------------	---	---

**FIRE SAFETY ROOM**

*Central Laundry*

105 CMR 451.353*	Interior Maintenance: Floor paint damaged	Responsible Staff: Maintenance Corrective Action: Grind and seal floor Completion Date: 7/16/25
105 CMR 451.353	Interior Maintenance: Dryer #1 out of order	Responsible Staff: Maintenance Corrective Action: Dryer repaired by vendor Completion Date: 6/9/25
105 CMR 451.353	Interior Maintenance: Washing machine #1 out of order	Responsible Staff: Maintenance Corrective Action: Washing machine repaired by vendor Completion Date: 6/9/25

**A UNITS**

*A1 Unit 1<sup>st</sup> Floor Showers*

105 CMR 451.123*	Maintenance: Door frame rotted in shower # AG-12 and # AG-13	Responsible Staff: Maintenance Corrective Action: Repair door frame Completion Date: 7/28/25
105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AG-12 and # AG-13	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date: 7/18/25
105 CMR 451.123*	Maintenance: Soap scum on the floor in shower # AG-13	Responsible Staff: EHSO / Unit Team Corrective Action: Cleaned Completion Date: 5/22/25

*A1 Unit 2<sup>nd</sup> Floor Showers*

105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AM-12 and AM-13	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date: 7/18/25
------------------	---	---

105 CMR 451.123*	Maintenance: Door frame rusted in shower #AM-12 and AM-13	Responsible Staff: Maintenance Corrective Action: Repair door frames Completion Date: 7/28/25
105 CMR 451.123*	Maintenance: Ceiling damaged in shower # AM-12	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 7/14/25
105 CMR 451.123*	Maintenance: Floor surface damaged in shower # AM-12 and AM-13	Responsible Staff: Maintenance Corrective Action: Repair floors Completion Date: 7/25/25
105 CMR 451.123	Maintenance: Ceiling dirty in shower # AM -12 and AM-13	Responsible Staff: Unit Team/EHSO Corrective Action: Cleaned Completion Date: 5/22/25

*A1 Unit Cells*

105 CMR 451.353*	Interior Maintenance: Wall paint damage in cell #1	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 7/25/25
------------------	--	--

*A1 Unit Common Area*

105 CMR 451.350*	Structural Maintenance: Window cracked near stairs	Responsible Staff: Maintenance Corrective Action: Replace window. Completion Date: 7/14/25
------------------	--	--

*Slop Sink #A1-1*

105 CMR 451.353*	Interior Maintenance: Floor paint damaged	Responsible Staff: Maintenance Corrective Action: Scrape and paint. Completion Date: 7/16/25
------------------	---	--

*A2 Unit 1<sup>st</sup> Floor Showers*

105 CMR 451.123*	Maintenance: Floor paint damaged in shower # AG-36.	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 7/25/25
105 CMR 451.123	Maintenance: Ceiling dirty in shower # AG -36	Responsible Staff: EHSO/Unit Team Corrective Action: Cleaned ceiling Completion Date: 5/27/25
105 CMR 451.123	Maintenance: Floor paint damaged in shower # AG-35	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 7/25/25

105 CMR 451.123	Maintenance: Wall epoxy damaged in shower # AG-35	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date: 7/18/25
105 CMR 451.123	Maintenance: Ceiling paint damaged in shower #AG-35	Responsible Staff: Maintenance Corrective Action: Scrape and repaint Completion Date: 7/21/25

*A2 Unit 2<sup>nd</sup> Floor Showers*

105 CMR 451.123*	Maintenance: Door frame rusted in shower # AM 35	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 7/28/25
105 CMR 451.123 *	Maintenance: Door frame rusted in shower #AM-36	Responsible Staff: Maintenance Corrective Action: Repair door frame Completion Date: 7/28/25
105 CMR 451.123*	Maintenance: Floor paint damaged in shower # AM-36.	Responsible Staff: Maintenance Corrective Action: Scrape and re-paint Completion Date: 7/25/25
105 CMR 451.123	Maintenance: Floor paint damaged in shower # AM-35	Responsible Staff: Maintenance Corrective Action: Scrape and re-paint Completion Date: 7/25/25
105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AM-36	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date 7/18/25
105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AM-35	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date: 7/18/25
105 CMR 451.123*	Maintenance: Mold on ceiling in shower # AM-36	Responsible Staff: EHSO / Housing Division Corrective Action: Cleaned ceiling Completion Date 5/27/25
105 CMR 451.123	Maintenance: Mold on ceiling in shower #AM-35	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned ceiling Completion Date: 5/27/25
105 CMR 451.123*	Maintenance: Door frame rotted in shower # AM-36	Responsible Staff: Maintenance Corrective Action: Repair door frame Completion Date: 7/18/25
105 CMR 451.123	Maintenance: Ceiling paint damaged in shower #AM-35	Responsible Staff: Maintenance Corrective Action: Scrape and repaint Completion Date: 7/21/25

105 CMR 451.123	Maintenance: Shower #AM-36 out of order	Responsible Staff: Maintenance Corrective Action: Repaired plumbing Completion Date: 6/2/25
102 CMR451.123	Maintenance: Door frame rotted in shower #AM-35	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 7/28/25

*A2 Unit Cells*

105 CMR 451.353	Interior Maintenance: Floor surface damaged in cell #11	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 7/28/25
-----------------	---	---

*All Cells*

105 CMR 451.320*	Cell Size: Inadequate floor space in some cells; some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
------------------	---	---

*A2 Common Area*

105 CMR 451.353*	Maintenance: Floor epoxy damaged on second level	Responsible Staff: Maintenance Corrective Action: Repair floor epoxy Completion Date: 7/14/25
105 CMR 451.353*	Interior Maintenance: Floor paint damage on handicapped ramp	Responsible Staff: Maintenance Corrective Action: Scrape and repaint ramp Completion Date: 7/14/25

**HEALTH SERVICES UNIT**

*Room #A1-57*

105 CMR 451.353	Maintenance: Floor surface damaged at entrance	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 6/25/25
-----------------	--	---

**B UNITS**

*B Control*

105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained	Responsible Staff: Maintenance Corrective Action: Replace ceiling tiles. Completion Date: 6/26/25
------------------	---	---

*All Cells*

105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
------------------	--	---

**B1 Unit**

*Common area*

105 CMR 451.353	Interior Maintenance: Floor paint damaged outside 1 <sup>st</sup> floor showers.	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date: 7/24/25
105 CMR 451.350	Structural Maintenance: Ceiling water damaged	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 7/24/25

*B1 Unit 1<sup>st</sup> Floor Showers*

105 CMR 451.123	Maintenance: Ceiling epoxy damaged in shower #BG-12	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date: 7/10/25
105 CMR 451.123	Maintenance: Door frame rusted in shower #BG-13	Responsible Staff: Maintenance Corrective Action: Repair door frame Completion Date: 7/8/25

**B2 Unit**

*Common Area*

105 CMR 451.353*	Interior Maintenance: Wall paint damaged outside shower # BG-35	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 7/10/25
------------------	---	--

*B2 Unit 1<sup>st</sup> Floor Showers*

105 CMR 451.123*	Maintenance: Ceiling rusted in shower # BG-35	Responsible Staff: Maintenance Corrective Action: Scrape and repaint Completion Date: 7/10/25
------------------	---	---

*B2 Unit Cells*

105 CMR 451.353	Interior Maintenance: Wall water damaged in cell #9	Responsible Staff: Maintenance Corrective Action: Clean and repaint
-----------------	---	--

Completion Date: 7/10/25

**FOOD SERVICE AREAS**

**Kitchen**

Northside Tray Return Area

105 CMR 451.200*	Plumbing System; Design, Construction, and Installation: Air gap missing between water supply inlet and the flood level rim of the sink, sink sprayer was hanging below the flood rim (PF). Standard found in 105 CMR 590; FC 5-202.13.	Responsible Staff: Maintenance Corrective Action: Install bracket Completion Date: 7/2/25
------------------	---	---

Ice Machine

105 CMR 451.200	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil/mold observed on interior surfaces of ice machine. Standard found in 105 CMR590; FC 4-602.11 (4)(b).	Responsible Staff: Maintenance Corrective Action: <b>**Corrected on Site**</b> Completion Date: 5/20/25
-----------------	--	---

Warmer Units

105 CMR 451.200*	Maintenance and Operations, Equipment: Equipment components not maintained in a state of good repair, external thermometer not functioning properly on warmer #3. Standard found in 105 CMR590; FC 4-501.11(B)	Responsible Staff: Maintenance Corrective Action: <b>**Corrected on Site**</b> Completion Date: 5/20/25
------------------	--	---

Dry Storage

105 CMR451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures-Methods; Facility not in good repair, floor surface damaged. Standard found in 105 CMR 590; FC 6-501.11.	Responsible Staff: Maintenance Corrective Action: Repair and re-paint Completion Date: 6/24/25
105 CMR 451.200	Maintenance and Operations; Premises, Structure, Attachments, and Fixtures- Methods: Facility not in good repair, ceiling damaged. Standard found in 105 CMR 590;FC 6-5011.11.	Responsible Staff: Maintenance Corrective Action: Repair damaged area Completion Date: 6/24/25

Oven Area:

105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, Fixtures-Methods: Facility not cleaned as often as necessary, floor dirty behind ovens. Standard found in 105 CMR 590; FC 6-501.12(A)	Responsible Staff: Kitchen Staff Corrective Action: Cleaned Completion Date: 5/20/25
-----------------	--	--

*Rinse/Dishwashing Area:*

105 CMR 451.200	Maintenance and Operations, Premises, Structure, Attachments, and Fixtures-Methods: Facility not cleaned as often as necessary, sprayer head dirty. Standard found in 105 CMR 590; FC 6-501.12(A)	Responsible Staff: Maintenance Corrective Action: <b>**Corrected on Site**</b> Completion Date: 5/20/25
105 CMR 451.200	Maintenance and Operations, Equipment: Inadequate water temperature in the mechanical warewashing machine (PF). Standard found in 105 CMR 590; FC 4-501.112(a)(2).	Responsible Staff: Maintenance Corrective Action: Temperature adjusted Completion Date: 5/20/25

*Recycling Area:*

105 CMR 451.200*	Maintenance and Operations, Equipment: Equipment not maintained in a state of good repair, recycling carts damaged. Standard found in 105 CMR 590; FC 4-501.11(A)	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 5/20/25
105 CMR 451.200	Maintenance and Operation: Premises, Structure, Attachments, and Fixtures-Methods: Facility not cleaned as often as necessary, recycling carts dirty and moldy. Standard found in 105 CMR 590; FC 6-501.12(A)	Responsible Staff: Maintenance Corrective Action: Cart replaced Completion Date: 5/20/25

**Staff Food Service**

*3 Compartment sink*

105 CMR 451.200*	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, faucet leaking. Standard found in 105 CMR 590; FC S-200.13	Responsible Staff: Maintenance Corrective Action: Repair plumbing Completion Date: 6/23/25
------------------	---	--

*Staff Dining Area:*

105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixture-Methods: Facility not in good repair, ceiling tiles missing. Standard found in 105 CMR 590; FC 6-501.11	Responsible Staff: Maintenance Corrective Action: Replace ceiling tiles Completion Date: 6/30/25
-----------------	--	--

**D UNITS**

*All Cells*

105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
------------------	--	---

**D1 Unit***D1 Unit Cells*

105 CMR 451.353*	Interior Maintenance: Floor surface damaged in cell #8	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 6/27/25
------------------	--	---

*Common Area:*

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water dispenser out of order	Responsible Staff: Maintenance Corrective Action: Repair plumbing Completion Date: 7/15/25
-----------------	--	--

*D1 Unit 1<sup>st</sup> Floor Showers*

105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure in shower #DG-12	Responsible Staff: Maintenance Corrective Action: Repair plumbing Completion Date: 7/15/25
-----------------	---	--

**D2 Unit***D2 Unit Cells*

105 CMR 451.353	Interior Maintenance: Wall water damaged in cell #7	Responsible Staff: Maintenance Corrective Action: Repair wall and paint Completion Date: 6/25/25
105 CMR 451.353*	Interior Maintenance: Ceiling damaged in cell #21	Responsible Staff: Maintenance Corrective Action: Repair and repaint ceiling Completion Date: 6/25/25
105 CMR 451.353	Interior Maintenance: Standing water on floor in cell #7	Responsible Staff: Unit Team Corrective Action: Area cleaned Completion Date: 5/20/25

*Common Area*

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water dispenser damaged	Responsible Staff: Maintenance Corrective Action: Repair plumbing Completion Date: 7/15/25
-----------------	---	--

*Utility Closet #D1-10*

105 CMR 451.353*	Interior Maintenance: Floor paint damaged	Responsible Staff: Maintenance Corrective Action: Scrape and paint.
------------------	---	--

		Completion Date: 7/14/25
105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged	Responsible Staff: Maintenance Corrective Action: Scrape and repaint Completion Date: 7/14/25

*D2 Unit 1<sup>st</sup> Floor Showers*

105 CMR 451.123	Maintenance: Door handle missing on shower #DG-35	Responsible Staff: Maintenance Corrective Action: Handle Replaced Completion Date: 5/27/25
-----------------	---	--

**BEHAVIORAL ASSESSMENT UNIT**

**Main Area**

*Showers*

105 CMR 451.123	Maintenance: Floor paint damaged in shower # 1	Responsible Staff: Maintenance Corrective Action: Scrape and Paint Completion Date: 7/21/25
105 CMR 451.123	Maintenance: Shower #2 out of order	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 5/30/25

*Cells*

105 CMR 451.353*	Interior Maintenance: Light shield damaged in cell #7	Responsible Staff: Maintenance Corrective Action: Repair light shield Completion Date: 6/9/25
105 CMR 451.350*	Structural Maintenance: Window cracked in cell #3 and 4	Responsible Staff: Maintenance Corrective Action: Replace windows. Completion Date: 7/11/25
105 CMR 451.353	Interior Maintenance: Walls damaged in cell #9	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 7/11/25
1105 CMR 451.353	Interior Maintenance: Floor damaged in cell #7	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 7/11/25

**MODULAR UNITS**

**South 1**

## Dorm Hallway

### SI Dorms

105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm room # 102, 103, 104, 107, and 108	Responsible Staff: Maintenance Corrective Action: Scrape/paint Completion Date: 6/25/25
105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room #101	Responsible Staff: Maintenance Corrective Action: Scrape/paint Completion Date: 6/25/25
105 CMR 451.344	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room #105 and 108	Responsible Staff: Maintenance Corrective Action: Replaced light Completion Date: 5/21/25
105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in dorm room # 113	Responsible Staff: Maintenance Corrective Action: Scrape/paint Completion Date: 6/23/25
105 CMR 451.353*	Interior Maintenance: Wall water damage in dorm room #113.	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/23/25
105 CMR 451.353*	Interior Maintenance: Door hardware damaged in dorm room # 109	Responsible Staff: Locksmith Corrective Action: Replaced door hardware. Completion Date: 5/21/25
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out in dorm #102	Responsible Staff: Maintenance Corrective Action: Replaced light. Completion Date: 5/21/25

### West Bathroom

105 CMR 451.123	Maintenance: Wall damaged near entrance	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/25/25
105 CMR 451.123*	Maintenance: Door frame rusted at entrance to showers	Responsible Staff: Maintenance Corrective Action: Scrape and repair. Completion Date: 6/25/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink #4	Responsible Staff: Maintenance Corrective Action: Repaired leak Completion Date: 5/27/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink #6	Responsible Staff: Maintenance Corrective Action: Repaired leak Completion Date: 5/27/25

*East Bathroom*

105 CMR 451.123*	Maintenance: Mold observed on ceiling outside showers	Responsible Staff: EHSO/Housing Division Corrective Action: Ceiling cleaned. Completion Date: 5/21/25
105 CMR 451.123*	Maintenance: Ceiling paint damaged near showers	Responsible Staff: Maintenance Corrective Action: Re-painted ceiling Completion Date: 5/22/25
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower #2 out-of-order	Responsible Staff: Maintenance Corrective Action: Repaired plumbing Completion Date: 5/30/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover missing in shower #5	Responsible Staff: Maintenance Corrective Action: Replaced Completion Date: 5/29/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink #6	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 5/29/25
105 CMR 451.123	Maintenance: Wall water damaged near entrance	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/26/25

**South 2**

**Common Area**

*Back Rooms*

105 CMR 451.353	Interior Maintenance: Wall damaged in left side back room.	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 6/16/25
-----------------	--	---

**Dorm Hallway**

*S2 Dorms*

105 CMR 451.350*	Structural Maintenance: Ceiling water damaged in dorm room # 201 and 207	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 6/30/25
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room # 203, and 211	Responsible Staff: Maintenance Corrective Action: Replaced light bulbs. Completion Date: 5/27/25

105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room #212	Responsible Staff: Maintenance Corrective Action: Replaced light bulbs. Completion Date: 5/27/25
105 CMR 451.344	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room #201, 206, 208 & 210	Responsible Staff: Maintenance Corrective Action: Replaced light bulbs. Completion Date: 5/27/25

*Utility Closet*

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink	Responsible Staff: Maintenance Corrective Action: Repaired leak Completion Date: 5/27/25
-----------------	---	--

*East Bathroom*

105 CMR 451.123*	Maintenance: Caulking dirty in shower # 5	Responsible Staff: EHSO/Housing Division Corrective Action: Area cleaned Completion Date: 5/28/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal #1 out of order	Responsible Staff: Maintenance Corrective Action: Scrape and paint. Completion Date: 6/27/25

*West Bathroom*

105 CMR 451.123*	Maintenance: Door rusted at entrance to shower area	Responsible Staff: Maintenance Corrective Action: Repair door Completion Date: 6/27/25
105 CMR 451.123	Maintenance: Soap scum on floor in shower #3	Responsible Staff: Unit Team/EHSO Corrective Action: Area cleaned Completion Date: 5/25/25

**North 1**

**Common Area**

*Old Laundry Area*

105 CMR 451.353*	Interior Maintenance: Wall paint damaged	Responsible Staff: Maintenance Corrective Action: Scrape and paint. Completion Date: 7/14/25
------------------	--	--

**Dorm Hallway**

*NI Dorms*

105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room #159	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 7/2/25
105 CMR 451.344	Illumination in Habitable Areas: Lights not functioning properly, light out in dorm room # 157	Responsible Staff: Maintenance Corrective Action: Replaced lights. Completion Date: 6/3/25
105 CMR 451.353*	Interior Maintenance: Wall damaged in dorm room #157.	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 7/2/25
105 CMR 451.353	Interior Maintenance: Floor damaged at entrance to dorm room #151	Responsible Staff: Maintenance Corrective Action: Repaired floor Completion Date: 7/6/25

*East Bathroom*

105 CMR 451.123*	Maintenance: Floor surface left unfinished next to showers	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 6/29/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower #5 out of order	Responsible Staff: Maintenance Corrective Action: Repaired shower Completion Date: 5/30/25
105 CMR 451.123	Maintenance: Wall damaged outside showers	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/29/25

*West Bathroom*

105 CMR 451.123*	Maintenance: Ceiling dirty outside showers	Responsible Staff: EHSO/Housing Division Corrective Action: Ceiling cleaned Completion Date: 5/23/25
105 CMR 451.123*	Maintenance: Ceiling paint damaged outside showers	Responsible Staff: Maintenance Corrective Action: Scrape and Paint. Completion Date: 7/25/25

**North 2**

105 CMR 451.353	Interior Maintenance: Ceiling water damaged outside entrance	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 6/17/25
-----------------	--	---

**Common Area**

*Old Laundry Area*

105 CMR 451.353	Interior Maintenance: Floor damaged	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 7/23/25
105 CMR 451.353	Interior Maintenance: Wall damaged	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 7/23/25

**Dorm Hallway**

*Dorms*

105 CMR 451.353*	Interior Maintenance: Wall damaged in dorm room # 254 and 261	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/20/25
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out in dorm #253	Responsible Staff: Maintenance Corrective Action: Replaced lights. Completion Date: 5/23/25
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm room # 260	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 7/8/25
105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room #258	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 7/8/25

*East Bathroom*

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower #3 out of order	Responsible Staff: Maintenance Corrective Action: Repaired plumbing Completion Date: 5/27/25
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower #1 leaking	Responsible Staff: Maintenance Corrective Action: Repaired plumbing Completion Date: 5/23/25

*West Bathroom*

105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, sink basin loose at handwash sink # 5	Responsible Staff: Maintenance Corrective Action: Repaired basin Completion Date: 5/30/25
105 CMR 451.123*	Maintenance: Door rusted at entrance to showers	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 5/30/25
105 CMR 451.123	Maintenance: Curtain missing at shower #2	Responsible Staff: Unit Team Corrective Action: Curtain replaced Completion Date: 5/20/25

**VEHICLE TRAP TOWER**

*Bathroom*

105 CMR 451.123*	Maintenance: Wall paint damaged	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 6/18/25
------------------	---------------------------------	--

*Rear Tower*

105 CMR 451.353	Interior Maintenance: Floor damaged	Responsible Staff: Maintenance Corrective Action: Repair damaged floor Completion Date: 7/31/25
-----------------	-------------------------------------	---

**COMMUNITY TRANSITION HOUSE**

**1<sup>ST</sup> Floor**

*Front Porch*

105CMR 451.353*	Interior Maintenance: Ceiling water damaged	Responsible Staff: Maintenance Corrective Action: Repair ceiling. Completion Date: 6/26/25
-----------------	---	--

**Basement**

105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged	Responsible Staff: Maintenance Corrective Action: Repair damage Completion Date: 7/14/25
------------------	---	--



The Commonwealth of Massachusetts  
 Executive Office of Health and Human Services  
 Department of Public Health  
 Bureau of Climate and Environmental Health  
 Division of Environmental Health Regulations and Standards

MAURA T. HEALEY  
 Governor

KIMBERLEY DRISCOLL  
 Lieutenant Governor

5 Randolph Street  
 Canton, MA 02021  
 Phone: 617-624-5757

KATHLEEN E. WALSH  
 Secretary

ROBERT GOLDSTEIN, MD, PhD  
 Commissioner

Tel: 617-624-6000  
[www.mass.gov/dph](http://www.mass.gov/dph)

June 17, 2025

Jeffrey Gonsalves, Superintendent  
 Massachusetts Treatment Center  
 30 Administration Road  
 Bridgewater, MA 02324 (electronic copy)

Re: Plan of Correction – Massachusetts Treatment Center, Bridgewater

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction (POC) in response to my inspection on May 19 and 20, 2025. After review, EHRS finds the plan appropriately addresses all the deficiencies noted with the following exception:

In regards to the issue of overcrowding, EHRS appreciates the limitations of correctional facilities and the need to accommodate the ever-increasing population; however we remain concerned with the overcrowded conditions.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Patrick Wallace  
 Environmental Health Inspector, EHRS, BCEH

cc: Sally Desrosiers, Deputy Superintendent  
 John Aponte, EHSO/FSO

(electronic copy)  
 (electronic copy)