



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards  
5 Randolph Street  
Canton, MA 02021  
617-624-6000 | mass.gov/dph

**Maura T. Healey**  
Governor

**Kimberley Driscoll**  
Lieutenant Governor

**Kiame Mahaniah, MD, MBA**  
Secretary

**Robert Goldstein, MD, PhD**  
Commissioner

December 3, 2025

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)  
Kiame Mahaniah, Secretary, Executive Office of Health and Human Services (electronic copy)  
Clerk, Massachusetts House of Representatives (electronic copy)  
Clerk, Massachusetts Senate (electronic copy)  
Michael Rosano, Environmental Health and Safety Officer (electronic copy)

Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Bridgewater State Hospital, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

A handwritten signature in blue ink that reads "Patrick Wallace".

Patrick Wallace  
Environmental Analyst, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)  
Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)  
Eric Badger, Health Agent, Bridgewater Health Department (electronic copy)  
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)  
Jeffrey Gonsalves, Superintendent (electronic copy)  
James Rioux, Deputy Superintendent (electronic copy)



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards  
5 Randolph Street Canton, MA 02021  
617-624-6000 | mass.gov/dph

**Maura T. Healey**  
Governor

**Kimberley Driscoll**  
Lieutenant Governor

**Kiame Mahaniah, MD, MBA**  
Secretary

**Robert Goldstein, MD, PhD**  
Commissioner

November 17, 2025

Jeffrey Gonsalves, Superintendent  
Bridgewater State Hospital  
20 Administration Road  
Bridgewater, MA 02324 (electronic copy)

Re: Facility Inspection – Bridgewater State Hospital

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Bridgewater State Hospital on October 29 and 30, 2025 accompanied by Sergeant Michael Rosano, Environmental Health and Safety Officer, Michael Durocher, Director of Engineering, and Norberto Melo, Facility Maintenance Manager in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 284 total deficiencies: 45 new deficiencies under the Required Standards (.100 and .200 series), 32 repeat deficiencies under the Required Standards, 40 new deficiencies under the Recommended Standards (.300 series), and 167 repeat deficiencies under the Recommended Standards.

## Overview

**Section 1** provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

**Section 2** provides information on areas that EHRS found to be compliant.

**Section 3** documents the areas that EHRS did not inspect.

**Section 4** provides information on submitting a Plan of Correction for the identified deficiencies.

**Section 5** outlines observations and recommendations related to the inspection.

## **SECTION 1: Health and Safety Deficiencies**

### **Building #1 – Administration**

#### **Deficiencies under the Required Standards (.100 and .200 series)**

1 new deficiency was found during the inspection:

1.	Second Floor	Bathroom # AM-202	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control leaking at handwash sink
----	--------------	-------------------	-----------------	--

#### **Deficiencies under the Recommended Standards (.300 series)**

2 new deficiencies were found during the inspection:

1.	Records Module		105 CMR 451.353	Interior Maintenance: Wall paint damaged in hallway
2.	Records Module		105 CMR 451.353	Interior Maintenance: Several ceiling vents dusty throughout

### **Building #2 – Adams**

#### **Deficiencies under the Required Standards (.100 and .200 series)**

12 new deficiencies and 1 repeat deficiency (indicated by an \*) were found during the inspection:

1.	A1 Unit	Room Corridor	Rooms	105 CMR 451.103	Mattresses: Mattress damaged in room # 115
2.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted
3.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Wall paint damaged
4.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged
5.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 4 leaking
6.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130	Hot Water: Shower water temperature 70°F at shower # 4
7.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling damaged
8.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Floor left unfinished next to handwash sinks
9.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 1 running continuously
10.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 1
11.	A2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 1 and 4
12.	A2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door frame rusted

#### **Deficiencies under the Recommended Standards (.300 series)**

10 new deficiencies and 8 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	A1 Unit	Main Area	Staff Break Room # A156	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged
----	---------	-----------	-------------------------	-----------------	---

2.	A1 Unit	Main Area	Slop Sink Closet # A155	105 CMR 451.353	Interior Maintenance: Floor paint damaged
3.	A1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
4.	A1 Unit	Main Area	Transfer Room # A124	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
5.	A1 Unit	Main Area	Transfer Room # A124	105 CMR 451.353	Interior Maintenance: Door frame rotted
6.	A1 Unit	Main Area	Room # A121	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged
7.	A1 Unit	Room Corridor	Nurse's Treatment Room # A125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 123
9.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 116 and 119
10.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 117
11.	A2 Unit	Room Corridor	Treatment Room # A2-221	105 CMR 451.353	Interior Maintenance: Wall paint damaged
12.	A2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 216
13.	A2 Unit	Dorm Corridor		105 CMR 451.353	Interior Maintenance: Paint damaged on hand sanitizer dispenser in hallway
14.	A2 Unit	Dorm Corridor	Dorm # 9	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
15.	A2 Unit	Dorm Corridor	Dorm # 11	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
16.	A2 Unit	Dorm Corridor	Dorm # 12	105 CMR 451.353	Interior Maintenance: Floor surface damaged
17.	A2 Unit	Dorm Corridor	Dorm # 10	105 CMR 451.353	Interior Maintenance: Floor paint damaged

### Building # 3 – Bradford

#### Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	B1 Unit	Control	Control Bathroom	105 CMR 451.123	Maintenance: Door damaged
2.	B1 Unit	Main Area	Nurse's Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink
3.	B1 Unit	Main Area	Slop Sink Closet	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink drain clogged
4.	B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on handwash sink unit
5.	B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on toilet partitions
6.	B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall vent dirty and clogged
7.	B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Paint damaged on countertop

**Deficiencies under the Recommended Standards (.300 series)**

5 new deficiencies and 17 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	B1 Unit	Main Area	Transfer Room	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
2.	B1 Unit	Main Area	Transfer Room	105 CMR 451.353	Interior Maintenance: Water pooling on floor around hot water tank
3.	B1 Unit	Main Area	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
4.	B1 Unit	Room Corridor		105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in hallway
5.	B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
6.	B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
7.	B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353	Interior Maintenance: Ceiling damaged
8.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 111, 118, and 120
9.	B1 Unit	Dorm Corridor	Room # B-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
10.	B1 Unit	Dorm Corridor	Room # B-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
11.	B1 Unit	Dorm Corridor	Room # B-112	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
12.	B2 Unit	Control		105 CMR 451.353	Interior Maintenance: Ceiling dirty around vent
13.	B2 Unit	Main Area	Mop Closet # B-250	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
14.	B2 Unit	Room Corridor	Treatment Room # B2-221	105 CMR 451.353	Interior Maintenance: Floor paint damaged
15.	B2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 204, 206, 209, 210, and 218

**Building # 4 - Cotter****Deficiencies under the Required Standards (.100 and .200 series)**

6 new deficiencies and 5 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	C1 Unit	Control	Control Bathroom	105 CMR 451.123	Maintenance: Door damaged
2.	C1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling damaged
3.	C1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door frame rusted
4.	C2 Unit	Main Area	Bathroom # C2-217	105 CMR 451.123*	Maintenance: Floor paint damaged
5.	C2 Unit	Main Area	Bathroom # C2-217	105 CMR 451.123	Maintenance: Door damaged
6.	C2 Unit	Room Corridor	Rooms	105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure at handwash sink in room # 203
7.	C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling dirty
8.	C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling water damaged
9.	C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Hand dryer out-of-order

10. C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted
11. C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on light fixture

#### Deficiencies under the Recommended Standards (.300 series)

9 new deficiencies and 60 repeat deficiencies (indicated by an \*) were found during the inspection:

1. C1 Unit	Main Area		105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in hallway
2. C1 Unit	Main Area		105 CMR 451.353	Interior Maintenance: Wall paint damaged in hallway
3. C1 Unit	Main Area	Mop Closet # C-155	105 CMR 451.353	Interior Maintenance: Floor paint damaged
4. C1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
5. C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
6. C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Door to exterior rotted
7. C1 Unit	Main Area	Storage Room # C-121	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8. C1 Unit	Room Corridor		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway
9. C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 115
10. C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 102, 103, 104, 105, 107, 108, 109, 110, 111, 112, 114, 115, 116, 118, 119, and 123
11. C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 103, 104, 106, 110, 113, 114, 116, and 119
12. C1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 112
13. C1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 120
14. C1 Unit	Dorm Corridor		105 CMR 451.353	Interior Maintenance: Ceiling damaged in hallway
15. C1 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C-105	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
16. C1 Unit	Dorm Corridor	Unit Director's Office # C-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
17. C1 Unit	Dorm Corridor	Treatment Team Office # C-107	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
18. C1 Unit	Dorm Corridor	Sensory Room # C-110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
19. C1 Unit	Dorm Corridor	Group Room # C-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
20. C2 Unit	Main Area	Staff Break Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
21. C2 Unit	Main Area	Room # C-220	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

22. C2 Unit	Main Area	Slop Sink Closet # C2-250	105 CMR 451.353	Interior Maintenance: Strong unpleasant odor present
23. C2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 223
24. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 203, 204, 205, 206, 207, 208, 211, 212, 214, 215, 216, 218, 219, and 221
25. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 210, 205, 212, 214, and 216
26. C2 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C-204	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
27. C2 Unit	Dorm Corridor	Unit Director's Office # C-205	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
28. C2 Unit	Dorm Corridor	Treatment Team Office # C-206	105 CMR 451.353	Interior Maintenance: Floor paint damaged
29. C2 Unit	Dorm Corridor	Sensory Room # C-208	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
30. C2 Unit	Dorm Corridor	Classroom # C-210	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

#### Building # 5 – Recovery Place

##### Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
2. Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Wall paint damaged

#### Building # 7 - Commons

##### Deficiencies under the Required Standards (.100 and .200 series)

10 new deficiencies were found during the inspection:

1. Lobby Area	Laundry	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control leaking at handwash sink
2. Main Area	Patient Bathroom	105 CMR 451.123	Maintenance: Toilet partitions rusted
3. Gym	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling paint damaged
4. School Corridor	Staff Bathroom # CS-01	105 CMR 451.123	Maintenance: Door damaged
5. School Corridor	Staff Bathroom # CS-01	105 CMR 451.123	Maintenance: Ceiling water damaged
6. Kitchen		105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, free standing fan dirty. Standard found in 105 CMR 590; FC 6-501.12(A). ** <b>Corrected On-Site **</b>

7.	Kitchen	Ice Machine	105 CMR 451.200	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil/mold observed on interior surfaces of ice machine. Standard found in 105 CMR 590; FC 4-602.11(E)(4)(b). <b>** Corrected On-Site **</b>
8.	Kitchen	Dishwashing Machine Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, sprayer dirty. Standard found in 105 CMR 590; FC 6-501.12(A). <b>** Corrected On-Site **</b>
9.	Kitchen	Refrigerator E	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, refrigerator out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A).
10.	Kitchen	Supply Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, Ceiling damaged. Standard found in 105 CMR 590; FC 6-501.11.

#### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 20 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Lobby Area		105 CMR 451.353*	Interior Maintenance: Ceiling damaged outside closet # SL-01
2.	Lobby Area	Laundry	105 CMR 451.353*	Interior Maintenance: Pipe insulation damaged
3.	Lobby Area	Control	105 CMR 451.353*	Interior Maintenance: Paint damaged on window frames
4.	Main Area		105 CMR 451.353*	Interior Maintenance: Ceiling damaged
5.	Main Area		105 CMR 451.353*	Interior Maintenance: Floor cracked
6.	Main Area	Storage Area # CL-11	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
7.	Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8.	Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353*	Interior Maintenance: Floor dirty
9.	Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353	Interior Maintenance: Wall paint damaged
10.	Gym	Storage Room # CG-23	105 CMR 451.353*	Interior Maintenance: Ceiling damaged



11. Back Hallway	Recycle Room # CG-11		105 CMR 451.353*	Interior Maintenance: Ceiling damaged
12. Back Hallway	Recycle Room # CG-11		105 CMR 451.353*	Interior Maintenance: Floor damaged
13. School Corridor	Library # CS-03		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
14. School Corridor	Life Skills Group Room # CS-10		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
15. School Corridor	Offices		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in # CS-29
16. School Corridor	Offices		105 CMR 451.353*	Interior Maintenance: Door damaged in # CS-29
17. Basement			105 CMR 451.353*	Interior Maintenance: Floor paint damaged in hallway
18. Basement			105 CMR 451.353	Interior Maintenance: Ceiling damaged in hallway
19. Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
20. Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
21. Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
22. Basement	Maintenance Department	Mechanical Room A # CB-10	105 CMR 451.353*	Interior Maintenance: Standing water on floor

#### Building # 8 – Hadley

##### Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 5 repeat deficiencies (indicated by an \*) were found during the inspection:

1. C-Corridor	Bathroom		105 CMR 451.123*	Maintenance: Countertop dirty
2. C-Corridor	Bathroom		105 CMR 451.123*	Maintenance: Floor surface damaged at entrance
3. C-Corridor	Bathroom		105 CMR 451.123*	Maintenance: Wall vent dusty
4. C-Corridor	Bathroom		105 CMR 451.123	Maintenance: Radiator rusted
5. C-Corridor	Bathroom		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, floor drain clogged
6. C-Corridor	Shower Area		105 CMR 451.123*	Maintenance: Door rusted
7. C-Corridor	Shower Area		105 CMR 451.123*	Maintenance: Door frame rusted
8. C-Corridor	Shower Area		105 CMR 451.123	Maintenance: Wall damaged

##### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 24 repeat deficiencies (indicated by an \*) were found during the inspection:

1. A-Corridor	Rooms		105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 101, 102, 104, 105, 106, 109, 110, 111, 112, 113, 114, and 115
2. B-Corridor	Rooms		105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 117, 120, 121, 122, 124, 128, 130, 131, and 132

3.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 123
4.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117
5.	C-Corridor		105 CMR 451.353	Interior Maintenance: Floor tiles damaged in hallway
6.	C-Corridor	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
7.	C-Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

## Building # 9 – Lenox

### Deficiencies under the Required Standards (.100 and .200 series)

5 new deficiencies and 6 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Control	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling paint damaged
2.	A Corridor	Rooms	105 CMR 451.103	Mattresses: Mattress cover missing in room # 111
3.	C Corridor	Slop Sink Closet # M-251	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink
4.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance
5.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Radiator rusted
6.	C Corridor	Patient Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 1 running continuously
7.	C Corridor	Patient Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink # 1 out-of-order
8.	C Corridor	Patient Bathroom	105 CMR 451.126*	Hot Water for Bathing and Hygiene: Hot water temperature 86°F at handwash sink # 2
9.	C Corridor	Shower Room	105 CMR 451.130*	Hot Water: Shower water temperature 86°F
10.	C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Door rusted
11.	C Corridor	Shower Room	105 CMR 451.123	Maintenance: Ceiling vent rusted

### Deficiencies under the Recommended Standards (.300 series)

4 new deficiencies and 21 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Control		105 CMR 451.353*	Interior Maintenance: Wall paint damaged
2.	A Corridor	Transfer Room # M-228	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
3.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 106, 108, 110, 111, and 113
4.	A Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 107
5.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 104 and 112

6.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 120, 124, 126, 127, 128, 129, 130, and 131
7.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Ceiling damaged in room # 124
8.	B Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 130
9.	C Corridor	Staff Break Room # M-252	105 CMR 451.353*	Interior Maintenance: Countertop damaged
10.	C Corridor	Slop Sink Closet # M-251	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
11.	C Corridor	Slop Sink Closet # M-251	105 CMR 451.353	Interior Maintenance: Wet mop in bucket
12.	C Corridor	Toxic/Caustic Closet # M-250	105 CMR 451.353	Interior Maintenance: Floor paint damaged

#### Building # 10 – Berkshire

##### Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an \*) was found during the inspection:

1.	Right Side	Slop Sink # MM-03	105 CMR 451.353*	Interior Maintenance: Door damaged
----	------------	-------------------	------------------	------------------------------------

#### Building # 11 – Lighthouse

##### Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 11 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Booking Corridor	Female Bathroom # H-172	105 CMR 451.123*	Maintenance: Partitions rusted
2.	Booking Corridor	Female Bathroom # H-172	105 CMR 451.123	Maintenance: Ceiling damaged
3.	Booking Corridor	Male Bathroom # H-173	105 CMR 451.123*	Maintenance: Floor cracked
4.	Booking Corridor	Male Bathroom # H-173	105 CMR 451.123*	Maintenance: Partitions rusted
5.	Infirmery	Dorm # 3/Bathroom	105 CMR 451.123*	Maintenance: Door frame rusted in bathroom
6.	Infirmery	Dorm # 3/Bathroom	105 CMR 451.123*	Maintenance: Handwash sink rusted
7.	Infirmery	Nurse's Bathroom	105 CMR 451.123*	Maintenance: Ceiling vent dusty
8.	Infirmery	Dorm # 4/Bathroom	105 CMR 451.123*	Maintenance: Door frame rusted in shower room
9.	Infirmery	Dorm # 4/Bathroom	105 CMR 451.123*	Maintenance: Wall tiles damaged in shower
10.	Infirmery	Shower Room	105 CMR 451.123	Maintenance: Door damaged
11.	Medical West Unit	Bathroom # 138 (Storage)	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, urinal running continuously
12.	Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Wall tile grout dirty
13.	Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Door frame rusted

**Deficiencies under the Recommended Standards (.300 series)**

6 new deficiencies and 12 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Basement	Mechanical Room	105 CMR 451.353	Interior Maintenance: Water pooling on floor
2. First Floor	Clinic Corridor Pharmacy # H-161	105 CMR 451.353	Interior Maintenance: Wall vent dusty
3. Old Seclusion Area		105 CMR 451.353	Interior Maintenance: Rear door stuck shut
4. Old Seclusion Area	Office # 207	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged
5. Booking Corridor		105 CMR 451.353	Interior Maintenance: Ceiling water damaged in hallway
6. Booking Corridor	Admissions Office # H-149	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
7. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Medical waste storage chest rusted
8. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Door frame rotted
9. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Door rusted
10. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior
11. Infirmary	Dorm # 3/Bathroom	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm
12. Infirmary	Dorm # 3/Bathroom	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm
13. Infirmary	Nurse's Office # H-145	105 CMR 451.353	Interior Maintenance: Ceiling dirty around vent
14. Infirmary	Dorm # 5	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
15. Laundry Hallway		105 CMR 451.353*	Interior Maintenance: Door to exterior rusted
16. Laundry Hallway	Laundry	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
17. Medical West Unit	Room # 5 # H-131	105 CMR 451.353*	Interior Maintenance: Floor rust stained
18. Medical West Unit	Room # 6 # H-130	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

**Staff Gym****Deficiencies under the Required Standards (.100 and .200 series)**

2 new deficiencies and 1 repeat deficiency (indicated by an \*) were found during the inspection:

1. Male Locker Room	105 CMR 451.123*	Maintenance: Ceiling tiles water stained
2. Male Locker Room	105 CMR 451.123	Maintenance: Wall water damaged

3. Female Locker Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet out-of-order in left side stall
-----------------------	-----------------	--

#### **Deficiencies under the Recommended Standards (.300 series)**

2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Common Area	105 CMR 451.353*	Interior Maintenance: Carpet damaged
2. Common Area	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained

### **SECTION 2: Areas Found to be in Compliance**

The EHRS inspected 273 additional areas of the facility which were found to be in compliance.

### **Section 3: Areas EHRS did not inspect**

EHRS did not inspect 10 areas of the facility because they were either in use, under construction, or presented security concerns:

1. BUILDING # 3 – BRADFORD	B1 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
2. BUILDING # 3 – BRADFORD	B2 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
3. BUILDING # 9 – Lenox	C Corridor	Storage Room # M-248		Unable to Inspect – Security Concerns
4. BUILDING # 9 – Lenox	C Corridor	Secure Interview Room # M-247		Unable to Inspect – Security Concerns
5. BUILDING # 9 – Lenox	C Corridor	Laundry Room # 1		Unable to Inspect – Security Concerns
6. BUILDING # 9 – Lenox	C Corridor	Laundry Room # 2		Unable to Inspect – Security Concerns
7. BUILDING # 9 – Lenox	C Corridor	Storage Room # M-243		Unable to Inspect – Security Concerns
8. BUILDING # 9 – Lenox	C Corridor	Group Rooms		Unable to Inspect – Security Concerns
9. BUILDING # 9 – Lenox	C Corridor	Secure Interview Room # M-234		Unable to Inspect – Security Concerns
10. BUILDING # 11 – LIGHTHOUSE (Medical)	Booking Corridor	New Admissions Area		Unable to Inspect – Under Construction

### **SECTION 4: Plan of Correction**

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff

5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

## **SECTION 5: Observations and Recommendations**

1. The patient population was 210 at the time of inspection.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Correctional Facilities" [105 CMR 451.000](#) is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Patrick Wallace,  
Environmental Health Officer, EHRS, BCEH



MAURA T. HEALEY  
Governor

KIMBERLEY DRISCOLL  
Lieutenant Governor

*The Commonwealth of Massachusetts*  
*Executive Office of Public Safety & Security*  
*Department of Correction*  
*Bridgewater State Hospital*  
*20 Administration Road*  
*Bridgewater, MA. 02324*  
*Tel: (508) 279-4500*  
*[www.mass.gov/doc](http://www.mass.gov/doc)*



TERRENCE M. REIDY  
Secretary

SHAWN P. JENKINS  
Commissioner

November 25, 2025

Mr. Patrick Wallace  
Environmental Health Inspector, CSP, BEH  
Department of Public Health, Bureau of Environmental Health  
Community Sanitation Program  
5 Randolph Street  
Canton, MA 02021

Dear Mr. Wallace:

Enclosed please find your inspection report for Bridgewater State Hospital dated 11/17/25. This report has been updated to include corrective action plans which address all violations. All responses are in bold.

Should you have any questions or require additional information, please don't hesitate to contact my office.

Sincerely,

Michael McDonald  
Acting Superintendent

CC: Shawn P. Jenkins, Commissioner  
Mitzi Peterson, Deputy Commissioner, Clinical Services & Re-entry  
Jeff Fisher, Assistant Deputy Commissioner, Clinical Services  
James Rioux, Deputy Superintendent  
Brianna Arruda, Director, Policy Development and Compliance Unit  
Michael Durocher, Director of Facility Maintenance  
Sergeant Michael Rosano, Environmental Health and Safety Officer

## **SECTION 1: Health and Safety Deficiencies**

### **Building #1 – Administration**

#### **Deficiencies under the Required Standards (.100 and .200 series)**

1 new deficiency was found during the inspection:

1.	Second Floor	Bathroom # AM-202	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control leaking at handwash sink <b>To be repaired by 11/28/25.</b>
----	--------------	-------------------	-----------------	--

#### **Deficiencies under the Recommended Standards (.300 series)**

2 new deficiencies were found during the inspection:

1.	Records Module		105 CMR 451.353	Interior Maintenance: Wall paint damaged in hallway <b>To be spackled and re-painted by 3/31/25.</b>
2.	Records Module		105 CMR 451.353	Interior Maintenance: Several ceiling vents dusty throughout <b>To be cleaned by 12/15/25.</b>

### **Building #2 – Adams**

#### **Deficiencies under the Required Standards (.100 and .200 series)**

12 new deficiencies and 1 repeat deficiency (indicated by an \*) were found during the inspection:

1.	A1 Unit	Room Corridor	Rooms	105 CMR 451.103	Mattresses: Mattress damaged in room # 115 <b>To be replaced by 11/21/25.</b>
2.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted <b>To be repaired and repainted by 12/31/25.</b>
3.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Wall paint damaged <b>To be repainted by 12/31/25.</b>
4.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged <b>To be repainted by 12/31/25.</b>
5.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 4 leaking <b>To be repaired by 11/28/25.</b>
6.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130	Hot Water: Shower water temperature 70°F at shower # 4 <b>To be repaired by 11/28/25.</b>
7.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling damaged <b>To be repaired and repainted by 12/31/25.</b>
8.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Floor left unfinished next to handwash sinks <b>To be repaired by 12/31/25.</b>



9.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 1 running continuously <b>To be repaired by 11/28/25.</b>
10.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 1 <b>To be repaired by 11/28/25.</b>
11.	A2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 1 and 4 <b>To be repaired by 11/28/25.</b>
12.	A2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door frame rusted <b>To be repaired by 12/31/25.</b>

#### Deficiencies under the Recommended Standards (.300 series)

10 new deficiencies and 8 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	A1 Unit	Main Area	Staff Break Room # A156	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged <b>To be repainted by 3/31/25.</b>
2.	A1 Unit	Main Area	Slop Sink Closet # A155	105 CMR 451.353	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
3.	A1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged <b>To be repaired and repainted by 3/31/25.</b>
4.	A1 Unit	Main Area	Transfer Room # A124	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
5.	A1 Unit	Main Area	Transfer Room # A124	105 CMR 451.353	Interior Maintenance: Door frame rotted <b>To be repaired and repainted by 3/31/25.</b>
6.	A1 Unit	Main Area	Room # A121	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged <b>To be repaired and repainted by 3/31/25.</b>
7.	A1 Unit	Room Corridor	Nurse's Treatment Room # A125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
8.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 123 <b>To be repaired and repainted by 3/31/25.</b>
9.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 116 and 119 <b>To be repainted by 3/31/25.</b>

10. A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 117 <b>To be repaired and repainted by 3/31/25.</b>
11. A2 Unit	Room Corridor	Treatment Room # A2-221	105 CMR 451.353	Interior Maintenance: Wall paint damaged <b>To be repainted by 3/31/25.</b>
12. A2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 216 <b>To be repainted by 3/31/25.</b>
13. A2 Unit	Dorm Corridor		105 CMR 451.353	Interior Maintenance: Paint damaged on hand sanitizer dispenser in hallway <b>To be repainted by 3/31/25.</b>
14. A2 Unit	Dorm Corridor	Dorm # 9	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 3/31/25.</b>
15. A2 Unit	Dorm Corridor	Dorm # 11	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
16. A2 Unit	Dorm Corridor	Dorm # 12	105 CMR 451.353	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 3/31/25.</b>
17. A2 Unit	Dorm Corridor	Dorm # 10	105 CMR 451.353	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>

### Building # 3 – Bradford

#### Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1. B1 Unit	Control	Control Bathroom	105 CMR 451.123	Maintenance: Door damaged <b>To be repaired by 12/31/25.</b>
2. B1 Unit	Main Area	Nurse's Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink <b>To be repaired by 11/28/25.</b>
3. B1 Unit	Main Area	Slop Sink Closet	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink drain clogged <b>To be repaired by 11/28/25.</b>
4. B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on handwash sink unit <b>To be repainted by 12/31/25.</b>
5. B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on toilet partitions <b>To be repainted by 12/31/25.</b>
6. B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall vent dirty and clogged <b>To be cleaned by 12/15/25.</b>



7.	B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Paint damaged on countertop <b>To be repaired and repainted by 12/31/25.</b>
----	---------	---------------	---------------	-----------------	--

**Deficiencies under the Recommended Standards (.300 series)**

5 new deficiencies and 17 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	B1 Unit	Main Area	Transfer Room	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged <b>To be repaired and repainted by 3/31/25.</b>
2.	B1 Unit	Main Area	Transfer Room	105 CMR 451.353	Interior Maintenance: Water pooling on floor around hot water tank <b>To be cleaned by 11/21/25.</b>
3.	B1 Unit	Main Area	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 3/31/25.</b>
4.	B1 Unit	Room Corridor		105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in hallway <b>To be repaired and repainted by 3/31/25.</b>
5.	B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
6.	B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repaired and repainted by 3/31/25.</b>
7.	B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 3/31/25.</b>
8.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 111, 118, and 120 <b>To be repainted by 3/31/25.</b>
9.	B1 Unit	Dorm Corridor	Room # B-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repaired and repainted by 3/31/25.</b>
10.	B1 Unit	Dorm Corridor	Room # B-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
11.	B1 Unit	Dorm Corridor	Room # B-112	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
12.	B2 Unit	Control		105 CMR 451.353	Interior Maintenance: Ceiling dirty around vent <b>To be cleaned by 12/15/25.</b>

13. B2 Unit	Main Area	Mop Closet # B-250	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 3/31/25.</b>
14. B2 Unit	Room Corridor	Treatment Room # B2-221	105 CMR 451.353	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
15. B2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 204, 206, 209, 210, and 218 <b>To be repainted by 3/31/25.</b>

#### Building # 4 - Carter

##### Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 5 repeat deficiencies (indicated by an \*) were found during the inspection:

1. C1 Unit	Control	Control Bathroom	105 CMR 451.123	Maintenance: Door damaged <b>To be repaired by 12/31/25.</b>
2. C1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling damaged <b>To be repaired and repainted by 12/31/25.</b>
3. C1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door frame rusted <b>To be repaired and repainted by 12/31/25.</b>
4. C2 Unit	Main Area	Bathroom # C2-217	105 CMR 451.123*	Maintenance: Floor paint damaged <b>To be repainted by 12/31/25.</b>
5. C2 Unit	Main Area	Bathroom # C2-217	105 CMR 451.123	Maintenance: Door damaged <b>To be repaired and repainted by 12/31/25.</b>
6. C2 Unit	Room Corridor	Rooms	105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure at handwash sink in room # 203 <b>To be repaired by 11/28/25.</b>
7. C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling dirty <b>To be cleaned by 11/28/25.</b>
8. C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling water damaged <b>To be repaired and repainted by 12/31/25.</b>
9. C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Hand dryer out-of-order <b>To be repaired by 12/15/25.</b>
10. C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted <b>To be repaired and repainted by 12/31/25.</b>
11. C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on light fixture <b>To be repainted by 12/31/25.</b>

##### Deficiencies under the Recommended Standards (.300 series)

9 new deficiencies and 60 repeat deficiencies (indicated by an \*) were found during the inspection:



1.	C1 Unit	Main Area		105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in hallway <b>To be repainted by 3/31/25.</b>
2.	C1 Unit	Main Area		105 CMR 451.353	Interior Maintenance: Wall paint damaged in hallway <b>To be repainted by 3/31/25.</b>
3.	C1 Unit	Main Area	Mop Closet # C-155	105 CMR 451.353	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
4.	C1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 3/31/25.</b>
5.	C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged <b>To be repainted by 3/31/25.</b>
6.	C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Door to exterior rotted <b>To be repaired and repainted by 3/31/25.</b>
7.	C1 Unit	Main Area	Storage Room # C-121	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
8.	C1 Unit	Room Corridor		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway <b>To be repainted by 3/31/25.</b>
9.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 115 <b>To be repaired and repainted by 3/31/25.</b>
10.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 102, 103, 104, 105, 107, 108, 109, 110, 111, 112, 114, 115, 116, 118, 119, and 123 <b>To be repainted by 3/31/25.</b>
11.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 103, 104, 106, 110, 113, 114, 116, and 119 <b>To be repainted by 3/31/25.</b>
12.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 112 <b>To be repainted by 3/31/25.</b>
13.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 120 <b>To be repaired and repainted by 3/31/25.</b>
14.	C1 Unit	Dorm Corridor		105 CMR 451.353	Interior Maintenance: Ceiling damaged in hallway <b>To be repaired and repainted by 3/31/25.</b>
15.	C1 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C-105	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
16.	C1 Unit	Dorm Corridor	Unit Director's Office # C-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>

17. C1 Unit	Dorm Corridor	Treatment Team Office # C-107	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
18. C1 Unit	Dorm Corridor	Sensory Room # C-110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
19. C1 Unit	Dorm Corridor	Group Room # C-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
20. C2 Unit	Main Area	Staff Break Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
21. C2 Unit	Main Area	Room # C-220	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
22. C2 Unit	Main Area	Slop Sink Closet # C2-250	105 CMR 451.353	Interior Maintenance: Strong unpleasant odor present <b>To be isolated and repaired by 11/28/25.</b>
23. C2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 223 <b>To be repainted by 3/31/25.</b>
24. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 203, 204, 205, 206, 207, 208, 211, 212, 214, 215, 216, 218, 219, and 221 <b>To be repainted by 3/31/25.</b>
25. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 210, 205, 212, 214, and 216 <b>To be repainted by 3/31/25.</b>
26. C2 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C-204	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
27. C2 Unit	Dorm Corridor	Unit Director's Office # C-205	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
28. C2 Unit	Dorm Corridor	Treatment Team Office # C-206	105 CMR 451.353	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
29. C2 Unit	Dorm Corridor	Sensory Room # C-208	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
30. C2 Unit	Dorm Corridor	Classroom # C-210	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>

#### Building # 5 – Recovery Place

##### Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
-------------------------	------------------	---



2. Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 3/31/25.</b>
-------------------------	------------------	--

#### Building # 7 - Commons

##### Deficiencies under the Required Standards (.100 and .200 series)

10 new deficiencies were found during the inspection:

1. Lobby Area	Laundry	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control leaking at handwash sink <b>To be repaired by 11/28/25.</b>
2. Main Area	Patient Bathroom	105 CMR 451.123	Maintenance: Toilet partitions rusted <b>To be replaced by 12/31/25.</b>
3. Gym	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling paint damaged <b>To be repainted by 12/31/25.</b>
4. School Corridor	Staff Bathroom # CS-01	105 CMR 451.123	Maintenance: Door damaged <b>To be repaired by 12/31/25.</b>
5. School Corridor	Staff Bathroom # CS-01	105 CMR 451.123	Maintenance: Ceiling water damaged <b>To be repaired and repainted by 12/31/25.</b>
6. Kitchen		105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, free standing fan dirty. Standard found in 105 CMR 590; FC 6-501.12(A). ** <b>Corrected On-Site **</b>
7. Kitchen	Ice Machine	105 CMR 451.200	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil/mold observed on interior surfaces of ice machine. Standard found in 105 CMR 590; FC 4-602.11(E)(4)(b). ** <b>Corrected On-Site **</b>
8. Kitchen	Dishwashing Machine Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, sprayer dirty. Standard found in 105 CMR 590; FC 6-501.12(A). ** <b>Corrected On-Site **</b>
9. Kitchen	Refrigerator E	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, refrigerator out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A). <b>To be removed by 3/31/25.</b>

10. Kitchen	Supply Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, Ceiling damaged. Standard found in 105 CMR 590; FC 6-501.11. <b>To be repaired and repainted by 3/31/25.</b>
-------------	-------------	-----------------	--

**Deficiencies under the Recommended Standards (.300 series)**

2 new deficiencies and 20 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Lobby Area		105 CMR 451.353*	Interior Maintenance: Ceiling damaged outside closet # SL-01 <b>To be repaired and repainted by 3/31/25.</b>
2. Lobby Area	Laundry	105 CMR 451.353*	Interior Maintenance: Pipe insulation damaged <b>To be replaced by 3/31/25.</b>
3. Lobby Area	Control	105 CMR 451.353*	Interior Maintenance: Paint damaged on window frames <b>To be repainted by 3/31/25.</b>
4. Main Area		105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 3/31/25.</b>
5. Main Area		105 CMR 451.353*	Interior Maintenance: Floor cracked <b>To be repaired and repainted by 3/31/25.</b>
6. Main Area	Storage Area # CL-11	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 3/31/25.</b>
7. Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
8. Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353*	Interior Maintenance: Floor dirty <b>To be cleaned by 11/21/25.</b>
9. Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353	Interior Maintenance: Wall paint damaged <b>To be repainted by 3/31/25.</b>
10. Gym	Storage Room # CG-23	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 3/31/25.</b>
11. Back Hallway	Recycle Room # CG-11	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 3/31/25.</b>
12. Back Hallway	Recycle Room # CG-11	105 CMR 451.353*	Interior Maintenance: Floor damaged



				<b>To be repaired and repainted by 3/31/25.</b>
13. School Corridor	Library # CS-03		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged <b>To be repaired and repainted by 3/31/25.</b>
14. School Corridor	Life Skills Group Room # CS-10		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged <b>To be repaired and repainted by 3/31/25.</b>
15. School Corridor	Offices		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in # CS-29 <b>To be repaired and repainted by 3/31/25.</b>
16. School Corridor	Offices		105 CMR 451.353*	Interior Maintenance: Door damaged in # CS-29 <b>To be repaired and repainted by 3/31/25.</b>
17. Basement			105 CMR 451.353*	Interior Maintenance: Floor paint damaged in hallway <b>To be repainted by 3/31/25.</b>
18. Basement			105 CMR 451.353	Interior Maintenance: Ceiling damaged in hallway <b>To be repaired and repainted by 3/31/25.</b>
19. Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 3/31/25.</b>
20. Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 3/31/25.</b>
21. Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
22. Basement	Maintenance Department	Mechanical Room A # CB-10	105 CMR 451.353*	Interior Maintenance: Standing water on floor <b>To be cleaned by 11/21/25.</b>

#### **Building # 8 – Hadley**

##### **Deficiencies under the Required Standards (.100 and .200 series)**

3 new deficiencies and 5 repeat deficiencies (indicated by an \*) were found during the inspection:

1. C-Corridor	Bathroom		105 CMR 451.123*	Maintenance: Countertop dirty <b>To be cleaned by 11/21/25.</b>
2. C-Corridor	Bathroom		105 CMR 451.123*	Maintenance: Floor surface damaged at entrance <b>To be repaired by 12/31/25.</b>
3. C-Corridor	Bathroom		105 CMR 451.123*	Maintenance: Wall vent dusty <b>To be cleaned by 12/15/25.</b>
4. C-Corridor	Bathroom		105 CMR 451.123	Maintenance: Radiator rusted <b>To be repaired and repainted by 12/31/25.</b>

5.	C-Corridor	Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, floor drain clogged <b>To be repaired by 11/28/25.</b>
6.	C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door rusted <b>To be repaired and repainted by 12/31/25.</b>
7.	C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door frame rusted <b>To be repaired and repainted by 12/31/25.</b>
8.	C-Corridor	Shower Area	105 CMR 451.123	Maintenance: Wall damaged <b>To be repaired and repainted by 12/31/25.</b>

#### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 24 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	A-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 101, 102, 104, 105, 106, 109, 110, 111, 112, 113, 114, and 115 <b>To be repainted by 3/31/25.</b>
2.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 117, 120, 121, 122, 124, 128, 130, 131, and 132 <b>To be repainted by 3/31/25.</b>
3.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 123 <b>To be repainted by 3/31/25.</b>
4.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117 <b>To be repaired and repainted by 3/31/25.</b>
5.	C-Corridor		105 CMR 451.353	Interior Maintenance: Floor tiles damaged in hallway <b>To be repainted by 3/31/25.</b>
6.	C-Corridor	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
7.	C-Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>

#### Building # 9 – Lenox

#### Deficiencies under the Required Standards (.100 and .200 series)

5 new deficiencies and 6 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Control	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling paint damaged <b>To be repainted by 12/31/25.</b>
2.	A Corridor	Rooms	105 CMR 451.103	Mattresses: Mattress cover missing in room # 111 <b>Cover provided on 11/24/25.</b>
3.	C Corridor	Slop Sink Closet # M-251	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink <b>To be repaired by 11/28/25.</b>



4.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance <b>To be repaired and repainted by 12/31/25.</b>
5.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Radiator rusted <b>To be repaired and repainted by 12/31/25.</b>
6.	C Corridor	Patient Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 1 running continuously <b>To be repaired by 11/28/25.</b>
7.	C Corridor	Patient Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink # 1 out-of-order <b>To be repaired by 11/28/25.</b>
8.	C Corridor	Patient Bathroom	105 CMR 451.126*	Hot Water for Bathing and Hygiene: Hot water temperature 86°F at handwash sink # 2 <b>To be repaired by 11/28/25.</b>
9.	C Corridor	Shower Room	105 CMR 451.130*	Hot Water: Shower water temperature 86°F <b>To be repaired by 11/28/25.</b>
10.	C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Door rusted <b>To be repaired and repainted by 12/31/25.</b>
11.	C Corridor	Shower Room	105 CMR 451.123	Maintenance: Ceiling vent rusted <b>To be repaired and repainted by 12/31/25.</b>

#### Deficiencies under the Recommended Standards (.300 series)

4 new deficiencies and 21 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Control		105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 3/31/25.</b>
2.	A Corridor	Transfer Room # M-228	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 3/31/25.</b>
3.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 106, 108, 110, 111, and 113 <b>To be repainted by 3/31/25.</b>
4.	A Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 107 <b>To be repainted by 3/31/25.</b>
5.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 104 and 112 <b>To be repaired and repainted by 3/31/25.</b>

6.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 120, 124, 126, 127, 128, 129, 130, and 131 <b>To be repainted by 3/31/25.</b>
7.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Ceiling damaged in room # 124 <b>To be repaired and repainted by 3/31/25.</b>
8.	B Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 130 <b>To be repainted by 3/31/25.</b>
9.	C Corridor	Staff Break Room # M-252	105 CMR 451.353*	Interior Maintenance: Countertop damaged <b>To be repaired and repainted by 3/31/25.</b>
10.	C Corridor	Slop Sink Closet # M-251	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
11.	C Corridor	Slop Sink Closet # M-251	105 CMR 451.353	Interior Maintenance: Wet mop in bucket <b>Mop appropriately stored on 11/18/25.</b>
12.	C Corridor	Toxic/Caustic Closet # M-250	105 CMR 451.353	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>

#### Building # 10 – Berkshire

##### Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an \*) was found during the inspection:

1.	Right Side	Slop Sink # MM-03	105 CMR 451.353*	Interior Maintenance: Door damaged <b>To be repaired and repainted by 3/31/25.</b>
----	------------	-------------------	------------------	---

#### Building # 11 – Lighthouse

##### Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 11 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Booking Corridor	Female Bathroom # H-172	105 CMR 451.123*	Maintenance: Partitions rusted <b>To be repaired and repainted by 12/31/25.</b>
2.	Booking Corridor	Female Bathroom # H-172	105 CMR 451.123	Maintenance: Ceiling damaged <b>To be repaired and repainted by 12/31/25.</b>
3.	Booking Corridor	Male Bathroom # H-173	105 CMR 451.123*	Maintenance: Floor cracked <b>To be repaired and repainted by 12/31/25.</b>

4. Booking Corridor	Male Bathroom # H-173	105 CMR 451.123*	Maintenance: Partitions rusted <b>To be repaired and repainted by 12/31/25.</b>
5. Infirmary	Dorm # 3/Bathroom	105 CMR 451.123*	Maintenance: Door frame rusted in bathroom <b>To be repaired and repainted by 12/31/25.</b>
6. Infirmary	Dorm # 3/Bathroom	105 CMR 451.123*	Maintenance: Handwash sink rusted <b>To be repaired and repainted by 12/31/25.</b>
7. Infirmary	Nurse's Bathroom	105 CMR 451.123*	Maintenance: Ceiling vent dusty <b>To be cleaned by 12/15/25.</b>
8. Infirmary	Dorm # 4/Bathroom	105 CMR 451.123*	Maintenance: Door frame rusted in shower room <b>To be repaired and repainted by 12/31/25.</b>
9. Infirmary	Dorm # 4/Bathroom	105 CMR 451.123*	Maintenance: Wall tiles damaged in shower <b>To be repaired and repainted by 12/31/25.</b>
10. Infirmary	Shower Room	105 CMR 451.123	Maintenance: Door damaged <b>To be repaired and repainted by 12/31/25.</b>
11. Medical West Unit	Bathroom # 138 (Storage)	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, urinal running continuously <b>To be repaired by 11/28/25.</b>
12. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Wall tile grout dirty <b>To be cleaned by 11/21/25.</b>
13. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Door frame rusted <b>To be repaired and repainted by 12/31/25.</b>

#### Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 12 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Basement	Mechanical Room	105 CMR 451.353	Interior Maintenance: Water pooling on floor <b>To be cleaned by 11/21/25.</b>
2. First Floor	Clinic Corridor Pharmacy # H-161	105 CMR 451.353	Interior Maintenance: Wall vent dusty <b>To be cleaned by 12/15/25.</b>
3. Old Seclusion Area		105 CMR 451.353	Interior Maintenance: Rear door stuck shut <b>To be repaired by 11/30/25.</b>
4. Old Seclusion Area	Office # 207	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged <b>To be repaired and repainted by 3/31/25.</b>
5. Booking Corridor		105 CMR 451.353	Interior Maintenance: Ceiling water damaged in hallway



			<b>To be repaired and repainted by 3/31/25.</b>
6. Booking Corridor	Admissions Office # H-149	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged <b>To be repaired and repainted by 3/31/25.</b>
7. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Medical waste storage chest rusted <b>To be repaired and repainted by 3/31/25.</b>
8. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Door frame rotted <b>To be repaired and repainted by 3/31/25.</b>
9. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Door rusted <b>To be repaired and repainted by 3/31/25.</b>
10. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior <b>To be made rodent and weathertight by 11/30/25.</b>
11. Infirmary	Dorm # 3/Bathroom	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm <b>To be repainted by 3/31/25.</b>
12. Infirmary	Dorm # 3/Bathroom	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm <b>To be repainted by 3/31/25.</b>
13. Infirmary	Nurse's Office # H-145	105 CMR 451.353	Interior Maintenance: Ceiling dirty around vent <b>To be cleaned by 12/15/25.</b>
14. Infirmary	Dorm # 5	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>
15. Laundry Hallway		105 CMR 451.353*	Interior Maintenance: Door to exterior rusted <b>To be repaired and repainted by 3/31/25.</b>
16. Laundry Hallway	Laundry	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 3/31/25.</b>
17. Medical West Unit	Room # 5 # H-131	105 CMR 451.353*	Interior Maintenance: Floor rust stained <b>To be repaired and repainted by 3/31/25.</b>
18. Medical West Unit	Room # 6 # H-130	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 3/31/25.</b>

#### Staff Gym

**Deficiencies under the Required Standards (.100 and .200 series)**

2 new deficiencies and 1 repeat deficiency (indicated by an \*) were found during the inspection:

1. Male Locker Room	105 CMR 451.123*	Maintenance: Ceiling tiles water stained <b>To be replaced by 12/31/25.</b>
2. Male Locker Room	105 CMR 451.123	Maintenance: Wall water damaged <b>To be repaired and repainted by 12/31/25.</b>
3. Female Locker Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet out-of-order in left side stall <b>To be repaired by 11/28/25.</b>

**Deficiencies under the Recommended Standards (.300 series)**

2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Common Area	105 CMR 451.353*	Interior Maintenance: Carpet damaged <b>To be repaired by 3/31/25.</b>
2. Common Area	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained <b>To be replaced by 12/31/25.</b>

**SECTION 2: Areas Found to be in Compliance**

The EHRS inspected 273 additional areas of the facility which were found to be in compliance.

**Section 3: Areas EHRS did not inspect**

EHRS did not inspect 10 areas of the facility because they were either in use, under construction, or presented security concerns:

1. BUILDING # 3 – BRADFORD	B1 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
2. BUILDING # 3 – BRADFORD	B2 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
3. BUILDING # 9 – Lenox	C Corridor	Storage Room # M-248		Unable to Inspect – Security Concerns
4. BUILDING # 9 – Lenox	C Corridor	Secure Interview Room # M-247		Unable to Inspect – Security Concerns
5. BUILDING # 9 – Lenox	C Corridor	Laundry Room # 1		Unable to Inspect – Security Concerns
6. BUILDING # 9 – Lenox	C Corridor	Laundry Room # 2		Unable to Inspect – Security Concerns
7. BUILDING # 9 – Lenox	C Corridor	Storage Room # M-243		Unable to Inspect – Security Concerns
8. BUILDING # 9 – Lenox	C Corridor	Group Rooms		Unable to Inspect – Security Concerns
9. BUILDING # 9 – Lenox	C Corridor	Secure Interview Room # M-234		Unable to Inspect – Security Concerns

10. BUILDING # 11 – LIGHTHOUSE (Medical)	Booking Corridor	New Admissions Area	Unable to Inspect – Under Construction
--	------------------	------------------------	---

#### **SECTION 4: Plan of Correction**

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

#### **SECTION 5: Observations and Recommendations**

1. The patient population was 210 at the time of inspection.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Correctional Facilities" 105 CMR 451.000 is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,

Patrick Wallace,  
Environmental Health Officer, EHRS, BCEH





The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards  
5 Randolph Street  
Canton, MA 02021  
617-624-6000 | mass.gov/dph

**Maura T. Healey**  
Governor

**Kimberley Driscoll**  
Lieutenant Governor

**Kiame Mahaniah, MD, MBA**  
Secretary

**Robert Goldstein, MD, PhD**  
Commissioner

December 2, 2025

Jeffrey Gonsalves, Superintendent  
Bridgewater State Hospital  
20 Administration Road  
Bridgewater, MA 02324 (electronic copy)

Re: Plan of Correction – Bridgewater State Hospital

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction (POC) in response to my inspection on October 29 and 30, 2025. After review, EHRS finds the plan appropriately addresses all the deficiencies noted in the report.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

A handwritten signature in blue ink that reads "Patrick Wallace".

Patrick Wallace  
Environmental Analyst, EHRS, BCEH

cc: James Rioux, Deputy Superintendent  
Michael Rosano, Environmental Health and Safety Officer

(electronic copy)  
(electronic copy)