

The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards  
5 Randolph Street  
Canton, MA 02021  
617-624-6000 | mass.gov/dph

**Maura T. Healey**  
Governor

**Kimberley Driscoll**  
Lieutenant Governor

**Kiame Mahaniah, MD, MBA**  
Secretary

**Robert Goldstein, MD, PhD**  
Commissioner

January 5, 2026

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)  
Kiame Mahaniah, Secretary, Executive Office of Health and Human Services (electronic copy)  
Clerk, Massachusetts House of Representatives (electronic copy)  
Clerk, Massachusetts Senate (electronic copy)  
John Aponte, Environmental Health and Safety Officer (electronic copy)

Greetings,


Pursuant to 105 CMR 451.403, please find the inspection report for Massachusetts Treatment Center, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

A handwritten signature in blue ink that reads "Patrick Wallace".

Patrick Wallace  
Environmental Analyst, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)  
Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)  
Eric J. Badger, Health Agent, Bridgewater Board of Health (electronic copy)  
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)  
Lisa Curto, Superintendent (electronic copy)  
Sally Desrosiers, Deputy Superintendent (electronic copy)



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards  
5 Randolph Street Canton, MA 02021  
617-624-6000 | [mass.gov/dph](http://mass.gov/dph)

**Maura T. Healey**  
Governor

**Kimberley Driscoll**  
Lieutenant Governor

**Kiame Mahaniah, MD, MBA**  
Secretary  
**Robert Goldstein, MD, PhD**  
Commissioner

November 26, 2025

Lisa Curto, Superintendent  
Massachusetts Treatment Center  
30 Administration Road  
Bridgewater, MA 02324      (electronic copy)

Re: Facility Inspection – Massachusetts Treatment Center, Bridgewater

Dear Superintendent Curto:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Massachusetts Treatment Center on November 12, 2025 accompanied by John Aponte, Environmental Health and Safety Officer and Nathan Frazier, Facility Maintenance Director, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 149 total deficiencies: 74 new deficiencies under the Required Standards (100 and .200 series), 14 repeat deficiencies under the Required Standards, 25 new deficiencies under the Recommended Standards (.300 series), and 36 repeat deficiencies under the Recommended Standards.

#### Overview

**Section 1** provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

**Section 2** provides information on areas that EHRS found to be compliant.

**Section 3** documents the areas that EHRS did not inspect.

**Section 4** provides information on submitting a Plan of Correction for the identified deficiencies.

**Section 5** outlines observations and recommendations related to the inspection.

## **SECTION 1: Health and Safety Deficiencies**

### **Front Lobby**

#### **Deficiencies under the Recommended Standards (.300 series)**

1 repeat deficiency (indicated by an \*) was found during the inspection:

1. Waiting Area	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
-----------------	------------------	---

### **Administration Area**

#### **Deficiencies under the Recommended Standards (.300 series)**

1 repeat deficiency (indicated by an \*) was found during the inspection:

1. Main Area	105 CMR 451.353*	Interior Maintenance: Ceiling tiles missing
--------------	------------------	---

### **Control Area**

#### **Deficiencies under the Recommended Standards (.300 series)**

1 repeat deficiency (indicated by an \*) was found during the inspection:

1. Central Tower	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
------------------	------------------	---

### **Fire Safety Room**

#### **Deficiencies under the Recommended Standards (.300 series)**

1 repeat deficiency (indicated by an \*) was found during the inspection:

1. Central Laundry	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
--------------------	------------------	---

### **A Units**

#### **Deficiencies under the Required Standards (.100 and .200 series)**

1 new deficiency and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1. A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # AM-12
2. A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Floor surface damaged in shower # AM-12
3. A1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # AG-13
4. A2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Mold observed on ceiling in shower # AG-36

#### **Deficiencies under the Recommended Standards (.300 series)**

1 new deficiency and 5 repeat deficiencies (indicated by an \*) were found during the inspection:

1. A1 Unit	Slop Sink # A1-1	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
2. A1 Unit	Cells	105 CMR 451.320*	Cell Size: Inadequate floor space, some cells double bunked
3. A1 Unit	Cells	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 1

4. A2 Unit	Common Area	105 CMR 451.353*	Interior Maintenance: Floor paint damaged on handicapped ramp
5. A2 Unit	Utility Closet	105 CMR 451.353	Interior Maintenance: Floor paint damaged
6. A2 Unit	Cells	105 CMR 451.320*	Cell Size: Inadequate floor space, some cells double bunked

## Health Services Unit

### Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an \*) was found during the inspection:

1. Room # A1-57	105 CMR 451.353*	Interior Maintenance: Floor damaged at entrance
-----------------	------------------	---

## B Units

### Deficiencies under the Required Standards (.100 and .200 series)

8 new deficiencies and 4 repeat deficiencies (indicated by an \*) were found during the inspection:

1. B1 Unit	Common Area	105 CMR 451.126*	Hot Water for Bathing and Hygiene: No hot water supplied to handwash sink
2. B1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Ceiling damaged in shower # BG-12
3. B2 Unit	Common Area	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 70°F at kitchenette handwash sink
4. B2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # BM-35
5. B2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # BM-36
6. B2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # BM-35 and BM-36
7. B2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Ceiling rusted in shower # BG-35
8. B2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # BG-35 and BG-36
9. B2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Soap scum on floor in shower # BG-35 and BG-36

### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1. B1 Unit	Cells	105 CMR 451.320*	Cell Size: Inadequate floor space, some cells double bunked
2. B2 Unit	Common Area	105 CMR 451.353*	Interior Maintenance: Wall paint damaged outside shower # BG-35
3. B2 Unit	Common Area	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty above kitchenette
4. B2 Unit	Slop Sink Closet # B1-11	105 CMR 451.353	Interior Maintenance: Mold observed on walls
5. B2 Unit	Cells	105 CMR 451.320*	Cell Size: Inadequate floor space, some cells double bunked

## Food Service Areas

### Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Kitchen		105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, floor tile grout dirty throughout. Standard found in 105 CMR 590; FC 6-501.12(A).
2. Kitchen	Handwash Sink	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, hot water not working. Standard found in 105 CMR 590; FC 5-205.15(B).
3. Kitchen	Serving Area	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, one tray warmer out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A).
4. Kitchen	Rinse/Dishwashing Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, sprayer head dirty. Standard found in 105 CMR 590; FC 6-501.12(A). <b>** Corrected On-Site **</b>
5. Kitchen	Dry Storage	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, floor surface damaged. Standard found in 105 CMR 590; FC 6-501.11.
6. Kitchen	Recycling Area	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, recycling carts damaged. Standard found in 105 CMR 590; FC 4-501.11(A).
7. Staff Food Service	Warewash Machine	105 CMR 451.200	Maintenance and Operation; Equipment: Chlorine Sanitizer solution tested lower than recommended concentration. Standard found in 105 CMR 590; FC 4-501.114(A).
8. Staff Food Service	Refrigerator # 7	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, refrigerator out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A).
9. Staff Food Service	3-Compartment Sink	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, water control leaking. Standard found in 105 CMR 590; FC 5-205.15(B).

## Gym

### Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1.	Male Staff Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink rusted
----	---------------------	-----------------	--

### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies were found during the inspection:

1.	Equipment Room	105 CMR 451.353	Interior Maintenance: Wall vent dusty
2.	Recreation Officer's Office	105 CMR 451.353	Interior Maintenance: Ceiling damaged

## C Units

### Deficiencies under the Required Standards (.100 and .200 series)

8 new deficiencies were found during the inspection:

1.	C1 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # CM-12 and CM-13
2.	C1 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Soap scum on floor in shower # CM-12 and CM-13
3.	C1 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Ceiling vent loose in shower # CM-13
4.	C2 Unit	Common Area	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink
5.	C2 Unit	Second Floor Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # CM-35 and CM-36

### Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies were found during the inspection:

1.	C1 Unit	Cells	105 CMR 451.320	Cell Size: Inadequate floor space, some cells double bunked
2.	C2 Unit	Slop Sink Closet # C1-11	105 CMR 451.353	Interior Maintenance: Walls dirty
3.	C2 Unit	Cells	105 CMR 451.320	Cell Size: Inadequate floor space, some cells double bunked

## D Units

### Deficiencies under the Required Standards (.100 and .200 series)

36 new deficiencies were found during the inspection:

1.	D1 Unit	2nd Floor Showers	105 CMR 451.130	Hot Water: Shower water temperature 89°F in shower # DM-13
2.	D1 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Floor epoxy damaged in shower # DM-12 and DM-13
3.	D1 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Soap scum on floor in shower # DM-12 and DM-13

4. D1 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Ceiling vent rusted in shower # DM-12
5. D1 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # DM-12 and DM-13
6. D1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # DG-12 and DG-13
7. D1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Floor epoxy damaged in shower # DG-12 and DG-13
8. D1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Soap scum on floor in shower # DG-12 and DG-13
9. D1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Wall caulking dirty in shower # DG-12 and DG-13
10. D1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Seat damaged in shower # DG-13
11. D1 Unit	Cells	105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure at handwash sink in cell # 18
12. D2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # DM-35
13. D2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # DM-35
14. D2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # DM-35 and DM-36
15. D2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Soap scum on floor in shower # DM-35 and DM-36
16. D2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # DM-35 and DM-36
17. D2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # DG-35 and DG-36
18. D2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Soap scum on floor in shower # DG-35 and DG-36
19. D2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # DG-35 and DG-36
20. D2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # DG-35 and DG-36
21. D2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Ceiling rusted in shower # DG-35 and DG-36

#### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1. D1 Unit	Common Area	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty above handwash sink
2. D1 Unit	Common Area	105 CMR 451.353	Interior Maintenance: Paper towel dispenser rusted
3. D1 Unit	Cells	105 CMR 451.320*	Cell Size: Inadequate floor space, some cells double bunked
4. D2 Unit	Cells	105 CMR 451.320*	Cell Size: Inadequate floor space, some cells double bunked
5. D2 Unit	Cells	105 CMR 451.353*	Interior Maintenance: Ceiling damaged in cell # 21

**B.A.U.****Deficiencies under the Required Standards (.100 and .200 series)**

2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Main Area	Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # 1
2. Main Area	Showers	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower # 2 out-of-order

**Deficiencies under the Recommended Standards (.300 series)**

4 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Main Area	Cells	105 CMR 451.353*	Interior Maintenance: Light shield damaged in cell # 7
2. Main Area	Cells	105 CMR 451.353*	Interior Maintenance: Floor damaged in cell # 7
3. Main Area	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # 3 and 4

**Modular Units – South****Deficiencies under the Required Standards (.100 and .200 series)**

4 new deficiencies and 2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. South 1	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Wall water damaged above showers
2. South 1	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Door frame rusted at entrance to showers
3. South 1	Dorm Hallway	East Bathroom	105 CMR 451.123*	Maintenance: Ceiling paint damaged near showers
4. South 1	Dorm Hallway	East Bathroom	105 CMR 451.123	Maintenance: Wall left unfinished near entrance
5. South 1	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 2 out-of-order
6. South 2	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water control missing at handwash sink # 5

**Deficiencies under the Recommended Standards (.300 series)**

10 new deficiencies and 14 repeat deficiencies (indicated by an \*) were found during the inspection:

1. South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm room # 102, 103, 104, 107, and 108
2. South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in dorm room # 113
3. South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall water damaged in dorm room # 113

4. South 1	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room # 106
5. South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Door hardware damaged in dorm room # 109
6. South 1	Dorm Hallway	Dorms	105 CMR 451.344	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 106 and 111
7. South 1	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Wall vent blocked in dorm room # 101, 102, 103, 104, 105, and 109
8. South 1	Dorm Hallway	Utility Closet	105 CMR 451.353	Interior Maintenance: Walls dirty
9. South 2	Common Area	Back Rooms	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in left side back room
10. South 2	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Ceiling damaged in dorm room # 201 and 207
11. South 2	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light flickering in dorm room # 211
12. South 2	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 206 and 210

#### Modular Units – North

##### Deficiencies under the Required Standards (.100 and .200 series)

10 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1. North 1	Dorm Hallway	Utility Closet	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink leaking
2. North 1	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control missing at handwash sink # 2
3. North 1	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 2 out-of-order
4. North 1	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Ceiling paint damaged outside showers
5. North 1	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Door frame rotted
6. North 2	Dorm Hallway	East Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower # 1 leaking
7. North 2	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink # 4

8.	North 2	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control missing at handwash sink # 4 and 6
9.	North 2	Dorm Hallway	West Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, sink basin loose at handwash sink # 5
10.	North 2	Dorm Hallway	West Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 1 and 3 out-of-order
11.	North 2	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Caulking dirty around handwash sink # 7

#### **Deficiencies under the Recommended Standards (.300 series)**

5 new deficiencies and 2 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	North 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall damaged in dorm room # 157
2.	North 1	Dorm Hallway	Dorms	105 CMR 451.344	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 153 and 160
3.	North 2	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Wall damaged in dorm room # 254 and 261
4.	North 2	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room # 253
5.	North 2	Dorm Hallway	Utility Closet	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket

#### **SECTION 2: Areas Found to be in Compliance**

EHRS inspected 180 additional areas of the facility which were found to be in compliance.

#### **Section 3: Areas EHRS did not inspect**

EHRS did not inspect 5 areas of the facility because they were either in use, locked, or under construction:

1.	A1 Unit	2nd Floor Showers	Unable to Inspect Shower # AM-13 - Under Construction
2.	A1 Unit	1st Floor Showers	Unable to Inspect Shower # AG-13 – In Use
3.	A2 Unit	2nd Floor Showers	Unable to Inspect – Under Construction
4.	D1 Unit	Therapy Room # D1-3	Unable to Inspect – Under Construction
5.	South 2	West Bathroom	Unable to Inspect – Under Construction

#### **SECTION 4: Plan of Correction**

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

#### **SECTION 5: Observations and Recommendations**

1. The inmate population was 508 at the time of inspection.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Correctional Facilities" [105 CMR 451.000](http://www.mass.gov/dph/dcs/105-cmr-451.000) is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Patrick Wallace  
Environmental Analyst, EHRS, BCEH



*The Commonwealth of Massachusetts*  
*Executive Office of Public Safety & Security*  
*Department of Correction*  
*Massachusetts Treatment Center*  
*30 Administration Road*  
*Bridgewater, MA 02324*  
*Tel: (508) 279-8100*  
*www.mass.gov/doc*



**MAURA T. HEALEY**  
*Governor*

**KIMBERLEY DRISCOLL**  
*Lieutenant Governor*

**GINA K. KWON**  
*Secretary*

**SHAWN P. JENKINS**  
*Commissioner*


December 4, 2025

Patrick Wallace, Environmental Health Inspector, CSP, BEH  
Bureau of Environmental Health  
Community Sanitation Program  
5 Randolph Street  
Canton, MA 01583

Dear Inspector Wallace:

I am in receipt of the bi-annual Department of Public Health Inspection, which was held on November 12, 2025, in accordance with Chapter 11, Section 5 and 20 of the Massachusetts General Laws; Department of Public Health Regulation 105 CMR 451: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

I have enclosed for your review Massachusetts Treatment Center's plan of corrective report. Many of the discrepancies noted have been corrected. Dates of completion have been provided for the discrepancies in need of resolution. Should you have any questions or require any additional information, please do not hesitate to contact my office.

Sincerely,  
  
Lisa M. Curto  
Superintendent

cc: Jeffrey Fisher, Assistant Deputy Commissioner, Health Services Division  
Sally Desrosiers, Deputy Superintendent of Operations  
Lynn Lizotte, Deputy Superintendent of Reentry  
Nathan Frazier, Director of Facility Maintenance  
John Aponte, Fire Safety/EHSO Officer

**INSTITUTION NAME:**

Massachusetts Treatment Center  
30 Administration Road  
Bridgewater, MA 02324

**SUPERINTENDENT:**

Lisa Curto, Superintendent

**ENVIRONMENTAL HEALTH OFFICER:**

John Aponte, Correction Officer

**INSPECTION DATE:**

November 12, 2025

**INSPECTOR:**

Patrick Wallace, Environmental Health Inspector, CSP, BEH

**FRONT LOBBY**

<i>Waiting Area</i>		<i>Interior Maintenance: Ceiling tiles missing</i>	<i>Responsible Staff: Maintenance Corrective Action: Scrap and Paint Completion Date: 12/30/25</i>
<i>105 CMR 451.353*</i>			

**Administration Area**

<i>Main Area</i>		<i>Interior Maintenance: Ceiling tiles missing</i>	<i>Responsible Staff: Maintenance Corrective Action: Changing to 2x2 Acoustics Completion Date: 2/17/26</i>
<i>105 CMR 451.353*</i>			

**CONTROL AREA**

<i>Central Tower</i>		<i>Interior Maintenance: Floor surface damaged</i>	<i>Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 11/20/25</i>
<i>105 CMR 451.353*</i>			

## FIRE SAFETY ROOM

<i>Central Laundry</i> 105 CMR 451.353*	Interior Maintenance: Floor paint damaged	Responsible Staff: Maintenance Corrective Action: Scrape, Grind, and seal Completion Date: 12/31/25
--	---	---

## A UNITS

<i>A1 Unit 1<sup>st</sup> Floor Showers</i>	
105 CMR 451.123	Maintenance: Door frame rusted in shower #AG-13
A1 Unit 1 <sup>st</sup> Floor Showers	Unable to Inspect shower # AG-13-In Use

<i>A1 Unit 2<sup>nd</sup> Floor Showers</i>	
105 CMR 451.123*	Maintenance: Door frame rusted in shower #AM-12
105 CMR 451.123*	Maintenance: Floor surface damaged in shower # AM-12
A1 Unit 2 <sup>nd</sup> Floor Showers	Unable to Inspect Shower # AM-13 Under Construction

<i>A1 Unit Cells</i>	
105 CMR 451.353*	Interior Maintenance: Wall paint damage in cell #1
105 CMR 451.320*	Cell Size: Inadequate floor space, some cells double bunked

<i>Slop Sink #A1-1</i>	
105 CMR 451.353*	Interior Maintenance: Floor paint damaged

<i>A2 Unit 1<sup>st</sup> Floor Showers</i>		Maintenance: Mold observed on ceiling in shower #AG-36	Responsible Staff: Maintenance Corrective Action: Cleaned Completion Date: 11/21/25
<i>A2 Unit 2<sup>nd</sup> Floor Showers</i>		Unable to Inspect-Under Construction	
<i>A2 Unit Cells</i>		Cell Size: Inadequate floor space, some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
<i>A2 Common Area</i>		Interior Maintenance: Floor paint damage on handicapped ramp	Responsible Staff: Maintenance Corrective Action: Grind and repaint ramp Completion Date: 1/23/26
<i>Utility Closet</i>		Interior Maintenance: Floor paint damaged.	Responsible Staff: Maintenance Corrective Action: Scrape and re-paint Completion Date: 1/23/26
<b><u>HEALTH SERVICES UNIT</u></b>			
<i>Room #41-57</i>		Maintenance: Floor surface damaged at entrance	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 12/23/25

## B UNITS

### B1 Unit

<i>All Cells</i>	
105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked

#### *Common area*

105 CMR 451.126*	Hot Water for Bathing and Hygiene: No hot water supplied to handwash sink
------------------	---

#### *B1 Unit 1<sup>st</sup> Floor Showers*

105 CMR 451.123*	Maintenance: Ceiling damaged in shower #BG-12
------------------	---

### B2 Unit

#### *Common Area*

105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 70 F at kitchenette handwash sink	Responsible Staff: Maintenance Corrective Action: Mixing valve fixed Completion Date: 12/1/25
105 CMR 451.353*	Interior Maintenance: Wall paint damaged outside shower #BG-35	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 12/19/25
105 CMR 451.353	Interior Maintenance: Ceiling vent dusty above kitchenette	Responsible Staff: Maintenance Corrective Action: Cleaned vents Completion Date: 12/19/25

#### *B2 Unit Cells*

105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
------------------	--	---

**B2 Unit 1<sup>st</sup> Floor Showers**

105 CMR 451.123*	Maintenance: Ceiling rusted in shower #BG-35	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/4/25
105 CMR 451.123	Maintenance: Ceiling damaged in shower BG-35 and BG-36	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/4/25
105 CMR 451.123	Maintenance: Soap scum on floor and shower #BG-35 BG-36	Responsible Staff: Maintenance Corrective Action: Cleaned floor and shower Completion Date: 11/24/25

**B2 Unit 2<sup>nd</sup> Floor Showers**

105 CMR 451.123*	Maintenance: Door frame rusted in shower #BM-35	Responsible Staff: Maintenance Corrective Action: Paint and scrape Completion Date: 12/30/25
105 CMR 451.123	Maintenance: Door frame rusted in shower #BM-36	Responsible Staff: Maintenance Corrective Action: Paint and scrape Completion Date: 12/30/25
105 CMR 451.123	Maintenance: Ceiling dirty in shower #BM-35 and BM-36	Responsible Staff: Maintenance Corrective Action: Cleaned shower Completion Date: 11/21/25

**Slop Sink Closet #B1-11**

105 CMR 451.353	Interior Maintenance: Mold observed on walls	Responsible Staff: Maintenance Corrective Action: Cleaned walls Completion Date: 11/21/25
-----------------	--	---

**FOOD SERVICE****Kitchen**

105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures-Methods; Facility not cleaned as often as necessary, floor tile grout dirty throughout. Standard found in 105 CMR 590; FC 6-501.11.	Responsible Staff: Maintenance Corrective Action: Cleaned area Completion Date: 11/13/25
-----------------	---	--

<i>Handwash sink</i>	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, hot water not working. Standard found in 105 CMR 590; FC 5-205.15(B).	Responsible Staff: Maintenance Corrective Action: Repaired plumbing Completion Date: 11/13/25
<i>Serving Area</i>			
105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair; one tray warmer out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A)	Responsible Staff: Maintenance Corrective Action: Cleaned area Completion Date: 11/12/25	
<i>Dry Storage</i>			
105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures-Methods; Facility not in good repair, floor surface damaged. Standard found in 105 CMR 590; FC 6-501.11.	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/22/25	
<i>Rinse/Dishwashing Area:</i>			
105 CMR 451.200*	Maintenance and Operations, Premises, Structure, Attachments, and Fixtures-Methods: Facility not cleaned as often as necessary, sprayer head dirty. Standard found in 105 CMR 590; FC 6-501.12(A)	Responsible Staff: Maintenance Corrective Action: **Corrected on Site** Completion Date: 11/12/25	
<i>Recycling Area:</i>			
105 CMR 451.200*	Maintenance and Operations, Equipment: Equipment not maintained in a state of good repair, recycling carts damaged. Standard found in 105 CMR 590; FC 4-501.11(A)	Responsible Staff: Maintenance Corrective Action: Fixed damaged recycling carts Completion Date: 12/22/25	
<i>3 Compartment sink</i>			
105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, water control leaking. Standard found in 105 CMR 590; FC S-205.15(B)	Responsible Staff: Maintenance Corrective Action: Plumbing repaired Completion Date: 12/26/25	
<i>Warewash Machine</i>			
105 CMR 451.200	Maintenance and Operation; Equipment: Chlorine Sanitizer solution tested lower than recommended concentration. Standard found in 105 CMR 590; FC 4-501.114(A)	Responsible Staff: Maintenance Corrective Action: Adjusted recommended concentration Completion Date: 11/17/25	

**Refrigerator #7**

105 CMR 451.200	Maintenance and Operation; Equipment: Equipment not maintained in a state of good repair, refrigerator out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A)	Responsible Staff: Maintenance Corrective Action: Repaired and in service Completion Date: 11/25/25
-----------------	--	---

**Gym:**

<i>Male Staff Bathroom</i>	Plumbing: Plumbing not in good repair; handwash sink rusted	Responsible Staff: Maintenance Corrective Action: Repair plumbing Completion Date: 2/11/25
----------------------------	---	--

<i>Equipment Room</i>	Interior Maintenance: Wall vent dusty	Responsible Staff: Maintenance Corrective Action: Cleaned vent Completion Date: 11/17/25
-----------------------	---------------------------------------	--

<i>Recreation Officer's Office</i>	Interior Maintenance: Ceiling damaged	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 12/17/25
------------------------------------	---------------------------------------	--

**C UNITS****C1 Unit**

<i>C1 Unit 2<sup>nd</sup> Floor Showers</i>	Maintenance: Soap scum on walls in shower #CM-12 and CM-13	Responsible Staff: Maintenance Corrective Action: Cleaned shower walls Completion Date: 11/21/25
105 CMR 451.123	Maintenance: Soap scum on floor in shower #CM-12 and CM-13	Responsible Staff: Maintenance Corrective Action: Cleaned shower floors Completion Date: 11/21/25
105 CMR 451.123	Maintenance: Ceiling vent loose in shower #CM-13	Responsible Staff: Maintenance Corrective Action: Vent tightened Completion Date: 12/5/25

<b>C1 Unit Cells</b>			
105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.	
<b>C2 Unit</b>			
<i>C2 Unit 2<sup>nd</sup> Floor Showers</i>		Responsible Staff: Maintenance	Corrective Action: Scrape and paint
105 CMR 451.123	Maintenance: Door frame rusted in shower #CM-35 and CM-36	Completion Date: 1/20/26	
<i>Common Area</i>		Responsible Staff: Maintenance	Corrective Action: Replace
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair; faucet leaking at handwash sink	Completion Date: 1/22/26	
<i>C2 Unit Cells</i>		Responsible Staff: Maintenance	Corrective Action: Replace
105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked	Completion Date: 1/22/26	
<i>Slop Sink Closet # C1-11</i>		Responsible Staff: Maintenance	Corrective Action: Cleaned Walls
105 CMR 451.353	Interior Maintenance: Walls dirty	Completion Date: 11/24/25	
<b>D UNITS</b>			
<b>D1 Unit</b>			
<i>All Cells</i>		Responsible Staff: Maintenance	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked	Completion Date: 11/24/25	

DI Unit Cells		Water Supply: Insufficient water supply in quantity and pressure at handwash sink in cell #18	Responsible Staff: Maintenance Corrective Action: Water pressure adjusted Completion Date: 12/1/25
<i>Common Area:</i>			
105 CMR 451.124		Interior Maintenance: Ceiling vent dusty above handwash sink	Responsible Staff: Maintenance Corrective Action: Cleaned vent Completion Date: 12/5/25
105 CMR 451.353		Interior Maintenance: Paper towel dispenser rusted	Responsible Staff: Maintenance Corrective Action: Dispenser replaced Completion Date: 12/5/25
<i>DI Unit 1<sup>st</sup> Floor Showers</i>			
105 CMR 451.123	DG-13	Maintenance: Door frame rusted in shower #DG-12 and DG-13	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 1/15/26
105 CMR 451.123	DG-13	Maintenance: Floor epoxy damaged in shower #DG-12 and DG-13	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 1/20/26
105 CMR 451.123	DG-13	Maintenance: Soap scum on floor in shower #DG-12 and DG-13	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 1/21/25
105 CMR 451.123	DG-13	Maintenance: Wall caulking dirty in shower # DG-12 and DG-13	Responsible Staff: Maintenance Corrective Action: Re-caulk Completion Date: 1/13/26
105 CMR 451.123		Maintenance: Seat damaged in shower #DG-13	Responsible Staff: Maintenance Corrective Action: Replace Completion Date: 1/10/26
<i>DI Unit 2<sup>nd</sup> Floor Showers</i>			
105 CMR 451.130	13	Hot Water: Shower water temperature 89 F in shower #DM-13	Responsible Staff: Maintenance Corrective Action: Water temperature adjusted Completion Date: 11/25/25
105 CMR 451.123	DM-13	Maintenance: Floor epoxy damaged in shower #DM-12 and DM-13	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 1/13/26

105 CMR 451-123	Maintenance: Soap scum on floor in shower #DM-12 and DM-13	Responsible Staff: Maintenance Corrective Action: Cleaned floor Completion Date: 11/20/25
105 CMR 451.123	Maintenance: Caulking dirty in shower # DM-12 and DM-13	Responsible Staff: Maintenance Corrective Action: Re-caulk Completion Date: 1/13/26
105 CMR 451.123`	Maintenance: Ceiling vent rusted in shower #DM-12	Responsible Staff: Maintenance Corrective Action: Replace Completion Date: 1/14/26

#### *D1 Unit Therapy room #D1-3*

105 CMR 451.130	Unable to Inspect: Under Construction
-----------------	---------------------------------------

#### **D2 Unit**

##### *D2 Unit Cells*

105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
105 CMR 451.353*	Interior Maintenance: Ceiling damaged in cell #21	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 1/27/26

##### *D2 Unit 1<sup>st</sup> Floor Showers*

105 CMR 451.123	Maintenance: Soap scum on walls in shower #DG-35 and DG-36	Responsible Staff: Maintenance Corrective Action: Cleaned walls Completion Date: 11/25/25
105 CMR 451.123	Maintenance: Soap scum on floor in shower #DG-35 and DG-36	Responsible Staff: Maintenance Corrective Action: Cleaned floor Completion Date: 11/25/25
105 CMR 451.123	Maintenance: Door frame rusted in shower # DG-35 and DG-36	Responsible Staff: Maintenance Corrective Action: Repair, scrap and paint Completion Date: 1/19/26
105 CMR 451.123	Maintenance: Ceiling rusted in shower # DG-35 and DG-36	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 1/20/26

105 CMR 451.123	Maintenance: Floor dirty in shower #DG-35 and DG-36	Responsible Staff: Maintenance Corrective Action: Cleaned shower Completion Date: 11/25/25
-----------------	---	--

#### D2 Unit 2<sup>nd</sup> Floor Showers

105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # DM-35	Responsible Staff: Maintenance Corrective Action: Cleaned vent Completion Date: 11/28/25
105 CMR 451.123	Maintenance: Soap scum on walls in shower # DM-35	Responsible Staff: Maintenance Corrective Action: Cleaned walls Completion Date: 11/24/25
105 CMR 451.123	Maintenance: Door frame rusted in shower # DM-35 and DM-36	Responsible Staff: Maintenance Corrective Action: Repair, scrape and paint Completion Date: 1/16/26
105 CMR 451.123	Maintenance: Soap scum on floor in shower # DM-35 and DM-36	Responsible Staff: Maintenance Corrective Action: Cleaned floors Completion Date: 11/25/25
105 CMR 451.123	Maintenance: Caulking dirty in shower # DM-35 and DM-36	Responsible Staff: Maintenance Corrective Action: Scrape caulking Completion Date: 1/16/26

#### BEHAVIORAL ASSESSMENT UNIT

##### Main Area

##### *Showers*

105 CMR 451.123*	Maintenance: Floor paint damaged in shower # 1	Responsible Staff: Maintenance Corrective Action: Scrape and Paint Completion Date: 12/18/25
105 CMR 451.130*	Maintenance: Shower #2 out of order	Responsible Staff: Maintenance Corrective Action: Repair Completion Date: 1/27/26

##### *Cells*

105 CMR 451.353*	Interior Maintenance: Light shield damaged in cell #7	Responsible Staff: Maintenance Corrective Action: Repair light shield Completion Date: 1/27/26
	Page 11 of 16	

105 CMR 451.350*	Structural Maintenance: Window cracked in cell #3 and 4	Responsible Staff: Maintenance Corrective Action: Replace windows. Completion Date: 1/28/26
1105 CMR 451.353*	Interior Maintenance: Floor damaged in cell #7	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 1/29/26

## MODULAR UNITS

### South 1

#### Dorm Hallway

##### *Dorm Hallway Utility Closet*

105 CMR 451.353	Interior Maintenance: Walls dirty	Responsible Staff: Maintenance Corrective Action: Cleaned walls Completion Date: 1/1/20/25
-----------------	-----------------------------------	--

##### *SI Dorms*

105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm room # 102, 103, 104, 107, and 108	Responsible Staff: Maintenance Corrective Action: Scrape/paint Completion Date: 1/16/26
105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room #106	Responsible Staff: Maintenance Corrective Action: Scrape/paint Completion Date: 1/16/26
105 CMR 451.344	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room #106 and 111	Responsible Staff: Maintenance Corrective Action: Replaced light Completion Date: 1/2/1/25
105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in dorm room # 113	Responsible Staff: Maintenance Corrective Action: Scrape/paint Completion Date: 1/15/26
105 CMR 451.353*	Interior Maintenance: Wall water damage in dorm room #113.	Responsible Staff: Maintenance Corrective Action: Paint wall Completion Date: 1/15/26
105 CMR 451.353*	Interior Maintenance: Door hardware damaged in dorm room # 109	Responsible Staff: Locksmith Corrective Action: Replaced door hardware. Completion Date: 1/12/1/25

105 CMR 451.353	Interior Maintenance: Wall vent blocked in dorm room # 101, 102, 103, 104, 105, and 109	Responsible Staff: Maintenance Corrective Action: Cleaned vents Completion Date: 12/1/25
-----------------	---	--

#### *West Bathroom*

105 CMR 451.123	Maintenance: Wall water damaged above showers	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 12/10/25
105 CMR 451.123*	Maintenance: Door frame rusted at entrance to showers	Responsible Staff: Maintenance Corrective Action: Scrape and repair. Completion Date: 12/10/25

#### *East Bathroom*

105 CMR 451.123*	Maintenance: Ceiling paint damaged near showers	Responsible Staff: Maintenance Corrective Action: Re-painted ceiling Completion Date: 12/9/25
105 CMR 451.123	Maintenance: Wall left unfinished near entrance	Responsible Staff: Maintenance Corrective Action: Painted wall Completion Date: 12/8/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 2 out-of-order	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/7/25

#### South 2

#### *Common Area*

#### *Back Rooms*

105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in left side back room.	Responsible Staff: Maintenance Corrective Action: Repair, scraped ceiling Completion Date: 12/16/25
------------------	---	---

#### *Dorm Hallway*

105 CMR 451.350*	Interior Maintenance: Ceiling water damaged in dorm room # 201 and 207	Responsible Staff: Maintenance Corrective Action: Scraped, Repaired ceiling Completion Date: 12/17/25
------------------	--	---

105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light flickering in dorm room 211	Responsible Staff: Maintenance Corrective Action: Replaced light bulbs. Completion Date: 12/11/25
105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room #206 and 210	Responsible Staff: Maintenance Corrective Action: Replaced light bulbs. Completion Date: 12/11/25

*West Bathroom*

S2 West Bathroom	Unable to Inspect-Under Construction
------------------	--------------------------------------

*East Bathroom*

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water control missing at handwash sink #5	Responsible Staff: Maintenance Corrective Action: Replaced Completion Date: 12/7/25
-----------------	--	---

North 1

**Common Area**

**Dorm Hallway**

*N1 Dorms*

105 CMR 451.344	Illumination in Habitable Areas: Inadequate lighting, light out in dorm room #153 and 160	Responsible Staff: Maintenance Corrective Action: Replaced lights. Completion Date: 12/22/25
105 CMR 451.353*	Interior Maintenance: Wall damaged in dorm room #157.	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 12/22/25

*Utility Closet*

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair; slop sink leaking	Responsible Staff: Maintenance Corrective Action: Repair leak Completion Date: 1/26/26
-----------------	---	--

<i>East Bathroom</i>	
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair; hot water control missing at handwash sink #2
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair; urinal #2 out-of-order

<i>West Bathroom</i>	
105 CMR 451.123	Maintenance: Door frame rotted
105 CMR 451.123*	Maintenance: Ceiling paint damaged outside showers

## North 2

### **Common Area**

### **Dorm Hallway**

<i>Dorms</i>	
105 CMR 451.353*	Interior Maintenance: Wall damaged in dorm room # 254 and 261
105 CMR 451.344*	Illumination in Habitable Areas: Inadequate lighting, light out in dorm #253

<i>East Bathroom</i>	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower #1 leaking
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink #4


105 CMR 451.130	Plumbing: Plumbing not maintained in good repair; hot water control missing at handwash sink #4 and 6	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/2/25
-----------------	---	---

*West Bathroom*

105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, sink basin loose at handwash sink # 5	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/1/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair; urinal #1 and 3 out-of-order	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/5/25/25
105 CMR 451.123	Maintenance: Caulking dirty around handwash sink #7	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 12/5/25

*Utility Closet*

105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket	Responsible Staff: Maintenance Corrective Action: Removed properly Completion Date: 11/21/25
-----------------	--	--



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards  
5 Randolph Street  
Canton, MA 02021  
617-624-6000 | [mass.gov/dph](http://mass.gov/dph)

# **Maura T. Healey**

## Governor

## **Kimberley Driscoll** Lieutenant Governor

## **Kiame Mahaniah, MD, MBA**

**Robert Goldstein, MD, PhD**  
Commissioner

January 2, 2026

Lisa Curto, Superintendent  
Massachusetts Treatment Center  
30 Administration Road  
Bridgewater, MA 02324 (electronic copy)

Re: Plan of Correction – Massachusetts Treatment Center, Bridgewater

Dear Superintendent Curto:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction (POC) in response to my inspection on November 12, 2025. After review, EHRS finds the plan appropriately addresses all the deficiencies noted with the following exception:

In regards to the issue of overcrowding, EHRS appreciates the limitations of correctional facilities and the need to accommodate the ever-increasing population; however we remain concerned with the overcrowded conditions.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Patrick Wallace

Patrick Wallace  
Environmental Analyst, EHRS, BCEH

cc: Sally Desrosiers, Deputy Superintendent  
John Aponte, EHSO/FSO

(electronic copy)  
(electronic copy)