

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street
Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

January 28, 2026

To:	Shawn Jenkins, Commissioner, Department of Corrections	(electronic copy)
	Kiame Mahaniah, Secretary, Executive Office of Health and Human Services	(electronic copy)
	Clerk, Massachusetts House of Representatives	(electronic copy)
	Clerk, Massachusetts Senate	(electronic copy)
	Matthew Lonergan, Environmental Health and Safety Officer	(electronic copy)

Greetings,


Pursuant to 105 CMR 451.403, please find the inspection report for Old Colony Correctional Center, the Plan of Correction (POC) from the facility, and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

A handwritten signature in blue ink that reads "Patrick Wallace".

Patrick Wallace
Environmental Analyst, EHRS, BCEH

Cc:	Robert Goldstein, MD, PhD, Commissioner, DPH	(electronic copy)
	Terrence Reidy, Secretary, Executive Office of Public Safety and Security	(electronic copy)
	Eric J. Badger, Health Agent, Bridgewater Board of Health	(electronic copy)
	Brianna Arruda, Director, Policy Development and Compliance Unit	(electronic copy)
	Jeffrey Gonsalves, Superintendent	(electronic copy)



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey

Governor

Kimberley Driscoll Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

January 2, 2026

Jeffrey Gonsalves, Superintendent
Old Colony Correctional Center
1 Administration Road
Bridgewater, MA 02324 (electronic copy)

Re: Facility Inspection – Old Colony Correctional Center, Bridgewater

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Old Colony Correctional Center on December 17, 2025 accompanied by Matthew Lonergan, Environmental Health and Safety Officer, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 268 total deficiencies: 44 new deficiencies under the Required Standards (.100 and .200 series), 138 repeat deficiencies under the Required Standards, 25 new deficiencies under the Recommended Standards (.300 series), and 61 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Old Colony Medium Building

Ground Level

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1. Records Area	Male Visitor Bathroom # FE-10	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 2 out-of-order
-----------------	-------------------------------	-----------------	---

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Visiting Area	Visiting Room # EE-29	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained
2. Visiting Area	Visiting Room # EE-29	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged

Second Level

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies were found during the inspection:

1. Lower Program Corridor	Female Bathroom # E1-17	105 CMR 451.123	Maintenance: Floor surface damaged
2. Lower Program Corridor	Male Bathroom # E1-18	105 CMR 451.123	Maintenance: Floor dirty

New Mans Unit # D2-10

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1. Intake Area	Office # D2-43	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained
----------------	----------------	------------------	---

Food Service

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 15 repeat deficiencies (indicated by an *) were found during the inspection:

1. Inmate Dining Room	Janitor's Closet # E2-7	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, slop sink rotted. Standard found in 105 CMR 590; FC 5-205.15(B).
-----------------------	-------------------------	-----------------	---

2. Inmate Dining Room	Janitor's Closet # E2-7	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, ceiling vent blocked. Standard found in 105 CMR 590; FC 6-501.12(A). ** Corrected On-Site **
3. Kitchen	Serving Line	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, floor tile grout dirty. Standard found in 105 CMR 590; FC 6-501.12(A).
4. Kitchen	Serving Line	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, light shields missing and damaged. Standard found in 105 CMR 590; FC 6-501.11.
5. Kitchen	Hallway	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, warmer gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B).
6. Kitchen	Hallway	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B).
7. Kitchen	Hallway	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, light shields missing. Standard found in 105 CMR 590; FC 6-501.11.
8. Kitchen	Hallway	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, refrigerator gaskets dirty. Standard found in 105 CMR 590; FC 6-501.12(A).
9. Main Kitchen		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, floor surface damaged throughout. Standard found in 105 CMR 590; FC 6-501.11.
10. Main Kitchen		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, light shields missing throughout. Standard found in 105 CMR 590; FC 6-501.11.
11. Main Kitchen	Ice Machines	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, left side ice machine out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A).

12. Main Kitchen	2-Compartment Sink	105 CMR 451.200*	Plumbing System; Numbers and Capacities: Missing backflow prevention device (Pf). Standard found in 105 CMR 590; FC 5-203.14(B).
13. Main Kitchen	Walk-In Cooler	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B).
14. Main Kitchen	Walk-In Cooler	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, floor surface damaged. Standard found in 105 CMR 590; FC 4-501.11(B).
15. Main Kitchen	Walk-In Cooler	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, door jamb damaged. Standard found in 105 CMR 590; FC 4-501.11(B).
16. Main Kitchen	Walk-In Freezer	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, floor surface rusted. Standard found in 105 CMR 590; FC 4-501.11(B).
17. Main Kitchen	Walk-In Freezer	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, excessive ice build-up throughout. Standard found in 105 CMR 590; FC 6-501.12(A).
18. Main Kitchen	Office	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, window cracked. Standard found in 105 CMR 590; FC 6-501.11.

Health Service Unit

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1. Dental # D2-20	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 91°F at handwash sink
2. Shower D2-79	105 CMR 451.123*	Maintenance: Door frame rusted
3. Shower D2-79	105 CMR 451.123*	Maintenance: Floor paint damaged
4. Shower D2-79	105 CMR 451.123*	Maintenance: Wall tiles damaged
5. Shower D2-79	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking
6. Shower # D2-80	105 CMR 451.123*	Maintenance: Door frame rusted
7. Shower # D2-80	105 CMR 451.123*	Maintenance: Door rotted
8. Code 99 Room # D2-54	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 99°F at handwash sink

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1. Control	105 CMR 451.350*	Structural Maintenance: Window cracked
2. Mental Health D2-18	105 CMR 451.353	Interior Maintenance: Exhaust vent not functioning properly
3. Nurse Practitioner I # D2-25	105 CMR 451.353*	Interior Maintenance: Upholstery damaged on examination table
4. Break Room # D2-67	105 CMR 451.353	Interior Maintenance: Exhaust vent not functioning properly
5. Phone Room # D2-72	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
6. Ward # D2-60	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
7. Room # D2-31	105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty

I.S.O.U**Deficiencies under the Required Standards (.100 and .200 series)**

3 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Common Area	Handicapped Shower	105 CMR 451.123	Maintenance: Ceiling vent rusted
2. Upper Level	Shower (Left)	105 CMR 451.130	Hot Water: Shower water temperature 86°F
3. Lower Level	Shower (Left)	105 CMR 451.123*	Maintenance: Ceiling dirty
4. Lower Level	Shower (Left)	105 CMR 451.123	Maintenance: Ceiling vent rusted

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1. Upper Level	Slop Sink Closet	105 CMR 451.353	Interior Maintenance: Floor surface damaged
2. Upper Level	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # M5, M8, M9, and M11
3. Lower Level	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Door frame rusted

Wellpath Office # C2-8**Deficiencies under the Required Standards (.100 and .200 series)**

1 new deficiency was found during the inspection:

1. Bathroom # C2-9	105 CMR 451.123	Maintenance: Radiator rusted
--------------------	-----------------	------------------------------

Sampson Unit**Deficiencies under the Required Standards (.100 and .200 series)**

5 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier	Shower # CM-14	105 CMR 451.123*	Maintenance: Soap scum on walls
2. Top Tier	Shower # CM-15	105 CMR 451.123*	Maintenance: Soap scum on walls
3. Top Tier	Shower # CM-15	105 CMR 451.123	Maintenance: Wall tile grout dirty
4. Top Tier	Shower # CM-15	105 CMR 451.123	Maintenance: Floor rusted

5. Top Tier	Shower # CM-15	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking
6. Bottom Tier	Shower # CG-14	105 CMR 451.123*	Maintenance: Wall epoxy damaged
7. Bottom Tier	Shower # CG-14	105 CMR 451.130	Hot Water: Shower water temperature 92°F
8. Bottom Tier	Shower # CG-15	105 CMR 451.123*	Maintenance: Floor epoxy damaged
9. Bottom Tier	Medical Room # C2-G1	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 86°F at handwash sink

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies were found during the inspection:

1. Common Area		105 CMR 451.350	Structural Maintenance: Window cracked
2. Top Tier	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # M10 and M11

Behavioral Adjustment Unit (Segregation)

Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Top Tier	Shower # CM-42	105 CMR 451.123	Maintenance: Ceiling paint damaged
2. Top Tier	Shower # CM-42	105 CMR 451.123	Maintenance: Ceiling rusted
3. Bottom Tier	Shower # CG-41	105 CMR 451.123	Maintenance: Ceiling rusted
4. Bottom Tier	Shower # CG-42	105 CMR 451.123	Maintenance: Ceiling rusted
5. Bottom Tier	Shower # CG-42	105 CMR 451.123*	Maintenance: Sprinkler head damaged

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Bottom Tier	Janitor's Closet # CG-40	105 CMR 451.353	Interior Maintenance: Floor rusted
2. Bottom Tier	Medical Room # C1-G15	105 CMR 451.353*	Interior Maintenance: Wall vent dusty
3. Bottom Tier	Medical Room # C1-G15	105 CMR 451.353*	Interior Maintenance: Upholstery damaged on examination table
4. Bottom Tier	Medical Room # C1-G15	105 CMR 451.353*	Interior Maintenance: Examination table dirty

Recovery Unit

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 11 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Shower (Left)	105 CMR 451.123*	Maintenance: Floor epoxy damaged
2. Top Tier Left Side	Shower (Left)	105 CMR 451.123*	Maintenance: Soap scum on walls
3. Top Tier Left Side	Shower (Left)	105 CMR 451.123*	Maintenance: Soap scum on floor
4. Top Tier Left Side	Shower (Left)	105 CMR 451.130	Hot Water: Shower water temperature 85°F
5. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Floor epoxy damaged
6. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Ceiling dirty

7. Top Tier Left Side	Cells	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet running continuously in cell # FM-1
8. Bottom Tier Left Side	Shower (Left)	105 CMR 451.123*	Maintenance: Soap scum on walls
9. Bottom Tier Left Side	Shower (Left)	105 CMR 451.123	Maintenance: Shower head rusted
10. Bottom Tier Right Side	Shower # G-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged
11. Bottom Tier Right Side	Shower # G-41	105 CMR 451.123	Maintenance: Ceiling dirty
12. Top Tier Right Side	Shower # M-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged
13. Top Tier Right Side	Shower # M-41	105 CMR 451.123*	Maintenance: Soap scum on floor
14. Top Tier Right Side	Shower # M-41	105 CMR 451.123	Maintenance: Soap scum on walls
15. Top Tier Right Side	Shower # M-42	105 CMR 451.123*	Maintenance: Soap scum on walls
16. Top Tier Right Side	Shower # M-42	105 CMR 451.123*	Maintenance: Floor epoxy damaged
17. Top Tier Right Side	Shower # M-42	105 CMR 451.123	Maintenance: Soap scum on floor

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # FM-12
2. Bottom Tier Left Side	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

Attucks 2 (SHU)

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 11 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Wall tiles damaged
2. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Soap scum on floor
3. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Soap scum on walls
4. Bottom Tier Left Side	Janitor's Closet	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking on slop sink
5. Bottom Tier Left Side	Shower Left Side	105 CMR 451.123	Maintenance: Ceiling paint damaged
6. Bottom Tier Right Side	Handicapped Shower	105 CMR 451.123*	Maintenance: Bench rusted
7. Bottom Tier Right Side	Handicapped Shower	105 CMR 451.123*	Maintenance: Door rusted
8. Bottom Tier Right Side	Handicapped Shower	105 CMR 451.123*	Maintenance: Door frame rusted
9. Bottom Tier Right Side	Handicapped Shower	105 CMR 451.123*	Maintenance: Ceiling rusted
10. Top Tier Right Side	Shower (Right)	105 CMR 451.123*	Maintenance: Soap scum on floor
11. Top Tier Right Side	Shower (Right)	105 CMR 451.123*	Maintenance: Soap scum on walls
12. Top Tier Right Side	Shower (Left)	105 CMR 451.123*	Maintenance: Soap scum on floor

Deficiencies under the Recommended Standards (.300 series)

5 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Common Area		105 CMR 451.353	Interior Maintenance: Floor tiles missing outside showers
2. Top Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # GM-12

3. Top Tier Left Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # GM-13
4. Bottom Tier Left Side	Janitor's Closet	105 CMR 451.353	Interior Maintenance: Light out
5. Bottom Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # GG-13
6. Bottom Tier Left Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # GG-9
7. Bottom Tier Right Side		105 CMR 451.353*	Interior Maintenance: Wall damaged in hallway
8. Bottom Tier Right Side	Medical Triage Room	105 CMR 451.353	Interior Maintenance: Floor tiles damaged

Attucks 3

Deficiencies under the Required Standards (.100 and .200 series)

20 repeat deficiencies (indicated by an *) were found during the inspection:

1. Bottom Tier Left Side	Shower # JG-14	105 CMR 451.123*	Maintenance: Floor epoxy damaged
2. Bottom Tier Left Side	Shower # JG-14	105 CMR 451.123*	Maintenance: Wall tiles damaged
3. Bottom Tier Left Side	Shower # JG-15	105 CMR 451.123*	Maintenance: Soap scum on walls
4. Bottom Tier Right Side	Shower # JG-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged
5. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Door rusted
6. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Door frame rotted
7. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Door paint damaged
8. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Bench rusted
9. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Bench dirty
10. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Ceiling dirty
11. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Soap scum on walls
12. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Wall tile grout dirty
13. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Floor epoxy damaged
14. Top Tier Right Side	Shower # JM-41	105 CMR 451.123*	Maintenance: Wall tile grout dirty
15. Top Tier Right Side	Shower # JM-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged
16. Top Tier Right Side	Shower # JM-41	105 CMR 451.123*	Maintenance: Soap scum on walls
17. Top Tier Right Side	Shower # JM-42	105 CMR 451.123*	Maintenance: Wall tile grout dirty
18. Top Tier Right Side	Shower # JM-42	105 CMR 451.123*	Maintenance: Floor epoxy damaged
19. Top Tier Right Side	Shower # JM-42	105 CMR 451.123*	Maintenance: Soap scum on floor
20. Top Tier Right Side	Shower # JM-42	105 CMR 451.123*	Maintenance: Soap scum on walls

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 8 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
2. Control		105 CMR 451.350*	Structural Maintenance: Window cracked
3. Common Area		105 CMR 451.353*	Interior Maintenance: Stair treads damaged
4. Top Tier Left Side	Janitor's Closet # JM-13	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
5. Bottom Tier Left Side	Janitor's Closet # JG-13	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
6. Bottom Tier Left Side	Cells	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in cell # JG-15
7. Bottom Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # JG-1
8. Bottom Tier Right Side		105 CMR 451.353	Interior Maintenance: Wall water damaged in hallway
9. Top Tier Right Side		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged outside showers
10. Top Tier Right Side	Janitor's Closet # JM-40	105 CMR 451.353	Interior Maintenance: Floor paint damaged

Attucks 4**Deficiencies under the Required Standards (.100 and .200 series)**

4 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Bottom Tier Right Side	Shower # HG-41	105 CMR 451.123*	Maintenance: Ceiling paint damaged
2. Bottom Tier Right Side	Handicapped Shower # HG-42	105 CMR 451.123*	Maintenance: Door rotted
3. Bottom Tier Right Side	Handicapped Shower # HG-42	105 CMR 451.123*	Maintenance: Door frame rotted
4. Bottom Tier Right Side	Handicapped Shower # HG-42	105 CMR 451.123	Maintenance: Ceiling dirty
5. Top Tier Right Side	Shower # HM-41	105 CMR 451.123	Maintenance: Ceiling dirty
6. Top Tier Right Side	Shower # HM-42	105 CMR 451.123*	Maintenance: Floor epoxy damaged
7. Top Tier Right Side	Shower # HM-42	105 CMR 451.123	Maintenance: Ceiling dirty
8. Top Tier Right Side	Shower # HM-42	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
2. Common Area		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged

3. Top Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # HM-14
4. Bottom Tier Right Side		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged outside showers
5. Bottom Tier Right Side		105 CMR 451.353	Interior Maintenance: Wall water damaged in hallway
6. Bottom Tier Right Side	Cells	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in cell # HG-16
7. Bottom Tier Right Side	Cells	105 CMR 451.353*	Interior Maintenance: Wall water damaged in cell # HG-16
8. Top Tier Right Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # HM-26

Dawes 1

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 23 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Shower # LM-14	105 CMR 451.123*	Maintenance: Soap scum on floor
2. Top Tier Left Side	Shower # LM-14	105 CMR 451.123*	Maintenance: Floor epoxy damaged
3. Top Tier Left Side	Shower # LM-15	105 CMR 451.123*	Maintenance: Wall tile grout dirty
4. Top Tier Left Side	Shower # LM-15	105 CMR 451.123*	Maintenance: Soap scum on floor
5. Top Tier Left Side	Shower # LM-15	105 CMR 451.123	Maintenance: Floor epoxy damaged
6. Bottom Tier Left Side	Shower # LG-14	105 CMR 451.123*	Maintenance: Wall tile grout dirty
7. Bottom Tier Left Side	Shower # LG-14	105 CMR 451.123*	Maintenance: Floor epoxy damaged
8. Bottom Tier Left Side	Shower # LG-14	105 CMR 451.123*	Maintenance: Soap scum on walls
9. Bottom Tier Left Side	Shower # LG-15	105 CMR 451.123*	Maintenance: Soap scum on walls
10. Bottom Tier Right Side	Shower # LG-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged
11. Bottom Tier Right Side	Shower # LG-41	105 CMR 451.123*	Maintenance: Soap scum on walls
12. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Door frame rusted
13. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Door rusted
14. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Wall tile grout dirty
15. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Soap scum on walls
16. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Soap scum on floor
17. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123	Maintenance: Bench rusted
18. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123	Maintenance: Ceiling dirty
19. Top Tier Right Side	Shower # LM-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged
20. Top Tier Right Side	Shower # LM-41	105 CMR 451.123*	Maintenance: Soap scum on floor
21. Top Tier Right Side	Shower # LM-41	105 CMR 451.123*	Maintenance: Soap scum on walls
22. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Wall tile grout dirty

23. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Floor epoxy damaged
24. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Wall tiles damaged
25. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Soap scum on floor
26. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Soap scum on walls

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
2. Common Area		105 CMR 451.353*	Interior Maintenance: Stair treads damaged
3. Top Tier Left Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # LM-2 and LM-11
4. Bottom Tier Left Side	Hallway	105 CMR 451.350*	Structural Maintenance: Window cracked at end of hallway
5. Bottom Tier Left Side	Cells	105 CMR 451.353	Interior Maintenance: Door frame rusted in cell # LG-13
6. Top Tier Right Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # LM-23

Dawes 2

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 18 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Shower # KM-14	105 CMR 451.123*	Maintenance: Wall tile grout dirty
2. Top Tier Left Side	Shower # KM-14	105 CMR 451.123*	Maintenance: Floor epoxy damaged
3. Top Tier Left Side	Shower # KM-14	105 CMR 451.123*	Maintenance: Wall tiles damaged
4. Top Tier Left Side	Shower # KM-15	105 CMR 451.123*	Maintenance: Soap scum on floor
5. Top Tier Left Side	Shower # KM-15	105 CMR 451.123*	Maintenance: Floor epoxy damaged
6. Bottom Tier Left Side	Shower # KG-14	105 CMR 451.123*	Maintenance: Soap scum on floor
7. Bottom Tier Left Side	Shower # KG-14	105 CMR 451.123*	Maintenance: Floor epoxy damaged
8. Bottom Tier Left Side	Shower # KG-14	105 CMR 451.123*	Maintenance: Wall tile grout dirty
9. Bottom Tier Left Side	Shower # KG-14	105 CMR 451.123	Maintenance: Wall tiles damaged
10. Bottom Tier Left Side	Shower # KG-15	105 CMR 451.123*	Maintenance: Floor epoxy damaged
11. Bottom Tier Left Side	Shower # KG-15	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking
12. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Floor surface left unfinished at entrance
13. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Door rusted
14. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Door frame rotted
15. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Floor epoxy damaged

16. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Soap scum on walls
17. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking
18. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123	Maintenance: Bench rusted
19. Top Tier Right Side	Shower # KM-41	105 CMR 451.123*	Maintenance: Wall tiles damaged
20. Top Tier Right Side	Shower # KM-41	105 CMR 451.123*	Maintenance: Wall tile grout dirty
21. Top Tier Right Side	Shower # KM-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 7 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
2. Common Area		105 CMR 451.350*	Structural Maintenance: Window cracked at entrance
3. Common Area		105 CMR 451.353*	Interior Maintenance: Stair treads damaged
4. Top Tier Left Side	Cells	105 CMR 451.353	Interior Maintenance Window not functioning properly in cell # KM-15
5. Bottom Tier Left Side	Janitor's Closet # KG-13	105 CMR 451.353	Interior Maintenance: Floor paint damaged
6. Bottom Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # KG-6
7. Bottom Tier Left Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # KG-13 and KG-15
8. Bottom Tier Right Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # KG-26
9. Bottom Tier Right Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # KG-16 and KG-18
10. Top Tier Right Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # KM-17 and KM-18

CPO Offices

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1. Hallway		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged outside offices
------------	--	------------------	---

Orientation Unit

Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 22 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier	Shower # OUM-1 – OUM-5	105 CMR 451.123*	Maintenance: Wall damaged in shower # OUM-4
2. Top Tier	Shower # OUM-1 – OUM-5	105 CMR 451.124*	Water Supply: Insufficient water supply in quantity and pressure in shower # OUM-2 and OUM-4
3. Top Tier	Shower # OUM-1 – OUM-5	105 CMR 451.123*	Maintenance: Door frame rotted in shower # OUM-2, OUM-4, and OUM-5
4. Top Tier	Shower # OUM-1 – OUM-5	105 CMR 451.123	Maintenance: Door frame rotted in shower # OUM-2, OUM-4, and OUM-3
5. Top Tier	Cells	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink in cell # 157
6. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.123*	Maintenance: Ceiling damaged in shower # OUG-1
7. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # OUG-3
8. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # OUG-3
9. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.123	Maintenance: Wall damaged in shower # OUG-3
10. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # OUG-3
11. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking
12. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Door paint damaged
13. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Door rusted
14. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Door frame rusted
15. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Soap scum on floor
16. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Soap scum on walls
17. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Floor dirty
18. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Shower control shroud missing
19. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Ceiling damaged
20. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Bench dirty
21. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Bench rusted

Deficiencies under the Recommended Standards (.300 series)

11 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
2. Common Area		105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained
3. Common Area		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
4. Top Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall water damaged around window in cell # 157 and 158
5. Top Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in all cells
6. Bottom Tier		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged outside showers
7. Bottom Tier		105 CMR 451.353*	Interior Maintenance: Floor paint damaged outside showers
8. Bottom Tier	Cells	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in cell # 110
9. Bottom Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall water damaged in cell # 120
10. Bottom Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in all cells

Industries Building**Deficiencies under the Required Standards (.100 and .200 series)**

3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Spectrum A2-24	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of refrigerator dirty
2. Spectrum A2-24	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of freezer rusted
3. Spectrum A2-24	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator gaskets damaged

Gym**Deficiencies under the Required Standards (.100 and .200 series)**

1 new deficiency was found during the inspection:

1. Staff Bathroom # A2-44	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet leaking
---------------------------	-----------------	--

Towers

Deficiencies under the Recommended Standards (.300 series)

3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Pedestrian Tower	105 CMR 451.353*	Interior Maintenance: Ceiling tiles missing
2. Pedestrian Tower	105 CMR 451.350*	Structural Maintenance: Windows cracked
3. Tower # 1	105 CMR 451.350*	Structural Maintenance: Windows cracked

SECTION 2: Areas Found to be in Compliance

EHRS inspected 245 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 4 areas of the facility because they were either in use, locked, or under construction.

1. Old Colony Medium Building	Second Level	Lower Program Corridor	Bathroom # DI-16	Unable to Inspect – Not Used
2. Old Colony Medium Building	New Mans Unit # D2-10	Intake Area	IPS Storage # D2-6	Unable to Inspect – Locked
3. Old Colony Minimum				Unable to Inspect – Permanently Closed
4. Old Colony Minimum	Gym			Unable to Inspect – Locked

SECTION 4: Plan of Correction

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 493 at the time of inspection.
2. The Old Colony Minimum facility has been permanently closed with no plans to re-open. The Minimum Gymnasium was being used by inmate workers that are brought in from other facilities to use the bathroom while they are working on the complex.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](http://105CMR451.000) available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Patrick Wallace
Environmental Analyst, EHRS, BCEH



*The Commonwealth of Massachusetts
Executive Office of Public Safety & Security
Department of Correction
Old Colony Correctional Center
Bridgewater, MA. 02324
Tel: (508) 279-6000
www.mass.gov/doc*



MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

GINA K. KWON
Secretary

SHAWN P. JENKINS
Commissioner

January 16, 2026

Patrick Wallace, CSP, BEH
Executive Office of Health and Human Services
Department of Public Health
Bureau of Environmental Health
Community Sanitation Program
5 Randolph St.
Canton, Ma 02021

Dear Mr. Wallace:

Attached is Old Colony Correctional Center's Plan of Action report addressing the deficiencies identified during your inspection conducted on 17 Dec 2025.

We appreciate your team's professionalism, guidance, and continued support as we work toward strengthening our facility's safety and sanitation standards.

Sincerely,

Jeffrey L. Gonsalves,
Superintendent

JG/jc

Enclosure

cc: Shawn P. Jenkins, Commissioner
Mitzi S. Peterson, Deputy Commissioner, Clinical Service & Reentry
Brianna Arruda, Director P.D.C.U.
EHSO, OCCC
File

SECTION 1: Health and Safety Deficiencies

Old Colony Medium Building

Ground Level

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1. Records Area	Male Visitor Bathroom # FE-10	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 2 out-of-Order Maintenance to repair by 1/30/26
-----------------	-------------------------------	-----------------	--

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Visiting Area	Visiting Room # EE-29	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained Maintenance to replace by 3/30/26
2. Visiting Area	Visiting Room # EE-29	105 CMR 451.353*	Interior Maintenance: Floor tiles Damaged Maintenance to repair by 3/30/26

Second Level

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies were found during the inspection:

1. Lower Program Corridor	Female Bathroom # E1-17	105 CMR 451.123	Maintenance: Floor surface Damaged Maintenance to repair by 2/30/26
2. Lower Program Corridor	Male Bathroom # E1-18	105 CMR 451.123	Maintenance: Floor dirty To be cleaned by workers by 1/10/26

New Mans Unit # D2-10

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1. Intake Area	Office # D2-43	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained Maintenance to replace by 3/30/26
----------------	----------------	------------------	---

Food Service

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 15 repeat deficiencies (indicated by an *) were found during the inspection:

1. Inmate Dining Room	Janitor's Closet # E2-7	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, slop sink rotted. Standard found in 105 CMR 590; FC 5-205.15(B). Maintenance to repair by 3/30/26
2. Inmate Dining Room	Janitor's Closet # E2-7	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, ceiling vent blocked. Standard found in 105 CMR 590; FC 6-501.12(A). ** Corrected On-Site **
3. Kitchen	Serving Line	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, floor tile grout dirty. Standard found in 105 CMR 590; FC 6-501.12(A). To be cleaned by workers by 1/10/26
4. Kitchen	Serving Line	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, light shields missing and damaged. Standard found in 105 CMR 590; FC 6-501.11. Maintenance to replace by 2/30/26
5. Kitchen	Hallway	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, warmer gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B). Maintenance to repair by 2/30/26
6. Kitchen	Hallway	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B). Maintenance to repair by 2/30/26
7. Kitchen	Hallway	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, light shields missing. Standard found in 105 CMR 590; FC 6-501.11. Maintenance to replace by 1/30/26
8. Kitchen	Hallway	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, refrigerator gaskets dirty. Standard found in 105 CMR 590; FC 6-501.12(A). To be cleaned by workers by 1/10/26

9. Main Kitchen		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, floor surface damaged throughout. Standard found in 105 CMR 590; FC 6-501.11. Maintenance to repair by 3/30/26
10. Main Kitchen		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility is not in good repair, light shields missing throughout. Standard found in 105 CMR 590; FC 6-501.11. Maintenance to replace by 1/30/26
11. Main Kitchen	Ice Machines	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, left side ice machine out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A). Maintenance to repair by 3/30/26
12. Main Kitchen	2-Compartment Sink	105 CMR 451.200*	Plumbing System; Numbers and Capacities: Missing backflow prevention device (Pf). Standard found in 105 CMR 590; FC 5-203.14(B). Maintenance to repair by 1/30/26
13. Main Kitchen	Walk-In Cooler	105 CMR 451.200*	Maintenance and Operation Equipment: Equipment components not maintained in a state of good repair, gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B). Maintenance to repair by 2/30/26
14. Main Kitchen	Walk-In Cooler	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, floor surface damaged. Standard found in 105 CMR 590; FC 4-501.11(B). Maintenance to repair by 3/30/26
15. Main Kitchen	Walk-In Cooler	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, door jamb damaged. Standard found in 105 CMR 590; FC 4-501.11(B). Maintenance to repair by 3/30/26
16. Main Kitchen	Walk-In Freezer	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, floor surface rusted. Standard found in 105 CMR 590; FC 4-501.11(B). Maintenance to repair by 3/30/26
17. Main Kitchen	Walk-In Freezer	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, excessive ice build-up throughout. Standard found in 105 CMR 590; FC 6-501.12(A). To be cleaned by workers by 1/10/26

18.. Main Kitchen	Office	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, window cracked. Standard found in 105 CMR 590; FC 6-501.11. Maintenance to repair by 2/30/26
-------------------	--------	------------------	--

Health Service Unit

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1. Dental # D2-20	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 91°F at handwash sink Maintenance to adjust by 1/30/26
2. Shower D2-79	105 CMR 451.123*	Maintenance: Door frame rusted Maintenance to repair by 3/30/26
3. Shower D2-79	105 CMR 451.123*	Maintenance: Floor paint damaged Maintenance to paint by 1/30/26
4. Shower D2-79	105 CMR 451.123*	Maintenance: Wall tiles damaged Maintenance to repair by 3/30/26
5. Shower D2-79	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking Maintenance to repair by 1/30/26
6. Shower # D2-80	105 CMR 451.123*	Maintenance: Door frame rusted Maintenance to repair by 3/30/26
7. Shower # D2-80	105 CMR 451.123*	Maintenance: Door rotted Maintenance to repair by 3/30/26
8. Code 99 Room # D2-54	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 99°F at handwash sink Maintenance to adjust by 1/30/26

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1. Control	105 CMR 451.350*	Structural Maintenance: Window cracked Maintenance to repair by 2/30/26
2. Mental Health D2-18	105 CMR 451.353	Interior Maintenance: Exhaust vent not functioning properly Maintenance to repair by 2/30/26
3. Nurse Practitioner I # D2-25	105 CMR 451.353*	Interior Maintenance: Upholstery damaged on examination table Maintenance to replace by 3/30/26
4. Break Room # D2-67	105 CMR 451.353	Interior Maintenance: Exhaust vent not functioning properly Maintenance to repair by 2/30/26
5. Phone Room # D2-72	105 CMR 451.353*	Interior Maintenance: Ceiling damaged Maintenance to repair by 3/30/26
6. Ward # D2-60	105 CMR 451.353*	Interior Maintenance: Floor surface Damaged Maintenance to repair by 3/30/26
7. Room # D2-31	105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty To be cleaned by workers by 1/10/26

I.S.O.U**Deficiencies under the Required Standards (.100 and .200 series)**

3 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Common Area	Handicapped Shower	105 CMR 451.123	Maintenance: Ceiling vent rusted Maintenance to repair by 1/30/26
2. Upper Level	Shower (Left)	105 CMR 451.130	Hot Water: Shower water temperature 86°F Maintenance to adjust by 1/10/26
3. Lower Level	Shower (Left)	105 CMR 451.123*	Maintenance: Ceiling dirty To be cleaned by workers by 1/10/26
4. Lower Level	Shower (Left)	105 CMR 451.123	Maintenance: Ceiling vent rusted Maintenance to replace by 1/30/26

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1. Upper Level	Slop Sink Closet	105 CMR 451.353	Interior Maintenance: Floor surface Damaged Maintenance to repair by 1/30/26
2. Upper Level	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # M5, M8, M9, and M11 Maintenance to repair by 2/30/26
3. Lower Level	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Door frame rusted Maintenance to repair by 3/30/26

Wellpath Office # C2-8**Deficiencies under the Required Standards (.100 and .200 series)**

1 new deficiency was found during the inspection:

1. Bathroom # C2-9	105 CMR 451.123	Maintenance: Radiator rusted Maintenance to repair by 1/30/26
--------------------	-----------------	---

Sampson Unit

Deficiencies under the Required Standards (.100 and .200 series)

5 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier	Shower # CM-14	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
2. Top Tier	Shower # CM-15	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
3. Top Tier	Shower # CM-15	105 CMR 451.123	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
4. Top Tier	Shower # CM-15	105 CMR 451.123	Maintenance: Floor rusted Maintenance to repair by 1/30/26
5. Top Tier	Shower # CM-15	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking Maintenance to repair by 1/30/26
6. Bottom Tier	Shower # CG-14	105 CMR 451.123*	Maintenance: Wall epoxy damaged Maintenance to repair by 2/30/26
7. Bottom Tier	Shower # CG-14	105 CMR 451.130	Hot Water: Shower water temperature 92°F Maintenance to adjust by 1/10/26
8. Bottom Tier	Shower # CG-15	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
9. Bottom Tier	Medical Room # C2-G1	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 86°F at handwash Sink Maintenance to adjust by 1/10/26

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies were found during the inspection:

1. Common Area		105 CMR 451.350	Structural Maintenance: Window Cracked Maintenance to repair by 2/30/26
2. Top Tier	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # M10 and M11 Maintenance to repair by 2/30/26

Behavioral Adjustment Unit (Segregation)

Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Top Tier	Shower # CM-42	105 CMR 451.123	Maintenance: Ceiling paint damaged Maintenance to paint by 1/30/26
2. Top Tier	Shower # CM-42	105 CMR 451.123	Maintenance: Ceiling rusted Maintenance to repair by 1/30/26
3. Bottom Tier	Shower # CG-41	105 CMR 451.123	Maintenance: Ceiling rusted Maintenance to repair by 1/30/26
4. Bottom Tier	Shower # CG-42	105 CMR 451.123	Maintenance: Ceiling rusted Maintenance to repair by 1/30/26
5. Bottom Tier	Shower # CG-42	105 CMR 451.123*	Maintenance: Sprinkler head damaged Maintenance to repair by 1/30/26

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Bottom Tier	Janitor's Closet # CG-40	105 CMR 451.353	Interior Maintenance: Floor rusted Maintenance to repair by 1/30/26
2. Bottom Tier	Medical Room # C1-G15	105 CMR 451.353*	Interior Maintenance: Wall vent Dusty To be cleaned by workers by 1/10/26
3. Bottom Tier	Medical Room # C1-G15	105 CMR 451.353*	Interior Maintenance: Upholstery damaged on examination table Maintenance to replace by 3/30/26
4. Bottom Tier	Medical Room # C1-G15	105 CMR 451.353*	Interior Maintenance: Examination table dirty To be cleaned by workers by 1/10/26

Recovery Unit**Deficiencies under the Required Standards (.100 and .200 series)**

6 new deficiencies and 11 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Shower (Left)	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
2. Top Tier Left Side	Shower (Left)	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
3. Top Tier Left Side	Shower (Left)	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
4. Top Tier Left Side	Shower (Left)	105 CMR 451.130	Hot Water: Shower water temperature 85°F Maintenance to adjust by 1/10/26
5. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
6. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Ceiling dirty To be cleaned by workers by 1/10/26
7. Top Tier Left Side	Cells	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet running continuously in cell # FM-1 Maintenance to repair by 1/30/26
8. Bottom Tier Left Side	Shower (Left)	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
9. Bottom Tier Left Side	Shower (Left)	105 CMR 451.123	Maintenance: Shower head rusted Maintenance to repair by 1/30/26
10. Bottom Tier Right Side	Shower # G-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
11. Bottom Tier Right Side	Shower # G-41	105 CMR 451.123	Maintenance: Ceiling dirty To be cleaned by workers by 1/10/26
12. Top Tier Right Side	Shower # M-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
13. Top Tier Right Side	Shower # M-41	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
14. Top Tier Right Side	Shower # M-41	105 CMR 451.123	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
15. Top Tier Right Side	Shower # M-42	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
16. Top Tier Right Side	Shower # M-42	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26

17. Top Tier Right Side	Shower # M-42	105 CMR 451.123	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
-------------------------	---------------	-----------------	---

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # FM-12 Maintenance to repair by 2/30/26
2. Bottom Tier Left Side	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint Damaged Maintenance to paint by 1/30/26

Attucks 2 (SHU)

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 11 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Wall tiles damaged Maintenance to repair by 2/30/26
2. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
3. Top Tier Left Side	Shower (Right)	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
4. Bottom Tier Left Side	Janitor's Closet	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking on slop sink Maintenance to repair by 1/30/26
5. Bottom Tier Left Side	Shower Left Side	105 CMR 451.123	Maintenance: Ceiling paint Damaged Maintenance to paint by 1/30/26
6. Bottom Tier Right Side	Handicapped Shower	105 CMR 451.123*	Maintenance: Bench rusted Maintenance to replace by 1/30/26
7. Bottom Tier Right Side	Handicapped Shower	105 CMR 451.123*	Maintenance: Door rusted Maintenance to repair by 2/30/26
8. Bottom Tier Right Side	Handicapped Shower	105 CMR 451.123*	Maintenance: Door frame rusted Maintenance to repair by 2/30/26
9. Bottom Tier Right Side	Handicapped Shower	105 CMR 451.123*	Maintenance: Ceiling rusted Maintenance to repair by 2/30/26
10. Top Tier Right Side	Shower (Right)	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
11. Top Tier Right Side	Shower (Right)	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
12. Top Tier Right Side	Shower (Left)	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26

Deficiencies under the Recommended Standards (.300 series)

5 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Common Area		105 CMR 451.353	Interior Maintenance: Floor tiles missing outside showers Maintenance to repair by 4/30/26
2. Top Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # GM-12 Maintenance to repair by 3/30/26

3. Top Tier Left Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # GM-13 Maintenance to repair by 3/30/26
4. Bottom Tier Left Side	Janitor's Closet	105 CMR 451.353	Interior Maintenance: Light out Maintenance to repair by 1/30/26
5. Bottom Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # GG-13 Maintenance to repair by 3/30/26
6. Bottom Tier Left Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # GG-9 Maintenance to repair by 3/30/26
7. Bottom Tier Right Side		105 CMR 451.353*	Interior Maintenance: Wall damaged in hallway Maintenance to repair by 4/30/26
8. Bottom Tier Right Side	Medical Triage Room	105 CMR 451.353	Interior Maintenance: Floor tiles Damaged Maintenance to repair by 4/30/26

Attucks 3

Deficiencies under the Required Standards (.100 and .200 series)

20 repeat deficiencies (indicated by an *) were found during the inspection:

1. Bottom Tier Left Side	Shower # JG-14	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
2. Bottom Tier Left Side	Shower # JG-14	105 CMR 451.123*	Maintenance: Wall tiles damaged Maintenance to repair by 3/30/26
3. Bottom Tier Left Side	Shower # JG-15	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
4. Bottom Tier Right Side	Shower # JG-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
5. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Door rusted Maintenance to repair by 3/30/26
6. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Door frame rotted Maintenance to repair by 3/30/26
7. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Door paint damaged Maintenance to repair by 1/30/26
8. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Bench rusted Maintenance to repair by 1/30/26
9. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Bench dirty To be cleaned by workers by 1/10/26
10. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Ceiling dirty To be cleaned by workers by 1/10/26
11. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
12. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
13. Bottom Tier Right Side	Handicapped Shower # JG-42	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
14. Top Tier Right Side	Shower # JM-41	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
15. Top Tier Right Side	Shower # JM-41	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
16. Top Tier Right Side	Shower # JM-41	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26

17. Top Tier Right Side	Shower # JM-42	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
18. Top Tier Right Side	Shower # JM-42	105 CMR 451.123*	Maintenance: Floor epoxy damaged Maintenance to repair by 2/30/26
19. Top Tier Right Side	Shower # JM-42	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
20. Top Tier Right Side	Shower # JM-42	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 8 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells Building falls under, and is compliant with, previous building standards/regulations
2. Control		105 CMR 451.350*	Structural Maintenance: Window Cracked Maintenance to repair by 3/30/26
3. Common Area		105 CMR 451.353*	Interior Maintenance: Stair treads Damaged Maintenance to repair by 3/30/26
4. Top Tier Left Side	Janitor's Closet # JM-13	105 CMR 451.353*	Interior Maintenance: Floor paint Damaged Maintenance to paint by 1/30/26
5. Bottom Tier Left Side	Janitor's Closet # JG-13	105 CMR 451.353*	Interior Maintenance: Floor paint Damaged Maintenance to paint by 1/30/26
6. Bottom Tier Left Side	Cells	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in cell # JG-15 Maintenance to repair by 2/30/26
7. Bottom Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # JG-1 Maintenance to repair by 3/30/26
8. Bottom Tier Right Side		105 CMR 451.353	Interior Maintenance: Wall water damaged in hallway Maintenance to repair by 4/30/26
9. Top Tier Right Side		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged outside showers Maintenance to repair by 4/30/26
10. Top Tier Right Side	Janitor's Closet # JM-40	105 CMR 451.353	Interior Maintenance: Floor paint Damaged Maintenance to paint by 1/30/26

Attucks 4**Deficiencies under the Required Standards (.100 and .200 series)**

4 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Bottom Tier Right Side	Shower # HG-41	105 CMR 451.123*	Maintenance: Ceiling paint Damaged Maintenance to paint by 1/30/26
2. Bottom Tier Right Side	Handicapped Shower # HG-42	105 CMR 451.123*	Maintenance: Door rotted Maintenance to repair by 3/30/26
3. Bottom Tier Right Side	Handicapped Shower # HG-42	105 CMR 451.123*	Maintenance: Door frame rotted Maintenance to repair by 3/30/26
4. Bottom Tier Right Side	Handicapped Shower # HG-42	105 CMR 451.123	Maintenance: Ceiling dirty To be cleaned by workers by 1/10/26
5. Top Tier Right Side	Shower # HM-41	105 CMR 451.123	Maintenance: Ceiling dirty To be cleaned by workers by 1/10/26

6. Top Tier Right Side	Shower # HM-42	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 2/30/26
7. Top Tier Right Side	Shower # HM-42	105 CMR 451.123	Maintenance: Ceiling dirty To be cleaned by workers by 1/10/26
8. Top Tier Right Side	Shower # HM-42	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking Maintenance to repair by 1/30/26

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells Building falls under, and is compliant with, previous building standards/regulations
2. Common Area		105 CMR 451.353*	Interior Maintenance: Floor tiles Damaged Maintenance to repair by 3/30/26
3. Top Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # HM-14 Maintenance to repair by 3/30/26
4. Bottom Tier Right Side		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged outside showers Maintenance to repair by 3/30/26
5. Bottom Tier Right Side		105 CMR 451.353	Interior Maintenance: Wall water damaged in hallway Maintenance to repair by 4/30/26
6. Bottom Tier Right Side	Cells	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in cell # HG-16 Maintenance to repair by 3/30/26
7. Bottom Tier Right Side	Cells	105 CMR 451.353*	Interior Maintenance: Wall water damaged in cell # HG-16 Maintenance to repair by 4/30/26
8. Top Tier Right Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # HM-26 Maintenance to repair by 3/30/26

Dawes 1

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 23 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Shower # LM-14	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
2. Top Tier Left Side	Shower # LM-14	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 2/30/26
3. Top Tier Left Side	Shower # LM-15	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
4. Top Tier Left Side	Shower # LM-15	105 CMR 451.123*	Maintenance: Soap scum on floor

			To be cleaned by workers by 1/10/26
5. Top Tier Left Side	Shower # LM-15	105 CMR 451.123	Maintenance: Floor epoxy Damaged Maintenance to repair by 4/30/26
6. Bottom Tier Left Side	Shower # LG-14	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
7. Bottom Tier Left Side	Shower # LG-14	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 4/30/26
8. Bottom Tier Left Side	Shower # LG-14	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
9. Bottom Tier Left Side	Shower # LG-15	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
10. Bottom Tier Right Side	Shower # LG-41	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 4/30/26
11. Bottom Tier Right Side	Shower # LG-41	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
12. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Door frame rusted Maintenance to repair by 4/30/26
13. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Door rusted Maintenance to repair by 4/30/26
14. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
15. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
16. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
17. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123	Maintenance: Bench rusted Maintenance to repair by 4/30/26
18. Bottom Tier Right Side	Handicapped Shower # LG-42	105 CMR 451.123	Maintenance: Ceiling dirty To be cleaned by workers by 1/10/26
19. Top Tier Right Side	Shower # LM-41	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 4/30/26
20. Top Tier Right Side	Shower # LM-41	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
21. Top Tier Right Side	Shower # LM-41	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
22. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
23. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 2/30/26

24. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Wall tiles damaged Maintenance to repair by 3/30/26
25. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
26. Top Tier Right Side	Shower # LM-42	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells Building falls under, and is compliant with, previous building standards/regulations
2. Common Area		105 CMR 451.353*	Interior Maintenance: Stair treads Damaged Maintenance to repair by 3/30/26
3. Top Tier Left Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # LM-2 and LM-11 Maintenance to repair by 3/30/26
4. Bottom Tier Left Side	Hallway	105 CMR 451.350*	Structural Maintenance: Window cracked at end of hallway Maintenance to repair by 3/30/26
5. Bottom Tier Left Side	Cells	105 CMR 451.353	Interior Maintenance: Door frame rusted in cell # LG-13 Maintenance to repair by 4/30/26
6. Top Tier Right Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # LM-23 Maintenance to repair by 3/30/26

Dawes 2

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 18 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier Left Side	Shower # KM-14	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
2. Top Tier Left Side	Shower # KM-14	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 2/30/26
3. Top Tier Left Side	Shower # KM-14	105 CMR 451.123*	Maintenance: Wall tiles damaged Maintenance to repair by 2/30/26
4. Top Tier Left Side	Shower # KM-15	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26
5. Top Tier Left Side	Shower # KM-15	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 2/30/26
6. Bottom Tier Left Side	Shower # KG-14	105 CMR 451.123*	Maintenance: Soap scum on floor To be cleaned by workers by 1/10/26

7. Bottom Tier Left Side	Shower # KG-14	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 2/30/26
8. Bottom Tier Left Side	Shower # KG-14	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
9. Bottom Tier Left Side	Shower # KG-14	105 CMR 451.123	Maintenance: Wall tiles damaged Maintenance to repair by 3/30/26
10. Bottom Tier Left Side	Shower # KG-15	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 2/30/26
11. Bottom Tier Left Side	Shower # KG-15	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking Maintenance to repair by 1/30/26
12. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Floor surface left unfinished at entrance Maintenance to repair by 3/30/26
13. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Door rusted Maintenance to repair by 3/30/26
14. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Door frame rotted Maintenance to repair by 4/30/26
15. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 2/30/26
16. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123*	Maintenance: Soap scum on walls To be cleaned by workers by 1/10/26
17. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking Maintenance to repair by 1/30/26
18. Bottom Tier Right Side	Handicapped Shower # KG-42	105 CMR 451.123	Maintenance: Bench rusted Maintenance to repair by 2/30/26
19. Top Tier Right Side	Shower # KM-41	105 CMR 451.123*	Maintenance: Wall tiles damaged Maintenance to repair by 3/30/26
20. Top Tier Right Side	Shower # KM-41	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by workers by 1/10/26
21. Top Tier Right Side	Shower # KM-41	105 CMR 451.123*	Maintenance: Floor epoxy Damaged Maintenance to repair by 2/30/26

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 7 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in all cells Building falls under, and is compliant with, previous building standards/regulations
2. Common Area	105 CMR 451.350*	Structural Maintenance: Window cracked at entrance Maintenance to repair by 3/30/26

3. Common Area		105 CMR 451.353*	Interior Maintenance: Stair treads damaged Maintenance to repair by 3/30/26
4. Top Tier Left Side	Cells	105 CMR 451.353	Interior Maintenance Window not functioning properly in cell # KM-15 Maintenance to repair by 1/30/26
5. Bottom Tier Left Side	Janitor's Closet # KG-13	105 CMR 451.353	Interior Maintenance: Floor paint damaged Maintenance to repair by 1/30/26
6. Bottom Tier Left Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # KG-6 Maintenance to repair by 3/30/26
7. Bottom Tier Left Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # KG-13 and KG-15 Maintenance to repair by 3/30/26
8. Bottom Tier Right Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # KG-26 Maintenance to repair by 3/30/26
9. Bottom Tier Right Side	Cells	105 CMR 451.350	Structural Maintenance: Window cracked in cell # KG-16 and KG-18 Maintenance to repair by 3/30/26
10. Top Tier Right Side	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # KM-17 and KM-18 Maintenance to repair by 3/30/26

CPO Offices

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1. Hallway	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged outside offices Maintenance to repair by 3/30/26
------------	------------------	--

Orientation Unit

Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 22 repeat deficiencies (indicated by an *) were found during the inspection:

1. Top Tier	Shower # OUM-1 – OUM-5	105 CMR 451.123*	Maintenance: Wall damaged in shower # OUM-4 Maintenance to repair by 2/30/26
2. Top Tier	Shower # OUM-1 – OUM-5	105 CMR 451.124*	Water Supply: Insufficient water supply in quantity and pressure in shower # OUM-2 and OUM-4 Maintenance to adjust by 1/10/26
3. Top Tier	Shower # OUM-1 – OUM-5	105 CMR 451.123*	Maintenance: Door frame rotted in shower # OUM-2, OUM-4, and OUM-5 Maintenance to repair by 4/30/26
4. Top Tier	Shower # OUM-1 – OUM-5	105 CMR 451.123	Maintenance: Door frame rotted in shower # OUM-2, OUM-4, and OUM-3 Maintenance to repair by 4/30/26
5. Top Tier	Cells	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink in cell # 157 Maintenance to repair by 1/30/26
6. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.123*	Maintenance: Ceiling damaged in shower # OUG-1 Maintenance to repair by 1/30/26
7. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # OUG-3 To be cleaned by workers by 1/10/26
8. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # OUG-3 To be cleaned by workers by 1/10/26
9. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.123	Maintenance: Wall damaged in shower # OUG-3 Maintenance to repair by 2/30/26
10. Bottom Tier	Shower # OUG-1 – OUG-4	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # OUG-3 Maintenance to repair by 1/30/26
11. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking Maintenance to repair by 1/30/26
12. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Door paint Damaged Maintenance to paint by 1/30/26
13. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Door rusted Maintenance to repair by 1/30/26
14. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Door frame rusted Maintenance to repair by 1/30/26

15. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Soap scum on Floor To be cleaned by workers by 1/10/26
16. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Soap scum on Walls To be cleaned by workers by 1/10/26
17. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Floor dirty To be cleaned by workers by 1/10/26
18. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Shower control shroud missing Maintenance to replace by 2/30/26
19. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Ceiling damaged Maintenance to repair by 2/30/26
20. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Bench dirty To be cleaned by workers by 1/10/26
21. Bottom Tier	Handicapped Shower # OUG-5	105 CMR 451.123*	Maintenance: Bench rusted Maintenance to repair by 1/30/26

Deficiencies under the Recommended Standards (.300 series)

11 repeat deficiencies (indicated by an *) were found during the inspection:

1. Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells Building falls under, and is compliant with, previous building standards/regulations
2. Common Area		105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained Maintenance to repair by 3/30/26
3. Common Area		105 CMR 451.353*	Interior Maintenance: Floor tiles Damaged Maintenance to repair by 4/30/26
4. Top Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall water damaged around window in cell # 157 and 158 Maintenance to repair by 4/30/26
5. Top Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in all cells Vents cleared 1/10/26
6. Bottom Tier		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged outside showers Maintenance to paint by 1/30/26
7. Bottom Tier		105 CMR 451.353*	Interior Maintenance: Floor paint damaged outside showers Maintenance to paint by 4/30/26
8. Bottom Tier	Cells	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in cell # 110 Maintenance to repair by 4/30/26
9. Bottom Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall water damaged in cell # 120 Maintenance to repair by 4/30/26
10. Bottom Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in all cells Vents cleared 1/10/26

Industries Building**Deficiencies under the Required Standards (.100 and .200 series)**

3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Spectrum A2-24	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of refrigerator dirty Maintenance to replace by 3/30/26
2. Spectrum A2-24	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of freezer rusted Maintenance to replace by 3/30/26
3. Spectrum A2-24	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator gaskets damaged Maintenance to replace by 3/30/26

Gym

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:


1. Staff Bathroom # A2-44	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet Leaking Maintenance to repair by 1/30/26
---------------------------	-----------------	---

Towers

Deficiencies under the Recommended Standards (.300 series)

3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Pedestrian Tower	105 CMR 451.353*	Interior Maintenance: Ceiling tiles Missing Maintenance to repair by 3/30/26
2. Pedestrian Tower	105 CMR 451.350*	Structural Maintenance: Windows Cracked Maintenance to repair by 3/30/26
3. Tower # 1	105 CMR 451.350*	Structural Maintenance: Windows Cracked Maintenance to repair by 3/30/26



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street
Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll Lieutenant Governor

Kiame Mahaniah, MD, MBA

Robert Goldstein, MD, PhD
Commissioner

January 23, 2026

Jeffrey Gonsalves, Superintendent
Old Colony Correctional Center
1 Administration Road
Bridgewater, MA 02324 (electronic copy)

Re: Plan of Correction – Old Colony Correctional Center, Bridgewater

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction (POC) in response to my inspection on December 17, 2025. After review, the EHRS finds the plan appropriately addresses all of the violations noted with the following exception:

In regards to the issue of overcrowding, the EHRS appreciates the limitations of correctional facilities and the need to accommodate the ever-increasing population; however we remain concerned with the overcrowded conditions.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Patrick Wallace

Patrick Wallace
Environmental Analyst, EHRS, BCEH

cc: Matthew Lonergan, EHSO/FSO

(electronic copy)