

The Commonwealth of Massachusetts
 Executive Office of Health and Human Services
 Department of Public Health
 Bureau of Climate and Environmental Health
 Division of Environmental Health Regulations and Standards
 5 Randolph Street
 Canton, MA 02021
 617-624-6000 | mass.gov/dph

Maura T. Healey
 Governor

Kiame Mahaniah, MD, MBA
 Secretary

Kimberley Driscoll
 Lieutenant Governor

Robert Goldstein, MD, PhD
 Commissioner

May 12, 2025

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)
 Kiame Mahaniah, Secretary, Executive Office of Health and Human Services (electronic copy)
 Clerk, Massachusetts House of Representatives (electronic copy)
 Clerk, Massachusetts Senate (electronic copy)
 Michael Moreira, Environmental Health and Safety Officer (electronic copy)


Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Bristol County Modular Building, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Patrick Wallace
 Environmental Analyst, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)
 Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)
 Christopher Michaud, Director, Dartmouth Board of Health (electronic copy)
 Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)
 Paul Heroux, Sheriff (electronic copy)
 Joseph Oliver III, Superintendent (electronic copy)



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

March 23, 2026

Paul Heroux, Sheriff
Bristol County Sheriff's Office
Bristol County Jail and House of Correction
400 Faunce Corner Road
North Dartmouth, MA 02747 (electronic copy)

Re: Facility Inspection - Bristol County Modular Building, North Dartmouth

Dear Sheriff Heroux:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Bristol County Modular Building on March 11, 2026, accompanied by Michael Moreira, Fire Safety/Environmental Health and Safety Officer and Officer Justin Samanica, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 131 total deficiencies: 23 new deficiencies under the Required Standards (.100 and .200 series), 62 repeat deficiencies under the Required Standards, 6 new deficiencies under the Recommended Standards (.300 series), and 40 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

First Floor

Deficiencies under the Required Standards (.100 and .200 series)

7 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Modular Kitchen	Staff Bathroom# 013 (near Loading Dock)	105 CMR 451.123	Maintenance: Floor dirty
2.	Modular Kitchen	Staff Bathroom# 013 (near Loading Dock)	105 CMR 451.123	Maintenance: Handwash sink dirty
3.	Modular Kitchen	Staff Bathroom# 013 (near Loading Dock)	105 CMR 451.117	Toilet Fixtures: Toilet fixture dirty
4.	Modular Kitchen	Staff Bathroom# 013 (near Loading Dock)	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 66°F at handwash sink
5.	Modular Kitchen	Traulsen Refrigerators	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, gaskets dirty on left and right side refrigerator. Standard found in 105 CMR 590; FC 4-501.11(A).
6.	Modular Kitchen	Traulsen Refrigerators	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, floor rusted in right side refrigerator. Standard found in 105 CMR 590; FC 4-501.11(A).
7.	Mods Intake Area	Bathroom # 030	105 CMR 451.117	Toilet Fixtures: Toilet fixtures dirty in stall # 2
8.	Mods Intake Area	Bathroom # 027	105 CMR 451.117	Toilet Fixtures: Toilet fixtures dirty in stall # 3
9.	Mods Intake Area	Bathroom # 027	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet out-of-order in stall # 1

1 West Housing Unit

Deficiencies under the Required Standards (.100 and .200 series)

9 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Bathroom 1 (Right Side)	Shower # 4	105 CMR 451.123*	Maintenance: Partition paint damaged
2.	Bathroom 1 (Right Side)	Shower # 4	105 CMR 451.123*	Maintenance: Soap scum on walls
3.	Bathroom 2 (Left Side)		105 CMR 451.117*	Toilet Fixtures: Urinal # 1 and 2 dirty
4.	Bathroom 2 (Left Side)	Shower # 3	105 CMR 451.123*	Maintenance: Partition paint damaged
5.	Bathroom 2 (Left Side)	Shower # 3	105 CMR 451.123*	Maintenance: Soap scum on walls
6.	Bathroom 2 (Left Side)	Shower # 4	105 CMR 451.123*	Maintenance: Soap scum on walls
7.	Bathroom 2 (Left Side)	Shower # 5	105 CMR 451.123*	Maintenance: Soap scum on walls
8.	Bathroom 2 (Left Side)	Shower # 5	105 CMR 451.123*	Maintenance: Partition paint damaged

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Main Area	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged outside laundry room
2. Dorms	105 CMR 451.320*	Cell Size: Inadequate floor space in all dorms
3. Dorms	105 CMR 451.353	Interior Maintenance: Electrical outlet burned in dorm # 110

1 East Housing Unit**Deficiencies under the Required Standards (.100 and .200 series)**

6 new deficiencies and 8 repeat deficiencies (indicated by an *) were found during the inspection:

1. Bathroom 1 (right side)		105 CMR 451.117*	Toilet Fixtures: Urinal dirty
2. Bathroom 1 (right side)		105 CMR 451.117*	Toilet Fixtures: Floor epoxy damaged
3. Bathroom 1 (right side)		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink # 6 running continuously
4. Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Walls dirty
5. Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Mold observed on partition
6. Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Partition paint damaged
7. Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Partition paint damaged
8. Bathroom 1 (right side)	Shower # 3	105 CMR 451.123*	Maintenance: Partition paint damaged
9. Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Partition paint damaged
10. Bathroom 1 (right side)	Shower # 5	105 CMR 451.123	Maintenance: Partition paint damaged
11. Bathroom 2 (left side)		105 CMR 451.123	Maintenance: Floor dirty
12. Bathroom 2 (left side)		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet clogged in stall # 5
13. Bathroom 2 (left side)		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink # 8 running continuously
14. Bathroom 2 (left side)	Shower # 9	105 CMR 451.123	Maintenance: Partition paint damaged

Deficiencies under the Recommended Standards (.300 series)

7 repeat deficiencies (indicated by an *) were found during the inspection:

1. Storage	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
2. Storage	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
3. Storage	105 CMR 451.353*	Interior Maintenance: Mold observed on walls
4. Main Area	105 CMR 451.353*	Interior Maintenance: Wall damaged behind officer's station
5. Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
6. Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Mold observed on ceiling
7. Dorms	105 CMR 451.320*	Cell Size: Inadequate floor space in all dorms

2 West Housing Unit

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 36 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Bathroom 1 (right side)		105 CMR 451.123*	Maintenance: Floor epoxy damaged at entrance
2.	Bathroom 1 (right side)		105 CMR 451.123*	Maintenance: Toilet partitions paint damaged
3.	Bathroom 1 (right side)		105 CMR 451.123*	Maintenance: Light shields rusted
4.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Partition paint damaged
5.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Floor dirty
6.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Walls dirty
7.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Mold observed on walls
8.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Mold observed on floor
9.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Partition paint damaged
10.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Walls dirty
11.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Floor dirty
12.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Soap scum on walls
13.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Mold observed on walls
14.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Mold observed on floor
15.	Bathroom 1 (right side)	Shower # 3	105 CMR 451.123*	Maintenance: Partition paint damaged
16.	Bathroom 1 (right side)	Shower # 3	105 CMR 451.123*	Maintenance: Walls dirty
17.	Bathroom 1 (right side)	Shower # 3	105 CMR 451.123*	Maintenance: Mold observed on walls
18.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Partition paint damaged
19.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Walls dirty
20.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Soap scum on walls
21.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Mold observed on walls
22.	Bathroom 1 (right side)	Shower # 5	105 CMR 451.123*	Maintenance: Partition paint damaged
23.	Bathroom 2 (left side)		105 CMR 451.123*	Maintenance: Wall vent paint damaged
24.	Bathroom 2 (left side)		105 CMR 451.123*	Maintenance: Wall surface damaged
25.	Bathroom 2 (left side)		105 CMR 451.123*	Maintenance: Ceiling cracked
26.	Bathroom 2 (left side)	Shower # 6	105 CMR 451.123*	Maintenance: Partition paint damaged
27.	Bathroom 2 (left side)	Shower # 7	105 CMR 451.123*	Maintenance: Partition paint damaged
28.	Bathroom 2 (left side)	Shower # 7	105 CMR 451.123*	Maintenance: Soap scum on walls
29.	Bathroom 2 (left side)	Shower # 8	105 CMR 451.123*	Maintenance: Partition paint damaged
30.	Bathroom 2 (left side)	Shower # 8	105 CMR 451.123*	Maintenance: Floor dirty
31.	Bathroom 2 (left side)	Shower # 8	105 CMR 451.123*	Maintenance: Soap scum on walls
32.	Bathroom 2 (left side)	Shower # 8	105 CMR 451.123*	Maintenance: Walls dirty
33.	Bathroom 2 (left side)	Shower # 9	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower out-of-order
34.	Bathroom 2 (left side)	Shower # 9	105 CMR 451.123*	Maintenance: Partition paint damaged
35.	Bathroom 2 (left side)	Shower # 9	105 CMR 451.123*	Maintenance: Mold observed on walls
36.	Bathroom 2 (left side)	Shower # 10	105 CMR 451.123*	Maintenance: Partition paint damaged
37.	Bathroom 2 (left side)	Shower # 10	105 CMR 451.123*	Maintenance: Mold observed on walls

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 26 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Mechanical Room	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
2.	Main Area	105 CMR 451.353*	Interior Maintenance: Baseboard damaged

3.	Main Area	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
4.	Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
5.	Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Wet mop stored in sink
6.	Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Mold observed on ceiling
7.	Dorm Hallway	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
8.	Dorms	105 CMR 451.320*	Cell Size: Inadequate floor space in all dorms
9.	Dorms	105 CMR 451.353*	Interior Maintenance: Mold observed on walls in dorm # 201, 202, 205, 206, 207, 211, and 212
10.	Dorms	105 CMR 451.353*	Interior Maintenance: Mold observed on ceiling in dorm # 203, 204, 205, 206, 207, 208, 210, 211, and 212
11.	Dorms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm # 207
12.	Dorms	105 CMR 451.353*	Interior Maintenance: Electrical outlet burned in dorm # 207
13.	Dorms	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in dorm # 208
14.	Dorms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm # 208 and 210
15.	Dorms	105 CMR 451.353	Interior Maintenance: Wall dirty around vent in dorm # 207

2 East Housing Unit

Deficiencies under the Required Standards (.100 and .200 series)

9 new deficiencies and 7 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Bathroom 1 (right side)		105 CMR 451.117*	Toilet Fixtures: Urinal dirty
2.	Bathroom 1 (right side)		105 CMR 451.123	Maintenance: Toilet partitions paint damaged
3.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123	Maintenance: Partition paint damaged
4.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123	Maintenance: Walls dirty
5.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123	Maintenance: Walls dirty
6.	Bathroom 1 (right side)	Shower # 3	105 CMR 451.123	Maintenance: Walls dirty
7.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123	Maintenance: Partition paint damaged
8.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123	Maintenance: Walls dirty
9.	Bathroom 1 (right side)	Shower # 5	105 CMR 451.123	Maintenance: Partition paint damaged
10.	Bathroom 1 (right side)	Shower # 5	105 CMR 451.123	Maintenance: Walls dirty
11.	Bathroom 2 (left side)		105 CMR 451.117*	Toilet Fixtures: Urinal # 1 and 2 dirty
12.	Bathroom 2 (left side)	Shower # 9	105 CMR 451.123*	Maintenance: Walls dirty
13.	Bathroom 2 (left side)	Shower # 9	105 CMR 451.123*	Maintenance: Floor dirty
14.	Bathroom 2 (left side)	Shower # 10	105 CMR 451.123*	Maintenance: Walls dirty
15.	Bathroom 2 (left side)	Shower # 10	105 CMR 451.123*	Maintenance: Floor dirty

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Storage		105 CMR 451.353*	Interior Maintenance: Mold observed on duct work
2.	Main Area		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
3.	Main Area		105 CMR 451.353*	Interior Maintenance: Water fountain rusted
4.	Main Area	Dorm Hallway	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
5.	Janitor's Closet	Dorm Hallway	105 CMR 451.353	Interior Maintenance: Wet mop stored in sink
6.	Dorms		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
7.	Dorms		105 CMR 451.353	Interior Maintenance: Wall water damaged in dorm # 242

SECTION 2: Areas Found to be in Compliance

EHRIS inspected 26 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRIS did not inspect

EHRIS inspected all areas of the facility.

SECTION 4: Plan of Correction

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. A signature by the Superintendent or Administrator responsible for the plan. The signed plan should be submitted to my attention, at the address listed above.

SECTION 4: Observations and Recommendations

1. The inmate population was 173 at the time of inspection.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#) is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Patrick Wallace
Environmental Analyst, EHRIS, BCEH



PAUL HEROUX
SHERIFF

THE COMMONWEALTH OF MASSACHUSETTS
OFFICE OF THE
BRISTOL COUNTY SHERIFF

400 Faunce Corner Road
North Dartmouth, MA 02747
TEL. (508) 995-6400
FAX. (508) 995-7835
www.bcs0-ma.us



April 7, 2026

Department of Public Safety
Division of Community Sanitation, c/o Mr. Patrick Wallace, EHRS, BCEH
5 Randolph St
Canton MA 02021

Dear Mr. Wallace,

Attached, please find the response from the Bristol County Sheriff's Office for the March 11th, 2026 DPH inspection of the Modular Units at the Dartmouth Complex located on 400 Faunce Corner Road in Dartmouth.

Please be aware that the Bristol County Sheriff's Office is committed to ongoing improvements within this facility and is attempting to correct or has already corrected all areas of non-compliance.

Should you have any questions or concerns, please feel free to contact me at 508-995-6400 ext. 2831 or MichaelMoreira@BCSO-MA.Org.

Respectfully,

Michael E. Moreira
Environmental Health and Safety

Paul Heroux
Sheriff of Bristol County

Acushnet•Attleboro•Berkley•Dartmouth•Dighton•Easton•Fairhaven•Fall River
Freetown•Mansfield•New Bedford•North Attleboro•Norton•Raynham•Rehoboth
Seekonk•Somerset•Swansea•Taunton•Westport



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

March 23, 2026

Paul Heroux, Sheriff
Bristol County Sheriff's Office
Bristol County Jail and House of Correction
400 Faunce Corner Road
North Dartmouth, MA 02747 (electronic copy)

Re: Facility Inspection - Bristol County Modular Building, North Dartmouth

Dear Sheriff Heroux:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Bristol County Modular Building on March 11, 2026, accompanied by Michael Moreira, Fire Safety/Environmental Health and Safety Officer and Officer Justin Samanica, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 131 total deficiencies: 23 new deficiencies under the Required Standards (.100 and .200 series), 62 repeat deficiencies under the Required Standards, 6 new deficiencies under the Recommended Standards (.300 series), and 40 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

First Floor

Deficiencies under the Required Standards (.100 and .200 series)

7 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Modular Kitchen	Staff Bathroom# 013	105 CMR 451.123	Maintenance: Floor dirty <u>RESPONSE: Floor to be cleaned by 4/24/26</u>
2.	Modular Kitchen	Staff Bathroom# 013	105 CMR 451.123	Maintenance: Handwash sink dirty <u>RESPONSE: Sink to be cleaned by 4/24/26</u>
3.	Modular Kitchen	Staff Bathroom# 013	105 CMR 451.117	Toilet Fixtures: Toilet fixture dirty <u>RESPONSE: Toilet to be cleaned by 4/24/26</u>
4.	Modular Kitchen	Staff Bathroom# 013	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 66°F at handwash sink <u>RESPONSE: Water temperature has been adjusted as of 4/5/26</u>
5.	Modular Kitchen	Traulsen Refrigerators	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, gaskets dirty on left and right side refrigerator. Standard found in 105 CMR 590; FC 4-501.11(A). <u>RESPONSE: Gaskets to be cleaned by 4/24/26</u>
6.	Modular Kitchen	Traulsen Refrigerators	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, floor rusted in right side refrigerator. Standard found in 105 CMR 590; FC 4-501.11(A). <u>RESPONSE: Floor to be repaired by 5/25/26</u>
7.	Mods Intake Area	Bathroom # 030	105 CMR 451.117	Toilet Fixtures: Toilet fixtures dirty in stall # 2 <u>RESPONSE: Fixtures to be cleaned by 4/24/26</u>
8.	Mods Intake Area	Bathroom # 027	105 CMR 451.117	Toilet Fixtures: Toilet fixtures dirty in stall # 3 <u>RESPONSE: Toilet to be cleaned by 4/24/26</u>
9.	Mods Intake Area	Bathroom # 027	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet out-of-order in stall # 1 <u>RESPONSE: Toilet has been repaired as of 4/5/26</u>

1 West Housing Unit

Deficiencies under the Required Standards (.100 and .200 series)

9 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Bathroom 1 (Right Side)	Shower # 4	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
2.	Bathroom 1 (Right Side)	Shower # 4	105 CMR 451.123*	Maintenance: Soap scum on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
3.	Bathroom 2 (Left Side)		105 CMR 451.117*	Toilet Fixtures: Urinal # 1 and 2 dirty <u>RESPONSE: Urinals to be cleaned by 4/24/26</u>
4.	Bathroom 2 (Left Side)	Shower # 3	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>

5. Bathroom 2 (Left Side)	Shower # 3	105 CMR 451.123*	Maintenance: Soap scum on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
6. Bathroom 2 (Left Side)	Shower # 4	105 CMR 451.123*	Maintenance: Soap scum on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
7. Bathroom 2 (Left Side)	Shower # 5	105 CMR 451.123*	Maintenance: Soap scum on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
8. Bathroom 2 (Left Side)			

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and **2 repeat deficiencies** (indicated by an *) were found during the inspection:

1. Main Area	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged outside laundry Room <u>RESPONSE: Floor tiles to be replaced by 5/25/26</u>
2. Dorms	105 CMR 451.320*	Cell Size: Inadequate floor space in all dorms <u>RESPONSE: Waiver to be submitted for approval</u>
3. Dorms	105 CMR 451.353	Interior Maintenance: Electrical outlet burned in dorm # 110 <u>RESPONSE: Outlet to be replaced by 5/25/26</u>

1 East Housing Unit

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and **8 repeat deficiencies** (indicated by an *) were found during the inspection:

1. Bathroom 1 (right side)		105 CMR 451.117*	Toilet Fixtures: Urinal dirty <u>RESPONSE: Urinal to be cleaned by 4/24/26</u>
2. Bathroom 1 (right side)		105 CMR 451.117*	Toilet Fixtures: Floor epoxy damaged <u>RESPONSE: Floor to be repaired by 5/25/26</u>
3. Bathroom 1 (right side)		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink # 6 running continuously <u>RESPONSE: Sink has been repaired as of 4/5/26</u>
4. Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Walls dirty <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
5. Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Mold observed on partition <u>RESPONSE: Partition to be cleaned by 4/24/26</u>
6. Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
7. Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
8. Bathroom 1 (right side)	Shower # 3	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
9. Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>

10. Bathroom 1 (right side)	Shower # 5	105 CMR 451.123	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
11. Bathroom 2 (left side)		105 CMR 451.123	Maintenance: Floor dirty <u>RESPONSE:Floor has been cleaned as of 4/5/26</u>
12. Bathroom 2 (left side)		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet clogged in stall # 5 <u>RESPONSE:Toilet has been cleared as of 4/5/26</u>
13. Bathroom 2 (left side)		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink # 8 running continuously <u>RESPONSE:Sink to be repaired by 5/25/26</u>
14. Bathroom 2 (left side)	Shower # 9	105 CMR 451.123	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>

Deficiencies under the Recommended Standards (.300 series)

7 repeat deficiencies (indicated by an *) were found during the inspection:

1. Storage	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <u>RESPONSE:Wall to be painted by 5/25/26</u>
2. Storage	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <u>RESPONSE:Floor to be painted by 5/25/26</u>
3. Storage	105 CMR 451.353*	Interior Maintenance: Mold observed on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
4. Main Area	105 CMR 451.353*	Interior Maintenance: Wall damaged behind officer's station <u>RESPONSE:Wall to be repaired by 5/25/26</u>
5. Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <u>RESPONSE:Ceiling to be repaired by 5/25/26</u>
6. Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Mold observed on ceiling <u>RESPONSE:Ceiling to be cleaned by 4/24/26</u>
7. Dorms	105 CMR 451.320*	Cell Size: Inadequate floor space in all dorms <u>RESPONSE:Waiver to be submitted for approval</u>

2 West Housing Unit

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and **36 repeat deficiencies** (indicated by an *) were found during the inspection:

1. Bathroom 1 (right side)		105 CMR 451.123*	Maintenance: Floor epoxy damaged at entrance <u>RESPONSE:Floor to be repaired by 5/25/26</u>
2. Bathroom 1 (right side)		105 CMR 451.123*	Maintenance: Toilet partitions paint Damaged <u>RESPONSE:Partitions to be painted by 5/25/26</u>
3. Bathroom 1 (right side)		105 CMR 451.123*	Maintenance: Light shields rusted <u>RESPONSE:Light shields to be painted by 5/25/26</u>
4. Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
5. Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Floor dirty <u>RESPONSE:Floor has been cleaned as of 4/5/26</u>

6.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Walls dirty <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
7.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Mold observed on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
8.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123*	Maintenance: Mold observed on floor <u>RESPONSE: Floor has been cleaned as of 4/5/26</u>
9.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
10.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Walls dirty <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
11.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Floor dirty <u>RESPONSE: Floor has been cleaned as of 4/5/26</u>
12.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Soap scum on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
13.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Mold observed on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
14.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123*	Maintenance: Mold observed on floor <u>RESPONSE: Floor has been cleaned as of 4/5/26</u>
15.	Bathroom 1 (right side)	Shower # 3	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
16.	Bathroom 1 (right side)	Shower # 3	105 CMR 451.123*	Maintenance: Walls dirty <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
17.	Bathroom 1 (right side)	Shower # 3	105 CMR 451.123*	Maintenance: Mold observed on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
18.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
19.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Walls dirty <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
20.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Soap scum on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
21.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123*	Maintenance: Mold observed on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
22.	Bathroom 1 (right side)	Shower # 5	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
23.	Bathroom 2 (left side)		105 CMR 451.123*	Maintenance: Wall vent paint damaged <u>RESPONSE: Wall vent to be painted by 5/25/26</u>
24.	Bathroom 2 (left side)		105 CMR 451.123*	Maintenance: Wall surface damaged <u>RESPONSE: Wall to be repaired by 5/25/26</u>
25.	Bathroom 2 (left side)		105 CMR 451.123*	Maintenance: Ceiling cracked <u>RESPONSE: Ceiling to be repaired by 5/25/26</u>
26.	Bathroom 2 (left side)	Shower # 6	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
27.	Bathroom 2 (left side)	Shower # 7	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
28.	Bathroom 2 (left side)	Shower # 7	105 CMR 451.123*	Maintenance: Soap scum on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
29.	Bathroom 2 (left side)	Shower # 8	105 CMR 451.123*	Maintenance: Partition paint damaged <u>RESPONSE: Partition to be painted by 5/25/26</u>
30.	Bathroom 2 (left side)	Shower # 8	105 CMR 451.123*	Maintenance: Floor dirty <u>RESPONSE: Floor has been cleaned as of 4/5/26</u>
31.	Bathroom 2 (left side)	Shower # 8	105 CMR 451.123*	Maintenance: Soap scum on walls <u>RESPONSE: Walls to be cleaned by 4/24/26</u>
32.	Bathroom 2 (left side)	Shower # 8	105 CMR 451.123*	Maintenance: Walls dirty <u>RESPONSE: Walls to be cleaned by 4/24/26</u>

33. Bathroom 2 (left side)	Shower # 9	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower out-of-order RESPONSE: Shower to be repaired by 5/25/26
34. Bathroom 2 (left side)	Shower # 9	105 CMR 451.123*	Maintenance: Partition paint damaged RESPONSE: Partition to be painted by 5/25/26
35. Bathroom 2 (left side)	Shower # 9	105 CMR 451.123*	Maintenance: Mold observed on walls RESPONSE: Walls to be cleaned by 4/24/26
36. Bathroom 2 (left side)	Shower # 10	105 CMR 451.123*	Maintenance: Partition paint damaged RESPONSE: Partition to be painted by 5/25/26
37. Bathroom 2 (left side)	Shower # 10	105 CMR 451.123*	Maintenance: Mold observed on walls RESPONSE: Walls to be cleaned by 4/24/26

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and **26 repeat deficiencies** (indicated by an *) were found during the inspection:

1. Mechanical Room	105 CMR 451.353*	Interior Maintenance: Floor surface damaged RESPONSE: Floor to be repaired by 5/25/26
2. Main Area	105 CMR 451.353*	Interior Maintenance: Baseboard damaged RESPONSE: Baseboard to be repaired or replaced by 5/25/26
3. Main Area	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged RESPONSE: Floor tiles to be replaced by 5/25/26
4. Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged RESPONSE: Ceiling to be painted by 5/25/26
5. Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Wet mop stored in sink RESPONSE: Mop stored correctly as of 4/5/26
6. Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Mold observed on ceiling RESPONSE: Ceiling to be cleaned by 4/24/26
7. Dorm Hallway	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged RESPONSE: Floor tiles to be replaced by 5/25/26
8. Dorms	105 CMR 451.320*	Cell Size: Inadequate floor space in all dorms RESPONSE: Waiver to be submitted for approval.
9. Dorms	105 CMR 451.353*	Interior Maintenance: Mold observed on walls in dorm # 201, 202, 205, 206, 207, 211, and 212 RESPONSE: Walls to be cleaned and scrubbed by 4/24/26
10. Dorms	105 CMR 451.353*	Interior Maintenance: Mold observed on ceiling in dorm # 203, 204, 205, 206, 207, 208, 210, 211, and 212 RESPONSE: Ceilings to be scrubbed and cleaned by 4/24/26.
11. Dorms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm # 207 RESPONSE: Wall to be painted by 5/25/26
12. Dorms	105 CMR 451.353*	Interior Maintenance: Electrical outlet burned in dorm # 207 RESPONSE: Outlet to be replaced by 5/25/26
13. Dorms	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in dorm # 208 RESPONSE: Ceiling to be painted by 5/25/26
14. Dorms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm # 208 and 210 RESPONSE: Walls to be painted by 5/25/26
15. Dorms	105 CMR 451.353	Interior Maintenance: Wall dirty around vent in dorm # 207 RESPONSE: Wall to be cleaned by 4/24/26

2 East Housing Unit

Deficiencies under the Required Standards (.100 and .200 series)

9 new deficiencies and **7 repeat deficiencies** (indicated by an *) were found during the inspection:

1.	Bathroom 1 (right side)		105 CMR 451.117*	Toilet Fixtures: Urinal dirty RESPONSE:Urinal has been cleaned as of 4/5/26
2.	Bathroom 1 (right side)		105 CMR 451.123	Maintenance: Toilet partitions paint damaged RESPONSE:Partitions to be painted by 5/25/26
3.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123	Maintenance: Partition paint damaged RESPONSE: Partition to be painted by 5/25/26
4.	Bathroom 1 (right side)	Shower # 1	105 CMR 451.123	Maintenance: Walls dirty RESPONSE: Walls to be cleaned by 4/24/26
5.	Bathroom 1 (right side)	Shower # 2	105 CMR 451.123	Maintenance: Walls dirty RESPONSE: Walls to be cleaned by 4/24/26
6.	Bathroom 1 (right side)	Shower # 3	105 CMR 451.123	Maintenance: Walls dirty RESPONSE: Walls to be cleaned by 4/24/26
7.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123	Maintenance: Partition paint damaged RESPONSE: Partition to be painted by 5/25/26
8.	Bathroom 1 (right side)	Shower # 4	105 CMR 451.123	Maintenance: Walls dirty RESPONSE: Walls to be cleaned by 4/24/26
9.	Bathroom 1 (right side)	Shower # 5	105 CMR 451.123	Maintenance: Partition paint damaged RESPONSE: Partition to be painted by 5/25/26
10.	Bathroom 1 (right side)	Shower # 5	105 CMR 451.123	Maintenance: Walls dirty RESPONSE: Walls to be cleaned by 4/24/26
11.	Bathroom 2 (left side)		105 CMR 451.117*	Toilet Fixtures: Urinal # 1 and 2 dirty RESPONSE:Urinals to be cleaned by 4/24/26
12.	Bathroom 2 (left side)	Shower # 9	105 CMR 451.123*	Maintenance: Walls dirty RESPONSE: Walls to be cleaned by 4/24/26
13.	Bathroom 2 (left side)	Shower # 9	105 CMR 451.123*	Maintenance: Floor dirty RESPONSE:Floor to be cleaned by 4/24/26
14.	Bathroom 2 (left side)	Shower # 10	105 CMR 451.123*	Maintenance: Walls dirty RESPONSE: Walls to be cleaned by 4/24/26
15.	Bathroom 2 (left side)	Shower # 10	105 CMR 451.123*	Maintenance: Floor dirty RESPONSE:Floor to be cleaned by 4/24/26

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Storage		105 CMR 451.353*	Interior Maintenance: Mold observed on duct Work RESPONSE:Duct work to be cleaned by 4/24/26
2.	Main Area		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged RESPONSE:Floor tiles to be replaced by 5/25/26
3.	Main Area		105 CMR 451.353*	Interior Maintenance: Water fountain rusted RESPONSE: Water fountain to be sanded by 5/25/26
4.	Main Area	Dorm Hallway	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged RESPONSE:Floor tiles to be replaced by 5/25/26
5.	Janitor's Closet	Dorm Hallway	105 CMR 451.353	Interior Maintenance: Wet mop stored in sink RESPONSE:Wet mop now stored correctly as of 4/5/26
6.	Dorms		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells RESPONSE:Waiver to be submitted for approval
7.	Dorms		105 CMR 451.353	Interior Maintenance: Wall water damaged in dorm # 242 RESPONSE:Wall to be repaired and painted by 5/25/26

SECTION 2: Areas Found to be in Compliance

EHRIS inspected 26 additional areas of the facility which were found to be in compliance.

SECTION 3: Areas EHRIS did not inspect

EHRIS inspected all areas of the facility.

SECTION 4: Plan of Correction

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. A signature by the Superintendent or Administrator responsible for the plan. The signed plan should be submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 173 at the time of inspection.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#) is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Patrick Wallace
Environmental Analyst, EHRIS, BCEH



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street
Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

April 17, 2026

Paul Heroux, Sheriff
Bristol County Sheriff's Office
Bristol County Jail and House of Correction
400 Faunce Corner Road
North Dartmouth, MA 02747 (electronic copy)

Re: Plan of Correction - Bristol County Modular Building, North Dartmouth

Dear Sheriff Heroux:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction in response to my inspection on March 11, 2026. After review, the EHRS finds the plan appropriately addresses all of the deficiencies noted in the report with the following exception:

In regards to the issue of overcrowding, EHRS appreciates the limitations of correctional facilities and the need to accommodate the ever-increasing population; however we remain concerned with the overcrowded

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

A handwritten signature in blue ink that reads "Patrick Wallace".

Patrick Wallace
Environmental Analyst, EHRS, BCEH

cc: Joseph Oliver III, Superintendent
Michael Moreira, EHSO

(electronic copy)
(electronic copy)