

The Commonwealth of Massachusetts
Executive Office of Health and Human Services Department
of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards

MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

5 Randolph Street
Canton, MA 02021
Phone: 617-624-5757

KATHLEEN E. WALSH
Secretary

ROBERT GOLDSTEIN, MD, PhD
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

March 17, 2025

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)
Kathleen E. Walsh, Secretary, Executive Office of Health and Human Services (electronic copy)
Clerk, Massachusetts House of Representatives (electronic copy)
Clerk, Massachusetts Senate (electronic copy)
John Aponte, Environmental Health and Safety Officer (electronic copy)

Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Massachusetts Treatment Center, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Patrick Wallace
Environmental Health Inspector, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)
Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)
Eric J. Badger, Health Agent, Bridgewater Board of Health (electronic copy)
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)
Jeffrey Gonsalves, Superintendent (electronic copy)
Sally Desrosiers, Deputy Superintendent (electronic copy)



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards

MAURA T. HEALEY
Governor
KIMBERLEY DRISCOLL
Lieutenant Governor

5 Randolph Street
Canton, MA 02021
Phone: 617-624-5757

KATHLEEN E. WALSH
Secretary
ROBERT GOLDSTEIN, MD, PhD
Commissioner
Tel: 617-624-6000
www.mass.gov/dph

February 14, 2025

Jeffrey Gonsalves, Superintendent
Massachusetts Treatment Center
30 Administration Road
Bridgewater, MA 02324 (electronic copy)

Re: Facility Inspection – Massachusetts Treatment Center, Bridgewater

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Massachusetts Treatment Center on November 25 and 26, 2024 accompanied by Nathan Frasier, Facilities Maintenance Director and John Aponte, Environmental Health and Safety Officer, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 254 total deficiencies: 53 deficiencies under the Required Standards (.100 and .200 series), 115 repeat deficiencies under the Required Standards, 25 deficiencies under the Recommended Standards (.300series), 59 repeat deficiencies under the Recommended Standards, and 2 new deficiencies under 105 CMR 451.402(B) (other conditions that may constitute a threat to health or safety)

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Front Lobby

Deficiencies under the Required Standards (.100 and .200 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Male Bathroom	105 CMR 451.123*	Maintenance: Trash barrel rotted
2. Male Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking at left side handwash sink

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Waiting Area	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged
2. Waiting Area	105 CMR 451.350*	Structural Maintenance: Front entrance not rodent and weathertight

Administration Area

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1. Main Area	105 CMR 451.353	Interior Maintenance: Ceiling tiles missing
--------------	-----------------	---

Control Area

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Central Tower	105 CMR 451.350	Structural Maintenance: Ceiling leaking
2. Central Tower	105 CMR 451.353*	Interior Maintenance: Floor surface damaged

Fire Safety Room

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1. Central Laundry	105 CMR 451.353	Interior Maintenance: Floor paint damaged
--------------------	-----------------	---

A Units

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 22 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Door frame rotted in shower # AG-12
2.	A1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Wall epoxy damaged in shower # AG-12
3.	A1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Door frame rotted in shower # AG-13
4.	A1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AG-13
5.	A1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # AG-13
6.	A1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Wall tile grout dirty in shower # AG-13
7.	A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AM-12 and AM-13
8.	A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # AM-12 and AM-13
9.	A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Ceiling damaged in shower # AM-12
10.	A1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Floor surface damaged in shower # AM-12 and AM-13
11.	A2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # AG-36
12.	A2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AG-36
13.	A2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Mold observed on ceiling in shower # AG-36
14.	A2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Walls dirty in shower # AG-36
15.	A2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # AG-36
16.	A2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # AG-36
17.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rotted in shower # AM-36
18.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # AM-36
19.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AM-36
20.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Mold observed on ceiling shower # AM-36
21.	A2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # AM-36

22.	A2 Unit	Common Area	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, Plumbing not maintained in good repair, handwash sink running continuously at kitchenette
-----	---------	-------------	-----------------	---

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A1 Unit	Cells	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 1
2.	A1 Unit	Common Area	105 CMR 451.350*	Structural Maintenance: Window cracked near stairs
3.	A1 Unit	Slop Sink # A1-1	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
4.	A2 Unit	Cells	105 CMR 451.353	Interior Maintenance: Floor surface damaged in cell # 6
5.	A2 Unit	Common Area	105 CMR 451.353	Interior Maintenance: Floor epoxy damaged on second level
6.	A2 Unit	Common Area	105 CMR 451.353*	Interior Maintenance: Floor paint damaged on handicapped ramp
7.	A2 Unit	Utility Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8.	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in some cells; some cells double bunked

Health Services Unit

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1.	Female Bathroom # A1-48		105 CMR 451.123	Maintenance: Floor surface damaged at entrance
----	-------------------------	--	-----------------	--

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	Room # A1-69		105 CMR 451.353*	Interior Maintenance: Floor surface damaged at entrance
----	--------------	--	------------------	---

Deficiencies under 105 CMR 451.402(B) (other conditions that may constitute a threat to health or safety)

2 new deficiencies were found during the inspection:

1.	Medical Records Room		105 CMR 451.402(B)	Procedures; Records; Record-Keeping Log: Generator did not maintain a record-keeping log for waste sent off-site for treatment, record keeping log missing entries for multiple recent pickups. Standard found in 105 CMR 480.500(B).
2.	Medical Records Room		105 CMR 451.402(B)	Tracking Medical or Biological Waste for Treatment: Generator did not confirm the shipment was received by the

treatment facility within 30 days on an approved tracking form, binder missing tracking form for multiple recent pickups. Standard found in 105 CMR 480.425(A).

B Units

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	B1 Unit	1st Floor Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head missing in shower # BG-13
2.	B1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # BM-12 and BM-13
3.	B1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door rusted in shower # BM-12
4.	B1 Unit	Common Area	105 CMR 451.141	Screens: Screen damaged near stairs
5.	B1 Unit	Common Area	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water not working at kitchenette handwash sink
6.	B2 Unit	Common Area	105 CMR 451.353	Interior Maintenance: Wall paint damaged outside shower # BG-35
7.	B2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Ceiling rusted in shower # BG-35 and BG-36
8.	B2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # BM-35

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1.	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double-bunked
2.	B Control		105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained
3.	B2 Unit	Common Area	105 CMR 451.353	Interior Maintenance: Wall paint damaged outside shower # BG-35

Food Service Areas

Deficiencies under the Required Standards (.100 and .200 series)

11 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Kitchen	Serving Area	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Time/temperature control for safety food not held at 135°F or above (Pf), tomato sauce recorded at 75°F. Standard found in 105 CMR 590; FC 3-501.16(A)(1).	Corrected On-Site
----	---------	--------------	-----------------	--	--------------------------

2.	Kitchen	Serving Area	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Time/temperature control for safety food not held at 135°F or above (Pf), meatballs recorded at 129°F. Standard found in 105 CMR 590; FC 3-501.16(A)(1).	Corrected On-Site
3.	Kitchen	Warmer Units	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, external thermometer not functioning properly on warmer # 3. Standard found in 105 CMR 590; FC 4-501.11(B).	
4.	Kitchen	Warmer Units	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, warmer # 3 not functioning properly. Standard found in 105 CMR 590; FC 4-501.11(A).	
5.	Kitchen	Utility/Toxic Closet	105 CMR 451.200	Maintenance and Operation: Premises, Structure, Attachments, and Fixtures - Methods; Wet mop stored in bucket. Standard found in 105 CMR 590; FC 6-501.16.	Corrected On-Site
6.	Kitchen	Utility/Toxic Closet	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, mop handles damaged. Standard found in 105 CMR 590; FC 6-501.11.	Corrected On-Site
7.	Kitchen	Dry Storage	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, floor surface damaged. Standard found in 105 CMR 590; FC 6-501.11.	
8.	Kitchen	Dry Storage	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; floor dirty behind shelving. Standard found in 105 CMR 590; FC 6-501.12(A).	Corrected On-Site
9.	Kitchen	Recycling Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, recycling carts damaged. Standard found in 105 CMR 590; FC 6-501.11.	
10.	Staff Food Service	3-Compartment Sink	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, faucet leaking. Standard found in 105 CMR 590; FC 5-205.15(B).	
11.	Staff Food Service	3-Compartment Sink	105 CMR 451.200	Maintenance and Operation; Equipment: Chlorine Sanitizer solution tested lower than recommended concentration. Standard found in 105 CMR 590; FC 4-501.114(A).	Corrected On-Site

12. Kitchen		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; floor grout dirty throughout. Standard found in 105 CMR 590; FC 6-501.12(A).
13. Kitchen	Dry Storage	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling damaged. Standard found in 105 CMR 590; FC 6-501.11.
14. Staff Food Service	Warewash Machine	105 CMR 451.200*	Maintenance and Operation; Equipment: Chlorine Sanitizer solution tested lower than recommended concentration. Standard found in 105 CMR 590; FC 4-501.114(A).

Gym

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1. Gym	Male Staff Bathroom	105 CMR 451.123	Maintenance: Partition rusted
--------	---------------------	-----------------	-------------------------------

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency was found during the inspection:

1. Gym	Recreation Officer's Office	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged
--------	-----------------------------	------------------	---

D Units

Deficiencies under the Required Standards (.100 and .200 series)

13 new deficiencies and 60 repeat deficiencies (indicated by an *) were found during the inspection:

1. D1 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # DG-12 and DG-13
2. D1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # Door frame rusted in shower # DG-12 and DG-13
3. D1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Wall caulking dirty in shower # DG-13
4. D1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # DG-12
5. D1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Ceiling dirty in shower # DG-13
6. D1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower # DG-12 and DG-13
7. D1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Floor dirty in shower # DG-12 and DG-13
8. D1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # DG-12 and DG-13

9.	D1 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Ceiling epoxy damaged in shower # DG-12
10.	D1 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # DM-12
11.	D1 Unit	2nd Floor Showers	105 CMR 451.130	Hot Water: Shower water temperature 89°F in shower # DM-13
12.	D1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # DM-12 and DM-13
13.	D1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door rusted in shower # DM-12 and DM-13
14.	D1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Walls dirty in shower # DM-13
15.	D1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # DM-12
16.	D1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower # DM-12 and DM-13
17.	D1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Ceiling epoxy damaged in shower # DM-12
18.	D1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # DM-12
19.	D1 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # DM-12 and DM-13
20.	D2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # DG-35 and DG-36
21.	D2 Unit	1st Floor Showers	105 CMR 451.123	Maintenance: Soap scum on floor in shower # DG-35 and DG-36
22.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # DG-35 and DG-36
23.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # DG-35 and DG-36
24.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Door rusted in shower # DG-35 and DG-36
25.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # DG-35 and DG-36
26.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Floor dirty in shower # DG-35 and DG-36
27.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Ceiling epoxy damaged in shower # DG-35 and DG-36
28.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # DG-35 and DG-36
29.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # DG-35 and DG-36
30.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Door rusted in shower # DG-35 and DG-36
31.	D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # DG-35 and DG-36

32. D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Floor dirty in shower # DG-35 and DG-36
33. D2 Unit	1st Floor Showers	105 CMR 451.123*	Maintenance: Ceiling epoxy damaged in shower # DG-35 and DG-36
34. D2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # DM-35 and DM-36
35. D2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # DM-35 and DM-36
36. D2 Unit	2nd Floor Showers	105 CMR 451.123	Maintenance: Mold on walls in shower # DM-35
37. D2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Door frame rusted in shower # DM-35 and DM-36
38. D2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # DM-35 and DM-36
39. D2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Floor surface damaged in shower # DM-35 and DM-36
40. D2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # DM-35 and DM-36
41. D2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Ceiling epoxy damaged in shower # DM-35 and DM-36
42. D2 Unit	2nd Floor Showers	105 CMR 451.123*	Maintenance: Ceiling vent paint damaged in shower # DM-35 and DM-36

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 7 repeat deficiencies (indicated by an *) were found during the inspection:

1. All Cells		105 CMR 451.321*	Cell Size: Inadequate floor space in cells, some cells double-bunked
2. D1 Unit	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 8
3. D1 Unit	Cells	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in cell # 8
4. D2 Unit	Cells	105 CMR 451.353	Interior Maintenance: Wall damaged in cell # 6
5. D2 Unit	Cells	105 CMR 451.353	Interior Maintenance: Ceiling damaged in cell # 21
6. D2 Unit	Common Area	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged
7. D2 Unit	Common Area	105 CMR 451.353*	Interior Maintenance: Floor epoxy damaged
8. D2 Unit	Room # D1-9	105 CMR 451.353*	Interior Maintenance: Ceiling water stained
9. D2 Unit	Utility Closet # D1-10	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged
10. D2 Unit	Utility Closet # D1-10	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

B.A.U.**Deficiencies under the Required Standards (.100 and .200 series)**

2 new deficiencies were found during the inspection:

1.	Main Area	Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 1 and 2
----	-----------	---------	-----------------	--

Deficiencies under the Recommended Standards (.300 series)

3 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Main Area	Cells	105 CMR 451.353*	Interior Maintenance: Light shield damaged in cell # 7
2.	Main Area	Cells	105 CMR 451.350*	Structural Maintenance: Window cracked in cell # 3 and 4

Modular Units – South**Deficiencies under the Required Standards (.100 and .200 series)**

5 new deficiencies and 14 repeat deficiencies (indicated by an *) were found during the inspection:

1.	South 1	Common Area	Day Room	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, water fountain damaged
2.	South 1	Common Area	Day Room	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, water fountain out-of-order
3.	South 1	Staff Area	Staff Bathroom	105 CMR 451.123	Maintenance: Hole in ceiling
4.	South 1	West Bathroom		105 CMR 451.123*	Maintenance: Wall water damaged above showers
5.	South 1	West Bathroom		105 CMR 451.123*	Maintenance: Door frame rusted at entrance to showers
6.	South 1	West Bathroom		105 CMR 451.123*	Maintenance: Walls dirty, possible mold/mildew outside showers
7.	South 1	East Bathroom		105 CMR 451.123*	Maintenance: Mold observed on ceiling outside showers
8.	South 1	East Bathroom		105 CMR 451.123*	Maintenance: Ceiling paint damaged near showers
9.	South 1	East Bathroom		105 CMR 451.123*	Plumbing: Plumbing not maintained in good repair, shower # 2 out-of-order
10.	South 1	East Bathroom		105 CMR 451.130*	Maintenance: Wall vent dusty
11.	South 2	Dorm Hallway	Utility Closet	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing at slop sink
12.	South 2	Dorm Hallway	East Bathroom	105 CMR 451.123*	Maintenance: Caulking dirty, possible mold/mildew in shower # 5
13.	South 2	Dorm Hallway	East Bathroom	105 CMR 451.123*	Maintenance: Wall paint damaged outside showers

14. South 2	Dorm Hallway	West Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # 1
15. South 2	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Wall vent paint damaged outside showers
16. South 2	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Door rusted at entrance to shower area
17. South 2	Dorm Hallway	West Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 2
18. South 2	Dorm Hallway	West Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control missing at handwash sink # 1 and 6

Deficiencies under the Recommended Standards (.300 series)

4 new deficiencies and 19 repeat deficiencies (indicated by an *) were found during the inspection:

1. South 1	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room # 103 and 107
2. South 1	Dorm Hallway	Dorms	105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light out in dorm room # 104
3. South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in dorm room # 113
4. South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall water damaged in dorm room # 113
5. South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm room # 102, 104, and 108
6. South 1	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Door hardware damaged in dorm room # 109
7. South 1	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out in dorm room # 106
8. South 1	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out in dorm room # 102
9. South 2	Common Area	Back Rooms	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in left side back room
10. South 2	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged in dorm room # 201
11. South 2	Dorm Hallway	Dorms	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged in dorm room # 201 and 207
12. South 2	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out in dorm room # 202, 204, 209, and 212
13. South 2	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room # 211 and 213

14. South 2	Dorm Hallway	Dorms	105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room # 203
15. South 2	Dorm Hallway	Utility Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged

Modular Units – North

Deficiencies under the Required Standards (.100 and .200 series)

10 new deficiencies and 10 repeat deficiencies (indicated by an *) were found during the inspection:

1. North 1	Common Area	Day Room	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, water fountain damaged
2. North 1	Dorm Hallway	Utility Closet	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing at slop sink
3. North 1	Dorm Hallway	Utility Closet	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink leaking
4. North 1	Dorm Hallway	East Bathroom	105 CMR 451.123*	Maintenance: Floor surface left unfinished next to showers
5. North 1	Dorm Hallway	East Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # 5
6. North 1	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Ceiling dirty, possible mold/mildew outside showers
7. North 1	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Ceiling paint damaged outside showers
8. North 1	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Door frame rotted
9. North 1	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Wall water damaged above toilets
10. North 1	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Wall paint damaged outside showers
11. North 1	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Caulking moldy outside showers
12. North 2	Staff Area	Staff Break Room	105 CMR 451.200	Food Storage, Preparation and Service: Food storage/preparation/service not in compliance with 105 CMR 590.000, single-use plastic utensils left uncovered and open to contamination
13. North 2	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control missing at handwash sink #1
14. North 2	Dorm Hallway	East Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 1 leaking
15. North 2	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Door frame rusted
16. North 2	Dorm Hallway	West Bathroom	105 CMR 451.123*	Maintenance: Wall paint damaged outside showers

17.North 2	Dorm Hallway	West Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot control missing at handwash sink # 6
18.North 2	Dorm Hallway	West Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, sink basin loose at handwash sink # 5
19.North 2	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Wall damaged near urinals
20.North 2	Dorm Hallway	West Bathroom	105 CMR 451.123	Maintenance: Curtain missing at shower # 2

Deficiencies under the Recommended Standards (.300 series)

12 new deficiencies and 15 repeat deficiencies (indicated by an *) were found during the inspection:

1.	North 1	Common Area	Old Laundry Area	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
2.	North 1	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Lights not functioning properly, light out in dorm room # 150, 153, 156, 159, and 160
3.	North 1	Dorm Hallway	Dorms	105 CMR 451.344	Illumination in Habitable Areas: Lights not functioning properly, light out in dorm room # 158 and 161
4.	North 1	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Wall damaged in dorm room # 157
5.	North 1	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room # 152
6.	North 1	Dorm Hallway	Utility Closet	105 CMR 451.353	Interior Maintenance: Ceiling damaged
7.	North 1	Dorm Hallway	Utility Closet	105 CMR 451.353	Interior Maintenance: Mold on ceiling
8.	North 1	Dorm Hallway	Utility Closet	105 CMR 451.353	Interior Maintenance: Mold on walls
9.	North 2	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall water damaged in dorm room # 254
10.	North 2	Dorm Hallway	Dorms	105 CMR 451.353*	Interior Maintenance: Wall damaged in dorm room # 261
11.	North 2	Dorm Hallway	Dorms	105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out in dorm room # 253, 254, 260, 262
12.	North 2	Dorm Hallway	Dorms	105 CMR 451.444*	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room # 252 and 258
13.	North 2	Dorm Hallway	Dorms	105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light out in dorm room # 251, 255, 257
14.	North 2	Dorm Hallway	Dorms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room # 260

15. North 2	Dorm Hallway	Utility Closet	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
16. North 2	Dorm Hallway	Utility Closet	105 CMR 451.353	Interior Maintenance: Standing water in mop bucket

Vehicle Trap / Rear Tower

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1. Bathroom	105 CMR 451.123	Maintenance: Wall paint damaged
-------------	-----------------	---------------------------------

Community Transition House

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. 1st Floor	Front Porch	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
2. Basement		105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged

SECTION 2: Areas Found to be in Compliance

EHRS inspected 166 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 9 areas of the facility because they were either in use, locked, or under construction.

1. Control Area	Control Room # A2-41	Unable to Inspect – Locked
2. A2 Unit	2 nd Floor Showers	Unable to Inspect Shower # AM-35 – In Use
3. A2 Unit	1 st Floor Showers	Unable to Inspect Shower # AG-35 – In Use
4. Booking Corridor	Mechanical Room	Unable to Inspect – Locked
5. Medical Closet # B1-13		Unable to Inspect – Locked
6. B2 Unit	2 nd Floor Showers	Unable to Inspect Shower # BM-36 – In Use
7. C Units		Unable to Inspect – Under Construction
8. Learning Center	Closet # B2-21	Unable to Inspect – Locked
9. Institutional Training Area		Unable to Inspect – Locked

SECTION 4: Plan of Correction

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 464 at the time of inspection.
2. At the time of inspection, the temperature of the food in the serving area of the kitchen was found to be out of compliance during food service. All food that was recorded at temperatures less than 135°F was reheated to the correct temperature and staff were informed to make sure that all food is at or above the correct temperature before serving.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" 105 CMR 451.000 is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- 105 CMR 205.000: Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- 105 CMR 480.000: Minimum requirements for the Management of Medical or Biological Waste
- 105 CMR 500.000: Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Patrick Wallace
Environmental Health Inspector, EHRS, BCEH



The Commonwealth of Massachusetts
Executive Office of Public Safety & Security
Department of Correction
Massachusetts Treatment Center
30 Administration Road
Bridgewater, MA 02324
Tel: (508) 279-8100
www.mass.gov/doc



MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

TERRENCE M. REIDY
Secretary

SHAWN P. JENKINS
Commissioner

February 26, 2024


Patrick Wallace, Environmental Health Inspector, CSP, BEH
Bureau of Environmental Health
Community Sanitation Program
5 Randolph Street
Canton, MA 01583

Dear Inspector Wallace:

I am in receipt of the bi-annual Department of Public Health Inspection sent February 14, 2025, which was conducted on November 25, and 26, 2024, in accordance with Chapter 11, Section 5 and 20 of the Massachusetts General Laws; Department of Public Health Regulation 105 CMR 451: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

I have enclosed for your review Massachusetts Treatment Center's plan of corrective action report. Many of the discrepancies noted have been corrected. Dates of completion have been provided for the discrepancies in need of resolution. Should you have any questions or require any additional information, please do not hesitate to contact my office.

Sincerely,



Jeffrey Gonsalves
Superintendent

cc: Jeffrey Fisher, Assistant Deputy Commissioner, Health Services Division
Sally Desrosiers, Deputy Superintendent of Operations
Lynn Lizotte, Deputy Superintendent of Reentry
Nathan Frazier, Director of Facility Maintenance
John Aponte, Fire Safety/EHSO Officer

INSTITUTION NAME: Massachusetts Treatment Center
30 Administration Road
Bridgewater, MA 02324

SUPERINTENDENT: Jeffrey Gonsalves, Superintendent

ENVIRONMENTAL HEALTH OFFICER: John Aponte, Correction Officer

INSPECTION DATE: November 25 and 26, 2024

INSPECTOR: Patrick Wallace, Environmental Health Inspector, CSP, BEH

FRONT LOBBY

Male Bathroom

105 CMR 451.123	Maintenance: Trash barrel rotted	Responsible Staff: Maintenance Corrective Action: Replace barrel Completion Date: 3/04/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at left side handwash sink	Responsible Staff: Maintenance Corrective Action: Repair faucet Completion Date: 3/14/25

Waiting Area

105 CMR 451.350*	Structural Maintenance: Ceiling water damage	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 3/15/25
105 CMR 451.350*	Structural Maintenance: Front entrance not rodent and weathertight	Responsible Staff: Maintenance Corrective Action: Install weather stripping Completion Date: 4/25/25

Administration Area

Main Area

105 CMR 451.353*	Interior Maintenance: Ceiling tiles missing	Responsible Staff: Maintenance Corrective Action: Replace ceiling tiles. Completion Date: 4/15/25
------------------	---	---

CONTROL AREA

Central Tower

105 CMR 451.353*	Interior Maintenance: Floor surface damaged	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 8/20/25
105 CMR 451.350	Structural Maintenance: Ceiling leaking	Responsible Staff: Maintenance Corrective Action: Repair leak Completion Date: 8/20/25

FIRE SAFETY ROOM

Central Laundry

105 CMR 451.353	Interior Maintenance: Floor paint damaged	Responsible Staff: Maintenance Corrective Action: Repaint floor Completion Date: 5/9/25
-----------------	---	---

A UNITS

A1 Unit 1st Floor Showers

105 CMR 451.123	Maintenance: Door frame rotted in shower # AG-12	Responsible Staff: Maintenance Corrective Action: Repair door frame Completion Date: 7/2/25
105 CMR 451.123	Maintenance: Wall epoxy damaged in shower # AG-12	Responsible Staff: Maintenance Corrective Action: Scrape and repaint walls Completion Date: 7/10/25
105 CMR 451.123*	Maintenance: Door frame rotted in shower # AG-13	Responsible Staff: Maintenance Corrective Action: Repair door frame Completion Date: 7/2/25
105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AG-13	Responsible Staff: Maintenance Corrective Action: Scrape and repaint walls Completion Date: 7/10/25
105 CMR 451.123*	Maintenance: Soap scum on the floor in shower # AG-13	Responsible Staff: EHSO / Unit Team Corrective Action: Cleaned Completion Date: 11/27/24

105 CMR 451.123*	Maintenance: Wall tile grout dirty in shower # AG -13	Responsible Staff: EHSO / Unit Team Corrective Action: Grout cleaned Completion Date: 11/27/24
------------------	---	--

A1 Unit 2nd Floor Showers

105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AM-12 and AM-13	Responsible Staff: Maintenance Corrective Action: Scrape and resurface. Completion Date: 7/11/25
105 CMR 451.123*	Maintenance: Door frame rusted in shower #AM-12 and AM-13	Responsible Staff: Maintenance Corrective Action: Repair door frames Completion Date: 7/9/25
105 CMR 451.123*	Maintenance: Ceiling damaged in shower # AM-12	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 7/14/25
105 CMR 451.123*	Maintenance: Floor surface damaged in shower # AM-12 and AM-13	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 7/15/25

A1 Unit Cells

105 CMR 451.353*	Interior Maintenance: Wall paint damage in cell #1	Responsible Staff: Maintenance Corrective Action: Scrape and repaint. Completion Date: 7/9/25
------------------	--	---

A1 Unit Common Area

105 CMR 451.350*	Structural Maintenance: Window cracked near stairs	Responsible Staff: Maintenance Corrective Action: Replace window. Completion Date: 4/4/25
------------------	--	---

Slop Sink #A1-1

105 CMR 451.353*	Interior Maintenance: Floor paint damaged	Responsible Staff: Maintenance Corrective Action: Scrape and paint. Completion Date: 3/19/25
------------------	---	--

A2 Unit 1st Floor Showers

105 CMR 451.123*	Maintenance: Floor paint damaged in shower # AG-36.	Responsible Staff: Maintenance Corrective Action: Scrape and paint Completion Date: 7/15/25
------------------	---	---

105 CMR 451.123*	Maintenance: Wall epoxy damage in shower # AG-36	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date: 7/17/25
105 CMR 451.123*	Maintenance: Mold observed on ceiling dirty in shower # AG-36	Responsible Staff: EHSO/Housing Division Corrective Action: Ceiling cleaned. Completion Date: 12/2/24
105 CMR 451.123*	Maintenance: Walls dirty in shower #AG-36	Responsible Staff: EHSO/Housing Division Corrective Action: Walls cleaned. Completion Date: 12/2/24
105 CMR 451.123*	Maintenance: Soap scum on floor in shower #AG-36.	Responsible Staff: EHSO/Housing Division Corrective Action: Floor cleaned Completion Date: 12/2/24
105 CMR 451.123*	Maintenance: Door frame rusted in shower # AG-36	Responsible Staff: Maintenance Corrective Action: Repair door frame Completion Date: 7/3/25

A2 Unit 2nd Floor Showers

105 CMR 451.123*	Maintenance: Door frame rotted in shower # AM 36	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 7/3/25
105 CMR 451.123*	Maintenance: Floor paint damaged in shower # AM-36.	Responsible Staff: Maintenance Corrective Action: Scrape and re-paint Completion Date: 7/15/25
105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # AM-36	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date: 7/18/25
105 CMR 451.123*	Maintenance: Mold observed on ceiling in shower # AM-36	Responsible Staff: EHSO / Housing Division Corrective Action: Cleaned ceiling Completion Date: 12/2/24
105 CMR 451.123*	Maintenance: Door frame rusted in shower # AM-36	Responsible Staff: Maintenance Corrective Action: Repair door frame Completion Date: 7/18/25

A2 Unit Cells

105 CMR 451.353	Interior Maintenance: Floor surface damaged in cell #6	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 12/9/24
-----------------	--	---

All Cells

105 CMR 451.320*	Cell Size: Inadequate floor space in some cells; some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
------------------	---	---

A2 Common Area

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink running continuously at kitchenette	Responsible Staff: Maintenance Corrective Action: Repaired sink Completion Date: 12/11/24
105 CMR 451.353	Maintenance: Floor epoxy damaged on second level	Responsible Staff: Maintenance Corrective Action: Repair floor epoxy Completion Date: 7/14/25
105 CMR 451.353*	Interior Maintenance: Floor paint damage on handicapped ramp	Responsible Staff: Maintenance Corrective Action: Scrape and repaint ramp Completion Date: 7/14/25

Utility Closet

105 CMR 451.353*	Interior Maintenance: Floor paint damaged.	Responsible Staff: Maintenance Corrective Action: Scrape and re-paint Completion Date: 7/15/25
------------------	--	--

HEALTH SERVICES UNIT*Room #A1-69*

105 CMR 451.353	Maintenance: Floor surface damaged at entrance	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 3/5/25
-----------------	--	--

Medical Records Room

105 CMR 451.402 (B)	Procedures; Records; Record-Keeping Log: Generator did not maintain a record-keeping log for waste sent off site for treatment, record keeping log missing entries for multiple recent pickups. Standard found in 105 CMR 480.500(B)	Responsible Staff: Medical Corrective Action: Corrected missing entries Completion Date: 11/26/24
105 CMR 451.402(B)	Tracking Medical or Biological Waste for Treatment Generator did not confirm the shipment was received by the treatment facility within 30 days on an approved tracking form, binder missing tracking form for multiple recent pickups. Standard found in 105 CMR 480.425(A)	Responsible Staff: Medical Corrective Action: Obtained missing shipment receiving slips/updated tracking form Completion Date: 11/26/24

Female Bathroom #A1-48

105 CMR 451.123	Maintenance: Floor surface damaged at entrance	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 3/5/25
-----------------	--	--

B UNITS**B Control**

105 CMR 451.353	Interior Maintenance: Ceiling tiles water stained	Responsible Staff: Maintenance Corrective Action: Replace ceiling tiles. Completion Date: 3/31/25
-----------------	---	---

B1 Unit*All Cells*

105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
------------------	--	---

Common area

105 CMR 451.141	Screens: Screen damaged near stairs	Responsible Staff: Maintenance Corrective Action: Repair screen Completion Date: 3/9/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water not working at kitchenette handwash sink	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 1/17/25

B1 Unit 1st Floor Showers

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head missing in shower # BG-13	Responsible Staff: Maintenance Corrective Action: Shower head replaced Completion Date: 12/17/24
-----------------	---	--

B1 Unit 2nd Floor Showers

105 CMR 451.123*	Maintenance: Door frame rusted in shower # BM-12 & BM-13	Responsible Staff: Maintenance Corrective Action: Repair door frames Completion Date: 5/13/25
105 CMR 451.123*	Maintenance: Door rusted in shower #BM-12	Responsible Staff: Maintenance

		Corrective Action: Repair door. Completion Date 5/13/25
--	--	--

B2 Unit

Common Area

105 CMR 451.353	Interior Maintenance: Wall paint damaged outside shower # BG-35	Responsible Staff: Maintenance Corrective Action: Repainted Completion Date: 5/2/25 *Deficiency Duplicated on Original Report*
-----------------	---	--

B2 Unit 1st Floor Showers

105 CMR 451.123	Maintenance: Ceiling rusted in shower # BG-35 and BG-36	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 5/16/25
-----------------	---	---

B2 Unit 2nd Floor Showers

105 CMR 451.123*	Maintenance: Door frame rusted in shower # BM-35	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 5/19/25
------------------	--	---

FOOD SERVICE

*The following food code violations listed in **BOLD** were observed to be corrected on-site.*

Kitchen

105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures-Methods: Facility not cleaned as often as necessary; floor grout dirty throughout: Standard found in 105 CMR 590; FC 6-501.12(A)	Responsible Staff: Maintenance Corrective Action: Re-grout floor Completion Date: 3/18/25
------------------	--	---

Serving Area

105 CMR 451.200	Limitation of Growth of Operations of Public Health Concern, Temperature and Time Control: Time/temperature control for safety food not held at 135° F or above (PF), tomato sauce recorded at 75 F. Standard found in 105 CMR 590; FC 3-501.16 (A)(1).	Responsible Staff: Maintenance Corrective Action: Corrected On-Site Completion Date: 11/26/24
------------------------	--	--

105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concerns, Temperature and Time Control: time/temperature control for safety food not held at 135 F or above (PF) meatballs recorded at 129 F. Standard found in 105 CMR 590; FC 3-501.16(A)(1)	Responsible Staff: Maintenance Corrective Action: Corrected On-Site Completion Date: 11/26/24
------------------------	--	--

Utility/Toxic Closet

105 CMR 451.200	Maintenance and Operations: Premises, Structure, Attachments, and Fixtures-Methods: Wet mop stored in bucket. Standard found in 105 CMR 590; FC 6-501.16.	Responsible Staff: Maintenance Corrective Action: Corrected On-Site Completion Date:
105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures-Methods: Facility not in good repair, mop handle damage. Standard found in 105 CMR 590; FC 6-501.11.	Responsible Staff: Maintenance Corrective Action: Corrected On-Site Completion Date: 11/26/24

Warmer Units

105 CMR 451.200	Maintenance and Operations, Equipment: Equipment components not maintained in a state of good repair, external thermometer not functioning properly on warmer #3. Standard found in 105 CMR590; FC 4-501.11(B)	Responsible Staff: Maintenance Corrective Action: Replace thermometer Completion Date: 3/25/2025
105 CMR 451.200	Maintenance and Operations, Equipment: Equipment components not maintained in a state of good repair, warmer #3 not functioning properly. Standard found in 105 CMR590; FC 4-501.11(A)	Responsible Staff: Maintenance Corrective Action: Repair warmer Completion Date: 3/25/2025

Dry Storage

105 CMR451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures-Methods; Facility not in good repair, floor surface damaged. Standard found in 105 CMR 590; FC 6-501.11.	Responsible Staff: Maintenance Corrective Action: Repair and re-paint Completion Date: 6/24/25
105 CMR 451.200	Maintenance and Operations; Premises, Structure, Attachments, and Fixtures- Methods: Facility not cleaned as often as necessary; floor dirty behind shelving. Standard found in 105 CMR 590; FC 6-501.12(A)	Responsible Staff: Maintenance Corrective Action: Corrected On-Site Completion Date: 11/26/24
105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures-Methods: Facility not in good repair, ceiling damaged. Standard found in 105 CMR 590; FC 6-501.11	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 3/24/25

Recycling Area

105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures-Methods: Facility not in good repair, recycling carts damaged. Standard found in 105 CMR 590; FC 6-501.11	Responsible Staff: Maintenance Corrective Action: Repair carts Completion Date: 6/24/25
-----------------	---	---

Staff Food Service*Warewash Machine*

FC 4-501.114(A)*	Maintenance and Operation; Equipment: Chlorine Sanitizer solution tested lower than recommended concentration. Standard found in 105 CMR 590; FC 4-501.114(A)	Responsible Staff: Maintenance Corrective Action: Adjusted Chemical Feed Completion Date: 12/2/24
------------------	---	---

3 Compartment sink

105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, faucet leaking. Standard found in 105 CMR 590; FC S-205.15(B)	Responsible Staff: Maintenance Corrective Action: Repaired faucet Completion Date: 12/9/24
105 CMR 451.200	Maintenance and Operation; Equipment: Chlorine Sanitizer solution tested lower than recommended concentration. Standard found in 105 CMR 590; FC 4-501.114(A)	Responsible Staff: Maintenance Corrective Action: Corrected On-Site Completion Date: 11/26/24

GYM*Recreation Officer's Office*

105 CMR 451.350*	Structural Maintenance: Ceiling water damaged	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 4/9/25
------------------	---	--

Male Staff Bathroom

105 CMR 451.123	Maintenance: Partition rusted	Responsible Staff: Maintenance Corrective Action: Replace partition Completion Date: 3/14/25
-----------------	-------------------------------	--

D UNITS

D1 Unit

All Cells

105 CMR 451.320*	Cell Size: Inadequate floor space in cells, some cells double bunked	Corrective Action: The facility falls under the previous building Standards/Regulations and is fully compliant.
------------------	--	---

D1 Unit 1st Floor Showers

105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # DG-12 and DG-13	Responsible Staff: Housing Division Corrective Action: Cleaned Completion Date: 12/4/24
105 CMR 451.123*	Maintenance: Door frame rusted in shower # DG-12 and DG-13	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 4/10/25
105 CMR 451.123*	Maintenance: Wall caulking dirty in shower # DG-13	Responsible Staff: Maintenance Corrective Action: Scrape caulking/replace. Completion Date: 4/11/25
105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # DG-12	Responsible Staff: Maintenance Corrective Action: Scrape and resurface. Completion Date: 4/14/25
105 CMR 451.123*	Maintenance: Ceiling dirty in shower # DG-13	Responsible Staff: EHSO/Housing Division Corrective Action: Area cleaned. Completion Date: 12/4/24
105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower #DG-12 and DG-13	Responsible Staff: Maintenance Corrective Action: Scrape and resurface. Completion Date: 4/16/25
105 CMR 451.123*	Maintenance: Floor dirty in shower #DG-12 & DG-13	Responsible Staff: EHSO/Housing Division Corrective Action: Shower cleaned. Completion Date: 12/4/24
105 CMR 451.123*	Maintenance: Soap scum on floor in shower #DG-12 and DG-13	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/4/24
105 CMR 451.123*	Maintenance: Ceiling epoxy damaged in shower #DG-12	Responsible Staff: Maintenance Corrective Action: Scrape and resurface. Completion Date: 4/21/25

D1 Unit 2nd Floor Showers

105 CMR 451.123	Maintenance: Ceiling dirty in shower # DM-12	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/5/24
105 CMR 451.130	Hot Water: Shower water temperature 89 F in Shower # DM-13	Responsible Staff: Maintenance Corrective Action: Temperature adjusted Completion Date: 11/27/24
105 CMR 451.123*	Maintenance: Door frame rusted in shower # DM-12 and DM-13	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 4/22/25
105 CMR 451.123*	Maintenance: Door rusted in shower # DM-12 & DM-13	Responsible Staff: Maintenance Corrective Action: Repair door Completion Date: 4/22/25
105 CMR 451.123*	Maintenance: Walls dirty in shower #DM-13	Responsible Staff: Housing Division Corrective Action: Cleaned. Completion Date: 12/5/24
105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # DM-12	Responsible Staff: Maintenance Corrective Action: Scrape and resurface. Completion Date: 4/25/25
105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower #DM-12 & DM-13.	Responsible Staff: Maintenance Corrective Action: Scrape and resurface. Completion Date: 4/24/25
105 CMR 451.123*	Maintenance: Ceiling epoxy damaged in shower #DM-12	Responsible Staff: Maintenance Corrective Action: Scrape and resurface Completion Date: 4/25/25
105 CMR 451.123*	Maintenance: Soap scum on walls in shower #DM-12	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/5/24
105 CMR 451.123*	Maintenance: Soap scum on floor in shower #DM-12 and DM-13	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/5/24

D1 Unit Cells

105 CMR 451.353*	Interior Maintenance: Floor surface damaged in cell #8	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 4/7/25
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell #8	Responsible Staff: Maintenance Corrective Action: Paint walls Completion Date: 4/2/25

D2 Unit

D2 Unit Cells

105 CMR 451.353	Interior Maintenance: Wall damaged in cell#6	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 4/7/25
105 CMR 451.353	Interior Maintenance: Ceiling damaged in cell #21	Responsible Staff: Maintenance Corrective Action: Repair and repaint ceiling Completion Date: 4/7/25

Common Area

105 CMR 451.350*	Structural Maintenance: Ceiling water damaged	Responsible Staff: Maintenance Corrective Action: Scrape/Paint Completion Date: 4/7/25
105 CMR 451.353	Interior Maintenance: Floor epoxy damaged	Responsible Staff: Maintenance Corrective Action: Scrape/Paint Completion Date: 4/8/25

D2 Unit Room D1-9

105 CMR 451.353*	Interior Maintenance: Ceiling water stained	Responsible Staff: Maintenance Corrective Action: Clean and paint. Completion Date: 4/18/25
------------------	---	---

Utility Closet #D1-10

105 CMR 451.353*	Interior Maintenance: Floor paint damaged	Responsible Staff: Maintenance Corrective Action: Scrape and paint. Completion Date: 4/21/25
105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged	Responsible Staff: Maintenance Corrective Action: Scrape and clean. Completion Date: 4/18/25

D2 Unit 1st Floor Showers

105 CMR 451.123	Maintenance: Soap scum on walls in shower # DG-35 and DG-36	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/6/24
105 CMR 451.123	Maintenance: Soap scum on floor in shower # DG-35 and DG-36	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/6/24

105 CMR 451.123*	Maintenance: Floor paint damaged in shower # DG-35 & DG-36	Responsible Staff: Maintenance Corrective Action: Scrape and re-paint Completion Date: 4/25/25 * Deficiency Duplicated on Original Report*
105 CMR 451.123*	Maintenance: Door frame rusted in shower # DG-35 and DG-36	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 4/22/25 *Deficiency Duplicated on Original Report*
105 CMR 451.123*	Maintenance: Door rusted in shower # DG-35 and DG-36	Responsible Staff: Maintenance Corrective Action: Repair door. Completion Date: 4/25/25 *Deficiency Duplicated on Original Report*
105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # DG-35 and DG-36	Responsible Staff: Maintenance Corrective Action: Scrape and resurface. Completion Date: 4/24/25 *Deficiency Duplicated on Original Report*
105 CMR 451.123*	Maintenance: Floor dirty in shower #DG-35 and DG-36	Responsible Staff: Housing Division Corrective Action: Shower cleaned. Completion Date: 12/6/24 *Deficiency Duplicated on Original Report*
105 CMR 451.123*	Maintenance: Ceiling epoxy damaged in shower # DG-35 and DG-36	Responsible Staff: Maintenance Corrective Action: Scraped and resurface. Completion Date: 4/29/25 *Deficiency Duplicated on Original Report*

D2 Unit 2nd Floor Showers

105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # DM-35 and DM-36	Responsible Staff: EHSO/Housing Division Corrective Action: Vent Cleaned Completion Date: 12/9/24
105 CMR 451.123	Maintenance: Soap scum on walls in shower # DM-35 and DM-36	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/9/24
105 CMR 451.123	Maintenance: Mold on walls in shower # DM-35	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/9/24
105 CMR 451.123*	Maintenance: Door frame rusted in shower #DM-35 & DM-36	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 4/22/25

105 CMR 451.123*	Maintenance: Soap scum on floors in shower DM-35 & DM-36	Responsible Staff: EHSO/Housing Division Corrective Action: Shower cleaned. Completion Date: 12/9/24
105 CMR 451.123*	Maintenance: Floor surface damaged in shower # DM-35 and DM-36	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 4/11/25
105 CMR 451.123*	Maintenance: Wall epoxy damaged in shower # DM-35 and DM-36	Responsible Staff: Maintenance Corrective Action: Scrape and resurface. Completion Date: 4/16/25
105 CMR 451.123*	Maintenance: Ceiling epoxy damaged in shower #DM-35 DM-36	Responsible Staff: Maintenance Corrective Action: Scrape and resurface. Completion Date: 4/16/25
105 CMR 451.123	Maintenance: Ceiling vent paint damaged in shower #DM-35 and DM-36	Responsible Staff: Maintenance Corrective Action: Scrape and paint. Completion Date: 4/15/25

BEHAVIORAL ASSESSMENT UNIT

Main Area

Showers

105 CMR 451.123	Maintenance: Floor paint damaged in shower # 1 and 2	Responsible Staff: Maintenance Corrective Action: Re-paint floors Completion Date: 3/12/25
-----------------	--	--

Cells

105 CMR 451.353*	Interior Maintenance: Light shield damaged in cell #7	Responsible Staff: Maintenance Corrective Action: Repair light shield Completion Date: 3/11/25
105 CMR 451.350*	Structural Maintenance: Window cracked in cell #3 and 4	Responsible Staff: Maintenance Corrective Action: Replace windows. Completion Date: 7/31/25

MODULAR UNITS

South 1

Staff Area

Staff Bathroom

105 CMR 451.123	Maintenance: Hole in ceiling	Responsible Staff: Maintenance Corrective Action: Repair ceiling. Completion Date: 6/4/25
-----------------	------------------------------	---

Common Area

S1 Unit Day Room

105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair; water fountain damaged	Responsible Staff: Maintenance Corrective Action: Remove water fountain Completion Date: 6/27/25
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, water fountain out of order	Responsible Staff: Maintenance Corrective Action: Remove water fountain Completion Date: 6/27/25

Dorm Hallway

S1 Dorms

105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room # 103 and 107	Responsible Staff: Maintenance Corrective Action: Scrape/paint Completion Date: 6/3/25
105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light out in dorm room # 104	Responsible Staff: Maintenance Corrective Action: Replaced light Completion Date: 11/29/24
105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in dorm room # 113	Responsible Staff: Maintenance Corrective Action: Scrape/paint Completion Date: 6/4/25
105 CMR 451.353*	Interior Maintenance: Wall water damage in dorm room #113.	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/4/25
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm room # 102, 104 and 108	Responsible Staff: Maintenance Corrective Action: Scrape/paint Completion Date: 6/5/25

105 CMR 451.353*	Interior Maintenance: Door hardware damaged in dorm room # 109	Responsible Staff: Locksmith Corrective Action: Replaced door hardware. Completion Date: 12/4/24
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out in dorm room # 106	Responsible Staff: Maintenance Corrective Action: Replaced light. Completion Date: 11/29/24
105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm #102	Responsible Staff: Maintenance Corrective Action: Replaced light. Completion Date: 11/29/24

West Bathroom

105 CMR 451.123*	Maintenance: Wall water damaged.	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/10/25
105 CMR 451.123*	Maintenance: Door frame rusted at entrance to showers	Responsible Staff: Maintenance Corrective Action: Scrape and repair. Completion Date: 6/11/25
105 CMR 451.123*	Maintenance: Walls dirty outside showers, possible mold/mildew	Responsible Staff: EHSO/Housing Division Corrective Action: Walls Cleaned. Completion Date: 12/10/24

East Bathroom

105 CMR 451.123*	Maintenance: Mold observed on ceiling outside showers	Responsible Staff: EHSO/Housing Division Corrective Action: Ceiling cleaned. Completion Date: 12/10/24
105 CMR 451.123*	Maintenance: Ceiling paint damaged near showers	Responsible Staff: Maintenance Corrective Action: Re-paint ceiling Completion Date: 6/3/25
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower #2 out-of-order	Responsible Staff: Maintenance Corrective Action: Repair plumbing Completion Date: 1/2/25
105 CMR 451.123*	Maintenance: Wall vent dusty	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/10/24

South 2

Common Area

Back Rooms

105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in left side back room.	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 6/16/25
------------------	---	---

Dorm Hallway

S2 Dorms

105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged in dorm room # 201	Responsible Staff: Maintenance Corrective Action: Scrape and repair. Completion Date: 6/16/25
105 CMR 451.350*	Structural Maintenance: Ceiling water damaged in dorm room # 201 and 207	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 6/17/25
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room #202, 204, 209, and 212	Responsible Staff: Maintenance Corrective Action: Replaced light bulbs. Completion Date: 11/29/24
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room #211 and 213	Responsible Staff: Maintenance Corrective Action: Replaced light bulbs. Completion Date: 11/29/24
105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room # 203	Responsible Staff: Maintenance Corrective Action: Replaced light bulbs. Completion Date: 11/29/24

Utility Closet

105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing at slop sink	Responsible Staff: Maintenance Corrective Action: Replaced drain cover Completion Date: 2/11/25
105 CMR 451.353*	Interior Maintenance: Floor surface damaged	Responsible Staff: Maintenance Corrective Action: Scrape & Repaint Completion Date: 6/10/25

East Bathroom

105 CMR 451.123*	Maintenance: Caulking dirty in shower # 5, possible mold/mildew	Responsible Staff: EHSO/Housing Division Corrective Action: Area cleaned. Completion Date: 12/11/24
105 CMR 451.123*	Maintenance: Wall paint damaged outside showers.	Responsible Staff: Maintenance Corrective Action: Scrape and paint. Completion Date: 6/5/25

West Bathroom

105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower #1	Responsible Staff: Maintenance Corrective Action: Repaired plumbing Completion Date: 12/11/24
105CMR 451.123	Maintenance: Wall vent paint damaged outside showers	Responsible Staff: Maintenance Corrective Action: Scrape and re-paint Completion Date: 6/5/25
105 CMR 451.123	Maintenance: Door rusted at entrance to shower area	Responsible Staff: Maintenance Corrective Action: Repair door Completion Date: 6/9/25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 2	Responsible Staff: Maintenance Corrective Action: Repaired faucet Completion Date: 12/11/24
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control missing at handwash sink # 1 and 6	Responsible Staff: Maintenance Corrective Action: Repaired hot water Completion Date: 12/11/24

North 1**Common Area***Day Room*

105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair; water fountain damaged	Responsible Staff: Maintenance Corrective Action: Remove water fountain Completion Date: 6/27/25
------------------	--	--

Old Laundry Area

105 CMR 451.353	Interior Maintenance: Wall paint damaged	Responsible Staff: Maintenance Corrective Action: Scrape and paint. Completion Date: 5/16/24
-----------------	--	--

Dorm Hallway

NI Dorms

105 CMR 451.344*	Illumination in Habitable Areas: Lights not functioning properly, light out in dorm room # 150, 153, 156, 159, and 160	Responsible Staff: Maintenance Corrective Action: Replaced lights. Completion Date: 12/3/24
105 CMR 451.344	Illumination in Habitable Areas: Lights not functioning properly, light out in dorm room # 158 and 161	Responsible Staff: Maintenance Corrective Action: Replaced lights. Completion Date: 12/3/24
105 CMR 451.353	Interior Maintenance: Wall damaged in dorm room #157.	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/5/25
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room #152	Responsible Staff: Maintenance Corrective Action: Replace lights. Completion Date: 12/3/24

Utility Closet

105 CMR 451.353	Interior Maintenance: Ceiling damaged	Responsible Staff: Maintenance Corrective Action: Repair ceiling Completion Date: 6/6/25
105 CMR 451.353	Interior Maintenance: Mold on ceiling	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/10/24
105 CMR 451.353	Interior Maintenance: Mold on walls	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/10/24
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing at slop sink	Responsible Staff: Maintenance Corrective Action: Replaced drain cover Completion Date: 12/2/24
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, slop sink leaking	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/2/24

East Bathroom

105 CMR 451.123*	Maintenance: Floor surface left unfinished next to showers	Responsible Staff: Maintenance Corrective Action: Repair floor Completion Date: 6/25/25
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower #5	Responsible Staff: Maintenance Corrective Action: Repaired shower head

		Completion Date: 12/13/24
--	--	---------------------------

West Bathroom

105 CMR 451.123*	Maintenance: Ceiling dirty outside showers, possible mold/mildew	Responsible Staff: EHSO/Housing Division Corrective Action: Ceiling cleaned Completion Date: 12/13/24
105 CMR 451.123*	Maintenance: Ceiling paint damaged outside showers	Responsible Staff: Maintenance Corrective Action: Scrape and Paint. Completion Date: 6/1/25
105 CMR 451.123*	Maintenance: Door frame rotted	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 6/2/25
105 CMR 451.123*	Maintenance: Wall water damaged above toilets	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/12/25
102 CMR 451.123	Maintenance: Wall paint damaged outside showers	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 6/12/25
105 CMR 451.123	Maintenance: Caulking moldy outside showers	Responsible Staff: EHSO/Housing Division Corrective Action: Cleaned Completion Date: 12/10/24

North 2

Staff Area

Staff Break Room

105 CMR 451.200	Food Storage, Preparation and Service: Food storage/preparation/service not in compliance with 105 CMR 590.000, single-use plastic utensils left uncovered and open to contamination	Responsible Staff: Maintenance Corrective Action: Storage made for utensils Completion Date: 12/16/24
-----------------	--	---

Dorm Hallway

Dorms

105 CMR 451.353*	Interior Maintenance: Wall water damaged in dorm room # 254	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/20/25
------------------	---	--

105 CMR 451.353*	Interior Maintenance: Wall damaged in dorm room # 261	Responsible Staff: Maintenance Corrective Action: Repair wall Completion Date: 6/20/25
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out in dorm #253, 254, 260, and 262	Responsible Staff: Maintenance Corrective Action: Replaced lights. Completion Date: 12/3/24
105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room #252 and 258	Responsible Staff: Maintenance Corrective Action: Replaced lights. Completion Date: 12/3/24
105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light flickering in dorm room # 251, 255, 257	Responsible Staff: Maintenance Corrective Action: Replaced lights. Completion Date: 12/3/24
105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm room # 260	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 6/17/25

Utility Closet

105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket	Responsible Staff: Maintenance Corrective Action: Corrected on Site Completion Date: 11/26/24
105 CMR 451.353	Interior Maintenance: Standing Water in mop bucket	Responsible Staff: Maintenance Corrective Action: Corrected on Site Completion Date: 11/26/24

East Bathroom

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control missing at handwash sink # 1	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/17/24
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower #1 leaking	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/17/24

West Bathroom

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot control missing at handwash sink #6	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/5/24
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, sink basin loose at handwash sink # 5	Responsible Staff: Maintenance Corrective Action: Repaired

		Completion Date: 12/5/24
105 CMR 451.123	Maintenance: Wall damaged near urinals	Responsible Staff: Maintenance Corrective Action: Repaired Completion Date: 12/5/24
105 CMR 451.123	Maintenance: Curtain missing at shower #2	Responsible Staff: EHSO/Housing Division Corrective Action: Replaced Completion Date: 12/5/24
105 CMR 451.130*	Maintenance: Door frame rusted	Responsible Staff: Maintenance Corrective Action: Repair door frame. Completion Date: 6/4/25
105 CMR 451.123	Maintenance: Wall paint damaged outside showers	Responsible Staff: Maintenance Corrective Action: Scrape and repaint. Completion Date: 6/9/25

VEHICLE TRAP TOWER

Bathroom

105 CMR 451.123	Maintenance: Wall paint damaged	Responsible Staff: Maintenance Corrective Action: Repaint Completion Date: 3/20/25
-----------------	---------------------------------	--

COMMUNITY TRANSITION HOUSE


1ST Floor

Front Porch

105CMR 451.353	Interior Maintenance: Ceiling water damaged	Responsible Staff: Maintenance Corrective Action: Repair ceiling. Completion Date: 5/23/25
----------------	---	--

Basement

105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged	Responsible Staff: Maintenance Corrective Action: Repair damage/paint Completion Date: 5/21/25
------------------	---	--



MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Community Sanitation Program
5 Randolph Street
Canton, MA 02021
Phone: 617-356-5387

KATHLEEN E. WALSH
Secretary

ROBERT GOLDSTEIN, MD, PhD
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

March 10, 2024

Jeffrey Gonsalves, Superintendent
Massachusetts Treatment Center
30 Administration Road
Bridgewater, MA 02324 (electronic copy)

Re: Plan of Correction – Massachusetts Treatment Center, Bridgewater

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction (POC) in response to my inspection on November 25 and 26, 2024. After review, EHRS finds the plan appropriately addresses all the deficiencies noted with the following exception:

In regards to the issue of overcrowding, EHRS appreciates the limitations of correctional facilities and the need to accommodate the ever-increasing population; however we remain concerned with the overcrowded conditions.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Patrick Wallace
Environmental Health Inspector, EHRS, BCEH

cc: Sally Desrosiers, Deputy Superintendent
John Aponte, EHSO/FSO

(electronic copy)
(electronic copy)