



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards

MAURA T. HEALEY  
Governor

KIMBERLEY DRISCOLL  
Lieutenant Governor

5 Randolph Street  
Canton, MA 02021  
Phone: 617-624-5757

KATHLEEN E. WALSH  
Secretary

ROBERT GOLDSTEIN, MD, PhD  
Commissioner

Tel: 617-624-6000  
[www.mass.gov/dph](http://www.mass.gov/dph)

May 6, 2025

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)  
Kathleen E. Walsh, Secretary, Executive Office of Health and Human Services (electronic copy)  
Clerk, Massachusetts House of Representatives (electronic copy)  
Clerk, Massachusetts Senate (electronic copy)  
Michael Rosano, Environmental Health and Safety Officer (electronic copy)

Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Bridgewater State Hospital, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Patrick Wallace  
Environmental Health Inspector, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)  
Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)  
Eric Badger, Health Agent, Bridgewater Health Department (electronic copy)  
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)  
James Rioux, Deputy Superintendent (electronic copy)



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards  
5 Randolph Street  
Canton, MA 02021  
Phone: 617-624-5757

MAURA T. HEALEY  
Governor

KIMBERLEY DRISCOLL  
Lieutenant Governor

KATHLEEN E. WALSH  
Secretary

ROBERT GOLDSTEIN, MD, PhD  
Commissioner

Tel: 617-624-6000  
[www.mass.gov/dph](http://www.mass.gov/dph)

April 24, 2025

Joy Gallant, Superintendent  
Bridgewater State Hospital  
20 Administration Road  
Bridgewater, MA 02324 (electronic copy)

Re: Facility Inspection – Bridgewater State Hospital

Dear Superintendent Gallant:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Bridgewater State Hospital on April 2, 2025 accompanied by Sergeant Michael Rosano, Environmental Health and Safety Officer and Norberto Melo, Facility Maintenance Manager, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 327 total deficiencies; 20 new deficiencies under the Required Standards (.100 and .200 series), 39 repeat deficiencies under the Required Standards, 35 new deficiencies under the Recommended Standards (.300 series), and 233 repeat deficiencies under the Recommended Standards.

## Overview

**Section 1** provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

**Section 2** provides information on areas that EHRS found to be compliant.

**Section 3** documents the areas that EHRS did not inspect.

**Section 4** provides information on submitting a Plan of Correction for the identified deficiencies.

**Section 5** outlines observations and recommendations related to the inspection.

## **SECTION 1: Health and Safety Deficiencies**

### **Building #2 – Adams**

#### **Deficiencies under the Required Standards (.100 and .200 series)**

2 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door frame rusted
2.	A1 Unit	Main Area	Nurse's Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink
3.	A2 Unit	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Ceiling paint damaged
4.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor surface left unfinished next to sinks
5.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged

#### **Deficiencies Identified under the Recommended Standards (.300 series)**

1 new deficiency and 17 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	A1 Unit	Main Area	Room # A121	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged
2.	A1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged
3.	A1 Unit	Main Area	Transfer Room # A124	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
4.	A1 Unit	Room Corridor	Nurse's Treatment Room # A125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
5.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 101 and 108
6.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 121 and 123
7.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 109
8.	A2 Unit	Dorm Corridor	Dorm # 11	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
9.	A2 Unit	Dorm Corridor	Dorm # 12	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
10.	A2 Unit	Dorm Corridor	Dorm # 9	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
11.	A2 Unit	Main Area	Nurse's Station # A-217	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
12.	A2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 204, 205, and 211
13.	A2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 211
14.	A2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 216

**Building # 3 – Bradford****Deficiencies under the Required Standards (.100 and .200 series)**

3 new deficiencies and 6 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on sink unit
2.	B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on toilet partitions
3.	B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall vent dirty and clogged
4.	B1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on bench
5.	B2 Unit	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Ceiling vent dusty
6.	B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet clogged in stall # 1
7.	B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink basin rusted
8.	B2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Caulking dirty
9.	B2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Walls rusted

**Deficiencies Identified under the Recommended Standards (.300 series)**

3 new deficiencies and 44 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	B1 Unit	Dorm Corridor	Room # B-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
2.	B1 Unit	Dorm Corridor	Room # B-110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
3.	B1 Unit	Dorm Corridor	Room # B-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
4.	B1 Unit	Dorm Corridor	Room # B-112	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
5.	B1 Unit	Dorm Corridor	Room # B-112	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
6.	B1 Unit	Main Area	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
7.	B1 Unit	Main Area	Transfer Room	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
8.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 104, 105, 106, 107, 108, 109, 110, 111, 113, 114, 115, 116, 117, 118, 119, 120, 121, 123, and 125
9.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 108, 109, and 123
10.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 106

11. B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
12. B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
13. B2 Unit	Dorm Corridor	Dorm # 10	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
14. B2 Unit	Dorm Corridor	Dorm # 11	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
15. B2 Unit	Dorm Corridor	Dorm # 12	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
16. B2 Unit	Dorm Corridor	Dorm # 8 (Comfort Room)	105 CMR 451.353	Interior Maintenance: Floor paint damaged
17. B2 Unit	Main Area	Interview Room # B-219	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
18. B2 Unit	Main Area	Mop Closet # B-250	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
19. B2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 204, 206, 209, 210, and 218
20. B2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 225
21. B2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Ceiling damaged in room # 220

#### Building # 4 - Cotter

##### Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 4 repeat deficiencies (indicated by an \*) were found during the inspection:

1. C1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged
2. C1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Ceiling dirty
3. C1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 2
4. C2 Unit	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Ceiling paint damaged
5. C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling dirty
6. C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted
7. C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on light fixture
8. C2 Unit	Main Area	Bathroom # C2-217	105 CMR 451.123	Maintenance: Floor paint damaged

**Deficiencies under the Recommended Standards (.300 series)**

2 new deficiencies and 75 repeat deficiencies (identified by an \*) were found during the inspection:

1.	C1 Unit	Common Room	Room # C-116	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
2.	C1 Unit	Dorm Corridor	Classroom # C-112	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
3.	C1 Unit	Dorm Corridor	Classroom # C-112	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
4.	C1 Unit	Dorm Corridor	Group Room # C-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
5.	C1 Unit	Dorm Corridor	Hygeine, Shaves, & Storage # C-105	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
6.	C1 Unit	Dorm Corridor	Sensory Room # C-110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
7.	C1 Unit	Dorm Corridor	Treatment Team Office # C-107	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8.	C1 Unit	Dorm Corridor	Unit Director's Office # C-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
9.	C1 Unit	Main Area	Storage Room # C-121	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
10.	C1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
11.	C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
12.	C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Door to exterior rotted
13.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 115
14.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 114, 115, 116, 118, 119, and 123
15.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 101, 103, 104, 106, 110, 113, 114, 116, and 119
16.	C1 Unit	Room Corridor	Supply Room # C-125	105 CMR 451.353	Interior Maintenance: Window frame damaged
17.	C1 Unit	Room Corridor		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway

18. C2 Unit	Dorm Corridor	Classroom # C-210	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
19. C2 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C-204	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
20. C2 Unit	Dorm Corridor	Sensory Room # C-208	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
21. C2 Unit	Dorm Corridor	Unit Director's Office # C-205	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
22. C2 Unit	Main Area	Room # C-220	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
23. C2 Unit	Main Area	Staff Break Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
24. C2 Unit	Main Area	Storage Room # C-219	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
25. C2 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
26. C2 Unit	Main Area		105 CMR 451.353*	Interior Maintenance: Wall paint damaged in hallway
27. C2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 206
28. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 203, 204, 205, 206, 207, 208, 211, 212, 213, 214, 215, 216, 218, 219, 220, and 221
29. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 201, 205, 209, 212, 213, 214, 216, 218, and 219

## Building # 5 – Recovery Place

### Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (identified by an \*) were found during the inspection:

1. Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
2. Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Wall paint damaged

## Building # 7 - Commons

### Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 1 repeat deficiency (indicated by an \*) were found during the inspection:

1.	Kitchen	Dining Area	105 CMR 451.200	Design, Construction, and Installation; Functionality: Outer openings not protected against the entry of insects and rodents, gap at bottom of door to exterior. Standard found in 105 CMR 590; FC 6-202.15(A)(3).
2.	Kitchen	Patient Bathroom # CK-21	105 CMR 451.123*	Maintenance: Ceiling damaged

### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 19 repeat deficiencies (identified by an \*) were found during the inspection:

1.	Back Hallway	Recycle Room # CG-11	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
2.	Back Hallway	Recycle Room # CG-11	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
3.	Back Hallway	Storage Room # CG-12	105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight
4.	Back Hallway	Storage Room # CG-12	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
5.	Basement	Maintenance Department Mechanical Room A # CB-10	105 CMR 451.353*	Interior Maintenance: Standing water pooling on floor
6.	Basement	Maintenance Department Tool Crib	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
7.	Basement	Maintenance Department Tool Crib	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
8.	Basement	Maintenance Department Tool Crib	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
9.	Basement		105 CMR 451.353*	Interior Maintenance: Floor paint damaged in hallway
10.	Gym	Storage Room # CG-23	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
11.	Lobby Area	Control	105 CMR 451.353*	Interior Maintenance: Paint damaged on window frames
12.	Lobby Area	Laundry	105 CMR 451.331*	Radiators and Heating Pipes: Pipe insulation damaged
13.	Lobby Area		105 CMR 451.350*	Structural Maintenance: Ceiling water damaged outside closet # SL-01
14.	Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
15.	Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353	Interior Maintenance: Floor dirty
16.	Main Area	Storage Area # CL-11	105 CMR 451.353	Interior Maintenance: Ceiling damaged
17.	Main Area		105 CMR 451.353*	Interior Maintenance: Ceiling damaged



18. Main Area		105 CMR 451.353*	Interior Maintenance: Floor cracked
19. School Corridor	Library # CS-03	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged
20. School Corridor	Life Skills Group Room # CS-10	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged
21. School Corridor	Offices	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged in Office # CS-28

#### Building # 8 – Hadley

##### Deficiencies under the Required Standards (.100 and .200 series)

6 repeat deficiencies (indicated by an \*) were found during the inspection:

1. C-Corridor	Bathroom	105 CMR 451.123*	Maintenance: Countertop dirty
2. C-Corridor	Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance
3. C-Corridor	Bathroom	105 CMR 451.123*	Maintenance: Wall vent dusty
4. C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door rusted
5. C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door frame rusted
6. Control	Control Bathroom	105 CMR 451.123*	Maintenance: Toilet seat not secured to fixture

##### Deficiencies Identified under the Recommended Standards (.300 series)

15 new deficiencies and 19 repeat deficiencies (indicated by an \*) were found during the inspection:

1. A-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, and 115
2. A-Corridor	Transfer Room	105 CMR 451.353*	Interior Maintenance: Floor dirty
3. B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 117, 119, 120, 121, 122, 124, 125, 126, 127, 128, 129, 130, 131, and 132
4. B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117 and 120
5. C-Corridor	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
6. C-Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

#### Building # 9 – Lenox

##### Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 5 repeat deficiencies (indicated by an \*) were found during the inspection:

1. A Corridor	Rooms	105 CMR 451.103	Mattresses: Mattress dirty in room # 103
2. B Corridor	Closet # M-276	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in

			compliance with 105 CMR 590.000, interior of microwave oven dirty
3.	C Corridor	Patient Bathroom	105 CMR 451.123* Maintenance: Floor surface damaged at entrance
4.	C Corridor	Patient Bathroom	105 CMR 451.123* Maintenance: Radiator rusted
5.	C Corridor	Patient Bathroom	105 CMR 451.126 Hot Water for Bathing and Hygiene: Hot water temperature 86°F at handwash sink
6.	C Corridor	Patient Bathroom	105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 2
7.	C Corridor	Shower Room	105 CMR 451.130 Hot Water: Shower water temperature 75°F
8.	C Corridor	Shower Room	105 CMR 451.123* Maintenance: Door frame rusted
9.	C Corridor	Shower Room	105 CMR 451.123* Maintenance: Door frame dirty
10.	C Corridor	Shower Room	105 CMR 451.123* Maintenance: Door rusted
11.	C Corridor	Slop Sink Closet # M-251	105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink

#### **Deficiencies under the Recommended Standards (.300 series)**

8 new deficiencies and 33 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 108, and 116
2.	A Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 106, 109, 110, 111, and 113
3.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 104
4.	A Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 112
5.	A Corridor	Transfer Room # M-228	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
6.	A Corridor	Transfer Room # M-228	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior
7.	A Corridor	Treatment Room # M-227	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8.	B Corridor	Closet # M-276	105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty
9.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 119, 120, 121, 122, 124, 125, 126, 128, 130, 131, and 132
10.	B Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 127 and 129
11.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117, 119, 122, 125, 127, 130, and 132

12. B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Ceiling damaged in room # 124
13. C Corridor	Laundry Room # 1	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
14. C Corridor	Secure Interview Room # M-234	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
15. C Corridor	Secure Interview Room # M-247	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
16. C Corridor	Slop Sink Closet # M-251	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
17. C Corridor	Staff Break Room # M-252	105 CMR 451.353*	Interior Maintenance: Countertop damaged
18. Control		105 CMR 451.353*	Interior Maintenance: Wall paint damaged

### Building # 10 – Berkshire

#### Deficiencies under the Required Standards (.100 and .200 series)

1 repeat deficiency (indicated by an \*) was found during the inspection:

1. Right Side	Female Bathroom	105 CMR 451.123*	Maintenance: Door damaged
---------------	-----------------	------------------	---------------------------

#### Deficiencies under the Recommended Standards (.300 series)

6 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Right Side		105 CMR 451.353*	Interior Maintenance: Baseboard damaged
2. Right Side		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in hallway
3. Right Side	Slop Sink # MM-03	105 CMR 451.353*	Interior Maintenance: Door damaged
4. Right Side	Slop Sink # MM-03	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
5. Left Side		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in hallway
6. Left Side	Training Room	105 CMR 451.353*	Interior Maintenance: Floor surface damaged

### Building # 11 – Lighthouse

#### Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 11 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Booking Corridor	Female Bathroom # H-172	105 CMR 451.123*	Maintenance: Partitions rusted
2. Booking Corridor	Female Bathroom # H-172	105 CMR 451.123*	Maintenance: Hole in ceiling
3. Booking Corridor	Male Bathroom # H-173	105 CMR 451.123*	Maintenance: Floor cracked
4. Booking Corridor	Male Bathroom # H-173	105 CMR 451.123*	Maintenance: Partitions rusted
5. Infirmary	Dorm # 3/ Bathroom	105 CMR 451.123*	Maintenance: Door frame rusted in bathroom

6. Infirmary	Dorm # 3/ Bathroom	105 CMR 451.123	Maintenance: Handwash sink unit rusted
7. Infirmary	Dorm # 4/ Bathroom	105 CMR 451.123*	Maintenance: Door frame to shower room rusted
8. Infirmary	Dorm # 4/ Bathroom	105 CMR 451.123*	Maintenance: Wall tiles damaged in shower
9. Infirmary	Nurse's Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty
10. Medical West Unit	Bathroom # 138 (Storage)	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal running continuously
11. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Wall tile grout dirty
12. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Ceiling vent rusted
13. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Door frame rusted
14. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Bench damaged

#### **Deficiencies under the Recommended Standards (.300 series)**

4 new deficiencies and 21 repeat deficiencies (identified by an \*) were found during the inspection:

1. Booking Corridor	Admissions Office # H-149	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged
2. Booking Corridor	Admissions Office # H-149	105 CMR 451.353*	Interior Maintenance: Desk surface damaged
3. Booking Corridor	Booking Trap # H-212	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior
4. Booking Corridor	Booking Trap # H-212	105 CMR 451.353*	Interior Maintenance: Door frame rotted
5. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.350*	Structural Maintenance: Door not rodent and weathertight, gap at bottom of door to exterior
6. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Medical waste storage chest rusted
7. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Door frame rotted
8. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Door rusted
9. Infirmary	Dorm # 3/ Bathroom	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm
10. Infirmary	Dorm # 3/ Bathroom	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm
11. Infirmary	Dorm # 4/ Bathroom	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in dorm
12. Infirmary	Dorm # 4/ Bathroom	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm
13. Infirmary	Dorm # 5	105 CMR 451.353	Interior Maintenance: Floor paint damaged

14. Infirmary	Nurse's Office # H-145	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
15. Laundry Hallway	Laundry	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
16. Laundry Hallway		105 CMR 451.353*	Interior Maintenance: Door to exterior rusted
17. Medical West Unit	Closet # H-121	105 CMR 451.353*	Interior Maintenance: Wall surface damaged
18. Medical West Unit	Closet # H-121	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged
19. Medical West Unit	Dorm # 7 # H-125	105 CMR 451.353	Interior Maintenance: Floor paint damaged
20. Medical West Unit	Dorm # 8 # H-126	105 CMR 451.353*	Interior Maintenance: Floor surface rusted
21. Medical West Unit	Room # 5 # H-131	105 CMR 451.353	Interior Maintenance: Floor rust stained
22. Medical West Unit	Room # 6 # H-130	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
23. Medical West Unit	RTA's Trap # H-133	105 CMR 451.353*	Interior Maintenance: Ceiling damaged
24. Old Seclusion Area		105 CMR 451.350*	Structural Maintenance: Door not rodent and weathertight, gap at bottom of door to exterior
25. Old Seclusion Area		105 CMR 451.353*	Interior Maintenance: Door to exterior rotted

#### Building # 12 – Vehicle Trap

##### Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1. Bathroom	105 CMR 451.123*	Maintenance: Door damaged
-------------	------------------	---------------------------

#### Staff Gym

##### Deficiencies under the Required Standards (.100 and .200 series)

2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Male Locker Room	105 CMR 451.123*	Interior Maintenance: Ceiling tiles water stained
1. Female Locker Room	105 CMR 451.123*	Maintenance: Light out above showers

##### Repeat Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an \*) were found during the inspection:

2. Common Area	105 CMR 451.353*	Interior Maintenance: Carpet damaged
3. Common Area	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained

## **SECTION 2: Areas Found to be in Compliance**

The EHRS inspected 307 additional areas of the facility which were found to be in compliance.

## **Section 3: Areas EHRS did not inspect**

EHRS did not inspect 2 areas of the facility because they were either in use, locked, or under construction.

1.	Building# 2 - Adams	A2 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
2.	Building # 11 – Lighthouse (Medical)	Booking Corridor	New Admissions Area		Unable to Inspect – Under Construction

## **SECTION 4: Plan of Correction**

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

## **SECTION 5: Observations and Recommendations**

1. The patient population was 240 at the time of inspection.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Correctional Facilities" [105 CMR 451.000](#) is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Patrick Wallace  
Environmental Health Inspector, EHRS, BCEH



MAURA T. HEALEY  
Governor

KIMBERLEY DRISCOLL  
Lieutenant Governor

*The Commonwealth of Massachusetts*  
*Executive Office of Public Safety & Security*  
*Department of Correction*  
*Bridgewater State Hospital*  
*20 Administration Road*  
*Bridgewater, MA. 02324*  
*Tel: (508) 279-4500*  
*[www.mass.gov/doc](http://www.mass.gov/doc)*



TERRENCE M. REIDY  
Secretary

SHAWN P. JENKINS  
Commissioner

May 1, 2025

Mr. Patrick Wallace  
Environmental Health Inspector, CSP, BEH  
Department of Public Health, Bureau of Environmental Health  
Community Sanitation Program  
5 Randolph Street  
Canton, MA 02021

Dear Mr. Wallace:

Enclosed please find your inspection report for Bridgewater State Hospital dated 4/24/25. This report has been updated to include corrective action plans which address all violations. All responses are in bold.

Should you have any questions or require additional information, please don't hesitate to contact my office.

Sincerely,

Joy Gallant  
Superintendent

CC: Shawn P. Jenkins, Commissioner  
Mitzi Peterson, Deputy Commissioner, Clinical Services & Re-entry  
Jeff Fisher, Assistant Deputy Commissioner, Clinical Services  
James Rioux, Deputy Superintendent  
Brianna Arruda, Director, Policy Development and Compliance Unit  
Michael Durocher, Director of Facility Maintenance  
Sergeant Michael Rosano, Environmental Health and Safety Officer

## **SECTION 1: Health and Safety Deficiencies**

### **Building #2 – Adams**

#### **Deficiencies under the Required Standards (.100 and .200 series)**

2 new deficiencies and 3 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	A1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door frame rusted <b>To be repaired by 6/30/25.</b>
2.	A1 Unit	Main Area	Nurse's Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink <b>Repaired after inspection.</b>
3.	A2 Unit	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Ceiling paint damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
4.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor surface left unfinished next to sinks <b>To be painted by 6/30/25.</b>
5.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>

#### **Deficiencies Identified under the Recommended Standards (.300 series)**

1 new deficiency and 17 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	A1 Unit	Main Area	Room # A121	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
2.	A1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
3.	A1 Unit	Main Area	Transfer Room # A124	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
4.	A1 Unit	Room Corridor	Nurse's Treatment Room # A125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
5.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 101 and 108 <b>To be repainted by 7/31/25.</b>
6.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 121 and 123 <b>To be repaired and repainted by 7/31/25.</b>
7.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 109 <b>To be repainted by 7/31/25.</b>



8. A2 Unit	Dorm Corridor	Dorm # 11	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
9. A2 Unit	Dorm Corridor	Dorm # 12	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
10. A2 Unit	Dorm Corridor	Dorm # 9	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 7/31/25.</b>
11. A2 Unit	Main Area	Nurse's Station # A-217	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 7/31/25.</b>
12. A2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 204, 205, and 211 <b>To be repainted by 7/31/25.</b>
13. A2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 211 <b>To be repainted by 7/31/25.</b>
14. A2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 216 <b>To be repainted by 7/31/25.</b>

#### Building # 3 – Bradford

##### Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 6 repeat deficiencies (indicated by an \*) were found during the inspection:

1. B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on sink unit <b>To be repainted by 6/30/25.</b>
2. B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on toilet partitions <b>To be repainted by 6/30/25.</b>
3. B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall vent dirty and clogged <b>Cleaned after inspection.</b>
4. B1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on bench <b>To be removed by 6/30/25.</b>
5. B2 Unit	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Ceiling vent dusty <b>Cleaned after inspection.</b>
6. B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet clogged in stall # 1 <b>Repaired after inspection.</b>
7. B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink basin rusted <b>To be sanded and repainted by 6/30/25.</b>
8. B2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Caulking dirty <b>Cleaned after inspection.</b>
9. B2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Walls rusted <b>To be cleaned by 5/31/25.</b>

**Deficiencies Identified under the Recommended Standards (.300 series)**

3 new deficiencies and 44 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	B1 Unit	Dorm Corridor	Room # B- 106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
2.	B1 Unit	Dorm Corridor	Room # B- 110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
3.	B1 Unit	Dorm Corridor	Room # B- 111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
4.	B1 Unit	Dorm Corridor	Room # B- 112	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
5.	B1 Unit	Dorm Corridor	Room # B- 112	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 7/31/25.</b>
6.	B1 Unit	Main Area	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 7/31/25.</b>
7.	B1 Unit	Main Area	Transfer Room	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged <b>To be repainted by 7/31/25.</b>
8.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 104, 105, 106, 107, 108, 109, 110, 111, 113, 114, 115, 116, 117, 118, 119, 120, 121, 123, and 125 <b>To be repainted by 7/31/25.</b>
9.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 108, 109, and 123 <b>To be repainted by 7/31/25.</b>
10.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 106 <b>To be repainted by 7/31/25.</b>
11.	B1 Unit	Room Corridor	Treatment Room # B- 125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
12.	B1 Unit	Room Corridor	Treatment Room # B- 125	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 7/31/25.</b>
13.	B2 Unit	Dorm Corridor	Dorm # 10	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>

14. B2 Unit	Dorm Corridor	Dorm # 11	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
15. B2 Unit	Dorm Corridor	Dorm # 12	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
16. B2 Unit	Dorm Corridor	Dorm # 8 (Comfort Room)	105 CMR 451.353	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
17. B2 Unit	Main Area	Interview Room # B-219	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged <b>To be sanded and repainted by 7/31/25.</b>
18. B2 Unit	Main Area	Mop Closet # B-250	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 7/31/25.</b>
19. B2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 204, 206, 209, 210, and 218 <b>To be repainted by 7/31/25.</b>
20. B2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 225 <b>To be repainted by 7/31/25.</b>
21. B2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Ceiling damaged in room # 220 <b>To be repaired and repainted by 7/31/25.</b>

#### Building # 4 - Carter

##### Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 4 repeat deficiencies (indicated by an \*) were found during the inspection:

1. C1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
2. C1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Ceiling dirty <b>Cleaned after inspection.</b>
3. C1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 2 <b>Repaired after inspection.</b>
4. C2 Unit	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Ceiling paint damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
5. C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling dirty <b>Cleaned after inspection.</b>
6. C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted <b>To be repaired and repainted by 6/30/25.</b>

7. C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on light fixture <b>To be repainted by 6/30/25.</b>
8. C2 Unit	Main Area	Bathroom # C2-217	105 CMR 451.123	Maintenance: Floor paint damaged <b>To be repainted by 6/30/25.</b>

**Deficiencies under the Recommended Standards (.300 series)**

2 new deficiencies and 75 repeat deficiencies (Identified by an \*) were found during the inspection:

1. C1 Unit	Common Room	Room # C-116	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 7/31/25.</b>
2. C1 Unit	Dorm Corridor	Classroom # C-112	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
3. C1 Unit	Dorm Corridor	Classroom # C-112	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 7/31/25.</b>
4. C1 Unit	Dorm Corridor	Group Room # C-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
5. C1 Unit	Dorm Corridor	Hygeine, Shaves, & Storage # C-105	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
6. C1 Unit	Dorm Corridor	Sensory Room # C-110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
7. C1 Unit	Dorm Corridor	Treatment Team Office # C-107	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
8. C1 Unit	Dorm Corridor	Unit Director's Office # C-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
9. C1 Unit	Main Area	Storage Room # C-121	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
10. C1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 7/31/25.</b>
11. C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged <b>To be sanded and repainted by 7/31/25.</b>
12. C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Door to exterior rotted <b>To be repaired and repainted by 7/31/25.</b>

13. C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 115 <b>To be repaired and repainted by 7/31/25.</b>
14. C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 114, 115, 116, 118, 119, and 123 <b>To be repainted by 7/31/25.</b>
15. C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 101, 103, 104, 106, 110, 113, 114, 116, and 119 <b>To be repainted by 7/31/25.</b>
16. C1 Unit	Room Corridor	Supply Room # C-125	105 CMR 451.353	Interior Maintenance: Window frame damaged <b>To be repaired by 7/31/25.</b>
17. C1 Unit	Room Corridor		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway <b>To be repainted by 7/31/25.</b>
18. C2 Unit	Dorm Corridor	Classroom # C-210	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
19. C2 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C- 204	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
20. C2 Unit	Dorm Corridor	Sensory Room # C- 208	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
21. C2 Unit	Dorm Corridor	Unit Director's Office # C- 205	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
22. C2 Unit	Main Area	Room # C- 220	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
23. C2 Unit	Main Area	Staff Break Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
24. C2 Unit	Main Area	Storage Room # C- 219	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
25. C2 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 7/31/25.</b>
26. C2 Unit	Main Area		105 CMR 451.353*	Interior Maintenance: Wall paint damaged in hallway <b>To be repainted by 7/31/25.</b>
27. C2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 206 <b>To be repainted by 7/31/25.</b>

28. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 203, 204, 205, 206, 207, 208, 211, 212, 213, 214, 215, 216, 218, 219, 220, and 221 <b>To be repainted by 7/31/25.</b>
29. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 201, 205, 209, 212, 213, 214, 216, 218, and 219 <b>To be repainted by 7/31/25.</b>

#### Building # 5 – Recovery Place

##### Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (identified by an \*) were found during the inspection:

1. Toxic/Caustic Closet		105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
2. Toxic/Caustic Closet		105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 7/31/25.</b>

#### Building # 7 – Commons/Attucks

##### Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 1 repeat deficiency (indicated by an \*) were found during the inspection:

1. Kitchen	Dining Area	105 CMR 451.200	Design, Construction, and Installation; Functionality: Outer openings not protected against the entry of insects and rodents, gap at bottom of door to exterior. Standard found in 105 CMR 590; FC 6-202.15(A)(3). <b>To be made rodent/insect tight by 5/15/25.</b>
2. Kitchen	Patient Bathroom # CK-21	105 CMR 451.123*	Maintenance: Ceiling damaged <b>To be repaired by 8/31/25 and upon completion of roof replacement.</b>

##### Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 19 repeat deficiencies (identified by an \*) were found during the inspection:

1. Back Hallway	Recycle Room # CG-11	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 8/31/25 and upon completion of roof repairs.</b>
2. Back Hallway	Recycle Room # CG-11	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>

3. Back Hallway	Storage Room # CG-12		105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight <b>To be made rodent/weathertight by 5/15/25.</b>
4. Back Hallway	Storage Room # CG-12		105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be repaired and repainted by 7/31/25.</b>
5. Basement	Maintenance Department	Mechanical Room A # CB-10	105 CMR 451.353*	Interior Maintenance: Standing water pooling on floor <b>Cleaned up after inspection.</b>
6. Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 8/31/25.</b>
7. Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 8/31/25.</b>
8. Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 8/31/25.</b>
9. Basement			105 CMR 451.353*	Interior Maintenance: Floor paint damaged in hallway <b>To be repainted by 8/31/25.</b>
10. Gym	Storage Room # CG-23		105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 7/31/25.</b>
11. Lobby Area	Control		105 CMR 451.353*	Interior Maintenance: Paint damaged on window frames <b>To be repainted by 7/31/25.</b>
12. Lobby Area	Laundry		105 CMR 451.331*	Radiators and Heating Pipes: Pipe insulation damaged <b>To be replaced by 6/30/25.</b>
13. Lobby Area			105 CMR 451.350*	Structural Maintenance: Ceiling water damaged outside closet # SL-01 <b>To be repaired and repainted by 8/31/25 and upon completion of roof replacement.</b>
14. Main Area	Chair Cot/Stretcher Room # CL-15		105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 8/31/25.</b>
15. Main Area	Chair Cot/Stretcher Room # CL-15		105 CMR 451.353	Interior Maintenance: Floor dirty <b>Cleaned after inspection.</b>
16. Main Area	Storage Area # CL-11		105 CMR 451.353	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 8/31/25 and upon completion of roof replacement.</b>

17. Main Area		105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired and repainted by 8/31/25 and upon completion of roof replacement.</b>
18. Main Area		105 CMR 451.353*	Interior Maintenance: Floor cracked <b>To be stripped, filled, and sealed by 7/31/25.</b>
19. School Corridor	Library # CS-03	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged <b>To be repaired and repainted by 8/31/25 and upon completion of roof replacement.</b>
20. School Corridor	Life Skills Group Room # CS-10	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged <b>To be repaired and repainted by 8/31/25 and upon completion of roof replacement.</b>
21. School Corridor	Offices	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged in Office # CS-28 <b>To be repaired and repainted by 8/31/25 and upon completion of roof replacement.</b>

#### Building # 8 – Hadley

##### Deficiencies under the Required Standards (.100 and .200 series)

6 repeat deficiencies (indicated by an \*) were found during the inspection:

1. C-Corridor	Bathroom	105 CMR 451.123*	Maintenance: Countertop dirty <b>Cleaned after inspection.</b>
2. C-Corridor	Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance <b>To be repaired by 6/30/25.</b>
3. C-Corridor	Bathroom	105 CMR 451.123*	Maintenance: Wall vent dusty <b>Cleaned after inspection.</b>
4. C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door rusted <b>To be repaired and repainted by 6/30/25.</b>
5. C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door frame rusted <b>To be repaired and repainted by 6/30/25.</b>
6. Control	Control Bathroom	105 CMR 451.123*	Maintenance: Toilet seat not secured to fixture <b>To be replaced by 4/30/25.</b>



**Deficiencies Identified under the Recommended Standards (.300 series)**

15 new deficiencies and 19 repeat deficiencies (indicated by an \*) were found during the inspection:

1. A-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, and 115 <b>To be repainted by 7/31/25.</b>
2. A-Corridor	Transfer Room	105 CMR 451.353*	Interior Maintenance: Floor dirty <b>Cleaned after inspection.</b>
3. B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 117, 119, 120, 121, 122, 124, 125, 126, 127, 128, 129, 130, 131, and 132 <b>To be repainted by 7/31/25.</b>
4. B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117 and 120 <b>To be repaired and repainted by 7/31/25.</b>
5. C-Corridor	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
6. C-Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>

**Building # 9 – Lenox****Deficiencies under the Required Standards (.100 and .200 series)**

6 new deficiencies and 5 repeat deficiencies (indicated by an \*) were found during the inspection:

1. A Corridor	Rooms	105 CMR 451.103	Mattresses: Mattress dirty in room # 103 <b>Mattress replaced after inspection.</b>
2. B Corridor	Closet # M-276	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty <b>Cleaned after inspection.</b>
3. C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance <b>To be repaired and repainted by 6/30/25.</b>
4. C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Radiator rusted <b>To be sanded and repainted by 6/30/25.</b>

5. C Corridor	Patient Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 86°F at handwash sink <b>Adjusted to appropriate temperature after inspection.</b>
6. C Corridor	Patient Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 2 <b>Repaired after inspection.</b>
7. C Corridor	Shower Room	105 CMR 451.130	Hot Water: Shower water temperature 75°F <b>Adjusted to appropriate temperature after inspection.</b>
8. C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Door frame rusted <b>To be sanded and repainted by 6/30/25.</b>
9. C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Door frame dirty <b>Cleaned after inspection.</b>
10. C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Door rusted <b>To be sanded and repainted by 6/30/25.</b>
11. C Corridor	Slop Sink Closet # M-251	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink <b>Repaired after inspection.</b>

**Deficiencies under the Recommended Standards (.300 series)**

8 new deficiencies and 33 repeat deficiencies (indicated by an \*) were found during the inspection:

1. A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 108, and 116 <b>To be repainted by 7/31/25.</b>
2. A Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 106, 109, 110, 111, and 113 <b>To be repainted by 7/31/25.</b>
3. A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 104 <b>To be repaired and repainted by 7/31/25.</b>
4. A Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 112 <b>To be repaired and repainted by 7/31/25.</b>
5. A Corridor	Transfer Room # M-228	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>

6. A Corridor	Transfer Room # M-228	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior <b>To be made rodent/weathertight by 5/15/25.</b>
7. A Corridor	Treatment Room # M-227	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
8. B Corridor	Closet # M-276	105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty <b>Cleaned after inspection.</b>
9. B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 119, 120, 121, 122, 124, 125, 126, 128, 130, 131, and 132 <b>To be repainted by 7/31/25.</b>
10. B Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 127 and 129 <b>To be repainted by 7/31/25.</b>
11. B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117, 119, 122, 125, 127, 130, and 132 <b>To be repaired and repainted by 7/31/25.</b>
12. B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Ceiling damaged in room # 124 <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
13. C Corridor	Laundry Room # 1	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
14. C Corridor	Secure Interview Room # M-234	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
15. C Corridor	Secure Interview Room # M-247	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
16. C Corridor	Slop Sink Closet # M-251	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
17. C Corridor	Staff Break Room # M-252	105 CMR 451.353*	Interior Maintenance: Countertop damaged <b>To be replaced by 8/31/25.</b>
18. Control		105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 7/31/25.</b>

**Building # 10 – Berkshire****Deficiencies under the Required Standards (.100 and .200 series)**

1 repeat deficiency (indicated by an \*) was found during the inspection:

1.	Right Side	Female Bathroom	105 CMR 451.123*	Maintenance: Door damaged <b>To be replaced by 6/30/25.</b>
----	------------	-----------------	------------------	--

**Deficiencies under the Recommended Standards (.300 series)**

6 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Right Side		105 CMR 451.353*	Interior Maintenance: Baseboard damaged <b>To be replaced by 7/31/25.</b>
2.	Right Side		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in hallway <b>To be replaced with LVT flooring by 7/31/25.</b>
3.	Right Side	Slop Sink # MM-03	105 CMR 451.353*	Interior Maintenance: Door damaged <b>To be replaced by 7/31/25.</b>
4.	Right Side	Slop Sink # MM-03	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
5.	Left Side		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged in hallway <b>To be replaced with LVT flooring by 7/31/25.</b>
6.	Left Side	Training Room	105 CMR 451.353*	Interior Maintenance: Floor surface damaged <b>To be replaced with LVT flooring by 7/31/25.</b>

**Building # 11 – Lighthouse****Deficiencies under the Required Standards (.100 and .200 series)**

3 new deficiencies and 11 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Booking Corridor	Female Bathroom # H-172	105 CMR 451.123*	Maintenance: Partitions rusted <b>To be sanded and repainted by 6/30/25.</b>
2.	Booking Corridor	Female Bathroom # H-172	105 CMR 451.123*	Maintenance: Hole in ceiling <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
3.	Booking Corridor	Male Bathroom # H-173	105 CMR 451.123*	Maintenance: Floor cracked <b>To be filled by 6/30/25.</b>
4.	Booking Corridor	Male Bathroom # H-173	105 CMR 451.123*	Maintenance: Partitions rusted <b>To be sanded and repainted by 6/30/25.</b>
5.	Infirmery	Dorm # 3/ Bathroom	105 CMR 451.123*	Maintenance: Door frame rusted in bathroom <b>To be sanded and repainted by 6/30/25.</b>
6.	Infirmery	Dorm # 3/ Bathroom	105 CMR 451.123	Maintenance: Handwash sink unit rusted <b>To be sanded and repainted by 6/30/25.</b>

7. Infirmary	Dorm # 4/ Bathroom	105 CMR 451.123*	Maintenance: Door frame to shower room rusted <b>To be sanded and repainted by 6/30/25.</b>
8. Infirmary	Dorm # 4/ Bathroom	105 CMR 451.123*	Maintenance: Wall tiles damaged in shower <b>To be replaced by 6/30/25.</b>
9. Infirmary	Nurse's Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty <b>Cleaned after inspection.</b>
10. Medical West Unit	Bathroom # 138 (Storage)	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal running continuously <b>Repaired after inspection.</b>
11. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Wall tile grout dirty <b>Cleaned after inspection.</b>
12. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Ceiling vent rusted <b>To be replaced by 6/30/25.</b>
13. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Door frame rusted <b>To be sanded and repainted by 6/30/25.</b>
14. Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Bench damaged <b>To be removed by 6/30/25.</b>

#### Deficiencies under the Recommended Standards (.300 series)

4 new deficiencies and 21 repeat deficiencies (identified by an \*) were found during the inspection:

1. Booking Corridor	Admissions Office # H-149	105 CMR 451.350*	Structural Maintenance: Ceiling water damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
2. Booking Corridor	Admissions Office # H-149	105 CMR 451.353*	Interior Maintenance: Desk surface damaged <b>To be replaced by 7/31/25.</b>
3. Booking Corridor	Booking Trap # H-212	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior <b>To be made rodent/weathertight by 7/31/25.</b>
4. Booking Corridor	Booking Trap # H-212	105 CMR 451.353*	Interior Maintenance: Door frame rotted <b>To be repaired and repainted by 7/31/25.</b>
5. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.350*	Structural Maintenance: Door not rodent and weathertight, gap at bottom of door to exterior <b>To be made rodent/weathertight by 5/15/25.</b>
6. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Medical waste storage chest rusted <b>To be replaced by 8/31/25.</b>
7. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Door frame rotted <b>To be repaired and repainted by 7/31/25.</b>
8. Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Door rusted <b>To be repaired and repainted by 7/31/25.</b>

9. Infirmary	Dorm # 3/ Bathroom	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm <b>To be repainted by 7/31/25.</b>
10. Infirmary	Dorm # 3/ Bathroom	105 CMR 451.353	Interior Maintenance: Wall paint damaged in dorm <b>To be repainted by 7/31/25.</b>
11. Infirmary	Dorm # 4/ Bathroom	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in dorm <b>To be repaired and repainted by 7/31/25.</b>
12. Infirmary	Dorm # 4/ Bathroom	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm <b>To be repainted by 7/31/25.</b>
13. Infirmary	Dorm # 5	105 CMR 451.353	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
14. Infirmary	Nurse's Office # H-145	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged <b>To be replaced by 7/31/25.</b>
15. Laundry Hallway	Laundry	105 CMR 451.353*	Interior Maintenance: Wall paint damaged <b>To be repainted by 7/31/25.</b>
16. Laundry Hallway		105 CMR 451.353*	Interior Maintenance: Door to exterior rusted <b>To be repaired and repainted by 7/31/25.</b>
17. Medical West Unit	Closet # H-121	105 CMR 451.353*	Interior Maintenance: Wall surface damaged <b>To be repaired and repainted by 7/31/25.</b>
18. Medical West Unit	Closet # H-121	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
19. Medical West Unit	Dorm # 7 # H- 125	105 CMR 451.353	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
20. Medical West Unit	Dorm # 8 # H- 126	105 CMR 451.353*	Interior Maintenance: Floor surface rusted <b>To be repaired and repainted by 7/31/25.</b>
21. Medical West Unit	Room # 5 # H- 131	105 CMR 451.353	Interior Maintenance: Floor rust stained <b>To be repaired and repainted by 7/31/25.</b>
22. Medical West Unit	Room # 6 # H- 130	105 CMR 451.353*	Interior Maintenance: Floor paint damaged <b>To be repainted by 7/31/25.</b>
23. Medical West Unit	RTA's Trap # H- 133	105 CMR 451.353*	Interior Maintenance: Ceiling damaged <b>To be repaired by 8/31/25 and upon completion of roof repairs.</b>
24. Old Seclusion Area		105 CMR 451.350*	Structural Maintenance: Door not rodent and weathertight, gap at bottom of door to exterior <b>To be made rodent/weathertight by 5/15/25.</b>
25. Old Seclusion Area		105 CMR 451.353*	Interior Maintenance: Door to exterior rotted <b>To be sanded and repainted by 7/31/25.</b>

**Building # 12 – Vehicle Trap****Deficiencies under the Required Standards (.100 and .200 series)**

1 new deficiency was found during the inspection:

1. Bathroom	105 CMR 451.123*	Maintenance: Door damaged To be sanded and repainted by 6/30/25.
-------------	------------------	---

**Staff Gym****Deficiencies under the Required Standards (.100 and .200 series)**

2 repeat deficiencies (indicated by an \*) were found during the inspection:

1. Male Locker Room	105 CMR 451.123*	Interior Maintenance: Ceiling tiles water stained To be replaced by 6/30/25.
1. Female Locker Room	105 CMR 451.123*	Maintenance: Light out above showers Replaced after inspection.

**Repeat Deficiencies under the Recommended Standards (.300 series)**

2 repeat deficiencies (indicated by an \*) were found during the inspection:

2. Common Area	105 CMR 451.353*	Interior Maintenance: Carpet damaged Section to be replaced by 7/31/25.
3. Common Area	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained To be replaced by 6/30/25.

**SECTION 2: Areas Found to be in Compliance**

The EHRS inspected 307 additional areas of the facility which were found to be in compliance.

**Section 3: Areas EHRS did not inspect**

EHRS did not inspect 2 areas of the facility because they were either in use, locked, or under construction.

1. Building# 2 - Adams	A2 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
2. Building # 11 – Lighthouse (Medical)	Booking Corridor	New Admissions Area		Unable to Inspect – Under Construction



MAURA T. HEALEY  
Governor

KIMBERLEY DRISCOLL  
Lieutenant Governor

# The Commonwealth of Massachusetts

Executive Office of Health and Human Services

Department of Public Health

Bureau of Climate and Environmental Health

Division of Environmental Health Regulations and Standards

5 Randolph Street

Canton, MA 02021

Phone: 617-624-5757

KATHLEEN E. WALSH  
Secretary

ROBERT GOLDSTEIN, MD, PhD  
Commissioner

Tel: 617-624-6000  
[www.mass.gov/dph](http://www.mass.gov/dph)

May 6, 2025

Joy Gallant, Superintendent  
Bridgewater State Hospital  
20 Administration Road  
Bridgewater, MA 02324 (electronic copy)

Re: Plan of Correction – Bridgewater State Hospital

Dear Superintendent Gallant:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction (POC) in response to my inspection on April 2 and 3, 2025. After review, EHRS finds the plan appropriately addresses all the deficiencies noted in the report.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

A handwritten signature in blue ink that reads "Patrick Wallace".

Patrick Wallace  
Environmental Health Inspector, EHRS, BCEH

cc: James Rioux, Deputy Superintendent  
Michael Rosano, Environmental Health and Safety Officer

(electronic copy)  
(electronic copy)