The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
100 Cambridge Street, 19th floor, Boston, MA 02114-2509
(617) 624-6000 | mass.gov/DPH

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

November 13, 2026

To:	Shawn Jenkins, Commissioner, Department of Corrections	(electronic copy)
	Kiame Mahaniah, Secretary, Executive Office of Health and Human Services	(electronic copy)
	Clerk, Massachusetts House of Representatives	(electronic copy)
	Clerk, Massachusetts Senate	(electronic copy)
	Michael Rosano, Environmental Health and Safety Officer	(electronic copy)

Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Bridgewater State Hospital, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Patrick Wallace
Environmental Analyst, EHRS, BCEH

Cc:	Robert Goldstein, MD, PhD, Commissioner, DPH	(electronic copy)
	Gina K. Kwon, Secretary, Executive Office of Public Safety and Security	(electronic copy)
	Eric Badger, Health Agent, Bridgewater Health Department	(electronic copy)
	Brianna Arruda, Director, Policy Development and Compliance Unit	(electronic copy)
	James Rioux, Superintendent	(electronic copy)

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
250 Washington Street, Boston, MA 02108-4619
(617) 624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

September 28, 2026

Jeffrey Gonsalves, Superintendent
Bridgewater State Hospital
20 Administration Road
Bridgewater, MA 02324 (electronic copy)

Re: Facility Inspection – Bridgewater State Hospital

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) Patrick Wallace and Hannah Lebeau conducted an inspection of the Bridgewater State Hospital on September 17 and 18, 2026 accompanied by Sergeant Michael Rosano, Environmental Health and Safety Officer, Michael Durocher, Director of Engineering, and Norberto Melo, Facility Maintenance Manager in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

This report identifies the number of new and repeat deficiencies which remain uncorrected since the previous inspection. The inspection identified 209 total deficiencies: 26 new deficiencies under the Required Standards (.100 and .200 series), 34 repeat deficiencies under the Required Standards, 26 new deficiencies under the Recommended Standards (.300 series), and 123 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Administration Building

Deficiencies under the Recommended Standards (.300 series)
1 repeat deficiency (indicated by an *) was found during the inspection:

	Area	Regulation	Description of Deficiency
1.	Front Control	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged

A1 Unit

Deficiencies under the Recommended Standards (.300 series)
2 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Transfer Room # A124	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
2.	Room Corridor	Nurse's Treatment Room # A125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
3.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 102 and 107
4.	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 104 and 118
5.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117 and 123

A2 Unit

Deficiencies under the Required Standards (.100 and .200 series)
2 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Area	Sub Area # 1	Regulation	Description of Deficiency
2.	Control	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling paint damaged
3.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling damaged
4.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor left unfinished next to handwash sinks
5.	Dorm Corridor	Dorm Shower	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 4
6.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Ceiling rusted

Deficiencies under the Recommended Standards (.300 series)
1 new deficiency and 5 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 216
2.	Dorm Corridor	Hallway	105 CMR 451.353	Interior Maintenance: Ceiling surface damaged
3.	Dorm Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Paint damaged on hand sanitizer dispenser
4.	Dorm Corridor	Dorms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm # 9, 11, and 10

B1 Unit

Deficiencies under the Required Standards (.100 and .200 series)
3 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Door damaged
2.	Main Area	Slop Sink Closet	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink out-of-order
3.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall vent dirty and clogged
4.	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 2 and 3
5.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Wall paint damaged
6.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Bench paint damaged

Deficiencies under the Recommended Standards (.300 series)
3 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
2.	Room Corridor	Treatment Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
3.	Room Corridor	Treatment Room	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
4.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 120

	Area	Sub Area # 1	Regulation	Description of Deficiency
5.	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 108 and 121
6.	Dorm Corridor	Room # B-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
7.	Dorm Corridor	Room # B-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8.	Dorm Corridor	Room # B-112	105 CMR 451.353	Interior Maintenance: Floor paint damaged

B2 Unit

Deficiencies under the Required Standards (.100 and .200 series)
7 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Mop Closet # B-250	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, slop sink drain clogged
2.	Main Area	Mop Closet # B-250	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, slop sink faucet leaking
3.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on countertop
4.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on soap dispenser
5.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Hand dryer out-of-order
6.	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 4
7.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Walls dirty
8.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Ceiling dirty
9.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Light fixture dirty
10.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door rusted
11.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door frame rusted

Deficiencies under the Recommended Standards (.300 series)
1 new deficiency and 5 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Mop Closet # B-250	105 CMR 451.353*	Interior Maintenance: Floor surface damaged

	Area	Sub Area # 1	Regulation	Description of Deficiency
2.	Room Corridor	Treatment Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
3.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 205, 206, and 210
4.	Dorm Corridor	Comfort Room	105 CMR 451.353	Interior Maintenance: Floor paint damaged

C1 Unit

Deficiencies under the Required Standards (.100 and .200 series)
3 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area	Regulation	Description of Deficiency
1.	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Door damaged
2.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling surface damaged
3.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted

Deficiencies under the Recommended Standards (.300 series)
3 new deficiencies and 21 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Hallway	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
2.	Main Area	Hallway	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
3.	Main Area	Mop Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
4.	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
5.	Main Area	Transfer Room	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
6.	Main Area	Storage Room	105 CMR 451.353	Interior Maintenance: Floor paint damaged
7.	Room Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
8.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 102, 103, 104, 109, 112, 114, 116, 118, and 119
9.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 116
10.	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 115 and 120

	Area	Sub Area # 1	Regulation	Description of Deficiency
11.	Dorm Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Paint damaged on hand sanitizer dispenser
12.	Dorm Corridor	Room # C-105	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
13.	Dorm Corridor	Office # C-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
14.	Dorm Corridor	Room # C-110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
15.	Dorm Corridor	Room # C-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

C2 Unit

Deficiencies under the Required Standards (.100 and .200 series)
1 new deficiency and 4 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling dirty
2.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged
3.	Dorm Corridor	Dorm Shower	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 3
4.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted
5.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on light fixture

Deficiencies under the Recommended Standards (.300 series)
2 new deficiencies and 18 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Staff Break Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
2.	Main Area	Room # C-220	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
3.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 204, 205, 208, 212, 214, 215, 218, 219, and 221
4.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 201 and 205
5.	Dorm Corridor	Hallway	105 CMR 451.353	Interior Maintenance: Paint damaged on hand sanitizer dispenser

	Area	Sub Area # 1	Regulation	Description of Deficiency
6.	Dorm Corridor	Room # C-204	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
7.	Dorm Corridor	Office # C-205	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8.	Dorm Corridor	Office # C-206	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
9.	Dorm Corridor	Room # C-208	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
10.	Dorm Corridor	Dorm # C-209	105 CMR 451.353	Interior Maintenance: Wall paint damaged
11.	Dorm Corridor	Classroom # C-210	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

Recovery Place

Deficiencies under the Recommended Standards (.300 series)
2 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Regulation	Description of Deficiency
1.	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
2.	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Wall paint damaged

Commons

Deficiencies under the Required Standards (.100 and .200 series)
7 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Laundry	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink
2.	School Corridor	Staff Bathroom	105 CMR 451.123*	Maintenance: Door damaged
3.	School Corridor	Staff Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged
4.	School Corridor	Staff Bathroom	105 CMR 451.123	Maintenance: Toilet partitions rusted
5.	Kitchen	Ice Machine	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A).
6.	Kitchen	Patient Bathroom	105 CMR 451.123	Maintenance: Ceiling paint damaged

	Area	Sub Area # 1	Regulation	Description of Deficiency
7.	Kitchen	Dishwashing Machine Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, wall surface damaged at entrance. Standard found in 105 CMR 590; FC 6-501.11.
8.	Kitchen	Freezer # 1	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, ice build-up observed at entrance. Standard found in 105 CMR 590; FC 6-501.12(A). **** Corrected On-Site ****
9.	Kitchen	Walk-In Refrigerator	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises. Standard found in 105 CMR 590; FC 6-501.114(A).
10.	Kitchen	Serving Line	105 CMR 451.200	Design and Construction; Cleanability: Multiuse food contact surface not smooth, several plastic serving trays damaged (Pf). Standard found in 105 CMR 590; FC 4-202.11(A)(1).

Deficiencies under the Recommended Standards (.300 series)
1 new deficiency and 9 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Laundry	105 CMR 451.353*	Interior Maintenance: Pipe insulation damaged
2.	Main Area	Control	105 CMR 451.353*	Interior Maintenance: Paint damaged on window frames
3.	Main Area	Storage Area # CL-11	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged
4.	Main Area	Room # CL-15	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
5.	School Corridor	Room # CS-10	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
6.	School Corridor	Room # CS-11	105 CMR 451.353	Interior Maintenance: Door frame dirty
7.	Basement	Hallway	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

	Area	Sub Area # 1	Regulation	Description of Deficiency
8.	Basement	Tool Crib	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
9.	Basement	Tool Crib	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
10.	Basement	Tool Crib	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged

Hadley

Deficiencies under the Required Standards (.100 and .200 series)
3 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	B-Corridor	Closet # M-176	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven damaged
2.	C-Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance
3.	C-Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Wall vent dusty
4.	C-Corridor	Patient Bathroom	105 CMR 451.123	Maintenance: Wall tiles damaged
5.	C-Corridor	Patient Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 2 clogged
6.	C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door rusted

Deficiencies under the Recommended Standards (.300 series)
6 new deficiencies and 21 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	A-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 101, 102, 104, 107, 110, 112, 113, 114, and 115
2.	A-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 106
3.	A-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 102, 112, and 114
4.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 120, 121, 122, 123, 124, 128, and 130
5.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 119
6.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 120
7.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 124

	Area	Sub Area # 1	Regulation	Description of Deficiency
8.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 124
9.	C-Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Paint damaged on hand sanitizer dispenser
10.	C-Corridor	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
11.	C-Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

Lenox

Deficiencies under the Required Standards (.100 and .200 series)
4 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance
2.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Radiator rusted
3.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on soap dispenser
4.	C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Door rusted

Deficiencies under the Recommended Standards (.300 series)
3 new deficiencies and 18 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Control	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
2.	A Corridor	Treatment Room	105 CMR 451.353	Interior Maintenance: Floor paint damaged
3.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 106, 107, and 113
4.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 107
5.	B Corridor	Closet # M-276	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
6.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 117, 119, 120, 121, 124, 125, 126, 127, 128, 129, 131, and 132
7.	C Corridor	Hallway	105 CMR 451.353	Interior Maintenance: Floor tiles damaged
8.	C Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

Lighthouse

Deficiencies under the Required Standards (.100 and .200 series)
2 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Control	Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet out-of-order
2.	Clinic Corridor	Clinic # H-168	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 100°F at handwash sink
3.	Booking Corridor	Female Bathroom	105 CMR 451.123*	Maintenance: Ceiling surface damaged
4.	Booking Corridor	Male Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged
5.	Infirmary	Shower Room	105 CMR 451.123*	Maintenance: Door damaged
6.	Medical West	Shower # H-137	105 CMR 451.123*	Maintenance: Wall tile grout dirty
7.	Medical West	Shower # H-137	105 CMR 451.123*	Maintenance: Door frame rusted

Deficiencies under the Recommended Standards (.300 series)
3 new deficiencies and 11 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Clinic Corridor	Room # H-154	105 CMR 451.353	Interior Maintenance: Ceiling water damaged
2.	Booking Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
3.	Booking Corridor	Room # H-215	105 CMR 451.353*	Interior Maintenance: Door frame rotted
4.	Booking Corridor	Room # H-215	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior
5.	Booking Corridor	Booking Trap # H-212	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior
6.	Booking Corridor	Booking Trap # H-212	105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty
7.	Infirmary	Room # 2	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8.	Infirmary	Dorm # 5	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
9.	Infirmary	TV Room # H-140	105 CMR 451.353	Interior Maintenance: Floor tiles damaged
10.	Infirmary	Laundry	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
11.	Medical West	Closet # H-121	105 CMR 451.353*	Interior Maintenance: Wall surface left unfinished

	Area	Sub Area # 1	Regulation	Description of Deficiency
12.	Medical West	Janitor's Closet # H-123	105 CMR 451.353	Interior Maintenance: Slop sink dirty
13.	Medical West	Dorm # 10	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
14.	Medical West	Room # 6	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

Staff Gym

Deficiencies under the Required Standards (.100 and .200 series)
1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	Area	Regulation	Description of Deficiency
2.	Female Locker Room	105 CMR 451.123	Maintenance: Ceiling tiles water damaged
3.	Male Locker Room	105 CMR 451.123*	Maintenance: Ceiling tiles water damaged

Deficiencies under the Recommended Standards (.300 series)
1 new deficiency was found during the inspection:

	Area	Regulation	Description of Deficiency
1.	Common Area	105 CMR 451.353	Interior Maintenance: Carpet damaged

SECTION 2: Areas Found to be in Compliance

The EHRS inspected 304 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 5 areas of the facility because they were either in use, locked, or under construction:

	Area	Sub Area # 1	Sun Area # 2	Reason for not Inspecting
1.	A1 Unit	Dorm Corridor	Dorm Bathroom	Unable to Inspect – Under Construction
2.	A1 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
3.	Old Seclusion Area			Unable to Inspect – Under Construction
4.	Property			Unable to Inspect – Under Construction
5.	Infirmary	Trauma Room		Unable to Inspect – In Use

SECTION 4: Plan of Correction

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. A signature by the Superintendent or Administrator responsible for the plan. The signed plan should be submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The patient population was 202 at the time of inspection.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" 105 CMR 451.000 is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found here.

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- 105 CMR 205.000: Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- 105 CMR 480.000: Minimum requirements for the Management of Medical or Biological Waste
- 105 CMR 500.000: Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,

Patrick Wallace,
Environmental Analyst, EHRS, BCEH

The Commonwealth of Massachusetts
Executive Office of Public Safety & Security
Department of Correction
Bridgewater State Hospital
20 Administration Road
Bridgewater, MA 02324
Tel: (508) 279-4500
www.mass.gov/doc

MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

GINA K. KWON
Secretary

SHAWN P. JENKINS
Commissioner

October 5, 2026

Mr. Patrick Wallace
Environmental Health Inspector, CSP, BEH
Department of Public Health, Bureau of Environmental Health
Community Sanitation Program
5 Randolph Street
Canton, MA 02021

Dear Mr. Wallace:

Enclosed please find your inspection report for Bridgewater State Hospital dated 9/28/26. This report has been updated to include corrective action plans which address all violations. All responses are in **bold**.

Should you have any questions or require additional information, please don't hesitate to contact my office.

Sincerely,

James Rioux
Acting Superintendent

CC: Shawn P. Jenkins, Commissioner
Mitzi Peterson, Deputy Commissioner, Clinical Services & Re-entry
Jeff Fisher, Assistant Deputy Commissioner, Clinical Services
Michael Rodrigues, Assistant Deputy Commissioner, Southern Region
James Rioux, Acting Superintendent
Brianna Arruda, Director, Policy Development and Compliance Unit
Michael Durocher, Director of Facility Maintenance
Sergeant Michael Rosano, Environmental Health and Safety Officer

SECTION 1: Health and Safety Deficiencies

Administration Building

Deficiencies under the Recommended Standards (.300 series)
1 repeat deficiency (indicated by an *) was found during the inspection:

	Area	Regulation	Description of Deficiency
1.	Front Control	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged **To be repaired and repainted by 2/28/27**

A1 Unit

Deficiencies under the Recommended Standards (.300 series)
2 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Transfer Room # A124	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
2.	Room Corridor	Nurse's Treatment Room # A125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
3.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 102 and 107 **To be repaired/repainted by 2/28/27**
4.	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 104 and 118 **To be repaired/repainted by 2/28/27**
5.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117 and 123 **To be repaired/repainted by 2/28/27**

A2 Unit

Deficiencies under the Required Standards (.100 and .200 series)
2 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Area	Sub Area # 1	Regulation	Description of Deficiency
2.	Control	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling paint damaged **To be repaired/repainted by 10/28/26**

3.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling damaged **To be repaired/repainted by 10/28/26**
4.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor left unfinished next to handwash sinks **To be repaired/repainted by 10/28/26**
5.	Dorm Corridor	Dorm Shower	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 4 **To be repaired by 10/14/26**
6.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Ceiling rusted **To be repaired by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 5 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 216 **To be repaired/repainted by 2/28/27**
2.	Dorm Corridor	Hallway	105 CMR 451.353	Interior Maintenance: Ceiling surface damaged **To be repaired/repainted by 2/28/27**
3.	Dorm Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Paint damaged on hand sanitizer dispenser **To be repaired by 2/28/27**
4.	Dorm Corridor	Dorms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm # 9, 11, and 10 **To be repaired/repainted by 2/28/27**

B1 Unit

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Door damaged **To be repaired by 10/28/26**
2.	Main Area	Slop Sink Closet	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink out-of-order **To be repaired by 10/14/26**
3.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall vent dirty and clogged **To be cleaned by 10/14/26**
4.	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 2 and 3 **To be repaired by 10/14/26**
5.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Wall paint damaged **To be repaired/repainted by 10/28/26**

6.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Bench paint damaged **To be repaired/repainted by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)
3 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged **To be repaired/repainted by 2/28/27**
2.	Room Corridor	Treatment Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
3.	Room Corridor	Treatment Room	105 CMR 451.353*	Interior Maintenance: Wall paint damaged **To be repaired/repainted by 2/28/27**
4.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 120 **To be repaired/repainted by 2/28/27**
5.	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 108 and 121 **To be repaired/repainted by 2/28/27**
6.	Dorm Corridor	Room # B-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
7.	Dorm Corridor	Room # B-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
8.	Dorm Corridor	Room # B-112	105 CMR 451.353	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**

B2 Unit

Deficiencies under the Required Standards (.100 and .200 series)
7 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Mop Closet # B-250	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, slop sink drain clogged **To be repaired by 10/14/26**
2.	Main Area	Mop Closet # B-250	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, slop sink faucet leaking **To be repaired by 10/14/26**
3.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on countertop **To be repaired by 10/28/26**

4.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on soap dispenser **To be repaired by 10/14/26**
5.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Hand dryer out-of-order **To be repaired by 10/14/26**
6.	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 4 **To be repaired by 10/14/26**
7.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Walls dirty **To be cleaned by 10/14/26**
8.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Ceiling dirty **To be cleaned by 10/14/26**
9.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Light fixture dirty **To be cleaned by 10/14/26**
10.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door rusted **To be repaired by 10/28/26**
11.	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Door frame rusted **To be repaired by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)
1 new deficiency and 5 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Mop Closet # B-250	105 CMR 451.353*	Interior Maintenance: Floor surface damaged **To be repaired/repainted by 2/28/27**
2.	Room Corridor	Treatment Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
3.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 205, 206, and 210 **To be repaired/repainted by 2/28/27**
4.	Dorm Corridor	Comfort Room	105 CMR 451.353	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**

C1 Unit

Deficiencies under the Required Standards (.100 and .200 series)
3 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area	Regulation	Description of Deficiency
1.	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Door damaged **To be repaired/repainted by 10/28/26**
2.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling surface damaged **To be repaired by 10/28/26**

3.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted **To be repaired by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)
3 new deficiencies and 21 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Hallway	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged **To be repaired/repainted by 2/28/27**
2.	Main Area	Hallway	105 CMR 451.353*	Interior Maintenance: Wall paint damaged **To be repaired/repainted by 2/28/27**
3.	Main Area	Mop Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
4.	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged **To be repaired/repainted by 2/28/27**
5.	Main Area	Transfer Room	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged **To be repaired/repainted by 2/28/27**
6.	Main Area	Storage Room	105 CMR 451.353	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
7.	Room Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged **To be repaired/repainted by 2/28/27**
8.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 102, 103, 104, 109, 112, 114, 116, 118, and 119 **To be repaired/repainted by 2/28/27**
9.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 116 **To be repaired/repainted by 2/28/27**
10.	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 115 and 120 **To be repaired/repainted by 2/28/27**
11.	Dorm Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Paint damaged on hand sanitizer dispenser **To be repaired by 2/28/27**
12.	Dorm Corridor	Room # C-105	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
13.	Dorm Corridor	Office # C-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
14.	Dorm Corridor	Room # C-110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**

	Area	Sub Area # 1	Regulation	Description of Deficiency
15.	Dorm Corridor	Room # C-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**

C2 Unit

Deficiencies under the Required Standards (.100 and .200 series)
1 new deficiency and 4 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling dirty **To be cleaned by 10/14/26**
2.	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged **To be repaired/repainted by 10/28/26**
3.	Dorm Corridor	Dorm Shower	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 3 **To be repaired by 10/14/26**
4.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted **To be repaired/repainted by 10/28/26**
5.	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on light fixture **To be repaired/repainted by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)
2 new deficiencies and 18 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Staff Break Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
2.	Main Area	Room # C-220	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
3.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 204, 205, 208, 212, 214, 215, 218, 219, and 221 **To be repaired/repainted by 2/28/27**
4.	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 201 and 205 **To be repaired by 2/28/27**
5.	Dorm Corridor	Hallway	105 CMR 451.353	Interior Maintenance: Paint damaged on hand sanitizer dispenser **To be repaired by 2/28/27**
6.	Dorm Corridor	Room # C-204	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**

	Area	Sub Area # 1	Regulation	Description of Deficiency
7.	Dorm Corridor	Office # C-205	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
8.	Dorm Corridor	Office # C-206	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
9.	Dorm Corridor	Room # C-208	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
10.	Dorm Corridor	Dorm # C-209	105 CMR 451.353	Interior Maintenance: Wall paint damaged **To be repaired/repainted by 2/28/27**
11.	Dorm Corridor	Classroom # C-210	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**

Recovery Place

Deficiencies under the Recommended Standards (.300 series)
2 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Regulation	Description of Deficiency
1.	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
2.	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Wall paint damaged **To be repaired/repainted by 2/28/27**

Commons

Deficiencies under the Required Standards (.100 and .200 series)
7 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Laundry	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink **To be repaired by 10/14/26**
2.	School Corridor	Staff Bathroom	105 CMR 451.123*	Maintenance: Door damaged **To be repaired by 10/28/26**
3.	School Corridor	Staff Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged **To be repaired/repainted by 10/28/26**
4.	School Corridor	Staff Bathroom	105 CMR 451.123	Maintenance: Toilet partitions rusted **To be repaired by 10/28/26**
5.	Kitchen	Ice Machine	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not

	Area	Sub Area # 1	Regulation	Description of Deficiency
				maintained in a state of good repair, out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A). **To be repaired by 10/28/26**
6.	Kitchen	Patient Bathroom	105 CMR 451.123	Maintenance: Ceiling paint damaged **To be repaired/repainted by 10/28/26**
7.	Kitchen	Dishwashing Machine Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, wall surface damaged at entrance. Standard found in 105 CMR 590; FC 6-501.11. **To be repaired by 10/28/26**
8.	Kitchen	Freezer # 1	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, ice build-up observed at entrance. Standard found in 105 CMR 590; FC 6-501.12(A). **** Corrected On-Site ****
9.	Kitchen	Walk-In Refrigerator	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises. Standard found in 105 CMR 590; FC 6-501.114(A). **To be repaired by 2/28/27**
10.	Kitchen	Serving Line	105 CMR 451.200	Design and Construction; Cleanability: Multiuse food contact surface not smooth, several plastic serving trays damaged (Pf). Standard found in 105 CMR 590; FC 4-202.11(A)(1). **To be replaced by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 9 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Laundry	105 CMR 451.353*	Interior Maintenance: Pipe insulation damaged **To be repaired by 2/28/27**
2.	Main Area	Control	105 CMR 451.353*	Interior Maintenance: Paint damaged on window frames **To be repaired/repainted by 2/28/27**

	Area	Sub Area # 1	Regulation	Description of Deficiency
3.	Main Area	Storage Area # CL-11	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged **To be repaired/repainted by 2/28/27**
4.	Main Area	Room # CL-15	105 CMR 451.353*	Interior Maintenance: Wall paint damaged **To be repaired/repainted by 2/28/27**
5.	School Corridor	Room # CS-10	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged **To be repaired/repainted by 2/28/27**
6.	School Corridor	Room # CS-11	105 CMR 451.353	Interior Maintenance: Door frame dirty **To be cleaned by 10/14/26**
7.	Basement	Hallway	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
8.	Basement	Tool Crib	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
9.	Basement	Tool Crib	105 CMR 451.353*	Interior Maintenance: Wall paint damaged **To be repaired/repainted by 2/28/27**
10.	Basement	Tool Crib	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged **To be repaired/repainted by 2/28/27**

Hadley

Deficiencies under the Required Standards (.100 and .200 series)
3 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	B-Corridor	Closet # M-176	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven damaged **To be replaced by 10/28/26**

	Area	Sub Area # 1	Regulation	Description of Deficiency
2.	C-Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance **To be repaired by 10/28/26**
3.	C-Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Wall vent dusty **To be cleaned by 10/14/26**
4.	C-Corridor	Patient Bathroom	105 CMR 451.123	Maintenance: Wall tiles damaged **To be repaired by 10/28/26**
5.	C-Corridor	Patient Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 2 clogged **To be repaired by 10/14/26**
6.	C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door rusted **To be repaired/repainted by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 21 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	A-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 101, 102, 104, 107, 110, 112, 113, 114, and 115 **To be repaired/repainted by 2/28/27**
2.	A-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 106 **To be repaired/repainted/ by 2/28/27**
3.	A-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 102, 112, and 114 **To be repaired/repainted by 2/28/27**
4.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 120, 121, 122, 123, 124, 128, and 130 **To be repaired/repainted by 2/28/27**
5.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 119 **To be repaired/repainted by 2/28/27**
6.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 120 **To be repaired/repainted by 2/28/27**
7.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor surface damaged in room # 124 **To be repaired/repainted by 2/28/27**
8.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 124 **To be repaired/repainted by 2/28/27**
9.	C-Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Paint damaged on hand sanitizer dispenser **To be repaired by 2/28/27**
10.	C-Corridor	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
11.	C-Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**

Lenox

Deficiencies under the Required Standards (.100 and .200 series)
4 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance **To be repaired by 10/28/26**
2.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Radiator rusted **To be repaired by 10/28/26**
3.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on soap dispenser **To be repaired by 10/28/26**
4.	C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Door rusted **To be repaired by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)
3 new deficiencies and 18 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Main Area	Control	105 CMR 451.353*	Interior Maintenance: Wall paint damaged **To be repaired by 2/28/27**
2.	A Corridor	Treatment Room	105 CMR 451.353	Interior Maintenance: Floor paint damaged **To be repaired and repainted by 2/28/27**
3.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 106, 107, and 113 **To be repaired/repainted by 2/28/27**
4.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 107 **To be repaired/repainted by 2/28/27**
5.	B Corridor	Closet # M-276	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty **To be cleaned by 2/28/27**
6.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 117, 119, 120, 121, 124, 125, 126, 127, 128, 129, 131, and 132 **To be repaired/repainted by 2/28/27**
7.	C Corridor	Hallway	105 CMR 451.353	Interior Maintenance: Floor tiles damaged **To be repaired by 2/28/27**
8.	C Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**

Lighthouse

Deficiencies under the Required Standards (.100 and .200 series)
2 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Control	Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet out-of-order **To be repaired by 10/14/26**
2.	Clinic Corridor	Clinic # H-168	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 100°F at handwash sink **To be repaired by 10/14/26**
3.	Booking Corridor	Female Bathroom	105 CMR 451.123*	Maintenance: Ceiling surface damaged **To be repaired/repainted by 10/28/26**
4.	Booking Corridor	Male Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged **To be repaired/ repainted by 10/28/26**
5.	Infirmary	Shower Room	105 CMR 451.123*	Maintenance: Door damaged **To be repaired by 10/28/26**
6.	Medical West	Shower # H-137	105 CMR 451.123*	Maintenance: Wall tile grout dirty **To be cleaned by 10/14/26**
7.	Medical West	Shower # H-137	105 CMR 451.123*	Maintenance: Door frame rusted **To be repaired/repainted by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)
3 new deficiencies and 11 repeat deficiencies (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Regulation	Description of Deficiency
1.	Clinic Corridor	Room # H-154	105 CMR 451.353	Interior Maintenance: Ceiling water damaged **To be repaired/repainted by 2/28/27**
2.	Booking Corridor	Hallway	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged **To be repaired/repainted by 2/28/27**
3.	Booking Corridor	Room # H-215	105 CMR 451.353*	Interior Maintenance: Door frame rotted **To be repaired and painted by 2/28/27**
4.	Booking Corridor	Room # H-215	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior **To be re[aired by 2/28/27**

	Area	Sub Area # 1	Regulation	Description of Deficiency
5.	Booking Corridor	Booking Trap # H-212	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior **To be repaired by 2/28/27**
6.	Booking Corridor	Booking Trap # H-212	105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty **To be cleaned by 10/28/26**
7.	Infirmary	Room # 2	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
8.	Infirmary	Dorm # 5	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**
9.	Infirmary	TV Room # H-140	105 CMR 451.353	Interior Maintenance: Floor tiles damaged **To be repaired/repainted by 2/28/27**
10.	Infirmary	Laundry	105 CMR 451.353*	Interior Maintenance: Wall paint damaged **To be repaired/repainted by 2/28/27**
11.	Medical West	Closet # H-121	105 CMR 451.353*	Interior Maintenance: Wall surface left unfinished **To be painted by 2/28/27**
12.	Medical West	Janitor's Closet # H-123	105 CMR 451.353	Interior Maintenance: Slop sink dirty **To be cleaned by 10/14/26**
13.	Medical West	Dorm # 10	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/replaced by 2/28/27**
14.	Medical West	Room # 6	105 CMR 451.353*	Interior Maintenance: Floor paint damaged **To be repaired/repainted by 2/28/27**

Staff Gym

Deficiencies under the Required Standards (.100 and .200 series)
1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	Area	Regulation	Description of Deficiency
2.	Female Locker Room	105 CMR 451.123	Maintenance: Ceiling tiles water damaged **To be replaced by 10/28/26**
3.	Male Locker Room	105 CMR 451.123*	Maintenance: Ceiling tiles water damaged **To be replaced by 10/28/26**

Deficiencies under the Recommended Standards (.300 series)
1 new deficiency was found during the inspection:

	Area	Regulation	Description of Deficiency
1.	Common Area	105 CMR 451.353	Interior Maintenance: Carpet damaged **To be replaced by 2/28/27**

SECTION 2: Areas Found to be in Compliance

The EHRS inspected 304 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 5 areas of the facility because they were either in use, locked, or under construction:

	Area	Sub Area # 1	Sun Area # 2	Reason for not Inspecting
1.	A1 Unit	Dorm Corridor	Dorm Bathroom	Unable to Inspect – Under Construction
2.	A1 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
3.	Old Seclusion Area			Unable to Inspect – Under Construction
4.	Property			Unable to Inspect – Under Construction
5.	Infirmary	Trauma Room		Unable to Inspect – In Use

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
100 Cambridge Street, 19th floor, Boston, MA 02114-2509
(617) 624-6000 | mass.gov/DPH

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

October 26, 2026

James Rioux, Superintendent
Bridgewater State Hospital
20 Administration Road
Bridgewater, MA 02324 (electronic copy)

Re: Plan of Correction – Bridgewater State Hospital

Dear Superintendent Rioux:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction (POC) in response to my inspection on September 17 and 18, 2026. After review, EHRS finds the plan appropriately addresses all the deficiencies noted in the report.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Patrick Wallace

Patrick Wallace
Environmental Analyst, EHRS, BCEH

cc: Michael Rosano, Environmental Health and Safety Officer (electronic copy)