

MAURA T. HEALEY Governor KIMBERLEY DRISCOLL Lieutenant Governor

The Commonwealth of Massachusetts

Executive Office of Health and Human Services
Department of Public Health

Bureau of Climate and Environmental Health Division of Environmental Health Regulations and Standards

5 Randolph Street Canton, MA 02021 Phone: 617-624-6000

KATHLEEN E. WALSH Secretary

ROBERT GOLDSTEIN, MD, PhD Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

February 11, 2025

To:	Shawn Jenkins, Commissioner, Department of Corrections	(electronic copy)
	Kathleen E. Walsh, Secretary, Executive Office of Health and Human Services	(electronic copy)
	Clerk, Massachusetts House of Representatives	(electronic copy)
	Clerk, Massachusetts Senate	(electronic copy)
	Noe Bard, Environmental Health and Safety Officer	(electronic copy)

Greetings,


Pursuant to 105 CMR 451.403, please find the inspection report for Worcester County Jail and House of Corrections, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Cory J. Holmes

Senior Advisor, EHRS, BCEH

Cc:	Robert Goldstein, MD, PhD, Commissioner, DPH	(electronic copy)
	Terrence Reidy, Secretary, Executive Office of Public Safety and Security	(electronic copy)
	Margaret Lee, Administrative Assistant, West Boylston Board of Health	(electronic copy)
	Brianna Arruda, Director, Policy Development and Compliance Unit	(electronic copy)
	Steven Hughes, Director, EHRS, BCEH	



Executive Office of Health and Human Services

Department of Public Health

Departmental Health Regulations and Stan

Division of Environmental Health Regulations and Standards

MAURA T. HEALEY Governor

KIMBERLEY DRISCOLL Lieutenant Governor 67 Forest Street, Suite # 100 Marlborough, MA 01752 Phone: 617-624-5757

KATHLEEN E. WALSH Secretary

ROBERT GOLDSTEIN, MD, PhD Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

January 13, 2025

Jason Rives, Superintendent
Worcester County House of Corrections and Jail
5 Paul X. Tivnan Drive
West Boylston, MA 01583 (electronic copy)

Re: Facility Inspection – Worcester County House of Corrections and Jail, West Boylston

Dear Superintendent Rives:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Worcester County Jail and House of Correction on November 18, 2024, accompanied by Noe Bard, Environmental Health and Safety Officer, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 309 total deficiencies; 145 new deficiencies under the Required Standards (.100 and .200 series), 18 repeat deficiencies under the Required Standards, 98 new deficiencies under the Recommended Standards (.300 series), and 48 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Deficiencies under the Required Standards (.100 and .200 series)

145 new deficiencies and 18 repeat deficiencies (indicated by an *) were found during the inspection:

Superintendent's Office	Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty
Male Staff Locker	Male Staff	105 CMR 451.123	Maintenance: Ceiling vent dusty
Male Staff Locker		105 CMR 451.123*	Maintenance: Heater damaged
Room			
Control Room		105 CMR 451.123*	Maintenance: Ceiling vent dusty
	Bathroom		
Control Room	Control	105 CMR 451.123	Maintenance: Wet mop stored in
	Bathroom		bucket
Visiting Room	Male	105 CMR 451.123	Maintenance: Ceiling tiles water
	Handicapped		damaged
	Bathroom		
Visiting Room	Female	105 CMR 451.123	Maintenance: Ceiling tiles damaged
-	Bathroom		
Visiting Room	Female	105 CMR 451.123	Maintenance: Wall paint damaged
_	Bathroom		behind toilet # 2
Visiting Room	Male	105 CMR 451.123*	Maintenance: Wall paint damaged
O	Bathroom		above urinal
Breakroom &		105 CMR 451.123*	Maintenance: Walls dirty in bathroom
			,
	Control	105 CMR 451.123*	Maintenance: Ceiling tile missing
		105 CMR 451.123	Maintenance: Ceiling vent dusty
			, and the same of
Control Booth		105 CMR 451.200	Food Storage, Preparation and
	,		Service: Food preparation not in
			compliance with 105 CMR 590.000,
			interior of microwave oven dirty
Control Booth	Staff Room	105 CMR 451.200	Food Storage, Preparation and
			Service: Food preparation not in
			compliance with 105 CMR 590.000,
			interior of microwave oven dirty
Control Booth	Control	105 CMR 451.123*	Maintenance: Ceiling vent dusty
			manuellander denning rente addet,
Control Booth		105 CMR 451 130*	Plumbing: Plumbing not maintained in
COTTO DOCE	•	200 0.0 102.1200	good repair; slop sink clogged
	(2011/1500113)		occa repair) stop strik clopped
Control			
Control Bathroom		105 CMR 451 123*	Maintenance: Floor paint damaged
Bathroom		105 CMR 451.123*	Maintenance: Floor paint damaged
Bathroom Control			
Bathroom Control Bathroom	Day Room	105 CMR 451.123*	Maintenance: Floor and walls dirty
Bathroom Control	Day Room		Maintenance: Floor and walls dirty Food Storage, Preparation and
Bathroom Control Bathroom	Day Room	105 CMR 451.123*	Maintenance: Floor and walls dirty Food Storage, Preparation and Service: Food preparation not in
Bathroom Control Bathroom	Day Room	105 CMR 451.123*	Maintenance: Floor and walls dirty Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000,
Bathroom Control Bathroom	Day Room Showers	105 CMR 451.123*	Maintenance: Floor and walls dirty Food Storage, Preparation and Service: Food preparation not in
	Office Male Staff Locker Room Male Staff Locker Room Control Room Control Room Visiting Room	Male Staff Locker Room Male Staff Locker Room Male Staff Locker Room Male Staff Locker Room Control Room Control Bathroom Control Bathroom Control Room Control Bathroom Visiting Room Visiting Room Visiting Room Female Bathroom Visiting Room Female Bathroom Visiting Room Control Bathroom Control Booth Control Bathroom	Male Staff Locker Room Bathroom Male Staff Locker Room Bathroom Male Staff Locker Room Bathroom Control Room Control Bathroom Control Room Control Bathroom Control Room Control Bathroom Control Room Control Bathroom Visiting Room Male Bathroom Visiting Room Female Bathroom Visiting Room Female Bathroom Visiting Room Female Bathroom Control Booth Day Room 105 CMR 451.123* Bathroom Control Booth Control Bathroom Control Booth Slop Sink 105 CMR 451.23* Bathroom Control Booth Slop Sink 105 CMR 451.123*

21. MAXI B	Lower Right Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 2
22. MAXI B	Lower Left Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 2
23. MAXI B	Lower Left Tier	Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1
24. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Soap scum on curtain in shower # 2
25. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged outside shower # 1
26. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged in shower # 1 and 2
27. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Mold on walls in shower # 1 and 2
28. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1
29. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 1
30. MAXI B	Upper Right Tier	Showers	105 CMR 451.123*	Maintenance: Soap scum on curtain in shower # 1
31. MAXI B	Upper Right Tier	Showers	105 CMR 451.123*	Maintenance: Wall paint and epoxy damaged in shower # 1 and 2
32. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged in shower # 2
33. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Drain flies observed in shower # 2
34. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Mold on wall in shower # 2
35. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 2
36. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 1
37. MAXI B	Upper Left Tier	Day Room	105 CMR 451.200	Destruction of Organisms of Public Health Concern; Cooking: Raw animal food not stirred properly during microwave cooking. Standard found in 105 CMR 590; FC 3-401.12(A).
38. Food Service	Main Kitchen	Control Bathroom	105 CMR 451.123	Maintenance: Wall tile damaged
39. Food Service	Main Kitchen	Inmate Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: No hot water supplied to handwash sink
40. Food Service	Main Kitchen	Inmate Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 95°F at handwash sink

41. Food Service	Main Kitchen	Bakery	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, standing water observed on floor below tables. Standard found in 105 CMR 590; FC 6-501.12(A).
42. Food Service	Main Kitchen	Bakery	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; floor dirty behind ovens. Standard found in 105 CMR 590; FC 6-501.12(A).
43. Food Service	Main Kitchen	Entire Kitchen	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Premises not maintained free of insects, drain flies observed throughout kitchen. Standard found in 105 CMR 590; FC 6- 501.111.
44. Food Service	Main Kitchen	Milk Cooler # 1	105 CMR 451.200	Preventing Contamination from the Premises; Food Storage: Milk stored below leaking condenser. Standard found in 105 CMR 590; FC 3-305.12.
45. Food Service	Main Kitchen	Produce Cooler # 2	105 CMR 451.200	Preventing Contamination from the Premises; Food Storage: Bread stored under leaking condenser. Standard found in 105 CMR 590; FC 3-305.12.
46. Food Service	Main Kitchen	Prep Cooler # 3	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; wall fan dusty. Standard found in 105 CMR 590; FC 6-501.12(A).
47. Food Service	Main Kitchen	Prep Cooler # 3	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; walls dirty. Standard found in 105 CMR 590; FC 6-501.12(A).
48. Food Service	Main Kitchen	Prep Cooler # 3	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, floor tiles damaged. Standard found in 105 CMR 590: FC 6-501.11.

49. Food Service	Main Kitchen	Freezer # 4	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, ice build-up on ceiling. Standard found in 105 CMR 590; FC 6-501.12(A).
50. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling paint damaged above warewash machine. Standard found in 105 CMR 590; FC 6-501.11.
51. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200*	Maintenance and Operation, Equipment: Inadequate water temperature in the mechanical warewashing machine (Pf). Standard found in 105 CMR 590; FC 4- 501.112(A)(2).
52. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling paint damaged above drains. Standard found in 105 CMR 590; FC 6-501.11.
53. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non- functional equipment not repaired or removed from premises, dishwasher not working. Standard found in 105 CMR 590; FC 6- 501.114(A).
54. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, sink sprayer dirty. Standard found in 105 CMR 590; FC 6-501.12(A).
55. Food Service	Main Kitchen	3-Compartment Sink # 1 and 2	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, mold on sprayer head. Standard found in 105 CMR 590; FC 6-501.12(A).

56. Food Service	Main Kitchen	Exterior Door	105 CMR 451.200	Design, Construction, and Installation; Functionality: Outer openings not protected against the entry of insects and rodents, exterior door not rodent and weather tight. Standard found in 105 CMR 590; FC 6-202.15(A)(3).
57. Food Service	Main Kitchen	Inmate Bathroom	105 CMR 451.123*	Maintenance: Door frame damaged
58. MAXI C	Upper Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 1 and 2
59. MAXI C	Lower Tier	Right-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
60. Programs	Female Staff B	athroom	105 CMR 451.123	Maintenance: Wall paint damaged near trash
61. Maintenance Corridor	Inmate Bathro	om	105 CMR 451.123	Maintenance: Wall paint damaged behind toilet
62. Deignan Building	Control Booth	Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty
63. Deignan Building	Control Booth	Bathroom	105 CMR 451.123	Maintenance: Floor paint damaged
64. Deignan Building	Common Area		105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
65. Deignan Building	Upper West	Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 2
66. Deignan Building	Upper West	Bathroom	105 CMR 451.123	Maintenance: Basin damaged at handwash sink # 2
67. Deignan Building	Upper West	Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water faucet missing at handwash sink # 4
68. Deignan Building	Lower East	Showers	105 CMR 451.123	Maintenance: Light out in shower # 2
69. Deignan Building	Lower East	Showers	105 CMR 451.123	Maintenance: Light rusted in shower # 1
70. Deignan Building	Lower East	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, backflow preventor cover missing
71. Deignan Building	Upper East	Showers	105 CMR 451.123	Maintenance: Ceiling panel rusted in shower # 1 and 2
72. Deignan Building	Upper East	Bathroom	105 CMR 451.123	Maintenance: Partition paint damaged in toilet stall # 2
73. Mini 5 Building		Bathroom	105 CMR 451.123	Maintenance: Curtain moldy in shower # 1
74. Mini 5 Building		Bathroom	105 CMR 451.123	Maintenance: Caulking moldy
75. Modular Administration	Special Services	Female Locker Room	105 CMR 451.123	Maintenance: Lights out

76. Modular Administration	Special Services	Female Locker Room	105 CMR 451.123	Maintenance: Floor tiles damaged in hallway
Building	Corridor			
77. Modular	Special	Female Locker Room	105 CMR 451.123	Maintenance: Ceiling rusted
Administration	Services			
Building	Corridor			
78. Modular	Special	Male Locker Room &	105 CMR 451.123	Maintenance: Floor dirty in shower #
Administration	Services	Bathroom	200 0 102.222	1
Building	Corridor			_
79. Modular	Special	Male Locker Room &	105 CMR 451.123	Maintenance: Floor damaged in
Administration	Services	Bathroom	103 01111 10111123	locker area
Building	Corridor			
80. Modular	Special	Male Locker Room &	105 CMR 451.123	Maintenance: Ceiling tiles water
Administration	Services	Bathroom	105 CIVII 151.125	damaged in locker area
Building	Corridor	Datin Com		admaged in looker area
81. Modular	Special	Male Locker Room &	105 CMR 451.123	Maintenance: Debris on floor
Administration	Services	Bathroom	100 CIVIN 701.120	Mantenance: Debris on Hoor
Building	Corridor	Datin John		
82. Modular Gym	COTTIGOT	Storage Room # 108	105 CMR 451.200	Food Storage, Preparation and
82. Widdulai Gyili		Storage Noom # 108	103 CIVIN 431.200	Service: Food preparation not in
				compliance with 105 CMR 590.000,
				interior of microwave oven dirty
92 I Building		Showers	105 CMR 451.123	· · · · · · · · · · · · · · · · · · ·
83. I Building		Silowers	103 CIVIN 431.123	Maintenance: Wall paint damaged in shower # 3
94 I Building		Showers	105 CMR 451.123	
84. I Building		Showers	105 CIVIK 451.125	Maintenance: Wall surface damaged
85. I Building		Showers	105 CMR 451.123	in shower # 4, 7, and 8 Maintenance: Soap scum on curtain
65. I bullullig		SHOWEIS	103 CIVIN 431.123	in showers # 1-10
86. I Building		Cells	105 CMR 451.141	Screens: Screen damaged in cell #
oo. I bullullig		Cells	103 CIVIN 431.141	171
87. J Building		Showers	105 CMR 451.123	Maintenance: Column rusted in
67. J Building		SHOWEIS	103 CIVIN 431.123	shower # 3 and 7
88. J Building		Showers	105 CMR 451.123	Maintenance: Walls dirty in shower #
oo. J builullig		SHOWEIS	103 CIVIN 431.123	3, 5, 8, and 10
89. J Building		Showers	105 CMR 451.123	Maintenance: Ceiling damaged in
J. J DUIIUIIIB		SHOWEIS	103 CIVIN 431.123	shower # 4, 5, 7, 8, 9, and 10
OO I Building		Cells	105 CMR 451.141	Screens: Screen damaged in cell #
90. J Building		CEIIS	103 CIVIN 431.141	273
01 K Building		Control Bathroom	10E CNAD AE1 122	
91. K Building		Control Bathroom	105 CMR 451.123	Maintenance: Ceiling vent cover
02 K D.::Ld::		Control Dath	10F CN4D 4F4 422	damaged
92. K Building		Control Bathroom	105 CMR 451.123	Maintenance: Wall dirty near sink
93. K Building		Showers	105 CMR 451.123	Maintenance: Walls dirty in shower #
			405 04	1
94. K Building		Showers	105 CMR 451.123	Maintenance: Column rusted in
				shower # 3, 4, 7, and 8
95. K Building		Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell
				# 305
96. L Building		Showers	105 CMR 451.123	Maintenance: Walls dirty in shower #
				9
97. L Building		Showers	105 CMR 451.123	Maintenance: Wall surface damaged
				in cell # 3, 4, and 8

98. L Building		Showers	105 CMR 451.123	Maintenance: Soap scum on curtain in shower # 1-10
99. L Building		Showers	105 CMR 451.123	Maintenance: Grout moldy in shower # 4, 5, 6, 7, and 8
100. L Building		Showers	105 CMR 451.123	Maintenance: Columns rusted in shower # 3 and 7
101. L Building		Chemical Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink leaking
102. MIU	Receiving	Medical Intake # 108	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink
103. Medical Entrance	Left Wing	Minor Proc # 173	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, sink out-of-order
104. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Soap scum on curtain in shower # 2 and 3
105. Medical Entrance	2nd Floor	Showers	105 CMR 451.130	Hot Water: Shower water temperature 89°F
106. Warehouse Building (outside)	Staff Gym	Female Bathroom/Locker Room	105 CMR 451.123	Maintenance: Wall damaged and bubbling
107. Warehouse Building (outside)	Staff Gym	Male Bathroom /Locker Room	105 CMR 451.123	Maintenance: Wall damaged in bathroom
108. Warehouse Building (outside)	Warehouse	Walk-In Freezer	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, wall dirty outside of freezer. Standard found in 105 CMR 590; FC 6- 501.12(A).
109. Warehouse Building (outside)	Warehouse	Exterior Cooler # 2	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; wall fan vent grate dusty. Standard found in 105 CMR 590; FC 6-501.12(A).
110. Warehouse Building (outside)	Warehouse	Exterior Cooler # 2	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling damaged near fans. Standard found in 105 CMR 590; FC 6-501.11.
111. Warehouse Building (outside)	Warehouse	Dry Storage Closet	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling damaged. Standard found in 105 CMR 590; FC 6-501.11.
112. Garage / Transport	Kitchen Area		105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

113. Garage / Transport	Kitchen Area	105 CMR 451.200	Food Storage, Preparation and Service: Food storage/preparation/service not in compliance with 105 CMR 590.000, refrigerator gaskets moldy
114. Garage / Transport	Bathroom # 2	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 91°F at handwash sink
115. Garage / Transport	Garage Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Deficiencies under the Recommended Standards (.300 series)

98 new deficiencies and 48 repeat deficiencies (indicated by an *) were found during the inspection.

1. Herman Building	Visiting Room	Inmate Visiting Side	105 CMR 451.353	Interior Maintenance: Countertop damaged in booth # 19
2. Herman Building	Visiting Room	Inmate Visiting Side	105 CMR 451.353*	Interior Maintenance: Countertop damaged in booth # 1 and 14
3. Old Receiving	Utility Closet		105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
4. Old Receiving	Utility Closet		105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
5. Old Receiving	Offices		105 CMR 451.353*	Interior Maintenance: Ceiling vent blocked in Parole Office
6. A1 Block	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
7. A1 Block	Control Booth	Cells (Upstairs)	105 CMR 451.360*	Protective Measures: Birds nest observed in window in cell # 9
8. A1 Block	Control Booth	Cells (Downstairs)	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 30
9. A1 Block	Control Booth	Cells (Downstairs)	105 CMR 451.360*	Protective Measures: Birds nest observed in window in cell # 24
10. A1 Block	Control Booth	Storage # 5	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
11. A1 Block	Control Booth	Cells (Upstairs)	105 CMR 451.353	Interior Maintenance: Walls dirty in cell # 2
12. A2 Block	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
13. A2 Block	Control Booth		105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged
14. A2 Block	Control Booth	Inmate Supply	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
15. A2 Block	Control Booth	Cells (Upstairs)	105 CMR 451.360	Protective Measures: Birds nest observed in window in cell # 45 and 48
16. A2 Block	Control Booth	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Slop sink dirty
17. A2 Block	Control Booth	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 52, 53, and 59
18. A2 Block	Control Booth	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 49
		-		-

19. MAXI B	Lower Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 129, 137, and 145
20. MAXI B	Lower Left Tier	Cells	105 CMR 451.353*	Interior Maintenance: Floor paint
ZU. IVIMAI D	Lower Left Her		103 CIVIN 431.333	damaged in cell # 123 and 127
21. MAXI B	Lower Right Tier	Showers	105 CMR 451.353*	Interior Maintenance: Seat missing at desk in cell # 142
22. MAXI B	Lower Disciplinary Unit		105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight outside Lower Disciplinary Unit
23. MAXI B	Upper Right Tier	Day Room	105 CMR 451.353*	Interior Maintenance: One seat missing at table
24. MAXI B	Upper Right Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 304, 312, 318, 320, 324, 326, 328, 330, 340, and 352
25. MAXI B	Upper Right Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 312 and 342
26. MAXI B	Upper Disciplinary	Unit	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 1
27. MAXI B	Upper Disciplinary	Unit	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 3
28. MAXI B	Upper Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 307, 309, 317, 325, 333, 335, and 347
29. MAXI B	Upper Left Tier	Cells	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 313
30. Main Gymnasium	Slop Sink Closet (Hallway)		105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty
31. Main Gymnasium	Basketball Court		105 CMR 451.350*	Structural Maintenance: Floor damaged
32. Main Gymnasium	Basketball Court		105 CMR 451.350*	Structural Maintenance: Walls damaged
33. Main Gymnasium	Booth		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
34. MAXI C	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
35. MAXI C	Lower Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 247
36. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor damaged under toilet in cell # 430
37. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 421, 439, and 443
38. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 419
39. MAXI C	Lower Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 219 and 224
40. MAXI C	Lower Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 231
41. MAXI C	Lower Tier	Slop Sink	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged
42. Programs	Offices		105 CMR 451.353	Interior Maintenance: Ceiling tiles missing

43. Deignan Building	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
44. Deignan	Control Booth		105 CMR 451.353*	Interior Maintenance: Floor paint
Building				damaged
45. Deignan	Control Booth		105 CMR 451.350*	Structural Maintenance: Window
Building				damaged
46. Deignan	Common Area		105 CMR 451.344*	Illumination in Habitable Areas:
Building				Light(s) not functioning properly, lights out
47. Deignan Building	Common Area		105 CMR 451.353*	Interior Maintenance: Ceiling fans dusty
48. Deignan Building	Upper West	Cells	105 CMR 451.350*	Structural Maintenance: Window broken in cell # 55
49. Deignan	Lower East	Cells	105 CMR 451.350*	Structural Maintenance: Window
Building				broken in cell # 14
50. Deignan	Upper East	Cells	105 CMR 451.350*	Structural Maintenance: Windowpane
Building				cracked in cell # 32
51. Deignan	Upper West	Slop Sink Room	105 CMR 451.353	Interior Maintenance: Wall paint
Building		·		damaged
52. Deignan Building	Upper East	Slop Sink Room	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
53. Mini 5	Mini 5 Building	Control Booth	105 CMR 451.353	Interior Maintenance: Floor paint
Building	_			damaged
54. Mini 5	Mini 5 Building	Office # 2	105 CMR 451.353	Interior Maintenance: Walls dirty
Building	_			·
55. Modular	Lobby	Mail Room	105 CMR 451.353	Interior Maintenance: Ceiling vents
Administration				dusty
Building				
56. Modular	Special Services C	orridor	105 CMR 451.353	Interior Maintenance: Wall damaged
Administration				near bathrooms
Building				
57. Modular	Special Services	Dispatch	105 CMR 451.353	Interior Maintenance: Ceiling vent
Administration	Corridor			dusty
Building				
58. Modular	2nd Floor	Copy Room	105 CMR 451.353	Interior Maintenance: Floor tile
Administration				damaged
Building				
59. Modular	Control 3		105 CMR 451.353*	Interior Maintenance: Floor damaged
Administration				throughout Control 3
Building				
60. Modular	Trap	Pedestrian	105 CMR 451.353*	Interior Maintenance: Floor tiles
Administration		Trap		damaged
Building				
61. Modular	Trap	Visits Waiting	105 CMR 451.353*	Interior Maintenance: Floor tiles
Administration		Area		damaged
Building				
62. Modular	Trap	Visits Waiting	105 CMR 451.353	Interior Maintenance: Wall damaged
Administration		Area		
Building				
63. Modular	Trap	Visits Waiting	105 CMR 451.350	Structural Maintenance: Exterior door
Administration		Area		not rodent and weathertight
Building				

64. Modular Administration Building	Trap	Visits Waiting Area	105 CMR 451.353	Interior Maintenance: Ceiling tiles dirty
65. Modular Gym	Modular Gym	Gym	105 CMR 451.353	Interior Maintenance: Wall paint damaged
66. Modular Gym	Modular Gym	Gym	105 CMR 451.360	Protective Measures: Birds nest observed in window
67. Modular Gym	Modular Gym	Gym	105 CMR 451.350*	Structural Maintenance: Back door not rodent and weathertight
68. Trailer # 3	Trailer # 3		105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged
69. H Building	H Building	Entire Building	105 CMR 451.353	Interior Maintenance: Ceiling tiles moldy and water damaged
70. H Building	H Building	All Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
71. H Building	H Building	Exterior	105 CMR 451.350*	Structural Maintenance: Exterior wall damaged
72. H Building	H Building	Cells	105 CMR 451.350*	Structural Maintenance: Unable to open or close cell windows
73. I Building	I Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling vent cover missing
74. I Building	I Building	Office	105 CMR 451.353	Interior Maintenance: Wall vent dusty
75. I Building	I Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 165
76. I Building	l Building	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 175, 182, 201, 204, 205, 210, and 211
77. I Building	I Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 206
78. I Building	I Building	Control Booth	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged
79. I Building	I Building	Cells	105 CMR 451.350*	Structural Maintenance: Unable to open or close cell windows
80. I Building	I Building	Cells	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 177
81. I Building	I Building	Cells	105 CMR 451.353*	Interior Maintenance: Seat missing at desk in cell # 196
82. I Building	I Building	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 201
83. J Building	J Building	Common Area	105 CMR 451.353	Interior Maintenance: Ceiling fans dusty
84. J Building	J Building	Common Area	105 CMR 451.353	Interior Maintenance: Wall fans dusty
85. J Building	J Building	Common Area	105 CMR 451.353*	Interior Maintenance: One seat cover damaged
86. J Building	J Building	Cells	105 CMR 451.350*	Structural Maintenance: Unable to open or close cell windows
87. J Building	J Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 252, 254, and 272
88. J Building	J Building	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 239 and 261

Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged
Building	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 293
Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 307, 311, 315, 327, 331, 335, and 339
Building	All Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
Building	Exterior	105 CMR 451.350*	Structural Maintenance: Black substance on exterior of building
Building	Control Booth	105 CMR 451.350*	Structural Maintenance: Window in door broken
Building	Cells	105 CMR 451.350*	Structural Maintenance: Unable to open or close cell windows
Building	Common Area	105 CMR 451.353	Interior Maintenance: Wall fans dusty
Building	Chemical Room	105 CMR 451.353	Interior Maintenance: Wet mop stored in sink
Building	All Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
eceiving	Janitor's Closet # 154	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
eceiving	Janitors Closet # 146	105 CMR 451.353	Interior Maintenance: Wall damaged
eft Wing	Medical Storage # 172	105 CMR 451.353	Interior Maintenance: Oxygen tanks not stored securely
nd Floor	Staff WC	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
taff Gym	Chemical Room	105 CMR 451.353	Interior Maintenance: Unlabeled chemical bottle
Varehouse	Chemical Room	105 CMR 451.353	Interior Maintenance: Chemical storage tables rusted and damaged
Varehouse	Chemical Room	105 CMR 451.353	Interior Maintenance: Floor damaged
t .	Building Ecciving Ecciving Ecciving Eft Wing End Floor Eaff Gym Varehouse	Building Cells Building Cells Building All Cells Building Exterior Building Control Booth Building Common Area Building Chemical Room Building All Cells Building All Cells Building Chemical Room Building Janitor's Closet # 154 ecciving Janitors Closet # 146 eft Wing Medical Storage # 172 Staff WC Caff Gym Chemical Room Varehouse Chemical Room	Building Cells 105 CMR 451.353 Building Cells 105 CMR 451.353 Building All Cells 105 CMR 451.320* Building Exterior 105 CMR 451.350* Building Control Booth 105 CMR 451.350* Building Cells 105 CMR 451.350* Building Common Area 105 CMR 451.353 Building Chemical Room 105 CMR 451.353 Building All Cells 105 CMR 451.353 Building All Cells 105 CMR 451.353 Building All Cells 105 CMR 451.353 Building Janitor's Closet 105 CMR 451.353 # 154 Exceiving Janitors Closet 105 CMR 451.353 # 146 Exterior 105 CMR 451.353 # 154 # 165 # 172 # 172 # 173 # 174 # 175 # 1

SECTION 2: Areas Found to be in Compliance

EHRS inspected 226 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 17 areas of the facility because they were either in use, locked, or under construction.

1. A1 Block	Control Booth	Cells (Upstairs)	Unable to Inspect Cell # 16 - Not in Use
2. A2 Block	Control Booth	Showers (Upstairs)	Unable to Inspect - In Use
3. Main Gymnasium	Inmate Toilets & Showers		Unable to Inspect - Not in Use
4. Main Gymnasium	Bathroom without Showers		Unable to Inspect - Closed
5. MAXI C	Upper Tier	Showers	Unable to Inspect Shower # 3 - In Use

6. Modular Administration Building	Special Services Corridor	Slop Sink Room	Unable to Inspect - Locked
7. Modular Administration	2nd Floor	Slop Sink Room	Unable to Inspect - Locked
Building			
8. Modular Administration	2nd Floor	Internal Affairs	Unable to Inspect - Locked
Building			
9. Modular Administration	Special Services Corridor	Special Services	Unable to Inspect - Locked
Building		Office	
10. Trailers	Trailer # 2 (Lieutenant Office	s)	Unable to Inspect - Locked
11. H Building	H Building	Office	Unable to Inspect - Not in Use
12. MIU	Receiving	Bathrooms # 151	Unable to Inspect Bathroom # 151 - In
		and 152	Use
13. Medical Entrance	2nd Floor	Showers	Unable to Inspect Shower # 2 - In Use
14. Other Areas	Work Release		Unable to Inspect - Closed
15. Other Areas	Tower		Unable to Inspect - Closed
16. MAXI B	Upper Disciplinary Unit		Unable to Inspect Cell # 4 - Not in Use
17. MAXI B	Lower Disciplinary Unit		Unable to Inspect - Not in Use

SECTION 4: Plan of Correction

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

- 1. Specific corrective steps to be taken
- 2. A timetable for the corrective actions for lager projects
- 3. The date by which correction will be achieved
- 4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
- 5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 687 at the time of the inspection.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" 105 CMR 451.000 is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found here.

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- <u>105 CMR 205.000</u>: Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- 105 CMR 480.000: Minimum requirements for the Management of Medical or Biological Waste
- 105 CMR 500.000: Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,

Amy Riordan, MPH

Senior Advisor, EHRS, BCEH



Commonwealth of Massachusetts

OFFICE OF THE SHERIFF

County of Worcester
Jail and House of Correction
5 Paul X. Tivnan Drive
West Boylston, Massachusetts 01583
Telephone: 508 854-1800

Lewis G. Evangelidis

FAX: 508 856-0465 TTY: 508 854-1888

SHERIFF

January 16, 2025

Cory J. Holmes
Senior Advisor for Indoor Air Quality Inspections, Audits, Outreach and Training
Division of Environmental Health Regulations and Standards
Massachusetts Department of Public Health
Bureau of Climate and Environmental Health
Donovan Health Building, 5 Randolph St.
Canton, MA 02021

Re: Plan of Correction - Worcester County House of Corrections and Jail

Dear Mr. Holmes:

Pursuant to the Department of Public Health (DPH) Regulations 105 CMR 451.000 – Minimum Health and Sanitations Standards and Inspection Procedures for Correctional Facilities, attached please find a corrected response to the inspection conducted on November 18, 2024.

This attachment addresses the exceptions noted in your correspondence, dated January 13, 2025.

If you require additional information, please feel free to contact me.

Sincerely.

Jason Fives Superintendent

cc: AS

AS Jason Butland Capt. Eric Locke Lt. Devon Walker

Diane M. Cook - Compliance Analyst

Area	Room	Item	Code	Description	Plan of Action	Deadline Date	Responsible Staff
1. Entrance	Superintendent's Office	Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty	Vent Cleaned		
2. Entrance	Male Staff Locker Room	Male Staff Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty	Vent Cleaned		
3. Entrance	Male Staff Locker Room	Male Staff Bathroom	105 CMR 451.123*	Maintenance: Heater damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz
4. Entrance	Control Room	Control Bathroom	105 CMR 451.123*	Maintenance: Ceiling vent dusty	Vent Cleaned		
5. Entrance	Control Room	Control Bathroom	105 CMR 451.123	Maintenance: Wet mop stored in bucket	Mop Removed		
6. Herman Building	Visiting Room	Male Handicapped Bathroom	105 CMR 451.123	Maintenance: Ceiling tiles water damaged	Damaged tiles to be replaced	February 28th, 2025	Hubacz
7. Herman Building	Visiting Room	Female Bathroom	105 CMR 451.123	Maintenance: Ceiling tiles damaged	Damaged tiles to be replaced	February 28th, 2025	Hubacz
8. Herman Building	Visiting Room	Female Bathroom	105 CMR 451.123	Maintenance: Wall paint damaged behind toilet # 2	Wall to be scraped and repainted	March 28th, 2025	Hubacz
9. Herman Building	Visiting Room	Male Bathroom	105 CMR 451.123*	Maintenance: Wall paint damaged above urinal	Wall to be scraped and repainted	March 28th, 2025	Hubacz
10. Old Receiving	Breakroom & Bathroom		105 CMR 451.123*	Maintenance: Walls dirty in bathroom	Walls Cleaned		
11. Central Control		Control Bathroom	105 CMR 451.123*	Maintenance: Ceiling tile missing	Missing tile to be replaced	February 28th, 2025	Hubacz
12. Central Control		Control Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty	Vent Cleaned		
13. A2 Block	Control Booth	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty	Microwave Cleaned		
14. A2 Block	Control Booth	Staff Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty	Microwave Cleaned		
15. A2 Block	Control Booth	Control Bathroom	105 CMR 451.123*	Maintenance: Ceiling vent dusty	Vent Cleaned		
16. A2 Block	Control Booth	Slop Sink (Downstairs)	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair; slop sink clogged	Maintenance to inspect and repair	March 28th, 2025	Hubacz
17. MAXI B	Control Bathroom		105 CMR 451.123*	Maintenance: Floor paint damaged	Floor to be scraped and repainted	March 28th, 2025	Dickhaut
18. MAXI B	Control Bathroom		105 CMR 451.123*	Maintenance: Floor and walls dirty	Bathroom Cleaned		

19. MAXI B	Lower Right Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty	Microwave Cleaned		
20. MAXI B	Lower Right Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged in shower # 1 and 2	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
21. MAXI B	Lower Right Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 2	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
22. MAXI B	Lower Left Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 2	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
23. MAXI B	Lower Left Tier	Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1	Shower Cleaned		
24. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Soap scum on curtain in shower # 2	Curtain to be replaced	January 28th, 2025	Dickhaut
25. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged outside shower # 1	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
26. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged in shower # 1 and 2	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
27. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Mold on walls in shower # 1 and 2	Showers Cleaned		
28. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1	Shower Cleaned		
29. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 1	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
30. MAXI B	Upper Right Tier	Showers	105 CMR 451.123*	Maintenance: Soap scum on curtain in shower # 1	Curtain to be replaced	January 28th, 2025	Dickhaut
31. MAXI B	Upper Right Tier	Showers	105 CMR 451.123*	Maintenance: Wall paint and epoxy damaged in shower # 1 and 2	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
32. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged in shower # 2	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
33. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Drain flies observed in shower # 2	Drains to be treated	January 28th, 2025	Hubacz
34. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Mold on wall in shower # 2	Shower Cleaned		
35. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 2	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
36. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 1	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
37. MAXI B	Upper Left Tier	Day Room	105 CMR 451.200	Destruction of Organisms of Public Health Concern; Cooking: Raw animal food not stirred properly during microwave cooking. Standard found in 105 CMR 590; FC 3-401.12(A).	Inmates do not have raw meat.		
38. Food Service	Main Kitchen	Control Bathroom	105 CMR 451.123	Maintenance: Wall tile damaged	Damaged tile to be replaced	February 28th, 2025	Hubacz

39. Food Service	Main Kitchen	Inmate Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: No hot water supplied to handwash sink	Maintenance to inspect and repair	March 28th, 2025	Hubacz
40. Food Service	Main Kitchen	Inmate Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 95°F at handwash sink	Maintenance to inspect and repair	March 28th, 2025	Hubacz
41. Food Service	Main Kitchen	Bakery	105 CMR 451.200	Maintenance and Corrected Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, standing water observed on floor below tables. Standard found in 105 CMR 590; FC 6-501.12(A).			
42. Food Service	Main Kitchen	Bakery	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; floor dirty behind ovens. Standard found in	Floor Cleaned		
43. Food Service	Main Kitchen	Entire Kitchen	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Premises not maintained free of insects, drain flies observed throughout kitchen. Standard found in 105 CMR 590; FC 6-	Drains Treated		
44. Food Service	Main Kitchen	Milk Cooler # 1	105 CMR 451.200	Preventing Contamination from the Premises; Food Storage: Milk stored below leaking condenser. Standard found in 105 CMR 590; FC 3-305.12	Condenser to be repaired	March 28th, 2025	Hubacz
45. Food Service	Main Kitchen	Produce Cooler # 2	105 CMR 451.200	Preventing Contamination from the Premises; Food Storage: Bread stored under leaking condenser. Standard found in 105 CMR 590: FC 3-305 12	Condenser to be repaired	March 28th, 2025	Hubacz
46. Food Service	Main Kitchen	Prep Cooler # 3	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; wall fan dusty. Standard found in 105 CMR	Fan Cleaned		
47. Food Service	Main Kitchen	Prep Cooler # 3	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; walls dirty. Standard found in 105 CMR 590;	Walls Cleaned		

48. Food Service	Main Kitchen	Prep Cooler # 3	105 CMR 451.200*	Maintenance and Operation; Premises,			
40. 1 000 SCI VICC	Wall Richell	Trep cooler # 3	103 CWW 431.200	Structure, Attachments, and Fixtures -			
				Methods: Facility not in good repair, floor tiles	D 147 4 1 1 1	E 1 20/1 2025	77.1
				damaged.	Damaged tiles to be replaced	February 28th, 2025	Hubacz
				Standard found in 105 CMR 590: FC			
				C FO1 11			
49. Food Service	Main Kitchen	Freezer # 4	105 CMR 451.200	Maintenance and Operation; Premises,			
				Structure, Attachments, and Fixtures -			
				Methods: Facility not cleaned as often as	Freezer to be cleaned	January 28th, 2025	Stone
				necessary, ice build-up on ceiling. Standard			
				found in			
50. Food Service	Main Kitchen	Dishwasher	105 CMR 451.200*	105 CMR 590- EC 6-501 12/A\ Maintenance and Operation; Premises,			
301100000011100		Area	200 0 1021200	Structure, Attachments, and Fixtures -			
		7.1.00		Methods: Facility not in good repair, ceiling	Ceiling to be scraped and	M 1 20d 2025	TT 1
				paint damaged above warewash machine.	repainted	March 28th, 2025	Hubacz
				Standard			
				found in 10E CMP E00, EC 6 E01 11			
51. Food Service	Main Kitchen	Dishwasher	105 CMR 451.200*	Maintenance and Operation, Equipment:			
		Area		Inadequate water temperature in the			
				mechanical warewashing machine (Pf).	Warewashing maching repaired		
				Standard found in 105 CMR 590; FC 4-			
				501.112(A)(2).			
52. Food Service	Main Kitchen	Dishwasher	105 CMR 451.200	Maintenance and Operation; Premises,			
		Area		Structure, Attachments, and Fixtures -			
				Methods: Facility not in good repair, ceiling	Ceiling to be scraped and	March 28th, 2025	Hubacz
				paint damaged above drains. Standard found in	repainted	, , , , ,	
				105			
53. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Maintenance and Operation; Premises,			
3311 334 361 1166		2.0	200 0 1021200	Structure, Attachments, and Fixtures -			
				Methods: Non- functional equipment not			
				repaired or removed from premises,	Warewashing maching repaired		
				dishwasher not working. Standard found in	warewashing maching repaired		
				105 CMR 590; FC 6-			
				501.114(A).			
54. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Maintenance and Operation; Corrected On-			
5 554 561 VICE	a Medicil	3.3	200 0.7111 102.200	Premises, Structure, site			
				Attachments, and Fixtures -			
				Methods: Facility not cleaned			
				as often as necessary, sink			
				sprayer dirty. Standard found			
				in 105 CMR 590;			
				FC 6-501.12(A).			
				1 C 0-301.12(A).			

Main Kitchen	3-Compartment Sink # 1 and 2	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, mold on sprayer head. Standard found in	Sprayer Cleaned		
Main Kitchen	Exterior Door	105 CMR 451.200	Design, Construction, and Installation; Functionality: Outer openings not protected against the entry of insects and rodents, exterior door not rodent and weather tight. Standard found in 105 CMR 590; FC 6-202.15(A)(3).	Maintenance to inspect and repair	March 28th, 2025	Hubacz
Main Kitchen	Inmate Bathroom	105 CMR 451.123*	Maintenance: Door frame damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz
Upper Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 1 and 2	Stainless Steel Inserts to be installed	March 28th, 2025	Hubacz
Lower Tier	Right-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty	Microwave Cleaned		
Female Staff Bat	hroom	105 CMR 451.123	Maintenance: Wall paint damaged near trash	Wall to be scraped and repainted	March 28th, 2025	Hubacz
Inmate Bathroor	m	105 CMR 451.123	Maintenance: Wall paint damaged behind toilet	Wall to be scraped and repainted	March 28th, 2025	Hubacz
Control Booth Ba	athroom	105 CMR 451.123	Maintenance: Ceiling vent dusty	Vent Cleaned		
Control Booth Ba	athroom	105 CMR 451.123	Maintenance: Floor paint damaged	Floor to be scraped and repainted	March 28th, 2025	Dickhaut
Common Area		105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000,	Microwave Cleaned		
Upper West	Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower #	Vent Cleaned		
Upper West	Bathroom	105 CMR 451.123	Maintenance: Basin damaged at handwash sink # 2	Maintenance to inspect and repair	March 28th, 2025	Hubacz
Upper West	Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water faucet missing at handwash sink # 4	Maintenance to inspect and repair	March 28th, 2025	Hubacz
Lower East	Showers	105 CMR 451.123	Maintenance: Light out in shower # 2	Light bulb to be replaced	February 28th, 2025	Hubacz
Lower East	Showers	105 CMR 451.123	Maintenance: Light rusted in shower # 1	Maintenance to inspect and repair	March 28th, 2025	Hubacz
Lower East	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, backflow preventor	Maintenance to inspect and repair	March 28th, 2025	Hubacz
Upper East	Showers	105 CMR 451.123	Maintenance: Ceiling panel rusted in shower # 1 and 2	Maintenance to inspect and repair	March 28th, 2025	Hubacz
	Main Kitchen Wain Kitchen Upper Tier Lower Tier Female Staff Bat Inmate Bathroor Control Booth Bat Control Booth Bat Common Area Upper West Upper West Upper West Lower East Lower East Lower East	Main Kitchen Exterior Door Main Kitchen Inmate Bathroom Upper Tier Showers Lower Tier Right-Side Day Room Inmate Bathroom Control Booth Bathroom Control Booth Bathroom Common Area Upper West Showers Upper West Bathroom Upper West Bathroom Lower East Showers Lower East Showers Lower East Showers	Main KitchenExterior Door105 CMR 451.200Main KitchenInmate Bathroom105 CMR 451.123*Upper TierShowers105 CMR 451.123Lower TierRight-Side Day Room105 CMR 451.200Female Staff Bathroom105 CMR 451.123Inmate Bathroom105 CMR 451.123Control Booth Bathroom105 CMR 451.123Control Booth Bathroom105 CMR 451.123Common Area105 CMR 451.200Upper WestShowers105 CMR 451.123Upper WestBathroom105 CMR 451.123Upper WestBathroom105 CMR 451.123Lower EastShowers105 CMR 451.123Lower EastShowers105 CMR 451.123Lower EastShowers105 CMR 451.123Lower EastSlop Sink Room105 CMR 451.130	Structure, Attachments, and Fixtures Methods: Facility not cleaned as often as necessary, mold on sprayer head. Standard found in 100 ms prayer prayer prayer. Standard found in 100 ms prayer. Standard found in 100 ms prayer prayer. Standard found prayer prayer. Standard found in 100 ms prayer. Standard fou	Structure, Attachments, and Extures - Methods: Facility not cleaned as often as necessary, mold on sprayer head. Standard found in	Structure, Attachments, and Extures Methods: Facility not cleaned as often as necessary, mold on sprayer head. Standard found in services of the service of the service of the services of th

72 Doignan	Unner East	Pathroom	105 CMR 451.123	Maintananca: Partition paint			
72. Deignan Building	Upper East	Bathroom	105 CWR 451.123	Maintenance: Partition paint damaged in toilet stall # 2	Partition to be scraped and repainted	March 28th, 2025	Hubacz
73. Mini 5 Building		Bathroom	105 CMR 451.123	Maintenance: Curtain moldy in shower # 1	Curtain to be replaced	January 28th, 2025	Dickhaut
74. Mini 5 Building		Bathroom	105 CMR 451.123	Maintenance: Caulking moldy	Bathroom Cleaned		
75. Modular Administration Building	Special Services Corridor	Female Locker Room	105 CMR 451.123	Maintenance: Lights out	Lightbulbs to be replaced	February 28th, 2025	Hubacz
76. Modular Administration Building	Special Services Corridor	Female Locker Room	105 CMR 451.123	Maintenance: Floor tiles damaged in hallway	Damaged tiles to be replaced	February 28th, 2025	Hubacz
77. Modular Administration Building	Special Services Corridor	Female Locker Room	105 CMR 451.123	Maintenance: Ceiling rusted	Maintenance to inspect and repair	March 28th, 2025	Hubacz
78. Modular Administration Building	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Floor dirty in shower # 1	Shower Cleaned		
79. Modular Administration Building	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Floor damaged in locker area	Maintenance to inspect and repair	March 28th, 2025	Hubacz
80. Modular Administration Building	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Ceiling tiles water damaged in locker area	Damaged tiles to be replaced	February 28th, 2025	Hubacz
81. Modular Administration Building	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Debris on floor	Floor Cleaned		
82. Modular Gym		Storage Room # 108	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty	Microwave Cleaned		
83. I Building		Showers	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 3	Wall to be scraped and repainted	March 28th, 2025	Hubacz
84. I Building		Showers	105 CMR 451.123	Maintenance: Wall surface damaged in shower # 4, 7, and 8	Maintenance to inspect and repair	March 28th, 2025	Hubacz
85. I Building		Showers	105 CMR 451.123	Maintenance: Soap scum on curtain in showers # 1-10	Curtains to be replaced	January 28th, 2025	Dowd
86. I Building		Cells	105 CMR 451.141	Screens: Screen damaged in cell # 171	Maintenance to inspect and repair	March 28th, 2025	Hubacz
87. J Building		Showers	105 CMR 451.123	Maintenance: Column rusted in shower # 3 and 7	Maintenance to inspect and repair	March 28th, 2025	Hubacz
88. J Building		Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 3, 5, 8, and 10	Showers Cleaned		
89. J Building		Showers	105 CMR 451.123	Maintenance: Ceiling damaged in shower # 4, 5, 7, 8, 9, and 10	Maintenance to inspect and repair	March 28th, 2025	Hubacz
90. J Building		Cells	105 CMR 451.141	Screens: Screen damaged in cell # 273	Maintenance to inspect and repair	March 28th, 2025	Hubacz
91. K Building		Control Bathroom	105 CMR 451.123	Maintenance: Ceiling vent cover damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz

92. K Building		Control Bathroom	105 CMR 451.123	Maintenance: Wall dirty near sink	Wall Cleaned		
93. K Building		Showers	105 CMR 451.123	Maintenance: Walls dirty in shower #	wan Cleaned		
		Showers	103 CWW 431.123	1	Shower Cleaned		
94. K Building		Showers	105 CMR 451.123	Maintenance: Column rusted in shower # 3, 4. 7. and 8	Maintenance to inspect and repair	March 28th, 2025	Hubacz
95. K Building		Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # 305	Mattress to be replaced	January 28th, 2025	Dowd
96. L Building		Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 9	Shower Cleaned		
97. L Building		Showers	105 CMR 451.123	Maintenance: Wall surface damaged in cell # 3, 4, and 8	Maintenance to inspect and repair	March 28th, 2025	Hubacz
98. L Building		Showers	105 CMR 451.123	Maintenance: Soap scum on curtain in shower # 1-10	Curtains to be replaced	January 28th, 2025	Dowd
99. L Building		Showers	105 CMR 451.123	Maintenance: Grout moldy in shower # 4, 5, 6, 7, and 8	Showers Cleaned		
100. L Building		Showers	105 CMR 451.123	Maintenance: Columns rusted in shower # 3 and 7	Maintenance to inspect and repair	March 28th, 2025	Hubacz
101. L Building		Chemical Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink leaking	Maintenance to inspect and repair	March 28th, 2025	Hubacz
102. MIU	Receiving	Medical Intake # 108	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink	Maintenance to inspect and repair	March 28th, 2025	Hubacz
103. Medical Entrance	Left Wing	Minor Proc # 173	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, sink out-of-order	Maintenance to inspect and repair	March 28th, 2025	Hubacz
104. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Soap scum on curtain in shower # 2 and 3	Curtains to be replaced	January 28th, 2025	Dowd
105. Medical Entrance	2nd Floor	Showers	105 CMR 451.130	Hot Water: Shower water temperature 89°F	Maintenance to inspect and repair	March 28th, 2025	Hubacz
106. Warehouse Building (outside)	Staff Gym	Female Bathroom/Locker Room	105 CMR 451.123	Maintenance: Wall damaged and bubbling	Maintenance to inspect and repair	March 28th, 2025	Hubacz
107. Warehouse Building (outside)	Staff Gym	Male Bathroom /Locker Room	105 CMR 451.123	Maintenance: Wall damaged in bathroom	Maintenance to inspect and repair	March 28th, 2025	Hubacz
108. Warehouse Building (outside)	Warehouse	Walk-In Freezer	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, wall dirty outside of freezer. Standard found in 105 CMR 590; FC 6- 501.12(A).	Freezer Cleaned		
109. Warehouse Building (outside)	Warehouse	Exterior Cooler # 2	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary; wall fan vent grate dusty. Standard found	Vent Cleaned		

110. Warehouse Building (outside)	Warehouse	Exterior Cooler # 2	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling damaged near fans. Standard found in 105 CMR 590; FC 6-501.11.	Ceiling secured with brace		
111. Warehouse Building (outside)	Warehouse	Dry Storage Closet	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling damaged. Standard found in 105 CMR 590; FC 6-	Maintenance to inspect and repair	March 28th, 2025	Hubacz
112. Garage / Transport	Kitchen Area		105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000,	Microwave Cleaned		
113. Garage / Transport	Kitchen Area		105 CMR 451.200	Food Storage, Preparation and Service: Food storage/preparation/service not in compliance with 105 CMR 590.000, refrigerator gaskets moldy	Gaskets to be replaced	March 28th, 2025	Stone
114. Garage / Transport	Bathroom # 2		105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 91°F at handwash sink	Maintenance to inspect and repair	March 28th, 2025	Hubacz
115. Garage / Transport	Garage Room		105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty.	Microwave Cleaned		
		andards (.300 series) ncies (indicated by an *) w	vere found during the insp	ection.			
1. Herman Building	Visiting Room	Inmate Visiting Side	105 CMR 451.353	Interior Maintenance: Countertop damaged in booth # 19	Maintenance to inspect and repair	March 28th, 2025	Hubacz
2. Herman Building	Visiting Room	Inmate Visiting Side	105 CMR 451.353*	Interior Maintenance: Countertop damaged in booth # 1 and 14	Maintenance to inspect and repair	March 28th, 2025	Hubacz
3. Old Receiving	Utility Closet		105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket	Mop Removed		
4. Old Receiving	Utility Closet		105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	Vent Cleaned		
5. Old Receiving	Offices		105 CMR 451.353*	Interior Maintenance: Ceiling vent blocked in Parole Office	Obstruction Removed		
6. A1 Block	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		

7. A1 Block	Control Booth	Cells (Upstairs)	105 CMR 451.360*	Protective Measures: Birds nest observed in window in cell # 9	Nest Removed		
8. A1 Block	Control Booth	Cells (Downstairs)	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 30	Obstruction Removed		
9. A1 Block	Control Booth	Cells (Downstairs)	105 CMR 451.360*	Protective Measures: Birds nest observed in window in cell # 24	Nest Removed		
10. A1 Block	Control Booth	Storage # 5	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket	Mop Removed		
11. A1 Block	Control Booth	Cells (Upstairs)	105 CMR 451.353	Interior Maintenance: Walls dirty in cell # 2	Walls Cleaned		
12. A2 Block	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
13. A2 Block	Control Booth		105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged	Damaged tiles to be replaced	February 28th, 2025	Hubacz
14. A2 Block	Control Booth	Inmate Supply	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	Vent Cleaned		
15. A2 Block	Control Booth	Cells (Upstairs)	105 CMR 451.360	Protective Measures: Birds nest observed in window in cell # 45 and 48	Nest Removed		
16. A2 Block	Control Booth	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Slop sink dirty	Sink Cleaned		
17. A2 Block	Control Booth	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 52, 53, and 59	Floors to be scraped and repainted	March 28th, 2025	Dickhaut
18. A2 Block	Control Booth	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 49	Wall to be scraped and repainted	March 28th, 2025	Dickhaut
19. MAXI B	Lower Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 129, 137, and 145	Floors to be scraped and repainted	March 28th, 2025	Dickhaut
20. MAXI B	Lower Left Tier	Cells	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 123 and 127	Floors to be scraped and repainted	March 28th, 2025	Dickhaut
21. MAXI B	Lower Right Tier	Showers	105 CMR 451.353*	Interior Maintenance: Seat missing at desk in cell # 142	Seat to be replaced	March 28th, 2025	Hubacz
22. MAXI B	Lower Disciplinary Unit		105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight outside Lower Disciplinary Unit	Maintenance to inspect and repair	March 28th, 2025	Hubacz
23. MAXI B	Upper Right Tier	Day Room	105 CMR 451.353*	Interior Maintenance: One seat missing at table	Seat to be replaced	March 28th, 2025	Hubacz
24. MAXI B	Upper Right Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 304, 312, 318, 320, 324, 326, 328, 330, 340, and 352	Walls to be scraped and repainted	March 28th, 2025	Dickhaut
25. MAXI B	Upper Right Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 312 and 342	Floors to be scraped and repainted	March 28th, 2025	Dickhaut
26. MAXI B	Upper Disciplinary Ur	nit	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 1	Floor to be scraped and repainted	March 28th, 2025	Dickhaut

27. MAXI B	Upper Disciplinary L	Jnit	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 3	Wall to be scraped and repainted	March 28th, 2025	Dickhaut
28. MAXI B	Upper Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 307, 309, 317, 325, 333, 335, and 347	Floors to be scraped and repainted	March 28th, 2025	Dickhaut
29. MAXI B	Upper Left Tier	Cells	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 313	Floor to be scraped and repainted	March 28th, 2025	Dickhaut
30. Main Gymnasium	Slop Sink Closet (Hallway)		105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty	Vent Cleaned		
31. Main Gymnasium	Basketball Court		105 CMR 451.350*	Structural Maintenance: Floor damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz
32. Main Gymnasium	Basketball Court		105 CMR 451.350*	Structural Maintenance: Walls damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz
33. Main Gymnasium	Booth		105 CMR 451.353*	Interior Maintenance: Floor tiles damaged	Damaged tiles to be replaced	February 28th, 2025	Hubacz
34. MAXI C	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
35. MAXI C	Lower Tier	Cells	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 247	Wall to be scraped and repainted	March 28th, 2025	Dickhaut
36. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor damaged under toilet in cell # 430	Floor to be scraped and repainted	March 28th, 2025	Dickhaut
37. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 421, 439, and 443	Floors to be scraped and repainted	March 28th, 2025	Dickhaut
38. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 419	Wall to be scraped and repainted	March 28th, 2025	Dickhaut
39. MAXI C	Lower Tier	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 219 and 224	Floors to be scraped and repainted	March 28th, 2025	Dickhaut
40. MAXI C	Lower Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 231	Wall to be scraped and repainted	March 28th, 2025	Dickhaut
41. MAXI C	Lower Tier	Slop Sink	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged	Ceiling to be scraped and repainted	March 28th, 2025	Dickhaut
42. Programs	Offices		105 CMR 451.353	Interior Maintenance: Ceiling tiles missing	Damaged tiles to be replaced	February 28th, 2025	Hubacz
43. Deignan Building	All Cells		105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
44. Deignan Building	Control Booth		105 CMR 451.353*	Interior Maintenance: Floor paint damaged	Floor to be scraped and repainted	March 28th, 2025	Dickhaut

45. Deignan Building	Control Booth		105 CMR 451.350*	Structural Maintenance: Window damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz
46. Deignan Building	Common Area		105 CMR 451.344*	Illumination in Habitable Areas: Light(s) not	_		
0 0				functioning properly, lights	Lightbulbs to be replaced	February 28th, 2025	Hubacz
				out			
47. Deignan Building	Common Area		105 CMR 451.353*	Interior Maintenance: Ceiling fans dusty	F (1 1 1	E-1 2041, 2025	II.d
					Fans to be cleaned	February 28th, 2025	Hubacz
48. Deignan	Upper West	Cells	105 CMR 451.350*	Structural Maintenance: Window	Maintenance to inspect and		
Building	• •			broken in cell # 55	repair	March 28th, 2025	Hubacz
		0.11	105 01 15 15 1 05 0 4		•		
49. Deignan Building	Lower East	Cells	105 CMR 451.350*	Structural Maintenance: Window broken in cell	Maintenance to inspect and	March 28th, 2025	Hubacz
				# 14	repair		
50. Deignan Building	Upper East	Cells	105 CMR 451.350*	Structural Maintenance: Windowpane cracked	Maintenance to inspect and	March 28th, 2025	Hubacz
				in cell # 32	repair	,	
51. Deignan	Upper West	Slop Sink Room	105 CMR 451.353	Interior Maintenance: Wall paint	Wall to be scraped and	March 28th, 2025	Dickhaut
Building				damaged	repainted	March 20th, 2023	Dickilaut
52. Deignan Building	Upper East	Slop Sink Room	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty			
					Vent Cleaned		
53. Mini 5	Mini 5 Building	Control Booth	105 CMR 451.353	Interior Maintenance: Floor paint	Electedes and		
	Willin 5 Bulluling	CONTROL BOOTH	103 CIVIN 431.333	•	Floor to be scraped and	March 28th, 2025	Dickhaut
Building				damaged	repainted		
54. Mini 5	Mini 5 Building	Office # 2	105 CMR 451.353	Interior Maintenance: Walls dirty	W/ II Cl		
Building					Walls Cleaned		
55. Modular	Lobby	Mail Room	105 CMR 451.353	Interior Maintenance: Ceiling vents dusty			
Administration	LODBY	Wall Room	103 CMM 431.333	interior Maintenance. Centing Vents dusty	Vents Cleaned		
Building					vend cionica		
56. Modular	Special Services Corrid	dor	105 CMR 451.353	Interior Maintenance: Wall damaged near			
Administration	Special Services corrie	201	103 CIVIN 431.333	bathrooms	Maintenance to inspect and	March 28th, 2025	Hubacz
Building				Datinoonis	repair	Waren Zoui, Zozo	Huouez
57. Modular	Special Services	Dispatch	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty			
Administration	Corridor	Dispatch	103 CIVIN 431.333	interior Maintenance. Ceiling Vent dusty	Vent Cleaned		
	Corridor				vent eleaned		
Building 58. Modular	2nd Floor	Copy Room	105 CMR 451.353	Interior Maintenance: Floor tile damaged			
	211u F1001	сору коопі	103 CIVIN 431.333	interior Maintenance. Floor the damaged	Damaged tile to be replaced	February 28th, 2025	Hubacz
Administration					Bamaged the to be replaced	1 coruar y 20th, 2023	Hubacz
<u>Ruilding</u> 59. Modular	Control 3		105 CMR 451.353*	Interior Maintenance: Floor damaged			
	Control 5		103 CIVIN 431.333	5	Maintenance to inspect and	March 28th, 2025	Hubacz
Administration				throughout Control 3	repair	March 20th, 2023	Hubacz
Building 60 Modular	Tran	Dodoctrian Tran	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged			
60. Modular	Trap	Pedestrian Trap	103 CIVIN 431.333°	Interior Maintenance: Floor tiles damaged	Damaged tiles to be replaced	February 28th, 2025	Hubacz
Administration					Damaged thes to be replaced	1 coruary 2011, 2023	HUUACZ
Building C1 Madular	Tran	\/iaita\\/-!t! ^	10F CMD 4F4 3F3*	Interior Maintenance, Floor tiles decree			
61. Modular	Trap	visits waiting Area	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged	Domogod tiles to be seed a	Folomiom, 2041, 2025	Harbar
Administration					Damaged tiles to be replaced	February 28th, 2025	Hubacz
Building	T	\	40F CMD 454 353	Intended Materials and Materia			
62. Modular	Trap	visits Waiting Area	105 CMR 451.353	Interior Maintenance: Wall damaged	Maintenance to inspect and	Manual 2041 2025	IIh
Administration					repair	March 28th, 2025	Hubacz
Ruilding	T	\	40F CMD 454 350	Charles and Market and an artist of the desired			
63. Modular	Trap	visits Waiting Area	105 CMR 451.350	Structural Maintenance: Exterior door not	Maintenance to inspect and	M 1 20:1 2025	TT 1
Administration				rodent and weathertight	repair	March 28th, 2025	Hubacz
Building					•		

64. Modular Administration Building	Trap	Visits Waiting Area	105 CMR 451.353	Interior Maintenance: Ceiling tiles dirty	Dirty tiles to be replaced	February 28th, 2025	Hubacz
65. Modular Gym	Modular Gym	Gym	105 CMR 451.353	Interior Maintenance: Wall paint damaged	Wall to be scraped and repainted	March 28th, 2025	Hubacz
66. Modular Gym	Modular Gym	Gym	105 CMR 451.360	Protective Measures: Birds nest observed in window	Nest Removed		
67. Modular Gym	Modular Gym	Gym	105 CMR 451.350*	Structural Maintenance: Back door not rodent and weathertight	Maintenance to inspect and repair	March 28th, 2025	Hubacz
68. Trailer # 3	Trailer # 3		105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged	Damaged tiles to be replaced	February 28th, 2025	Hubacz
69. H Building	H Building	Entire Building	105 CMR 451.353	Interior Maintenance: Ceiling tiles moldy and water damaged	Damaged tiles to be replaced	February 28th, 2025	Hubacz
70. H Building	H Building	All Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
71. H Building	H Building	Exterior	105 CMR 451.350*	Structural Maintenance: Exterior wall damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz
72. H Building	H Building	Cells	105 CMR 451.350*	Structural Maintenance: Unable to open or close cell windows	Renovation Plan awaiting DCAMM Funding	Will Keep Updated	Ennis
73. I Building	I Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling vent cover missing	Maintenance to inspect and repair	March 28th, 2025	Hubacz
74. I Building	I Building	Office	105 CMR 451.353	Interior Maintenance: Wall vent dusty	Vent Cleaned		
75. I Building	I Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 165	Obstruction Removed		
76. I Building	I Building	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 175, 182, 201, 204, 205. 210. and 211	Walls to be scraped and repainted	March 28th, 2025	Dowd
77. I Building	I Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 206	Ceiling to be scraped and repainted	March 28th, 2025	Dowd
78. I Building	I Building	Control Booth	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged	Damaged tiles to be replaced	February 28th, 2025	Hubacz
79. I Building	I Building	Cells	105 CMR 451.350*	Structural Maintenance: Unable to open or close cell windows	Renovation Plan awaiting DCAMM Funding	Will Keep Updated	Ennis
80. I Building	I Building	Cells	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 177	Ceiling to be scraped and repainted	March 28th, 2025	Dowd
81. I Building	I Building	Cells	105 CMR 451.353*	Interior Maintenance: Seat missing at desk in cell # 196	Seat to be replaced	March 28th, 2025	Hubacz
82. I Building	I Building	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 201	Obstruction Removed		
83. J Building	J Building	Common Area	105 CMR 451.353	Interior Maintenance: Ceiling fans dusty	Fans to be cleaned	February 28th, 2025	Hubacz
84. J Building	J Building	Common Area	105 CMR 451.353	Interior Maintenance: Wall fans dusty	Fans to be cleaned	February 28th, 2025	Hubacz

J Building	Common Area	105 CMR 451.353*	Interior Maintenance: One seat cover damaged	Seat to be replaced	March 28th, 2025	Hubacz
J Building	Cells	105 CMR 451.350*	Structural Maintenance: Unable to open or close cell windows	Renovation Plan awaiting DCAMM Funding	Will Keep Updated	Ennis
J Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 252, 254, and 272	Obstructions Removed		
J Building	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 239 and 261	Walls to be scraped and repainted	March 28th, 2025	Dowd
K Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged	Damaged tiles to be replaced	February 28th, 2025	Hubacz
K Building	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 293	Wall to be scraped and repainted	March 28th, 2025	Dowd
K Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 307, 311, 315, 327, 331, 335, and 339	Ceilings to be scraped and repainted	March 28th, 2025	Dowd
K Building	All Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
K Building	Exterior	105 CMR 451.350*	Structural Maintenance: Black substance on exterior of building	Building to be powerwashed	March 28th, 2025	Hubacz
K Building	Control Booth	105 CMR 451.350*	Structural Maintenance: Window in door broken	Maintenance to inspect and repair	March 28th, 2025	Hubacz
K Building	Cells	105 CMR 451.350*	Structural Maintenance: Unable to open or close cell windows	Renovation Plan awaiting DCAMM Funding	Will Keep Updated	Ennis
L Building	Common Area	105 CMR 451.353	Interior Maintenance: Wall fans dusty	Fans to be cleaned	February 28th, 2025	Hubacz
L Building	Chemical Room	105 CMR 451.353	Interior Maintenance: Wet mop stored in sink	Mop Removed	-	
L Building	All Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
Receiving	Janitor's Closet # 154	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket	Mop Removed		
Receiving	Janitors Closet # 146	105 CMR 451.353	Interior Maintenance: Wall damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz
Left Wing	Medical Storage # 172	105 CMR 451.353	Interior Maintenance: Oxygen tanks not stored securely	Oxygen tanks to be secured	January 28th, 2025	Carlo
e 2nd Floor	Staff WC	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	Vent Cleaned		
Staff Gym	Chemical Room	105 CMR 451.353	Interior Maintenance: Unlabeled chemical bottle	Label added		
	J Building J Building K Building K Building K Building K Building K Building K Building K Building L Building L Building L Building L Building L Building L Building L Building L Building L Building L Building L Building	J Building Cells J Building Cells K Building Control Booth K Building Cells K Building Exterior K Building Control Booth K Building Control Booth K Building Control Booth L Building Common Area L Building Chemical Room L Building All Cells Receiving Janitor's Closet # 154 Receiving Janitor's Closet # 146 Left Wing Medical Storage # 172 e 2nd Floor Staff WC	J Building Cells 105 CMR 451.350* J Building Cells 105 CMR 451.353 K Building Control Booth 105 CMR 451.353 K Building Cells 105 CMR 451.353 K Building Control Booth 105 CMR 451.320* K Building Control Booth 105 CMR 451.350* K Building Cells 105 CMR 451.350* L Building Common Area 105 CMR 451.353 L Building Chemical Room 105 CMR 451.353 L Building Chemical Room 105 CMR 451.353 L Building All Cells 105 CMR 451.353 Chemical Room 105 CMR 451.353 H 154 Receiving Janitor's Closet 105 CMR 451.353 # 154 Receiving Janitor's Closet 105 CMR 451.353 # 146 Left Wing Medical 105 CMR 451.353 Storage # 172 Pe 2nd Floor Staff WC 105 CMR 451.353	J Building Cells 105 CMR 451.350* Structural Maintenance: Unable to open or close cell windows J Building Cells 105 CMR 451.353 Interior Maintenance: Wall vent blocked in cell # 252, 254, and 272 J Building Cells 105 CMR 451.353 Interior Maintenance: Wall paint damaged in cell # 239 and 261 K Building Control Booth 105 CMR 451.353 Interior Maintenance: Ceiling tiles water damaged in cell # 239 and 261 K Building Cells 105 CMR 451.353 Interior Maintenance: Wall paint damaged in cell # 207, 311, 315, 327, 331, 335, and 339 K Building Cells 105 CMR 451.350* Interior Maintenance: Ceiling paint damaged in cell # 307, 311, 315, 327, 331, 335, and 339 K Building All Cells 105 CMR 451.350* Structural Maintenance: Window in door broken K Building Control Booth 105 CMR 451.350* Structural Maintenance: Window in door broken K Building Cells 105 CMR 451.350* Structural Maintenance: Unable to open or close cell windows L Building Common Area 105 CMR 451.353 Interior Maintenance: Wet mop stored in sink L Building Chemical Room 105 CMR 451.353 Interior Maintenance: Wet mop stored in sink L Building All Cells 105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket Receiving Janitor's Closet 105 CMR 451.353 Interior Maintenance: Wall damaged # 154 Receiving Janitor's Closet 105 CMR 451.353 Interior Maintenance: Wall damaged # 154 Receiving Janitors Closet 105 CMR 451.353 Interior Maintenance: Wall damaged # 166 Left Wing Medical 105 CMR 451.353 Interior Maintenance: Ceiling vent dusty Staff Gym Chemical Room 105 CMR 451.353 Interior Maintenance: Ceiling vent dusty	Building Cells 105 CMR 451.350* Structural Maintenance: Unable to open or close cell windows DCAMM Funding	J Bullding Cells 105 CMR 451.350° Structural Maintenance: Unable to open or close cell windows. J Bullding Cells 105 CMR 451.353 Interior Maintenance: Wall paint damaged in cell graphical and property of the cells 105 CMR 451.353 Interior Maintenance: Wall paint damaged in cell graphical and graphical graphical and graphical graphica

104. Warehouse Building (outside)	Warehouse	Chemical Room	105 CMR 451.353	Interior Maintenance: Chemical storage tables rusted and damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz
105. Warehouse Building (outside)	Warehouse	Chemical Room	105 CMR 451.353	Interior Maintenance: Floor damaged	Maintenance to inspect and repair	March 28th, 2025	Hubacz



MAURA T. HEALEY Governor KIMBERLEY DRISCOLL Lieutenant Governor

The Commonwealth of Massachusetts

Executive Office of Health and Human Services
Department of Public Health

Bureau of Climate and Environmental Health Division of Environmental Health Regulations and Standards

5 Randolph Street Canton, MA 02021 Phone: 617-624-6000

KATHLEEN E. WALSH Secretary

ROBERT GOLDSTEIN, MD, PhD Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

February 19, 2025

To: Shawn Jenkins, Commissioner, Department of Corrections
Kathleen E. Walsh, Secretary, Executive Office of Health and Human Services
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Noe Bard, Environmental Health and Safety Officer

(electronic copy)
(electronic copy)
(electronic copy)

Greetings,

Pursuant to 105 CMR 451.403, please find a Plan of Correction (POC) dated February 12, 2025 for Worcester County Jail and House of Corrections, along with the final POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Cory J. Holmes

Senior Advisor, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH
Terrence Reidy, Secretary, Executive Office of Public Safety and Security
Margaret Lee, Administrative Assistant, West Boylston Board of Health
Brianna Arruda, Director, Policy Development and Compliance Unit
Steven Hughes, Director, EHRS, BCEH

(electronic copy)
(electronic copy)



Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

The Commonwealth of Massachusetts

Executive Office of Health and Human Services Department of Public Health

Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards

5 Randolph Street, Canton, MA 02021 Phone: 781-828-7700 Fax: 781-828-770

KATHLEEN E. WALSH Secretary

ROBERT GOLDSTEIN, MD, PhD Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

January 31, 2025

Jason Rives, Superintendent
Worcester County House of Corrections and Jail
5 Paul X. Tivnan Drive
West Boylston, MA 01583 (electronic copy)

Re: Plan of Correction - Worcester County House of Corrections and Jail, West Boylston

Dear Superintendent Rives:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction in response to my inspection on November 18, 2024. After review, the EHRS finds the plan addresses all the deficiencies noted in the report with the following exceptions:

- In areas your facility was cited for the inability of cell windows to open and close, your Plan of Correction (POC) states "Renovation Plan awaiting DCAMM Funding". While the EHRS understands you do not have control over DCAMM's allotment of funds, we remain concerned with these areas and would ask to be kept apprised of the DCAMM funding progress. In addition, the EHRS asks that you provide a plan describing the interim measures you have implemented to ensure the health and safety of inmates and staff in said areas.
- In regards to the issue of cell size, the EHRS appreciates the limitations of correctional facilities and the need to accommodate the ever-increasing population; however we remain concerned with the inadequate cell size.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Cory J. Holmes

Senior Advisor, EHRS, BCEH

Cc: Noe Bard, Environmental Health and Safety Officer
Lieutenant Devon Walker, Policy, Procedure, Accreditation and Compliance

(electronic copy) (electronic copy)



Commonwealth of Massachusetts

OFFICE OF THE SHERIFF

County of Worcester
Jail and House of Correction
5 Paul X. Tivnan Drive
West Boylston, Massachusetts 01583
Telephone: 508 854-1800

Lewis G. Evangelidis Sheriff

FAX: 508 856-0465 TTY: 508 854-1888

February 12, 2025

Cory J. Holmes
Senior Advisor for Indoor Air Quality Inspections, Audits, Outreach and Training
Division of Environmental Health Regulations and Standards
Massachusetts Department of Public Health
Bureau of Climate and Environmental Health
Donovan Health Building, 5 Randolph St.
Canton, MA 02021

Re: Plan of Correction – Worcester County House of Corrections and Jail

Dear Mr. Holmes:

Pursuant to the Department of Public Health (DPH) Regulations 105 CMR 451.000 – Minimum Health and Sanitations Standards and Inspection Procedures for Correctional Facilities, attached please find a corrected response to the inspection conducted on November 18, 2024. In reply to the observations and recommendations, we note the following.

• The WCSO is awaiting funding from DCAMM for the process of replacing all windows for the H, I, J, K, and L Buildings. The project cost is estimated at \$17M and cannot be supported from the WCSO operating budget. Therefore, we require assistance from DCAMM. Parts for repair are unavailable. However, the modular housing unit windows will be allowed open to provide airflow into the facility after the outdoor temperatures are warm enough, typically by the end of April. The WCSO will continue to monitor temperatures and ensure that temperatures and airflow remain within the required range.

As always, we will continue to keep DPH apprised of any updates.

If you require additional information, please feel free to contact me.

Sincerely

Jason Rives Superintendent

cc:

AS Jason Butland Capt. Eric Locke Lt. Devon Walker Diane M. Cook – Compliance Analyst



MAURA T. HEALEY Governor KIMBERLEY DRISCOLL Lieutenant Governor

The Commonwealth of Massachusetts

Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health

Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards

5 Randolph Street Canton, MA 02021 Phone: 617-624-6000

KATHLEEN E. WALSH Secretary

ROBERT GOLDSTEIN, MD, PhD Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

February 19, 2025

Jason Rives, Superintendent
Worcester County House of Corrections and Jail
5 Paul X. Tivnan Drive
West Boylston, MA 01583 (electronic copy)

Re: Plan of Correction - Worcester County House of Corrections and Jail, West Boylston

Dear Superintendent Rives:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction dated February 12, 2025. After review, the EHRS finds the plan addresses all the deficiencies noted.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Cory J. Holmes

Senior Advisor, EHRS, BCEH

Cc: Noe Bard, Environmental Health and Safety Officer

Lieutenant Devon Walker, Policy, Procedure, Accreditation and Compliance

(electronic copy) (electronic copy)