

The Commonwealth of Massachusetts  
 Executive Office of Health and Human Services  
 Department of Public Health  
 Bureau of Climate and Environmental Health  
 Division of Environmental Health Regulations and Standards  
 67 Forest Street, Suite # 100  
 Marlborough, MA 01752  
 617-624-6000 | mass.gov/dph

**Maura T. Healey**  
 Governor

**Kiame Mahaniah, MD, MBA**  
 Secretary

**Kimberley Driscoll**  
 Lieutenant Governor

**Robert Goldstein, MD, PhD**  
 Commissioner

March 24, 2026

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)  
 Kiame Mahaniah, MD, MBA, Secretary, Executive Office of Health and Human Services (electronic copy)  
 Clerk, Massachusetts House of Representatives (electronic copy)  
 Clerk, Massachusetts Senate (electronic copy)  
 Lieutenant Jason Graham, Compliance Officer (electronic copy)


Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Hampshire County Jail and House of Correction, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Thomas Murphy  
 Environmental Analyst, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)  
 Gina K. Kwon, Secretary, Executive Office of Public Safety and Security (electronic copy)  
 Merridith O’Leary, Commissioner, Northampton Health and Human Services (electronic copy)  
 Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)  
 Patrick J. Cahillane, Sheriff (electronic copy)  
 Glen Sexton, Superintendent (electronic copy)



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards  
67 Forest Street, Suite # 100 Marlborough, MA 01752  
617-624-6000 | mass.gov/dph

**Maura T. Healey**  
Governor

**Kimberley Driscoll**  
Lieutenant Governor

**Kiame Mahaniah, MD, MBA**  
Secretary

**Robert Goldstein, MD, PhD**  
Commissioner

March 16, 2026

Patrick J. Cahillane, Sheriff  
Hampshire County Jail and House of Correction  
205 Rocky Hill Road  
Northampton, MA 01060 (electronic copy)

Re: Facility Inspection – Hampshire County Jail and House of Correction, Northampton

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Hampshire County Jail and House of Correction on March 11, 2026, accompanied by Lieutenant Jason Graham, Compliance Officer, and Lieutenant Bryan Luszczki, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 41 total deficiencies: 28 new deficiencies under the Required Standards (.100 and .200 series), 8 repeat deficiencies under the Required Standards, 4 new deficiencies under the Recommended Standards (.300 series), and 1 repeat deficiency under the Recommended Standards.

## Overview

**Section 1** provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

**Section 2** provides information on areas that EHRS found to be compliant.

**Section 3** documents the areas that EHRS did not inspect.

**Section 4** provides information on submitting a Plan of Correction for the identified deficiencies.

**Section 5** outlines observations and recommendations related to the inspection.

## SECTION 1: Health and Safety Deficiencies

### **Deficiencies under the Required Standards (.100 and .200 series)**

28 new deficiencies and 8 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Administration	Main Control	Control Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 103°F at handwash sink
2.	Special Management Unit	A Block	Upper Shower	105 CMR 451.123	Maintenance: Ceiling damaged
3.	Special Management Unit	A Block	Lower Shower	105 CMR 451.123	Maintenance: Ceiling damaged
4.	Special Management Unit	B Block	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # J19 and J23
5.	Special Management Unit	B Block	Upper Shower	105 CMR 451.123	Maintenance: Ceiling dirty
6.	Special Management Unit	B Block	Lower Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged
7.	Housing Units	Unit - 1	Shower	105 CMR 451.123	Maintenance: Floor damaged
8.	Housing Units	Unit – 2	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C9
9.	Housing Units	Unit – 2	Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged
10.	Housing Units	Unit – 3	Lower Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged
11.	Housing Units	Unit – 4	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C25, C26, and C27
12.	Housing Units	Unit – 4	Upper Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged
13.	Housing Units	Unit – 5	Upper Shower	105 CMR 451.123*	Maintenance: Floor paint damaged
14.	Housing Units	Unit – 5	Upper Shower	105 CMR 451.123	Maintenance: Mold observed on ceiling
15.	Housing Units	Unit – 5	Lower Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged
16.	Housing Units	Unit – 5	Lower Shower	105 CMR 451.123*	Maintenance: Mold observed on ceiling
17.	Housing Units	Unit – 6	Upper Shower	105 CMR 451.123*	Maintenance: Ceiling damaged
18.	Housing Units	Unit – 6	Upper Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged
19.	Housing Units	Unit – 6	Lower Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged
20.	Housing Units	Unit – 7	Upper Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged
21.	Housing Units	Unit – 8	Upper Shower	105 CMR 451.123	Maintenance: Soap scum on walls
22.	Housing Units	Unit – 8	Lower Shower	105 CMR 451.123	Maintenance: Mold observed on ceiling
23.	Lower Level Housing	Control Bathroom		105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 103°F at handwash sink
24.	Lower Level Housing	Housing Unit 2	Showers	105 CMR 451.123	Maintenance: Soap scum on floor

25.	Lower Level Housing	Housing Unit 2	Showers	105 CMR 451.123	Maintenance: Soap scum on walls
26.	Lower Level Housing	Housing Unit 2	Showers	105 CMR 451.123	Maintenance: Floor damaged
27.	Kitchen	Walk-in Freezer # 1		105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B).
28.	Kitchen	Dishwashing Area		105 CMR 451.200	Numbers and Capacities, Cleaning Agents and Sanitizers: Chemical sanitizers not available during all hours of operation. Standard found in 105 CMR 590; FC 4-303.11(B).
29.	Kitchen	Walk-in Cooler # 2		105 CMR 451.200*	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C).
30.	Kitchen	2-Compartment Sink		105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, 2-compartment sink out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A).
31.	Kitchen	Serving Line		105 CMR 451.200	Design and Construction; Cleanability: Multiuse food contact surface not smooth (Pf), serving trays in poor condition. Standard found in 105 CMR 590; FC 4-202.11(A)(1).
32.	Kitchen	Inmate Bathroom		105 CMR 451.123	Maintenance: Faucet fixture broken
33.	Modular Units	Culinary Arts Kitchen	Traulsen Cooler	105 CMR 451.200	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C).

### Deficiencies under the Recommended Standards (.300 series)

4 new deficiencies and 1 repeat deficiency (indicated by an \*) were found during the inspection:

1.	Outer Administration	Property Room		105 CMR 451.353	Interior Maintenance: Ceiling tile water damaged
2.	Housing Units	House 1 Control		105 CMR 451.353	Interior Maintenance: Floor damaged
3.	Housing Units	Unit – 5	Cells	105 CMR 451.353*	Interior Maintenance: Floor trim/coving damaged in cell # C41
4.	Housing Units	Unit - 7	Storage Closet (lower)	105 CMR 451.353	Interior Maintenance: Wall vent dusty
5.	Housing Units	Unit - 8	Storage Closet (lower)	105 CMR 451.353	Interior Maintenance: Wall vent dusty

### SECTION 2: Areas Found to be in Compliance

EHRIS inspected 196 additional areas of the facility which were found to be in compliance.

### **Section 3: Areas EHRS did not inspect**

EHRS did not inspect 14 areas of the facility because they were either in use, locked, or under construction.

1. Special Management Unit	A Block	Cells	Unable to Inspect – Cell # J1 out-of-order
2. Special Management Unit	A Block	Storage Closet (upper)	Unable to Inspect – Not in Use
3. Special Management Unit	B Block	Storage Closet (upper)	Unable to Inspect – Not in Use
4. Housing Units	Unit – 3	Storage Closet (upper)	Unable to Inspect – Not in Use
5. Housing Units	Unit – 4	Storage Closet (upper)	Unable to Inspect – Not in Use
6. Housing Units	Unit – 5	Storage Closet (upper)	Unable to Inspect – Not in Use
7. Housing Units	Unit – 6	Storage Closet (upper)	Unable to Inspect – Not in Use
8. Housing Units	Unit - 7	Storage Closet (upper)	Unable to Inspect – Not in Use
9. Housing Units	Unit - 8	Storage Closet (upper)	Unable to Inspect – Not in Use
10. Main Building Gym	Female Staff Locker Room		Unable to Inspect – Locked
11. Main Building Gym	Bathroom (located within Female Staff Locker Room)		Unable to Inspect – Locked
12. Main Building Gym	Control		Unable to Inspect - Locked
13. Modular Units	Old Dining Area/Case Worker’s Area	Dental Office	Unable to Inspect – Locked
14. Old Cane Shop Building	Testing Center		Unable to Inspect – Locked

### **SECTION 4: Plan of Correction**

This facility does not comply with the Department’s regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. A signature by the Superintendent or Administrator responsible for the plan. The signed plan should be submitted to my attention, at the address listed above.

### **SECTION 5: Observations and Recommendations**

1. The inmate population was 131 at the time of inspection.
2. During the inspection of the kitchen, it was observed that only one side of the exhaust system has a service tag attached. Please ensure that service tags are applied and visible on both sides of the exhaust system to confirm proper service and compliance.
3. During the inspection, the EHRS received a complaint about the condition of the serving trays in the kitchen. While in the kitchen the trays were inspected and found to be in poor condition. It was recommended that all trays showing signs of deterioration be removed from service and replaced - kitchen staff began removing the affected trays immediately. In the event that a sufficient number of replacement trays are not available, kitchen staff were advised to implement temporary alternative methods for serving until all trays have been adequately replaced.
4. The South Housing Unit in the Modular Building was unoccupied at the time of the inspection.

5. At the time of inspection, the EHRS recommended numbering all showers throughout the institution. This will assist the EHRS and County Sheriff's employees to better recognize where issues exist.
6. Hot water temperature range for handwash sinks is 110°F - 130°F.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Correctional Facilities" [105 CMR 451.000](#) available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,




Thomas Murphy  
Environmental Analyst, EHRS, BCEH



THE COMMONWEALTH OF MASSACHUSETTS

**Hampshire Sheriff's Office  
Jail & House of Correction**

P.O. Box 7000  
205 Rocky Hill Road  
Northampton, Massachusetts 01061-7000



***Sheriff***

PATRICK J. CAHILLANE

***Superintendent***

GLEN N. SEXTON

TELEPHONE  
(413) 584-5911  
FAX  
(413)-584-2695

Mr. Thomas Murphy  
Environmental Analyst, CSP, BEH  
Commonwealth of Massachusetts  
Executive Office Health & Human Services  
Department of Public Health  
Bureau of Environmental Health  
Community Sanitation Program  
23 Service Center Road  
Northampton, MA 01060


March 17<sup>th</sup>, 2026

Re: Hampshire County Jail & HOC Inspection dated March 16<sup>th</sup>, 2026

Dear Mr. Murphy,

At your request the following items have been addressed, please refer to the enclosed documentation for the corrective actions that have been taken.

Sincerely yours,

  
Patrick J. Cahillane  
Sheriff

## SECTION 1: Health and Safety Deficiencies

### Deficiencies under the Required Standards (.100 and .200 series)


28 new deficiencies and 8 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Administration	Main Control	Control Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 103°F at handwash sink Water Temperature will be fixed by maintenance department by 4/6/26
2.	Special Management Unit	A Block	Upper Shower	105 CMR 451.123	Maintenance: Ceiling damaged Ceiling to be repaired by maintenance department by 5/4/26
3.	Special Management Unit	A Block	Lower Shower	105 CMR 451.123	Maintenance: Ceiling damaged Ceiling to be repaired by maintenance department by 5/4/26
4.	Special Management Unit	B Block	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # J19 and J23 Mattresses replaced on 3/16/26
5.	Special Management Unit	B Block	Upper Shower	105 CMR 451.123	Maintenance: Ceiling dirty Ceiling to be painted by 4/16/26
6.	Special Management Unit	B Block	Lower Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27
7.	Housing Units	Unit - 1	Shower	105 CMR 451.123	Maintenance: Floor damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27
8.	Housing Units	Unit - 2	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C9 Mattress replaced on 4/16/26
9.	Housing Units	Unit - 2	Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27
10.	Housing Units	Unit - 3	Lower Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged Ceiling to be painted by 4/16/26
11.	Housing Units	Unit - 4	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C25, C26, and C27 Mattresses replaced on 3/16/26
12.	Housing Units	Unit - 4	Upper Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged Ceiling to be painted by 4/16/26
13.	Housing Units	Unit - 5	Upper Shower	105 CMR 451.123*	Maintenance: Floor paint damaged Floor to be painted by 4/16/26
14.	Housing Units	Unit - 5	Upper Shower	105 CMR 451.123	Maintenance: Mold observed on ceiling Ceiling to be cleaned and painted by 4/16/26
15.	Housing Units	Unit - 5	Lower Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be

appropriated in fiscal year 27

16.	Housing Units	Unit – 5	Lower Shower	105 CMR 451.123*	Maintenance: Mold observed on ceiling Ceiling to be cleaned and painted by 4/16/26
17.	Housing Units	Unit – 6	Upper Shower	105 CMR 451.123*	Maintenance: Ceiling damaged Ceiling to be repaired by 4/16/26
18.	Housing Units	Unit – 6	Upper Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27
19.	Housing Units	Unit – 6	Lower Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged Ceiling to be painted by 4/16/26
20.	Housing Units	Unit – 7	Upper Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27
21.	Housing Units	Unit – 8	Upper Shower	105 CMR 451.123	Maintenance: Soap scum on walls Shower cleaned 3/16/26
22.	Housing Units	Unit – 8	Lower Shower	105 CMR 451.123	Maintenance: Mold observed on ceiling Ceiling to be cleaned and painted by 4/16/26
23.	Lower Level Housing	Control Bathroom		105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 103°F at handwash sink Water Temperature will be fixed by maintenance department by 4/6/26
24.	Lower Level Housing	Unit 2	Showers	105 CMR 451.123	Maintenance: Soap scum on floor Shower cleaned on 3/16/26
25.	Lower Level Housing	Unit 2	Showers	105 CMR 451.123	Maintenance: Soap scum on walls Shower cleaned on 3/16/26
26.	Lower Level Housing	Unit 2	Showers	105 CMR 451.123	Maintenance: Floor damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27
28.	Kitchen	Dishwashing Area		105 CMR 451.200	Numbers and Capacities, Cleaning Agents and Sanitizers: Chemical sanitizers not available during all hours of operation. Standard found in 105 CMR 590; FC 4-303.11(B). Chemical sanitizers as of 3/16/256 are now available at all time of operation.
29.	Kitchen	Walk-in Cooler # 2		105 CMR 451.200*	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C). Walk-in cooler is being replaced on 4/6/26
30.	Kitchen	2-Compartment Sink		105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, 2-compartment sink out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A). 2-Compartment sink repaired on 3/13/26

31. Kitchen	Serving Line	105 CMR 451.200	Design and Construction; Cleanability: Multiuse food contact surface not smooth (Pf), serving trays in poor condition. Standard found in 105 CMR 590; FC 4-202.11(A)(1). Serving trays replaced by kitchen staff on 3/11/26
32. Kitchen	Inmate Bathroom	105 CMR 451.123	Maintenance: Faucet fixture broken Faucet to be fix by 4/6/26
33. Modular Units	Culinary Arts Kitchen Traulsen Cooler	105 CMR 451.200	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C). Equipment cleaned on 3/16/26
34. Outer Administration	Property Room	105 CMR 451.353	Interior Maintenance: Ceiling tile water damaged Ceiling tile to be replaced by 4/6/26
35. Housing Units	House 1 Control	105 CMR 451.353	Interior Maintenance: Floor damaged HSO has received two quote's from outside companies to replace the floor, expected replacement date 8/16/26
36. Housing Units	Unit – 5 Cells	105 CMR 451.353*	Interior Maintenance: Floor trim/coving damaged in cell # C41 Trim to be replaced by 4/6/26
37. Housing Units	Unit – 7 Storage Closet (lower)	105 CMR 451.353	Interior Maintenance: Wall vent dusty Wall vent cleaned as of 3/16/26



The Commonwealth of Massachusetts  
 Executive Office of Health and Human Services  
 Department of Public Health  
 Bureau of Climate and Environmental Health  
 Division of Environmental Health Regulations and Standards  
 67 Forest Street, Suite # 100  
 Marlborough, MA 01752  
 617-624-6000 | mass.gov/dph

**Maura T. Healey**  
 Governor

**Kiame Mahaniah, MD, MBA**  
 Secretary

**Kimberley Driscoll**  
 Lieutenant Governor

**Robert Goldstein, MD, PhD**  
 Commissioner

March 17, 2026

Patrick J. Cahillane, Sheriff  
 Hampshire County Jail and House of Correction  
 205 Rocky Hill Road  
 Northampton, MA 01060 (electronic copy)

Re: Plan of Correction - Hampshire County Jail and House of Correction, Northampton

Dear Sheriff Cahillane:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction in response to an inspection on March 11, 2026. After review, the EHRS finds the plan addresses all the deficiencies noted with the following exceptions:

1. Your Plan of Correction (POC) does not provide a date of completion for shower repair work which requires DCAMM funding. While the EHRS understands you do not have control over DCAMM’s allotment of funds, we cannot approve any item that does not identify a reasonable time frame for repair. The EHRS remains concerned with the uncorrected deficiencies and asks you to provide a plan describing the interim measures you have implemented to ensure the health and safety of inmates and staff. In addition, we ask to be kept apprised of the DCAMM funding progress.
2. Please provide a corrective action for the wall vent dusty in Unit 8 Lower Storage Closet.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Thomas Murphy  
 Environmental Analyst, EHRS, BCEH

cc: Glen Sexton, Superintendent  
 Lieutenant Jason Graham, Compliance Officer

(electronic copy)  
 (electronic copy)



THE COMMONWEALTH OF MASSACHUSETTS

**Hampshire Sheriff's Office  
Jail & House of Correction**

P.O. Box 7000  
205 Rocky Hill Road  
Northampton, Massachusetts 01061-7000



***Sheriff***

PATRICK J. CAHILLANE

***Superintendent***

GLEN N. SEXTON

TELEPHONE  
(413) 584-5911  
FAX  
(413)-584-2695

Mr. Thomas Murphy  
Environmental Analyst, CSP, BEH  
Commonwealth of Massachusetts  
Executive Office Health & Human Services  
Department of Public Health  
Bureau of Environmental Health  
Community Sanitation Program  
23 Service Center Road  
Northampton, MA 01060

March 17<sup>th</sup>, 2026

Re: Hampshire County Jail & HOC Inspection dated March 16<sup>th</sup>, 2026

Dear Mr. Murphy,

At your request the following items have been addressed, please refer to the enclosed documentation for the corrective actions that have been taken.

Sincerely yours,

A handwritten signature in blue ink that reads "Patrick J. Cahillane".

Patrick J. Cahillane  
Sheriff

## SECTION 1: Health and Safety Deficiencies


### **Deficiencies under the Required Standards (.100 and .200 series)**

28 new deficiencies and 8 repeat deficiencies (indicated by an \*) were found during the inspection:

1.	Administration	Main Control	Control Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 103°F at handwash sink Water Temperature will be fixed by maintenance department by 4/6/26
2.	Special Management Unit	A Block	Upper Shower	105 CMR 451.123	Maintenance: Ceiling damaged Ceiling to be repaired by maintenance department by 5/4/26
3.	Special Management Unit	A Block	Lower Shower	105 CMR 451.123	Maintenance: Ceiling damaged Ceiling to be repaired by maintenance department by 5/4/26
4.	Special Management Unit	B Block	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # J19 and J23 Mattresses replaced on 3/16/26
5.	Special Management Unit	B Block	Upper Shower	105 CMR 451.123	Maintenance: Ceiling dirty Ceiling to be painted by 4/16/26
6.	Special Management Unit	B Block	Lower Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27. Anticipated repairs to be completed 11/18/26.
7.	Housing Units	Unit - 1	Shower	105 CMR 451.123	Maintenance: Floor damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27. Anticipated repairs to be completed 11/18/26
8.	Housing Units	Unit - 2	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C9 Mattress replaced on 4/16/26
9.	Housing Units	Unit - 2	Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27. Anticipated repairs to be completed 11/18/26
10.	Housing Units	Unit - 3	Lower Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged Ceiling to be painted by 4/16/26
11.	Housing Units	Unit - 4	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C25, C26, and C27 Mattresses replaced on 3/16/26
12.	Housing Units	Unit - 4	Upper Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged Ceiling to be painted by 4/16/26
13.	Housing Units	Unit - 5	Upper Shower	105 CMR 451.123*	Maintenance: Floor paint damaged Floor to be painted by 4/16/26
14.	Housing Units	Unit - 5	Upper Shower	105 CMR 451.123	Maintenance: Mold observed on ceiling Ceiling to be cleaned and painted by 4/16/26

15.	Housing Units	Unit – 5	Lower Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27. Anticipated repairs to be completed 11/18/26
16.	Housing Units	Unit – 5	Lower Shower	105 CMR 451.123*	Maintenance: Mold observed on ceiling Ceiling to be cleaned and painted by 4/16/26
17.	Housing Units	Unit – 6	Upper Shower	105 CMR 451.123*	Maintenance: Ceiling damaged Ceiling to be repaired by 4/16/26
18.	Housing Units	Unit – 6	Upper Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27. Anticipated repairs to be completed 11/18/26
19.	Housing Units	Unit – 6	Lower Shower	105 CMR 451.123	Maintenance: Ceiling paint damaged Ceiling to be painted by 4/16/26
20.	Housing Units	Unit – 7	Upper Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27. Anticipated repairs to be completed 11/18/26
21.	Housing Units	Unit – 8	Upper Shower	105 CMR 451.123	Maintenance: Soap scum on walls Shower cleaned 3/16/26
22.	Housing Units	Unit – 8	Lower Shower	105 CMR 451.123	Maintenance: Mold observed on ceiling Ceiling to be cleaned and painted by 4/16/26
23.	Lower Level Housing	Control Bathroom		105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 103°F at handwash sink Water Temperature will be fixed by maintenance department by 4/6/26
24.	Lower Level Housing	Unit 2	Showers	105 CMR 451.123	Maintenance: Soap scum on floor Shower cleaned on 3/16/26
25.	Lower Level Housing	Unit 2	Showers	105 CMR 451.123	Maintenance: Soap scum on walls Shower cleaned on 3/16/26
26.	Lower Level Housing	Unit 2	Showers	105 CMR 451.123	Maintenance: Floor damaged Awaiting approval from DCAM for repairs to shower floors, anticipation that monies will be appropriated in fiscal year 27. Anticipated repairs to be completed 11/18/26
28.	Kitchen	Dishwashing Area		105 CMR 451.200	Numbers and Capacities, Cleaning Agents and Sanitizers: Chemical sanitizers not available during all hours of operation. Standard found in 105 CMR 590; FC 4-303.11(B). Chemical sanitizers as of 3/16/256 are now available at all time of operation.
29.	Kitchen	Walk-in Cooler # 2		105 CMR 451.200*	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C). Walk-in cooler is being replaced on 4/6/26

30.	Kitchen	2- Compartment Sink	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, 2-compartment sink out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A). 2-Compartment sink repaired on 3/13/26
31.	Kitchen	Serving Line	105 CMR 451.200	Design and Construction; Cleanability: Multiuse food contact surface not smooth (Pf), serving trays in poor condition. Standard found in 105 CMR 590; FC 4-202.11(A)(1). Serving trays replaced by kitchen staff on 3/11/26
32.	Kitchen	Inmate Bathroom	105 CMR 451.123	Maintenance: Faucet fixture broken Faucet to be fix by 4/6/26
33.	Modular Units	Culinary Arts Kitchen Traulsen Cooler	105 CMR 451.200	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C). Equipment cleaned on 3/16/26
34.	Outer Administration	Property Room	105 CMR 451.353	Interior Maintenance: Ceiling tile water damaged Ceiling tile to be replaced by 4/6/26
35.	Housing Units	House 1 Control	105 CMR 451.353	Interior Maintenance: Floor damaged HSO has received two quote's from outside companies to replace the floor, expected replacement date 8/16/26
36.	Housing Units	Unit – 5 Cells	105 CMR 451.353*	Interior Maintenance: Floor trim/coving damaged in cell # C41 Trim to be replaced by 4/6/26
37.	Housing Units	Unit – 7 Storage Closet (lower)	105 CMR 451.353	Interior Maintenance: Wall vent dusty Wall vent cleaned as of 3/16/26
38.	Housing Units	Unit – 8 Storage Closet (Lower)	105 CMR 451.353	Interior Maintenance: Wall vent dusty Wall vent cleaned as of 3/16/26



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Climate and Environmental Health  
Division of Environmental Health Regulations and Standards  
67 Forest Street, Suite # 100  
Marlborough, MA 01752  
617-624-6000 | mass.gov/dph

**Maura T. Healey**  
Governor

**Kiame Mahaniah, MD, MBA**  
Secretary

**Kimberley Driscoll**  
Lieutenant Governor

**Robert Goldstein, MD, PhD**  
Commissioner

March 23, 2026

Patrick J. Cahillane, Sheriff  
Hampshire County Jail and House of Correction  
205 Rocky Hill Road  
Northampton, MA 01060 (electronic copy)

Re: Plan of Correction - Hampshire County Jail and House of Correction, Northampton

Dear Sheriff Cahillane:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction dated March 17, 2026. After review, the EHRS finds the plan addresses all the deficiencies noted.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

A handwritten signature in blue ink, appearing to read "Thomas Murphy".

Thomas Murphy  
Environmental Analyst, EHRS, BCEH

cc: Glen Sexton, Superintendent  
Lieutenant Jason Graham, Compliance Officer

(electronic copy)  
(electronic copy)