

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
Phone: 617-624-6000

MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

KATHLEEN E. WALSH
Secretary

ROBERT GOLDSTEIN, MD, PhD
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

June 23, 2025

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)
Kathleen E. Walsh, Secretary, Executive Office of Health and Human Services (electronic copy)
Clerk, Massachusetts House of Representatives (electronic copy)
Clerk, Massachusetts Senate (electronic copy)
Michael Beland, Environmental Health and Safety Officer (electronic copy)


Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for MCI Framingham, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Hannah LeBeau
Environmental Health Inspector, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)
Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)
Bill Murphy, Director, Framingham Department of Public Health (electronic copy)
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)
Ryan Donlon, Superintendent (electronic copy)



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest St, Suite # 100
Marlborough, MA 01752
Phone: 617-624-5757

MAURA T. HEALEY
Governor

KIMBERLEY L. DRISCOLL
Lieutenant Governor

KATHLEEN E. WALSH
Secretary

ROBERT GOLDSTEIN, MD,
PhD Commissioner

Tel: 617-624-6000
www.mass.gov/dph

May 8, 2025

Ryan Donlon, Superintendent
MCI Framingham
99 Loring Drive
P.O. Box 9007
Framingham, MA 01704 (electronic copy)

Re: Facility Inspection – MCI Framingham

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of MCI Framingham on May 5 and 6, 2025 accompanied by Karen Allison, Training Officer, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 135 total deficiencies: 64 deficiencies under the Required Standards (.100 and .200 series), 47 repeat deficiencies under the Required Standards, 14 deficiencies under the Recommended Standards (.300 series), 10 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Main Building

Deficiencies under the Required Standards (.100 and .200 series)

33 new deficiencies and 10 repeat deficiencies (indicated by an *) were found during the inspection:

1. Lobby	Female Bathroom # C133A	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink leaking underneath
2. Visiting Area	Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food service not in compliance with 105 CMR 590.000, sandwiches in vending machine with use-by date of 5/2/25
3. Smith Food Service # 173		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, gaskets dirty on warmer. Standard found in 105 CMR 590; FC 6-501.12(A).
4. Smith Food Service # 173		105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, handwash sink dirty. Standard found in 105 CMR 590; FC 6-501.12(A).
5. Smith Food Service # 173		105 CMR 451.200	Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Wet cloth not stored in sanitizer solution. Standard found in 105 CMR 590; FC 3-304.14(B)(1).
6. Smith Food Service # 173		105 CMR 451.200	Numbers and Capacity; Handwashing Sinks: No hand drying method available at handwashing sink (Pf). Standard found in 105 CMR 590; FC 6-301.12.
7. Smith Food Service # 173		105 CMR 451.200	Numbers and Capacity; Handwashing Sinks: No soap at handwash sink (Pf). Standard found in 105 CMR 590; FC 6-301.11.
8. Smith Food Service # 173		105 CMR 451.200	Plumbing System; Operations and Maintenance: Handwashing sink used for an unapproved purpose (Pf); wet rag stored in handwash sink. Standard found in 105 CMR 590; FC 5-205.11(B).
9. Smith Food Service # 173		105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling tiles water damaged. Standard found in 105 CMR 590; FC 6-501.11.
10. Smith Hallway	Officer's Room # C174	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
11. ATU East	Lower Level Showers	105 CMR 451.123*	Maintenance: Paint damaged on left side of tub
12. ATU East	Lower Level Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # 3

13. ATU East	Lower Level Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # 1, 2, and 3
14. ATU East	Lower Level Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 1, 2, and 3
15. ATU East	Lower Level Showers	105 CMR 451.123	Maintenance: Baseboard moldy in shower # 3
16. ATU East	Upper Level Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 1 and 2
17. ATU East	Upper Level Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # 1, 2, and 3
18. ATU East	Upper Level Showers	105 CMR 451.123	Maintenance: Dead drain flies on ceiling in shower # 1
19. ATU East	Upper Level Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 2
20. ATU West	Lower Level Showers	105 CMR 451.123*	Maintenance: Paint damaged on right side of tub
21. ATU West	Lower Level Showers	105 CMR 451.123*	Maintenance: Caulking damaged in shower # 3
22. ATU West	Lower Level Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # 1, 2, and 3
23. ATU West	Lower Level Showers	105 CMR 451.123*	Maintenance: Floor dirty in shower # 2 and 3
24. ATU West	Lower Level Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # 1 and 3
25. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Standing water observed outside of showers
26. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Drain flies observed outside of showers
27. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Shower # 2 out-of-order
28. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 1 and 3
29. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # 3
30. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 3
31. SAU	Lower Level Showers	105 CMR 451.123	Maintenance: Shower # 1 out-of-order

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Lower Control		105 CMR 451.353	Interior Maintenance: Light shield missing
2. Admissions	Fingerprint Room # C148A	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged
3. Admissions	Storage Room # 107A	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged
4. Visiting Area	Janitor's Closet # 139A	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
5. Smith Hallway	Old Smith Dining Hall Room # 172-1	105 CMR 451.353*	Interior Maintenance: One tabletop damaged
6. ATU West	Lower Level Janitor's Closet	105 CMR 451.353	Interior Maintenance: Wet mop stored upside down
7. SAU	Common Area	105 CMR 451.353*	Interior Maintenance: Soap dispenser damaged in kitchenette
8. SAU	Common Area	105 CMR 451.353	Interior Maintenance: Countertop damaged around handwash sink at kitchenette

BAU

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Lower Level Showers	105 CMR 451.123	Maintenance: No curtain in shower # 113
2.	Lower Level Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 112
3.	Upper Level Showers	105 CMR 451.123*	Maintenance: Caulking moldy in shower # 207 and 208
4.	Cells	105 CMR 451.101	Blankets: Blanket damaged in cell # 104

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1.	Cells	105 CMR 451.346	Safe Wiring: Inappropriate use of temporary wiring, extension cord in doorway in cell # 112
----	-------	-----------------	---

HSU Building

Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1.	2nd Floor	Day Room	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator gaskets damaged and moldy
2.	2nd Floor	Showers	105 CMR 451.123*	Maintenance: Floor tiles damaged throughout
3.	2nd Floor	Showers	105 CMR 451.123*	Maintenance: Floor tiles damaged in shower # 1 and 2
4.	2nd Floor	Showers	105 CMR 451.123	Maintenance: Caulking damaged in shower # 1 and 3
5.	2nd Floor	Showers	105 CMR 451.123	Maintenance: Walls moldy outside of showers
6.	1st Floor	Infirmary Shower Room	105 CMR 451.123*	Maintenance: Grout deteriorated outside of showers
7.	1st Floor	Clinical Area Inmate Bathroom # 5	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover missing at handwash sink

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	2nd Floor	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 206
2.	2nd Floor	Storage Closet (with Slop Sink)	105 CMR 451.353	Interior Maintenance: Floor dirty
3.	1st Floor	Infirmary Medical Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in all cells

Cottages

Deficiencies under the Required Standards (.100 and .200 series)

5 new deficiencies and 13 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Laurel	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty
2.	Laurel	Handicapped Bathroom (A)	105 CMR 451.123*	Maintenance: Ceiling vent dusty

3.	Laurel	Cells (A)	105 CMR 451.103*	Mattresses: Mattress cover missing in cell # 3
4.	Laurel	Shower Room (B & C)	105 CMR 451.123	Maintenance: Floor damaged outside shower # 1
5.	Laurel	Shower Room (B & C)	105 CMR 451.123	Maintenance: Ceiling panels missing
6.	Laurel	Shower Room (B & C)	105 CMR 451.123	Maintenance: Ceiling panels not secure
7.	Laurel	Shower Room (B & C)	105 CMR 451.123	Maintenance: Grout dirty in shower # 3
8.	Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # 2 and 3
9.	Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Metal brackets rusted in shower # 3
10.	Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Baseboard damaged in shower # 1
11.	Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Floor damaged in shower # 1
12.	Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Mold on grout in shower # 1, 2, and 3
13.	Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Grout damaged in shower # 1, 2, and 3

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	Laurel	Kitchen Area	105 CMR 451.353*	Interior Maintenance: Soap dispenser damaged
2.	Algon	Cells (A)	105 CMR 451.353	Interior Maintenance: Ceiling tiles damaged in cell # 9

Old Administration Building

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	C Corridor	Culinary Arts	Staff Dining Room	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises, refrigerator out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A).
2.	C Corridor	Culinary Arts	Kitchen	105 CMR 451.200	Preventing Contamination after Receiving; Preventing Food and Ingredient Contamination: Raw animal food not stored separate from cooked ready-to-eat food (Pf), eggs stored over ready-to-eat food. Standard found in 105 CMR 590; FC 3-302.11(A)(1)(b). **Corrected On-Site**
3.	C Corridor	Main Serving Room	Inmate Dining Room	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, wall mounted fan dusty. Standard found in 105 CMR 590; FC 6-501.12(A).
4.	C Corridor	Main Serving Room	Janitor's Closet	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Wet mop stored on floor. Standard found in 105 CMR 590; FC 6-501.16.
5.	C Corridor	Main Serving Room	Handwash Sink	105 CMR 451.200	Plumbing System; Design, Construction and Installation: Insufficient hot water temperature at handwashing sinks (Pf), temperature recorded at 95°F. Standard found in 105 CMR 590; FC 5-202.12(A).

6.	C Corridor	Main Serving Room	Mechanical Warewashing Room	105 CMR 451.200	Plumbing System; Design, Construction, and Installation: Air gap missing between water supply inlet and the flood level rim of the sink, sink sprayer was laying in the sink (Pf). Standard found in 105 CMR 590; FC 5-202.13.
7.	2nd Floor	Education	Inmate Bathroom	105 CMR 451.117*	Toilet Fixtures: Toilet fixture # 1 and 2 dirty
8.	2nd Floor	Industries # 224	Staff Industries Bathroom	105 CMR 451.126*	Hot Water for Bathing and Hygiene: Hot water temperature 95°F at handwash sink
9.	3rd Floor	Chapel		105 CMR 451.141*	Screens: Screen missing

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Lobby	Janitor's Closet # A101 & A103		105 CMR 451.353	Interior Maintenance: Door knob missing in Janitor's Closet # A103
2.	B Corridor	Offices		105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged and missing
3.	C Corridor			105 CMR 451.353	Interior Maintenance: Floor tile damaged throughout
4.	D Corridor	Cosmetology # D141, D143, & D145		105 CMR 451.353	Interior Maintenance: Ceiling damaged
5.	2nd Floor	Industries # 224		105 CMR 451.353*	Interior Maintenance: Floor damaged in shipping and receiving room
6.	Basement	Laundry Area		105 CMR 451.353*	Interior Maintenance: Standing water on floor near laundry machines
7.	Basement	Laundry Area		105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight
8.	Basement	Property		105 CMR 451.353*	Interior Maintenance: Cleaning chemical stored in old food container

Central Kitchen

Deficiencies under the Required Standards (.100 and .200 series)

13 new deficiencies and 13 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Officer's Area	Inmate's Bathroom		105 CMR 451.123	Maintenance: Soap dispenser damaged
2.	Officer's Area	Inmate's Bathroom		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover missing at handwash sink
3.	Kitchen Area	3-Compartment Sink		105 CMR 451.200	Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Wet cloth not stored in sanitizer solution. Standard found in 105 CMR 590; FC 3-304.14(B)(1). **Corrected On-Site**
4.	Kitchen Area	Dumb Waiters		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises, dumb waiters out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A).

5.	Kitchen Area	Prep Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, interior of microwave oven dirty. Standard found in 105 CMR 590; FC 6-501.12(A).
6.	Kitchen Area	Prep Area	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, tape over floor drain where kettle was removed. Standard found in 105 CMR 590; FC 5-205.15(B).
7.	Kitchen Area	Broom Storage Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, standing water observed on floor. Standard found in 105 CMR 590; FC 6-501.12(A).
8.	Kitchen Area	Broom Storage Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, mold on wall around slop bucket refrigerator. Standard found in 105 CMR 590; FC 6-501.12(A).
9.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, walls dirty. Standard found in 105 CMR 590; FC 6-501.12(A).
10.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Refuse, Recyclables, and Returnables; Facilities on the Premises: Soiled receptacles not cleaned after use, swill bucket encrusted with food debris. Standard found in 105 CMR 590; FC 6-501.116(B).
11.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, mold on floor. Standard found in 105 CMR 590; FC 6-501.12(A).
12.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Preventing Contamination from the Premises; Food Storage: Food exposed to splash, dust, or other contamination, fans in cooler dusty. Standard found in 105 CMR 590; FC 3-305.11(A)(2). **Corrected On-Site**
13.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, wood on walls damaged and moldy. Standard found in 105 CMR 590; FC 6-501.11.
14.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, door dragging on floor. Standard found in 105 CMR 590; FC 6-501.11.
15.	Kitchen Area	Dry/Baking Storage	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, floor dirty behind orange storage containers. Standard found in 105 CMR 590; FC 6-501.12(A). **Corrected On-Site**

16. Kitchen Area	Refrigerator # 5	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Refrigerated time/temperature control for safety food prepared on site not clearly marked indicating the date or day by which the food shall be consumed or discarded (Pf). Standard found in 105 CMR 590; FC 3-501.17(A). **Corrected On-Site**
17. Kitchen Area	Refrigerator # 5	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food. Standard found in 105 CMR 590; FC 3-302.12. **Corrected On-Site**
18. Kitchen Area	Freezer # 6	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food. Standard found in 105 CMR 590; FC 3-302.12. **Corrected On-Site**
19. Kitchen Area	Freezer # 6	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Refrigerated time/temperature control for safety food prepared on site not clearly marked indicating the date or day by which the food shall be consumed or discarded (Pf). Standard found in 105 CMR 590; FC 3-501.17(A). **Corrected On-Site**
20. Back Room	Storage Area	105 CMR 451.200	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil/mold observed on interior surfaces of ice machine. Standard found in 105 CMR 590; FC 4-602.11(E)(4)(b). **Corrected On-Site**
21. Back Hallway	Walk-In Refrigerator	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Refrigerated time/temperature control for safety food prepared on site not clearly marked indicating the date or day by which the food shall be consumed or discarded (Pf). Standard found in 105 CMR 590; FC 3-501.17(A). **Corrected On-Site**
22. Back Hallway	Walk-In Refrigerator	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food. Standard found in 105 CMR 590; FC 3-302.12. **Corrected On-Site**
23. Food Manager's Office		105 CMR 451.200*	Materials for Construction and Repair; Indoor Areas: Ceiling surface not smooth and easily cleanable, ceiling paint damaged. Standard found in 105 CMR 590; FC 6-101.11(A)(1).
24. Food Manager's Office		105 CMR 451.200*	Materials for Construction and Repair; Indoor Areas: Floor surface not smooth and easily cleanable, floor paint damaged. Standard found in 105 CMR 590; FC 6-101.11(A)(1).

25. Food Manager's Office	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, mold on gaskets in Traulsen refrigerator. Standard found in 105 CMR 590; FC 4-501.11(B). **Corrected On-Site**
26. Food Manager's Office Bathroom	105 CMR 451.123*	Maintenance: Floor paint damaged

Power Plant

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Power Plant Building # 3	105 CMR 451.350*	Structural Maintenance: Stairs at entrance damaged and deteriorated
2. Power Plant Building # 3	105 CMR 451.360	Protective Measures: Birds nest in ceiling above Chief Engineer's Office

SECTION 2: Areas Found to be in Compliance

EHRS inspected 227 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 22 areas of the facility because they were either in use, locked, or under construction.

1. Main Building	Officer's Area	Mail Room # 116A	Unable to Inspect – Locked
2. Main Building	Officer's Area	Tool Control # 127A	Unable to Inspect – Locked
3. Main Building	Admissions	Bathroom # 103A (outside of Admissions)	Unable to Inspect – Locked
4. Main Building	Smith Hallway	Staff Bathroom # C154	Unable to Inspect – Locked
5. Main Building	ATU East	Trap	Day Room # C130 Unable to Inspect – Locked
6. Main Building	ATU East	Cell Block	Unit Sergeant's Office # 123 Unable to Inspect – Locked
7. Main Building	SAU	Trap	CPO's Office # 157 Unable to Inspect – Locked
8. BAU	Cell Block	Medical Room	Unable to Inspect – Locked
9. BAU	2nd Floor Office Area	EHSO Office (Blood Bourne Pathogen Training)	Unable to Inspect – Locked
10. Modular Building			Unable to Inspect – Closed
11. Brewster 1 and 2			Unable to Inspect – Closed
12. HSU Building	1st Floor	Infirmary	Biohazard Storage Room Unable to Inspect – Locked
13. HSU Building	1st Floor	Clinical Area	Treatment Room # 8 Unable to Inspect – In Use
14. Cottages	Laurel Building	Shower Room (A & B)	Unable to Inspect – In Use
15. Cottages	Algon Building	Handicapped Bathroom (A)	Unable to Inspect – Locked
16. Cottages	Algon Building	Shower Room (A & B)	Unable to Inspect – In Use
17. Old Administration Building	Lobby	Garden Tool Crib # A107	Unable to Inspect – Locked
18. Old Administration Building	Lobby	Work Office Tool Crib # A106	Unable to Inspect – Locked

19. Old Administration Building	Lobby	Storage Closet # A102	Unable to Inspect – Locked
20. Old Administration Building	A Corridor	Pre-Release Office & Bathroom (New Horizons) # A116 & A118	Unable to Inspect – Locked
21. Old Administration Building	C Corridor	Store Room	Unable to Inspect – Locked
22. Old Administration Building	D Corridor	Psychology Corridor	Unable to Inspect – Under Construction

SECTION 4: Plan of Correction

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 229 at the time of inspection.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#) is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Hannah LeBeau
Environmental Health Inspector, EHRS, BCEH



MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

The Commonwealth of Massachusetts
Executive Office of Public Safety & Security
Department of Correction
MCI Framingham
99 Loring Drive, P.O. Box 9007
Framingham, MA 01701
Tel: (508) 532-5100
www.mass.gov/doc



TERRENCE M. REIDY
Secretary

SHAWN P. JENKINS
Commissioner

May 22, 2025

Hannah LeBeau, Environmental Health Inspector, EHRS, BCEH
Department of Public Health
Community Sanitation Program
67 Forest Street, Suite #100
Marlborough, MA 01752

Re: MCI Framingham – Plan of Correction

Dear Ms. LeBeau,

Attached please find MCI-Framingham's response to violations noted in your letter dated May 8, 2025.

Please feel free to contact me if you should have any additional questions or concerns.

Sincerely,


Ryan Donlon
Superintendent

RD/pb

cc: Shawn Jenkins, Commissioner, DOC
Brianna Arruda, Director, Policy Development and Compliance Unit, DOC
Michael Beland, EHSO, MCI Framingham
File

SECTION 1: Health and Safety Deficiencies

Main Building

Deficiencies under the Required Standards (.100 and .200 series)

33 new deficiencies and 10 repeat deficiencies (indicated by an *) were found during the inspection:

1. Lobby	Female Bathroom # C133A	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink leaking underneath The drainpipe will be repaired with an anticipation date of 5/30/25.
2. Visiting Area	Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food service not in compliance with 105 CMR 590.000, sandwiches in vending machine with use-by date of 5/2/25 The expired food was removed by the vendor on 5/8/25.
3. Smith Food Service # 173		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, gaskets dirty on warmer. Standard found in 105 CMR 590; FC 6-501.12(A). The gaskets were cleaned on 5/21/25 and will continue to be cleaned weekly by an inmate work crew.
4. Smith Food Service # 173		105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, handwash sink dirty. Standard found in 105 CMR 590; FC 6-501.12(A). The handwash sink was cleaned on 5/5/25.
5. Smith Food Service # 173		105 CMR 451.200	Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Wet cloth not stored in sanitizer solution. Standard found in 105 CMR 590; FC 3-304.14(B)(1). A new wet cloth was placed in sanitizer solution on 5/5/25.
6. Smith Food Service # 173		105 CMR 451.200	Numbers and Capacity; Handwashing Sinks: No hand drying method available at handwashing sink (Pf). Standard found in 105 CMR 590; FC 6-301.12. Paper towels were stored next to the handwashing sink on 5/5/25.
7. Smith Food Service # 173		105 CMR 451.200	Numbers and Capacity; Handwashing Sinks: No soap at handwash sink (Pf). Standard found in 105 CMR 590; FC 6-301.11. Soap was added to the soap dispenser on 5/5/25.
8. Smith Food Service # 173		105 CMR 451.200	Plumbing System; Operations and Maintenance: Handwashing sink used for an unapproved purpose (Pf); wet rag stored in

			handwash sink. Standard found in 105 CMR 590; FC 5-205.11(B). Wet ragged removed from handwash sink on 5/5/25.
9. Smith Food Service # 173		105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling tiles water damaged. Standard found in 105 CMR 590; FC 6-501.11. Ceiling tiles will be replaced with an anticipated date of 5/30/25.
10. Smith Hallway	Officer's Room # C174	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty The microwave was cleaned on 5/5/25.
11. ATU East	Lower Level Showers	105 CMR 451.123*	Maintenance: Paint damaged on left side of tub The left side of the tube will be repainted with an anticipated date of 6/7/25.
12. ATU East	Lower Level Showers	105 CMR 451.123*	Maintenance: Floor paint damaged in shower # 3 The shower floor will be repainted with an anticipated date of 6/7/25.
13. ATU East	Lower Level Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # 1, 2, and 3 The dirty caulking was cleaned on 5/8/25. It will be removed and recalked with an anticipated date of 6/14/25.
14. ATU East	Lower Level Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 1, 2, and 3 Shower floors cleaned on 5/5/25.
15. ATU East	Lower Level Showers	105 CMR 451.123	Maintenance: Baseboard moldy in shower # 3 The baseboard will be replaced with an anticipated date of 6/14/25.
16. ATU East	Upper Level Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 1 and 2 Shower floors cleaned on 5/5/25.
17. ATU East	Upper Level Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # 1, 2, and 3 The dirty caulking was cleaned on 5/8/25. It will be removed and recalked with an anticipated date of 6/14/25.
18. ATU East	Upper Level Showers	105 CMR 451.123	Maintenance: Dead drain flies on ceiling in shower # 1 Drain flies removed on 5/5/25.
19. ATU East	Upper Level Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 2 The shower floor will be repainted with an anticipated date of 6/14/25.
20. ATU West	Lower Level Showers	105 CMR 451.123*	Maintenance: Paint damaged on right side of tub The right side of the tube will be repainted with an anticipated date of 6/7/25.
21. ATU West	Lower Level Showers	105 CMR 451.123*	Maintenance: Caulking damaged in shower # 3

22. ATU West	Lower Level Showers	105 CMR 451.123*	The damage caulking will be removed and recalked with an anticipated date of 6/14/25. Maintenance: Floor paint damaged in shower # 1, 2, and 3 The shower floor will be repainted with an anticipated date of 6/14/25.
23. ATU West	Lower Level Showers	105 CMR 451.123*	Maintenance: Floor dirty in shower # 2 and 3 The shower floor cleaned on 5/5/25.
24. ATU West	Lower Level Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # 1 and 3 The dirty caulking was cleaned on 5/8/25. It will be removed and recalked with an anticipated date of 6/14/25
25. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Standing water observed outside of showers Standing water removed on 5/5/25.
26. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Drain flies observed outside of showers Drain flies removed from area on 5/5/25. Pest control will monitor.
27. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Shower # 2 out-of-order Shower back online on 5/21/25.
28. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 1 and 3 The shower floor will be repainted with an anticipated date of 6/14/25.
29. ATU West	Upper Level Showers	105 CMR 451.123	
30. ATU West	Upper Level Showers	105 CMR 451.123	Maintenance: Caulking dirty in shower # 3 The dirty caulking was cleaned on 5/8/25. It will be removed and recalked with an anticipated date of 6/14/25
31. SAU	Lower Level Showers	105 CMR 451.123	Maintenance: Shower # 1 out-of-order Shower back online on 5/8/25.

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Lower Control		105 CMR 451.353	Interior Maintenance: Light shield missing Light shield added on 5/8/25.
2. Admissions	Fingerprint Room # C148A	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged Ceiling tiles will be replaced with an anticipated date of 5/22/25.
3. Admissions	Storage Room # 107A	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged Ceiling tiles will be replaced with an anticipated date of 5/22/25.
4. Visiting Area	Janitor's Closet # 139A	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty The ceiling vent was cleaned on 5/20/25.
5. Smith Hallway	Old Smith Dining Hall Room # 172-1	105 CMR 451.353*	Interior Maintenance: One tabletop damaged The table was replaced on 5/21/25.

6. ATU West	Lower Level Janitor's Closet	105 CMR 451.353	Interior Maintenance: Wet mop stored upside down The wet mopped was repositioned on 5/5/25.
7. SAU	Common Area	105 CMR 451.353*	Interior Maintenance: Soap dispenser damaged in kitchenette The soap dispenser was replaced on 5/8/25.
8. SAU	Common Area	105 CMR 451.353	Interior Maintenance: Countertop damaged around handwash sink at kitchenette The countertop will be removed with an anticipation date of 5/23/25.

BAU

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Lower Level Showers	105 CMR 451.123	Maintenance: No curtain in shower # 113 Curtain added to shower on 5/8/25.
2. Lower Level Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 112 The shower walls were cleaned on 5/5/25
3.	105 CMR 451.123*	Maintenance: Caulking moldy in shower # 207 and 208 The moldy caulking was cleaned on 5/8/25 and will be recalked with an anticipated date of 6/14/25
4. Cells	105 CMR 451.101	Blankets: Blanket damaged in cell # 104 The blanket was replaced on 5/5/25.

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1. Cells	105 CMR 451.346	Safe Wiring: Inappropriate use of temporary wiring, extension cord in doorway in cell # 112 The extension cord was removed on 5/6/25.
----------	-----------------	---

HSU Building

Deficiencies under the Required Standards (.100 and .200 series)

4 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1. 2nd Floor Day Room	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator gaskets damaged and moldy Gaskets cleaned on 5/20/25.
2. 2nd Floor Showers	105 CMR 451.123*	Maintenance: Floor tiles damaged throughout The floor tiles will be replaced/repared with an anticipated date of 6/15/25.
3. 2nd Floor Showers	105 CMR 451.123*	Maintenance: Floor tiles damaged in shower # 1 and 2 The floor tiles will be replaced/repared with an anticipated date of 6/15/25.
4. 2nd Floor Showers	105 CMR 451.123	Maintenance: Caulking damaged in shower # 1 and 3

5.	2nd Floor	Showers		105 CMR 451.123	The damage caulking will be removed and recalked with an anticipated date of 6/14/25 Maintenance: Walls moldy outside of showers The walls were cleaned on 5/6/25.
6.	1st Floor	Infirmary	Shower Room	105 CMR 451.123*	Maintenance: Grout deteriorated outside of showers The Grout will be replaced/repared with an anticipated date of 6/14/25.
7.	1st Floor	Clinical Area	Inmate Bathroom # 5	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover missing at handwash sink A drain cover was added on 5/21/25.

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	2nd Floor	Cells		105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 206 Debris that was blocking vent was removed on 5/6/25.
2.	2nd Floor	Storage Closet (with Slop Sink)		105 CMR 451.353	Interior Maintenance: Floor dirty The floor was cleaned on 5/6/25.
3.	1st Floor	Infirmary	Medical Cells	105 CMR 451.320*	Cell Size: Inadequate floor space in all cells Inmates were removed out of the unit to comply with 105 CMR 451.320 on 5/6/25.

Cottages

Deficiencies under the Required Standards (.100 and .200 series)

5 new deficiencies and 13 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Laurel	Control Bathroom		105 CMR 451.123	Maintenance: Ceiling vent dusty The ceiling vent was cleaned on 5/6/25
2.	Laurel	Handicapped Bathroom (A)		105 CMR 451.123*	Maintenance: Ceiling vent dusty The ceiling vent was cleaned on 5/6/25
3.	Laurel	Cells (A)		105 CMR 451.103*	Mattresses: Mattress cover missing in cell # 3 A new mattress was replaced on 5/7/25.
4.	Laurel	Shower Room (B & C)		105 CMR 451.123	Maintenance: Floor damaged outside shower # 1 The floor will be repaired with an anticipation date of 6/27/25.
5.	Laurel	Shower Room (B & C)		105 CMR 451.123	Maintenance: Ceiling panels missing Ceiling panels were added on 5/9/25.
6.	Laurel	Shower Room (B & C)		105 CMR 451.123	Maintenance: Ceiling panels not secure Ceiling panels were resecured on 5/9/25.
7.	Laurel	Shower Room (B & C)		105 CMR 451.123	Maintenance: Grout dirty in shower # 3 Grout was cleaned on 5/7/25. Grout will be repaired/replaced with an anticipated date of 6/27/25.
8.	Algon	Shower Room (B & C)		105 CMR 451.123*	Maintenance: Floor paint damaged in shower # 2 and 3 The shower floor will be repainted with an anticipated date of 6/27/25.
9.	Algon	Shower Room (B & C)		105 CMR 451.123*	Maintenance: Metal brackets rusted in shower # 3

			The metal brackets will be replaced with an anticipated date of 6/27/25.
10. Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Baseboard damaged in shower # 1 The baseboard will be repaired/replaced with an anticipated date of 6/27/25.
11. Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Floor damaged in shower # 1 The floor will be repaired with an anticipated date of 6/27/25.
12. Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Mold on grout in shower # 1, 2, and 3 Mold on Grout was cleaned on 5/7/25.
13. Algon	Shower Room (B & C)	105 CMR 451.123*	Maintenance: Grout damaged in shower # 1, 2, and 3 Grout will be repaired/replaced with an anticipated date of 6/27/25.

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Laurel	Kitchen Area	105 CMR 451.353*	Interior Maintenance: Soap dispenser damaged Soap dispenser was replaced on 5/6/25.
2. Algon	Cells (A)	105 CMR 451.353	Interior Maintenance: Ceiling tiles damaged in cell # 9 The ceiling tiles will be replaced with an anticipated date of 5/23/25.

Old Administration Building

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. C Corridor	Culinary Arts	Staff Dining Room	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises, refrigerator out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A). The refrigerator will be removed with an anticipated date of 6/6/25.
2. C Corridor	Culinary Arts	Kitchen	105 CMR 451.200	Preventing Contamination after Receiving; Preventing Food and Ingredient Contamination: Raw animal food not stored separate from cooked ready-to-eat food (Pf), eggs stored over ready-to-eat food. Standard found in 105 CMR 590; FC 3-302.11(A)(1)(b). **Corrected On-Site**
3. C Corridor	Main Serving Room	Inmate Dining Room	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, wall mounted fan dusty. Standard found in 105 CMR 590; FC 6-501.12(A). The wall floor cleaned on 5/21/25.

4.	C Corridor	Main Serving Room	Janitor's Closet	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Wet mop stored on floor. Standard found in 105 CMR 590; FC 6-501.16. The wet mop was removed off floor on 5/5/25.
5.	C Corridor	Main Serving Room	Handwash Sink	105 CMR 451.200	Plumbing System; Design, Construction and Installation: Insufficient hot water temperature at handwashing sinks (Pf), temperature recorded at 95°F. Standard found in 105 CMR 590; FC 5-202.12(A). The water temperature was readjusted to the proper temperature on 5/6/25. The new temperature is reading at 111 degrees.
6.	C Corridor	Main Serving Room	Mechanical Warewashing Room	105 CMR 451.200	Plumbing System; Design, Construction, and Installation: Air gap missing between water supply inlet and the flood level rim of the sink, sink sprayer was laying in the sink (Pf). Standard found in 105 CMR 590; FC 5-202.13. Sink sprayer hose was shortened on 5/21/25
7.	2nd Floor	Education	Inmate Bathroom	105 CMR 451.117*	Toilet Fixtures: Toilet fixture # 1 and 2 dirty The toilets were cleaned on 5/6/25
8.	2nd Floor	Industries # 224	Staff Industries Bathroom	105 CMR 451.126*	Hot Water for Bathing and Hygiene: Hot water temperature 95°F at handwash sink The water temperature was readjusted to the proper temperature on 5/6/25. The new temperature is reading at 111 degrees.
9.	3rd Floor	Chapel		105 CMR 451.141*	Screens: Screen missing The screen will be added to the window with an anticipated date of 6/27/25.

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Lobby	Janitor's Closet # A101 & A103	105 CMR 451.353	Interior Maintenance: Doorknob missing in Janitor's Closet # A103 A doorknob will be added to the door with an anticipated date of 5/23/25.
2.	B Corridor	Offices	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged and missing Ceiling tiles will be replaced with an anticipated date of 6/7/25.
3.	C Corridor		105 CMR 451.353	Interior Maintenance: Floor tile damaged throughout Floor tiles will be replaced with an anticipated date of 6/7/25.
4.	D Corridor	Cosmetology # D141, D143, & D145	105 CMR 451.353	Interior Maintenance: Ceiling damaged Ceiling tiles will be replaced with an anticipated date of 6/7/25.
5.	2nd Floor	Industries # 224	105 CMR 451.353*	Interior Maintenance: Floor damaged in shipping and receiving room The floor will be replaced with plywood with an anticipated date of 6/27/25.

6.	Basement	Laundry Area	105 CMR 451.353*	Interior Maintenance: Standing water on floor near laundry machines The standing water was removed on 5/6/25.
7.	Basement	Laundry Area	105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight Weatherstripping will be added to the door with an anticipated date of 6/6/25.
8.	Basement	Property	105 CMR 451.353*	Interior Maintenance: Cleaning chemical stored in old food container Cleaning chemical was removed from area on 5/6/25.

Central Kitchen

Deficiencies under the Required Standards (.100 and .200 series)

13 new deficiencies and 13 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Officer's Area	Inmate's Bathroom	105 CMR 451.123	Maintenance: Soap dispenser damaged Soap dispenser was replaced on 5/7/25.
2.	Officer's Area	Inmate's Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover missing at handwash sink A drain cover will be added to drain with an anticipated date of 6/17/25.
3.	Kitchen Area	3-Compartment Sink	105 CMR 451.200	Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Wet cloth not stored in sanitizer solution. Standard found in 105 CMR 590; FC 3-304.14(B)(1). **Corrected On-Site**
4.	Kitchen Area	Dumb Waiters	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises, dumb waiters out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A). Waiting for an assessment for removal. Dumb waiters will be boarded up with an anticipated date of 6/27.
5.	Kitchen Area	Prep Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, interior of microwave oven dirty. Standard found in 105 CMR 590; FC 6-501.12(A). The microwave was cleaned on 5/6/25.
6.	Kitchen Area	Prep Area	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, tape over floor drain where kettle was removed. Standard found in 105 CMR 590; FC 5-205.15(B). The tape was removed from the drain on 5/7/25. A new drain cover was added to the area.

7.	Kitchen Area	Broom Storage Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, standing water observed on floor. Standard found in 105 CMR 590; FC 6-501.12(A). The standing water was removed on 5/6/25.
8.	Kitchen Area	Broom Storage Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, mold on wall around slop bucket refrigerator. Standard found in 105 CMR 590; FC 6-501.12(A). Mold removed and walls cleaned on 5/7. The inmate work crew will continue this detail weekly or as needed.
9.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, walls dirty. Standard found in 105 CMR 590; FC 6-501.12(A). Walls were cleaned on 5/7. The inmate work crew will continue this detail weekly or as needed.
10.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Refuse, Recyclables, and Returnables; Facilities on the Premises: Soiled receptacles not cleaned after use, swill bucket encrusted with food debris. Standard found in 105 CMR 590; FC 6-501.116(B). The receptacles were cleaned on 5/7/25. The inmate work crew will continue this detail after each use. New swill buckets are on order for replacement.
11.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, mold on floor. Standard found in 105 CMR 590; FC 6-501.12(A). The mold on floor was removed on 5/7/25. The inmate work crew will continue this detail weekly or as needed.
12.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Preventing Contamination from the Premises; Food Storage: Food exposed to splash, dust, or other contamination, fans in cooler dusty. Standard found in 105 CMR 590; FC 3-305.11(A)(2). **Corrected On-Site**
13.	Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, wood on walls damaged and moldy. Standard found in 105 CMR 590; FC 6-501.11. The mold on the wall was removed on 5/7/25. Walls will be replaced with an anticipated date of 5/27/25.

14. Kitchen Area	Slop Bucket Refrigerator	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, door dragging on floor. Standard found in 105 CMR 590; FC 6-501.11. The door will be repositioned with an anticipated date of 5/27/25.
15. Kitchen Area	Dry/Baking Storage	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, floor dirty behind orange storage containers. Standard found in 105 CMR 590; FC 6-501.12(A). **Corrected On-Site**
16. Kitchen Area	Refrigerator # 5	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Refrigerated time/temperature control for safety food prepared on site not clearly marked indicating the date or day by which the food shall be consumed or discarded (Pf). Standard found in 105 CMR 590; FC 3-501.17(A). **Corrected On-Site**
17. Kitchen Area	Refrigerator # 5	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food. Standard found in 105 CMR 590; FC 3-302.12. **Corrected On-Site**
18. Kitchen Area	Freezer # 6	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food. Standard found in 105 CMR 590; FC 3-302.12. **Corrected On-Site**
19. Kitchen Area	Freezer # 6	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Refrigerated time/temperature control for safety food prepared on site not clearly marked indicating the date or day by which the food shall be consumed or discarded (Pf). Standard found in 105 CMR 590; FC 3-501.17(A). **Corrected On-Site**
20. Back Room	Storage Area	105 CMR 451.200	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil/mold observed on interior surfaces of ice machine. Standard found in 105 CMR 590; FC 4-602.11(E)(4)(b). **Corrected On-Site**
21. Back Hallway	Walk-In Refrigerator	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Refrigerated time/temperature control for safety food prepared on site not clearly marked indicating the date or day by which the food shall be consumed or discarded (Pf). Standard found in 105 CMR 590; FC 3-501.17(A). **Corrected On-Site**


22. Back Hallway	Walk-In Refrigerator	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food. Standard found in 105 CMR 590; FC 3-302.12. **Corrected On-Site**
23. Food Manager's Office		105 CMR 451.200*	Materials for Construction and Repair; Indoor Areas: Ceiling surface not smooth and easily cleanable, ceiling paint damaged. Standard found in 105 CMR 590; FC 6-101.11(A)(1). The ceiling will be repainted then sanded down with an anticipated date of 6/13/25.
24. Food Manager's Office		105 CMR 451.200*	Materials for Construction and Repair; Indoor Areas: Floor surface not smooth and easily cleanable, floor paint damaged. Standard found in 105 CMR 590; FC 6-101.11(A)(1). The floor will be repainted then sanded down with an anticipated date of 6/13/25.
25. Food Manager's Office		105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, mold on gaskets in Traulsen refrigerator. Standard found in 105 CMR 590; FC 4-501.11(B). **Corrected On-Site**
26. Food Manager's Office	Bathroom	105 CMR 451.123*	Maintenance: Floor paint damaged The floor will be repainted with an anticipated date of 6/13/25.

Power Plant

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Power Plant Building # 3	105 CMR 451.350*	Structural Maintenance: Stairs at entrance damaged and deteriorated Premade stairs have been ordered to replace the original staircase. The anticipated date for the replacement is 6/20/25.
2. Power Plant Building # 3	105 CMR 451.360	Protective Measures: Birds nest in ceiling above Chief Engineer's Office The bird nest was removed from ceiling on 5/7/25.



MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

The Commonwealth of Massachusetts

Executive Office of Health and Human Services

Department of Public Health

Bureau of Climate and Environmental Health

Division of Environmental Health Regulations and Standards

67 Forest Street, Suite # 100

Marlborough, MA 01752

Phone: 617-624-5757

KATHLEEN E. WALSH
Secretary

ROBERT GOLDSTEIN, MD, PhD
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

June 3, 2025

Ryan Donlon, Superintendent
MCI Framingham
99 Loring Drive, P.O. Box 9007
Framingham, MA 01701 (electronic copy)

Re: Plan of Correction – MCI Framingham

Dear Superintendent Donlon:

The Massachusetts Department of Public Health, Division of Environmental Regulations and Standards (EHRS) has received your Plan of Correction in response to my inspection conducted on May 5 and 6, 2025. After review, the EHRS finds the plan addresses all the deficiencies noted with the following exception:

In regards to the issue of overcrowding, the EHRS appreciates the limitations of correctional facilities and the need to accommodate the ever-increasing population; however we remain concerned with the overcrowded conditions.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Hannah LeBeau
Environmental Health Inspector, EHRS, BCEH

cc: Michael Beland, EHSO/FSO

(electronic copy)