

The Commonwealth of Massachusetts
 Executive Office of Health and Human Services
 Department of Public Health
 Bureau of Climate and Environmental Health
 Division of Environmental Health Regulations and Standards
 5 Randolph Street
 Canton, MA 02021
 617-624-6000 | mass.gov/dph

Maura T. Healey
 Governor

Kiame Mahaniah, MD, MBA
 Secretary

Kimberley Driscoll
 Lieutenant Governor

Robert Goldstein, MD, PhD
 Commissioner

May 7, 2026

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)
 Kiame Mahaniah, Secretary, Executive Office of Health and Human Services (electronic copy)
 Clerk, Massachusetts House of Representatives (electronic copy)
 Clerk, Massachusetts Senate (electronic copy)
 Michael Rosano, Environmental Health and Safety Officer (electronic copy)

Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Bridgewater State Hospital, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Patrick Wallace
 Environmental Analyst, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)
 Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)
 Eric Badger, Health Agent, Bridgewater Health Department (electronic copy)
 Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)
 Jeffrey Gonsalves, Superintendent (electronic copy)
 James Rioux, Deputy Superintendent (electronic copy)



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

April 13, 2026

Jeffrey Gonsalves, Superintendent
Bridgewater State Hospital
20 Administration Road
Bridgewater, MA 02324 (electronic copy)

Re: Facility Inspection – Bridgewater State Hospital

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Bridgewater State Hospital on March 30 and 31, 2026 accompanied by, Sergeant Michael Rosano, Environmental Health and Safety Officer, Michael Durocher, Director of Engineering, and Norberto Melo, Facility Maintenance Manager in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 254 total deficiencies: 25 new deficiencies under the Required Standards (.100 and .200 series), 30 repeat deficiencies under the Required Standards, 34 new deficiencies under the Recommended Standards (.300 series), and 165 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Administration Building

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1.	Front Control	105 CMR 451.353	Interior Maintenance: Ceiling surface damaged
----	---------------	-----------------	---

Building #2 – Adams

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A1 Unit	Room Corridor	105 CMR 451.102	Pillows and Linens: Pillow damaged in room # 123	
2.	A1 Unit	Dorm Corridor	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower # 4 leaking	
3.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling damaged
4.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor left unfinished next to handwash sinks
5.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 3
6.	A2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 1 and 4

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 13 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A1 Unit	Main Area	Transfer Room # A124	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
2.	A1 Unit	Room Corridor	Nurse's Treatment Room # A125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
3.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117 and 123
4.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 116 and 119
5.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall damaged in room # 113
6.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 102 and 107
7.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 108 and 112
8.	A1 Unit	Dorm Corridor	Dorm # 6	105 CMR 451.353	Interior Maintenance: Floor paint damaged
9.	A2 Unit	Room Corridor	Treatment Room # A2-221	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
10.	A2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 216

11. A2 Unit	Dorm Corridor		105 CMR 451.353*	Interior Maintenance: Paint damaged on hand sanitizer dispenser in hallway
12. A2 Unit	Dorm Corridor	Dorm # 9	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
13. A2 Unit	Dorm Corridor	Dorm # 11	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
14. A2 Unit	Dorm Corridor	Dorm # 12	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
15. A2 Unit	Dorm Corridor	Dorm # 10	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

Building # 3 – Bradford

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1. B1 Unit	Control	Control Bathroom	105 CMR 451.123	Maintenance: Door damaged
2. B1 Unit	Main Area	Nurse's Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink
3. B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on handwash sink unit
4. B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on toilet partitions
5. B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall vent dirty and clogged
6. B1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Wall paint damaged
7. B1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Bench paint damaged
8. B2 Unit	Main Area	Mop Closet # B-250	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain clogged at slop sink
9. B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on countertop
10. B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Wall vent damaged
11. B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Paint damaged on soap dispenser

Deficiencies under the Recommended Standards (.300 series)

5 new deficiencies and 16 repeat deficiencies (indicated by an *) were found during the inspection:

1. B1 Unit	Main Area	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
2. B1 Unit	Room Corridor		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway
3. B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
4. B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
5. B1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 111, 118, and 120

6.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 104 and 116
7.	B1 Unit	Dorm Corridor	Room # B-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
8.	B1 Unit	Dorm Corridor	Room # B-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
9.	B2 Unit	Main Area	Mop Closet # B-250	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
10.	B2 Unit	Main Area	Nurse's Station	105 CMR 451.353	Interior Maintenance: Desk surface damaged
11.	B2 Unit	Room Corridor	Treatment Room # B2-221	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
12.	B2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 204, 206, 210, and 218
13.	B2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 205 and 223

Building # 4 - Cotter

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 7 repeat deficiencies (indicated by an *) were found during the inspection:

1.	C1 Unit	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Door damaged
2.	C1 Unit	Control	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling vent damaged
3.	C1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling surface damaged
4.	C1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted
5.	C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling dirty
6.	C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged
7.	C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 2 running continuously
8.	C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted
9.	C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on light fixture

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 63 repeat deficiencies (indicated by an *) were found during the inspection:

1.	C1 Unit	Main Area		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway
2.	C1 Unit	Main Area		105 CMR 451.353*	Interior Maintenance: Wall paint damaged in hallway
3.	C1 Unit	Main Area	Mop Closet # C-155	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
4.	C1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged
5.	C1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353	Interior Maintenance: Wall paint damaged
6.	C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged
7.	C1 Unit	Room Corridor		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway

8.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 115 and 120
9.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 102, 103, 104, 105, 107, 108, 109, 110, 111, 112, 114, 115, 116, 118, 119, and 123
10.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 106
11.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 103, 104, 106, 110, 114, 116, and 119
12.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 121
13.	C1 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C-105	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
14.	C1 Unit	Dorm Corridor	Unit Director's Office # C-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
15.	C1 Unit	Dorm Corridor	Treatment Team Office # C-107	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
16.	C1 Unit	Dorm Corridor	Sensory Room # C- 110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
17.	C1 Unit	Dorm Corridor	Group Room # C- 111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
18.	C2 Unit	Main Area	Staff Break Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
19.	C2 Unit	Main Area	Room # C-220	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
20.	C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 203, 204, 205, 206, 208, 211, 212, 214, 215, 216, 218, 219, 221, and 223
21.	C2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 209
22.	C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 205, 210, 212, 214, and 215
23.	C2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 201 and 218
24.	C2 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C-204	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
25.	C2 Unit	Dorm Corridor	Unit Director's Office # C-205	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
26.	C2 Unit	Dorm Corridor	Treatment Team Office # C-206	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
27.	C2 Unit	Dorm Corridor	Sensory Room # C- 208	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
28.	C2 Unit	Dorm Corridor	Dorm # C-209	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
29.	C2 Unit	Dorm Corridor	Dorm # C-210	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

Building # 5 – Recovery Place

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Toxic/Caustic Closet		105 CMR 451.353*	Interior Maintenance: Floor paint damaged
2. Toxic/Caustic Closet		105 CMR 451.353*	Interior Maintenance: Wall paint damaged

Building # 7 - Commons

Deficiencies under the Required Standards (.100 and .200 series)

5 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Lobby Area	Laundry	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink
2. School Corridor	Staff Bathroom # CS-01	105 CMR 451.123*	Maintenance: Door damaged
3. School Corridor	Staff Bathroom # CS-01	105 CMR 451.123*	Maintenance: Ceiling water damaged
4. Kitchen		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, free standing fan dirty. Standard found in 105 CMR 590; FC 6-501.12(A). ** Corrected On-Site **
5. Kitchen	Handwash Sink	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 63°F at handwash sink ** Corrected On-Site **
6. Kitchen	Walk-In Refrigerator	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises, refrigerator out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A).
7. Kitchen	Supply Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling surface damaged. Standard found in 105 CMR 590; FC 6-501.11.
8. Kitchen	Serving Line	105 CMR 451.200	Protection of Clean Items; Drying: Cleaned, sanitized equipment and utensils not allowed to fully air dry before contact with food, plastic serving trays . Standard found in 105 CMR 590; FC 4-901.11(A). ** Corrected On-Site **
9. Kitchen	Diet Cooler C	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B).

Deficiencies under the Recommended Standards (.300 series)

16 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Lobby Area		105 CMR 451.353*	Interior Maintenance: Ceiling damaged
2.	Lobby Area		105 CMR 451.353*	Interior Maintenance: Floor cracked
3.	Lobby Area	Laundry	105 CMR 451.353*	Interior Maintenance: Pipe insulation damaged
4.	Lobby Area	Control	105 CMR 451.353*	Interior Maintenance: Paint damaged on window frames
5.	Main Area	Storage Area # CL-11	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged
6.	Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
7.	Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353*	Interior Maintenance: Floor dirty
8.	Main Area	Chair Cot/Stretcher Room # CL-15	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
9.	Gym	Storage Room # CG-23	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged
10.	Back Hallway	Recycle Room # CG-11	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged
11.	School Corridor	Library # CS-03	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
12.	School Corridor	Life Skills Group Room # CS-10	105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
13.	Basement		105 CMR 451.353*	Interior Maintenance: Floor paint damaged in hallway
14.	Basement	Maintenance Department	Tool Crib 105 CMR 451.353*	Interior Maintenance: Floor paint damaged
15.	Basement	Maintenance Department	Tool Crib 105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged
16.	Basement	Maintenance Department	Tool Crib 105 CMR 451.353*	Interior Maintenance: Wall paint damaged

Building # 8 – Hadley**Deficiencies under the Required Standards (.100 and .200 series)**

4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	C-Corridor	Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance
2.	C-Corridor	Bathroom	105 CMR 451.123*	Maintenance: Wall vent dusty
3.	C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door rusted
4.	C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Wall damaged

Deficiencies under the Recommended Standards (.300 series)

4 new deficiencies and 23 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 101, 102, 104, 109, 110, 111, 112, 113, 114, and 115
2.	A-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 107
3.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 117, 120, 121, 122, 123, 124, 128, 130, and 131
4.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 126
5.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117
6.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 120
7.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 124
8.	C-Corridor		105 CMR 451.353	Interior Maintenance: Paint damaged on hand sanitizer dispenser in hallway
9.	C-Corridor	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
10.	C-Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

Building # 9 – Lenox**Deficiencies under the Required Standards (.100 and .200 series)**

3 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A Corridor	Rooms	105 CMR 451.103	Mattresses: Mattress damaged in cell # 102
2.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance
3.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Radiator rusted
4.	C Corridor	Patient Bathroom	105 CMR 451.123	Maintenance: Paint damaged on soap dispenser
5.	C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Door rusted
6.	C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Ceiling vent rusted
7.	C Corridor	Shower Room	105 CMR 451.123	Maintenance: Ceiling cracked

Deficiencies under the Recommended Standards (.300 series)

5 new deficiencies and 17 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Control		105 CMR 451.353*	Interior Maintenance: Wall paint damaged
2.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 106, 107, 110, 111, and 113
3.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 104 and 112
4.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 120, 124, 126, 127, 128, 129, and 131
5.	B Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 117, 119, 121, 125, and 132
6.	C Corridor	Toxic/Caustic Closet # M-250	105 CMR 451.353*	Interior Maintenance: Floor paint damaged

Building # 10 – Berkshire**Deficiencies under the Recommended Standards (.300 series)**

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	Right Side	Slop Sink Closet # MM-30	105 CMR 451.353*	Interior Maintenance: Door damaged
----	------------	--------------------------	------------------	------------------------------------

Building # 11 – Lighthouse**Deficiencies under the Required Standards (.100 and .200 series)**

3 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Basement	Mechanical Room		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, several pipes leaking
2.	First Floor	Clinic Corridor	Clinic # H-168	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink
3.	Booking Corridor	Female Bathroom # H-172		105 CMR 451.123*	Maintenance: Ceiling damaged
4.	Booking Corridor	Male Bathroom # H-173		105 CMR 451.123*	Maintenance: Floor surface damaged
5.	Infirmary	Shower Room		105 CMR 451.123*	Maintenance: Door damaged
6.	Medical West Unit	Bathroom # 138 (Storage)		105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, urinal running continuously
7.	Medical West Unit	Shower # H-137		105 CMR 451.123*	Maintenance: Wall tile grout dirty
8.	Medical West Unit	Shower # H-137		105 CMR 451.123*	Maintenance: Door frame rusted
9.	Medical West Unit	Staff Bathroom		105 CMR 451.123	Maintenance: Wall vent dusty

Deficiencies under the Recommended Standards (.300 series)

7 new deficiencies and 12 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Basement	Mechanical Room		105 CMR 451.353*	Interior Maintenance: Water pooling on floor
2.	First Floor	Clinic Corridor	Pharmacy # H-161	105 CMR 451.353*	Interior Maintenance: Wall vent dusty
3.	Booking Corridor			105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in hallway
4.	Booking Corridor	Medical Waste Storage Room # H-215		105 CMR 451.353*	Interior Maintenance: Door frame rotted
5.	Booking Corridor	Medical Waste Storage Room # H-215		105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior
6.	Booking Corridor	Booking Trap # H-212		105 CMR 451.350	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior
7.	Booking Corridor	Booking Trap # H-212		105 CMR 451.353	Interior Maintenance: Ceiling vent dusty

8. Infirmary		105 CMR 451.353	Interior Maintenance: Ceiling water damaged in hallway
9. Infirmary	Room # 2 /Bathroom	105 CMR 451.353	Interior Maintenance: Floor paint damaged in dorm
10. Infirmary	Dorm # 3 /Bathroom	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm
11. Infirmary	Dorm # 3 /Bathroom	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm
12. Infirmary	Dorm # 5	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
13. Laundry Hallway	Laundry	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
14. Medical West Unit	Closet # H-121	105 CMR 451.353	Interior Maintenance: Wall surface left unfinished
15. Medical West Unit	Janitor's Closet # H-123	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
16. Medical West Unit	Room # 5	105 CMR 451.353*	Interior Maintenance: Floor rust stained
17. Medical West Unit	Room # 5	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
18. Medical West Unit	Dorm # 10 /Bathroom	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm
19. Medical West Unit	Room # 6	105 CMR 451.353	Interior Maintenance: Floor paint damaged

Building # 12 – Vehicle Trap

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1. Tower		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control leaking at handwash sink
----------	--	-----------------	--

Staff Gym

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Female Locker Room		105 CMR 451.123	Maintenance: Drain flies observed in shower # 1
2. Male Locker Room		105 CMR 451.123*	Maintenance: Ceiling tiles water stained

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Common Area		105 CMR 451.353*	Interior Maintenance: Carpet damaged
2. Common Area		105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained

SECTION 2: Areas Found to be in Compliance

The EHRS inspected 314 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 3 areas of the facility because they were either in use, locked, or under construction.

1. Building # 3 – Bradford	B2 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
2. Building # 11 – Lighthouse (medical)	Old Seclusion Area			Unable to Inspect – Under Construction
3. Building # 11 – Lighthouse (medical)	Booking Corridor	Former Property Area		Unable to Inspect – Under Construction

SECTION 4: Plan of Correction

This facility does not comply with the Department’s Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. A signature by the Superintendent or Administrator responsible for the plan. The signed plan should be submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The patient population was 203 at the time of inspection.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#) is available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:


- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Patrick Wallace,
Environmental Analyst, EHRS, BCEH



The Commonwealth of Massachusetts
Executive Office of Public Safety & Security
Department of Correction
Bridgewater State Hospital
20 Administration Road
Bridgewater, MA 02324
Tel: (508) 279-4500
www.mass.gov/doc



MAURA T. HEALEY
Governor

GINA K. KWON
Secretary

KIMBERLEY DRISCOLL
Lieutenant Governor

SHAWN P. JENKINS
Commissioner

April 14, 2026

Mr. Patrick Wallace
Environmental Health Inspector, CSP, BEH
Department of Public Health, Bureau of Environmental Health
Community Sanitation Program
5 Randolph Street
Canton, MA 02021

Dear Mr. Wallace:

Enclosed please find your inspection report for Bridgewater State Hospital dated 4/13/26. This report has been updated to include corrective action plans which address all violations. All responses are in bold.

Should you have any questions or require additional information, please don't hesitate to contact my office.

Sincerely,

Jeffrey L. Gonsalves
Superintendent

CC: Shawn P. Jenkins, Commissioner
Mitzi Peterson, Deputy Commissioner, Clinical Services & Re-entry
Jeff Fisher, Assistant Deputy Commissioner, Clinical Services
James Rioux, Deputy Superintendent
Brianna Arruda, Director, Policy Development and Compliance Unit
Michael Durocher, Director of Facility Maintenance
Sergeant Michael Rosano, Environmental Health and Safety Officer

SECTION 1: Health and Safety Deficiencies

Administration Building

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1.	Front Control		105 CMR 451.353	Interior Maintenance: Ceiling surface damaged To be repaired and repainted by 8/15/26.
----	---------------	--	-----------------	--

Building #2 – Adams

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A1 Unit	Room Corridor		105 CMR 451.102	Pillows and Linens: Pillow damaged in room # 123 To be replaced by 4/17/26.
2.	A1 Unit	Dorm Corridor		105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower # 4 leaking To be repaired by 4/30/26.
3.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling damaged To be repaired and repainted by 5/15/26.
4.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor left unfinished next to handwash sinks To be repaired and repainted by 5/15/26.
5.	A2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 3 To be repaired by 4/30/26.
6.	A2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking at shower # 1 and 4 To be repaired by 4/30/26.

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 13 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A1 Unit	Main Area	Transfer Room # A124	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
2.	A1 Unit	Room Corridor	Nurse's Treatment Room # A125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
3.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117 and 123 To be repaired and repainted by 8/15/26.
4.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 116 and 119 To be repainted by 8/15/26.

5.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall damaged in room # 113 To be repaired and repainted by 8/15/26.
6.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 102 and 107 To be repainted by 8/15/26.
7.	A1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 108 and 112 To be repainted by 8/15/26.
8.	A1 Unit	Dorm Corridor	Dorm # 6	105 CMR 451.353	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
9.	A2 Unit	Room Corridor	Treatment Room # A2-221	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
10.	A2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 216 To be repainted by 8/15/26.
11.	A2 Unit	Dorm Corridor		105 CMR 451.353*	Interior Maintenance: Paint damaged on hand sanitizer dispenser in hallway To be repainted by 8/15/26.
12.	A2 Unit	Dorm Corridor	Dorm # 9	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
13.	A2 Unit	Dorm Corridor	Dorm # 11	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
14.	A2 Unit	Dorm Corridor	Dorm # 12	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
15.	A2 Unit	Dorm Corridor	Dorm # 10	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.

Building # 3 – Bradford

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 5 repeat deficiencies (indicated by an *) were found during the inspection:

1.	B1 Unit	Control	Control Bathroom	105 CMR 451.123	Maintenance: Door damaged To be repaired by 6/15/26.
2.	B1 Unit	Main Area	Nurse's Bathroom	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink To be repaired by 4/30/26.
3.	B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on handwash sink unit To be repainted by 5/15/26.

4.	B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on toilet partitions To be repainted by 5/15/26.
5.	B1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall vent dirty and clogged To be cleaned by 4/30/26.
6.	B1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Wall paint damaged To be repainted by 5/15/26.
7.	B1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123	Maintenance: Bench paint damaged To be repainted by 5/15/26.
8.	B2 Unit	Main Area	Mop Closet # B-250	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain clogged at slop sink To be repaired by 4/30/26.
9.	B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Paint damaged on countertop To be repainted by 5/15/26.
10.	B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Wall vent damaged To be replaced by 5/15/26.
11.	B2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123	Maintenance: Paint damaged on soap dispenser To be repainted by 5/15/26.

Deficiencies under the Recommended Standards (.300 series)

5 new deficiencies and 16 repeat deficiencies (indicated by an *) were found during the inspection:

1.	B1 Unit	Main Area	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged To be repaired and repainted by 8/15/26.
2.	B1 Unit	Room Corridor		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway To be repaired and repainted by 8/15/26.
3.	B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
4.	B1 Unit	Room Corridor	Treatment Room # B-125	105 CMR 451.353*	Interior Maintenance: Wall paint damaged To be repainted by 8/15/26.
5.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 111, 118, and 120 To be repainted by 8/15/26.
6.	B1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 104 and 116 To be repainted by 8/15/26.
7.	B1 Unit	Dorm Corridor	Room # B-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
8.	B1 Unit	Dorm Corridor	Room # B-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.

9.	B2 Unit	Main Area	Mop Closet # B-250	105 CMR 451.353*	Interior Maintenance: Floor surface damaged To be repaired and repainted by 8/15/26.
10.	B2 Unit	Main Area	Nurse's Station	105 CMR 451.353	Interior Maintenance: Desk surface damaged To be repaired and repainted by 8/15/26.
11.	B2 Unit	Room Corridor	Treatment Room # B2-221	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
12.	B2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 204, 206, 210, and 218 To be repainted by 8/15/26.
13.	B2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 205 and 223 To be repainted by 8/15/26.

Building # 4 - Cotter

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 7 repeat deficiencies (indicated by an *) were found during the inspection:

1.	C1 Unit	Control	Control Bathroom	105 CMR 451.123*	Maintenance: Door damaged To be repaired by 6/15/26.
2.	C1 Unit	Control	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling vent damaged To be replaced by 5/15/26.
3.	C1 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling surface damaged To be repaired and repainted by 5/15/26.
4.	C1 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted To be repaired by 5/15/26.
5.	C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling dirty To be cleaned by 4/17/26.
6.	C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.123*	Maintenance: Ceiling water damaged To be repaired and repainted by 5/15/26.
7.	C2 Unit	Dorm Corridor	Dorm Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 2 running continuously To be repaired by 4/30/26.
8.	C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Door frame rusted To be repaired by 5/15/26.
9.	C2 Unit	Dorm Corridor	Dorm Shower	105 CMR 451.123*	Maintenance: Paint damaged on light fixture To be repainted by 5/15/26.

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 63 repeat deficiencies (indicated by an *) were found during the inspection:

1.	C1 Unit	Main Area		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway To be repaired and repainted by 8/15/26.
2.	C1 Unit	Main Area		105 CMR 451.353*	Interior Maintenance: Wall paint damaged in hallway To be repainted by 8/15/26.
3.	C1 Unit	Main Area	Mop Closet # C-155	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
4.	C1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor surface damaged To be repaired and repainted by 8/15/26.
5.	C1 Unit	Main Area	Toxic/Caustic Closet	105 CMR 451.353	Interior Maintenance: Wall paint damaged To be repainted by 8/15/26.
6.	C1 Unit	Main Area	Transfer Room # C-124	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged To be repaired and repainted by 8/15/26.
7.	C1 Unit	Room Corridor		105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in hallway To be repaired and repainted by 8/15/26.
8.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 115 and 120 To be repaired and repainted by 8/15/26.
9.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 102, 103, 104, 105, 107, 108, 109, 110, 111, 112, 114, 115, 116, 118, 119, and 123 To be repainted by 8/15/26.
10.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 106 To be repainted by 8/15/26.
11.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 103, 104, 106, 110, 114, 116, and 119 To be repainted by 8/15/26.
12.	C1 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 121 To be repainted by 8/15/26.
13.	C1 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C-105	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
14.	C1 Unit	Dorm Corridor	Unit Director's Office # C-106	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
15.	C1 Unit	Dorm Corridor	Treatment Team Office # C-107	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
16.	C1 Unit	Dorm Corridor	Sensory Room # C-110	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
17.	C1 Unit	Dorm Corridor	Group Room # C-111	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
18.	C2 Unit	Main Area	Staff Break Room	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.

19. C2 Unit	Main Area	Room # C-220	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
20. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 203, 204, 205, 206, 208, 211, 212, 214, 215, 216, 218, 219, 221, and 223 To be repainted by 8/15/26.
21. C2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 209 To be repainted by 8/15/26.
22. C2 Unit	Room Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 205, 210, 212, 214, and 215 To be repainted by 8/15/26.
23. C2 Unit	Room Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 201 and 218 To be repainted by 8/15/26.
24. C2 Unit	Dorm Corridor	Hygiene, Shaves, & Storage # C-204	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
25. C2 Unit	Dorm Corridor	Unit Director's Office # C-205	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
26. C2 Unit	Dorm Corridor	Treatment Team Office # C-206	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
27. C2 Unit	Dorm Corridor	Sensory Room # C- 208	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
28. C2 Unit	Dorm Corridor	Dorm # C-209	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
29. C2 Unit	Dorm Corridor	Dorm # C-210	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.

Building # 5 – Recovery Place

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Toxic/Caustic Closet			105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
2. Toxic/Caustic Closet			105 CMR 451.353*	Interior Maintenance: Wall paint damaged To be repainted by 8/15/26.

Building # 7 - Commons

Deficiencies under the Required Standards (.100 and .200 series)

5 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Lobby Area	Laundry		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink To be repaired by 4/30/26.
2. School Corridor	Staff Bathroom # CS-01		105 CMR 451.123*	Maintenance: Door damaged To be repaired by 6/15/26.
3. School Corridor	Staff Bathroom # CS-01		105 CMR 451.123*	Maintenance: Ceiling water damaged To be repaired and repainted by 5/15/26.

4.	Kitchen		105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, free standing fan dirty. Standard found in 105 CMR 590; FC 6-501.12(A). ** Corrected On-Site **
5.	Kitchen	Handwash Sink	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 63°F at handwash sink ** Corrected On-Site **
6.	Kitchen	Walk-In Refrigerator	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises, refrigerator out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A). Replacement received and to be installed by 6/15/26.
7.	Kitchen	Supply Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling surface damaged. Standard found in 105 CMR 590; FC 6-501.11. To be repaired and repainted by 6/15/26.
8.	Kitchen	Serving Line	105 CMR 451.200	Protection of Clean Items; Drying: Cleaned, sanitized equipment and utensils not allowed to fully air dry before contact with food, plastic serving trays . Standard found in 105 CMR 590; FC 4-901.11(A). ** Corrected On-Site **
9.	Kitchen	Diet Cooler C	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B). To be replaced by 5/15/26.

Deficiencies under the Recommended Standards (.300 series)

16 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Lobby Area		105 CMR 451.353*	Interior Maintenance: Ceiling damaged To be repaired and repainted by 8/15/26.
2.	Lobby Area		105 CMR 451.353*	Interior Maintenance: Floor cracked To be repaired and repainted by 8/15/26.
3.	Lobby Area	Laundry	105 CMR 451.353*	Interior Maintenance: Pipe insulation damaged To be replaced by 8/15/26.
4.	Lobby Area	Control	105 CMR 451.353*	Interior Maintenance: Paint damaged on window frames To be repaired and repainted by 8/15/26.

5.	Main Area	Storage Area # CL-11		105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged To be repaired and repainted by 8/15/26.
6.	Main Area	Chair Cot/Stretcher Room # CL-15		105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
7.	Main Area	Chair Cot/Stretcher Room # CL-15		105 CMR 451.353*	Interior Maintenance: Floor dirty To be cleaned by 4/17/26.
8.	Main Area	Chair Cot/Stretcher Room # CL-15		105 CMR 451.353*	Interior Maintenance: Wall paint damaged To be repainted by 8/15/26.
9.	Gym	Storage Room # CG-23		105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged To be repaired and repainted by 8/15/26.
10.	Back Hallway	Recycle Room # CG-11		105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged To be repaired and repainted by 8/15/26.
11.	School Corridor	Library # CS-03		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged To be repaired and repainted by 8/15/26.
12.	School Corridor	Life Skills Group Room # CS-10		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged To be repaired and repainted by 8/15/26.
13.	Basement			105 CMR 451.353*	Interior Maintenance: Floor paint damaged in hallway To be repainted by 8/15/26.
14.	Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
15.	Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Ceiling surface damaged To be repaired and repainted by 8/15/26.
16.	Basement	Maintenance Department	Tool Crib	105 CMR 451.353*	Interior Maintenance: Wall paint damaged To be repainted by 8/15/26.

Building # 8 – Hadley

Deficiencies under the Required Standards (.100 and .200 series)

4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	C-Corridor	Bathroom		105 CMR 451.123*	Maintenance: Floor surface damaged at entrance To be repaired and repainted by 5/15/26.
2.	C-Corridor	Bathroom		105 CMR 451.123*	Maintenance: Wall vent dusty To be cleaned by 4/30/26.

3.	C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Door rusted To be repaired by 6/15/26.
4.	C-Corridor	Shower Area	105 CMR 451.123*	Maintenance: Wall damaged To be repaired and repainted by 5/15/26.

Deficiencies under the Recommended Standards (.300 series)

4 new deficiencies and 23 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 101, 102, 104, 109, 110, 111, 112, 113, 114, and 115 To be repainted by 8/15/26.
2.	A-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 107 To be repainted by 8/15/26.
3.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 117, 120, 121, 122, 123, 124, 128, 130, and 131 To be repainted by 8/15/26.
4.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 126 To be repainted by 8/15/26.
5.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 117 To be repaired and repainted by 8/15/26.
6.	B-Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 120 To be repaired and repainted by 8/15/26.
7.	B-Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 124 To be repainted by 8/15/26.
8.	C-Corridor		105 CMR 451.353	Interior Maintenance: Paint damaged on hand sanitizer dispenser in hallway To be repainted by 8/15/26.
9.	C-Corridor	Slop Sink Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
10.	C-Corridor	Toxic/Caustic Closet	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.

Building # 9 – Lenox

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A Corridor	Rooms	105 CMR 451.103	Mattresses: Mattress damaged in cell # 102 To be replaced by 4/17/26.
2.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Floor surface damaged at entrance To be repaired and repainted by 5/15/26.
3.	C Corridor	Patient Bathroom	105 CMR 451.123*	Maintenance: Radiator rusted To be repaired and repainted by 5/15/26.

4.	C Corridor	Patient Bathroom	105 CMR 451.123	Maintenance: Paint damaged on soap dispenser To be repainted by 5/15/26.
5.	C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Door rusted To be repaired by 5/15/26.
6.	C Corridor	Shower Room	105 CMR 451.123*	Maintenance: Ceiling vent rusted To be replaced by 5/15/26.
7.	C Corridor	Shower Room	105 CMR 451.123	Maintenance: Ceiling cracked To be repaired and repainted by 5/15/26.

Deficiencies under the Recommended Standards (.300 series)

5 new deficiencies and 17 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Control		105 CMR 451.353*	Interior Maintenance: Wall paint damaged To be repainted by 8/15/26.
2.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 103, 106, 107, 110, 111, and 113 To be repainted by 8/15/26.
3.	A Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor surface damaged in room # 104 and 112 To be repaired and repainted by 8/15/26.
4.	B Corridor	Rooms	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in room # 120, 124, 126, 127, 128, 129, and 131 To be repainted by 8/15/26.
5.	B Corridor	Rooms	105 CMR 451.353	Interior Maintenance: Floor paint damaged in room # 117, 119, 121, 125, and 132 To be repainted by 8/15/26.
6.	C Corridor	Toxic/Caustic Closet # M-250	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.

Building # 10 – Berkshire

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	Right Side	Slop Sink Closet # MM-30	105 CMR 451.353*	Interior Maintenance: Door damaged To be repaired by 6/15/26.
----	------------	--------------------------	------------------	---

Building # 11 – Lighthouse

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Basement	Mechanical Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, several pipes leaking To be repaired by 7/15/26.
2.	First Floor	Clinic Corridor	Clinic # H-168 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink To be repaired by 4/30/26.
3.	Booking Corridor	Female Bathroom # H-172	105 CMR 451.123*	Maintenance: Ceiling damaged To be repaired and repainted by 5/15/26.

4.	Booking Corridor	Male Bathroom # H-173	105 CMR 451.123*	Maintenance: Floor surface damaged To be repaired and repainted by 5/15/26.
5.	Infirmary	Shower Room	105 CMR 451.123*	Maintenance: Door damaged To be repaired by 6/15/26.
6.	Medical West Unit	Bathroom # 138 (Storage)	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, urinal running continuously To be repaired by 4/30/26.
7.	Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Wall tile grout dirty To be cleaned by 4/17/26.
8.	Medical West Unit	Shower # H-137	105 CMR 451.123*	Maintenance: Door frame rusted To be repaired by 5/15/26.
9.	Medical West Unit	Staff Bathroom	105 CMR 451.123	Maintenance: Wall vent dusty To be cleaned by 4/30/26.

Deficiencies under the Recommended Standards (.300 series)

7 new deficiencies and 12 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Basement	Mechanical Room	105 CMR 451.353*	Interior Maintenance: Water pooling on floor To be cleaned by 4/17/26.
2.	First Floor	Clinic Corridor Pharmacy # H-161	105 CMR 451.353*	Interior Maintenance: Wall vent dusty To be cleaned by 4/30/26.
3.	Booking Corridor		105 CMR 451.353*	Interior Maintenance: Ceiling water damaged in hallway To be repaired and repainted by 8/15/26.
4.	Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.353*	Interior Maintenance: Door frame rotted To be repaired and repainted by 8/15/26.
5.	Booking Corridor	Medical Waste Storage Room # H-215	105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior To be made rodent and weathertight by 5/15/26.
6.	Booking Corridor	Booking Trap # H-212	105 CMR 451.350	Structural Maintenance: Area not rodent and weathertight, gap at bottom of door to exterior To be repaired and repainted by 5/15/26.
7.	Booking Corridor	Booking Trap # H-212	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty To be cleaned by 4/30/26.
8.	Infirmary		105 CMR 451.353	Interior Maintenance: Ceiling water damaged in hallway To be repaired and repainted by 8/15/26.
9.	Infirmary	Room # 2 /Bathroom	105 CMR 451.353	Interior Maintenance: Floor paint damaged in dorm To be repainted by 8/15/26.

10. Infirmary	Dorm # 3 /Bathroom	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm To be repainted by 8/15/26.
11. Infirmary	Dorm # 3 /Bathroom	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in dorm To be repainted by 8/15/26.
12. Infirmary	Dorm # 5	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
13. Laundry Hallway	Laundry	105 CMR 451.353*	Interior Maintenance: Wall paint damaged To be repainted by 8/15/26.
14. Medical West Unit	Closet # H-121	105 CMR 451.353	Interior Maintenance: Wall surface left unfinished To be repaired and repainted by 8/15/26.
15. Medical West Unit	Janitor's Closet # H-123	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket Mop stored property on 4/14/26.
16. Medical West Unit	Room # 5	105 CMR 451.353*	Interior Maintenance: Floor rust stained To be repaired and repainted by 8/15/26.
17. Medical West Unit	Room # 5	105 CMR 451.353*	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.
18. Medical West Unit	Dorm # 10 /Bathroom	105 CMR 451.353*	Interior Maintenance: Floor paint damaged in dorm To be repainted by 8/15/26.
19. Medical West Unit	Room # 6	105 CMR 451.353	Interior Maintenance: Floor paint damaged To be repainted by 8/15/26.

Building # 12 – Vehicle Trap

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency was found during the inspection:

1. Tower	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control leaking at handwash sink To be repaired by 4/30/26.
----------	-----------------	---

Staff Gym

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Female Locker Room	105 CMR 451.123	Maintenance: Drain flies observed in shower # 1 Clean drain by 4/17/26.
-----------------------	-----------------	---

2. Male Locker Room	105 CMR 451.123*	Maintenance: Ceiling tiles water stained To be replaced by 5/15/26.
---------------------	------------------	---

Deficiencies under the Recommended Standards (.300 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Common Area	105 CMR 451.353*	Interior Maintenance: Carpet damaged To be repaired by 6/15/26.
2. Common Area	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained To be replaced by 6/15/26.


SECTION 2: Areas Found to be in Compliance

The EHRS inspected 314 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 3 areas of the facility because they were either in use, locked, or under construction.

1. Building # 3 – Bradford	B2 Unit	Dorm Corridor	Dorm Shower	Unable to Inspect – In Use
2. Building # 11 – Lighthouse (medical)	Old Seclusion Area			Unable to Inspect – Under Construction
3. Building # 11 – Lighthouse (medical)	Booking Corridor	Former Property Area		Unable to Inspect – Under Construction



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street
Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kiame Mahaniah, MD, MBA
Secretary

Kimberley Driscoll
Lieutenant Governor

Robert Goldstein, MD, PhD
Commissioner

April 17, 2026

Jeffrey Gonsalves, Superintendent
Bridgewater State Hospital
20 Administration Road
Bridgewater, MA 02324 (electronic copy)

Re: Plan of Correction – Bridgewater State Hospital

Dear Superintendent Gonsalves:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction (POC) in response to my inspection on March 30 and 31, 2026. After review, EHRS finds the plan appropriately addresses all the deficiencies noted in the report.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

A handwritten signature in blue ink that reads "Patrick Wallace".

Patrick Wallace
Environmental Analyst, EHRS, BCEH

cc: James Rioux, Deputy Superintendent
Michael Rosano, Environmental Health and Safety Officer

(electronic copy)
(electronic copy)