

CHARLES D. BAKER Governor

KARYN E. POLITO Lieutenant Governor

The Commonwealth of Massachusetts Executive Office of Health and Human Services Department of Public Health Bureau of Environmental Health Community Sanitation Program 5 Randolph Street, Canton, MA 02021 Phone: 781-828-7700 Fax: 781-774-6700

MARYLOU SUDDERS Secretary

MARGRET R. COOKE Acting Commissioner

Tel: 617-624-6000 www.mass.gov/dph

January 12, 2022

Victor Correia, Superintendent Massachusetts Treatment Center 30 Administration Road Bridgewater, MA 02324 (electronic copy)

Re: Plan or Correction - Massachusetts Treatment Center, Bridgewater

Dear Superintendent Correia:

The Massachusetts Department of Public Health, Community Sanitation Program (CSP) has received your Plan of Correction in response to my inspection on November 3 and 4, 2021. After review, the CSP finds the plan does not appropriately addresses all the violations noted in the report.

Please provide an appropriate corrective action and date of completion for the following violations:

- 1. Floor surface damaged in cell # 9 and 10 in A1 unit;
- 2. Ceiling dirty in shower # AG-36 in A2 unit;
- 3. Stair treads damaged in common area of B1 unit;
- 4. Tile grout dirty on walls in shower # BM-35 and BM-36 in B2 unit;
- 5. Ceiling paint damaged in shower # BM-35 and BM-36 in B2 unit;
- 6. Door frame rusted in shower # BG-35 in B2 unit;
- 7. Floor surface damaged in cell # 14 in B2 unit;
- 8. Floor surface damaged in North-Side Dining Area;
- 9. Door not shutting properly on ice machine in main kitchen;
- 10. Ceiling dirty in shower # CM-13 in C1 unit;
- 11. Ceiling dirty in shower # DM-35 in D2 unit;
- 12. Ceiling dirty in shower # DG-36 in D2 unit;
- 13. Mold growth observed on ceiling outside showers in East Bathroom of South 1 unit;
- 14. Shower head leaking in shower # 5 in East Bathroom of South 1 unit;
- 15. Water leaking into shower # 5 from above in East Bathroom of South 1 unit;
- 16. Caulking dirty in shower # 5 in East Bathroom of South 2 unit; and
- 17. Drain cover missing at slop sink in Utility Closet in North 2 unit.

In regards to the following violations, the time frame for completion seems excessive:

- 1. Ceiling dirty in shower # AG-36 in A2 unit;
- 2. Excessive ice build-up observed at entrance to freezer in main kitchen;
- 3. Ceiling dirty in shower # CM-13 in C1 unit;
- 4. Ceiling dirty in shower # DM-35 in D2 unit;
- 5. Wall tile grout dirty in shower # DG-35 in D2 unit;
- 6. Ceiling dirty in shower # DG-36 in D2 unit;
- 7. No functioning thermometer in refrigerator in Staff Office # B2-40;
- 8. Mold growth observed on ceiling outside showers in East Bathroom of South 1 unit; and
- 9. Caulking dirty in shower # 5 in East Bathroom of South 2 unit.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Catuch Wallace

Patrick Wallace Environmental Health Inspector, CSP, BEH

cc: Margret R. Cooke, Acting Commissioner, DPH

Nalina Narain, Director, BEH

Steven Hughes, Director, CSP, BEH

Marylou Sudders, Secretary, Executive Office of Health and Human Services (electronic copy) Carol A. Mici, Commissioner, DOC (electronic copy) Terrence Reidy, Secretary, EOPSS (electronic copy) Timothy Gotovich, Director, Policy Development and Compliance Unit (electronic copy) Sally Desrosiers, Deputy Superintendent (electronic copy) David Dufresne, EHSO/FSO (electronic copy) Eric J. Badger, CHO, Health Agent, Bridgewater Health Department (electronic copy) Clerk, Massachusetts House of Representatives (electronic copy) Clerk, Massachusetts Senate (electronic copy)