

CHARLES D. BAKER Governor

KARYN E. POLITO Lieutenant Governor

# The Commonwealth of Massachusetts Executive Office of Health and Human Services Department of Public Health Bureau of Environmental Health Community Sanitation Program 180 Beaman Street, West Boylston, MA 01583 Phone: 508-792-7880 Fax: 508-792-7706 TTY: 508-835-9796

MARYLOU SUDDERS Secretary

MONICA BHAREL, MD, MPH Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

January 29, 2018

Peter J. Koutoujian, Sheriff Middlesex County Sheriff's Office 400 Mystic Avenue Medford, MA 02155

Re: Facility Inspection - Middlesex County Jail and House of Corrections, Billerica

Dear Sheriff Koutoujian:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Middlesex County Jail and House of Corrections on January 19, 22, and 23, 2018 accompanied by Sergeant Shane Cassidy, EHSO; Captain William Buckley, EHSO; Deputy Dan Finn, and Captain Daniel Lee. Violations noted during the inspection are listed below including 78 repeat violations:

#### **HEALTH AND SAFETY VIOLATIONS**

(\* indicates conditions documented on previous inspection reports)

## CHECKPOINT BUILDING

Janitor's Closet

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Control Desk

No Violations Noted

#### PODULAR BUILDING

Lobby

Water Fountain

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

**Administration Wing** 

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

Unable to Inspect - Locked

Kitchenette

No Violations Noted

Visiting Area

No Violations Noted

Visitor's Side

No Violations Noted

**Central Control** 

No Violations Noted

Bathroom

105 CMR 451.123

Maintenance: Ceiling vent dusty

Attorney Visit Hallway

Janitor's Closet

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Visiting Control Room

No Violations Noted

Inmate Bathroom

105 CMR 451.123

Maintenance: Floor dirty

Urinalyses Room

Unable to Inspect - Locked ·

Visiting Area - Inmate Side

No Violations Noted

## Entrance Hallway for Pod A & B

Nurse's Station

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, hot water handle leaking at handwash

sink

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Caseworker's Office

No Violations Noted

Pod A

Common Area

No Violations Noted

Storage Cage (Barber Shop)

No Violations Noted

Janitor's Closet

No Violations Noted

Pod Storage Room

No Violations Noted

Lower Level Shower Area # 1-5

105 CMR 451.124\* Water Supply: Insufficient water supply in quantity and pressure in shower unit # 4

105 CMR 451.123 Maintenance: Soap scum observed on bench in shower # 5

Lower Cells

105 CMR 451.126\* Hot Water: Hot water temperature recorded at 90°F in cell # 1-24

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, cold water continually running in

cell # 1-09, 1-15, and 1-21

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, toilet clogged in cell # 1-04

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, handwash sink not draining properly

in cell # 1-01

105 CMR 451.353 Interior Maintenance: Floor paint damaged in cell # 1-13

105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 1-24

Upper Level Shower Area #6-10 Maintenance: Handwash sink out-of-order ·105 CMR 451.123 Maintenance: Ceiling damaged outside shower #9 105 CMR 451.123 Maintenance: Walls dirty outside shower #9 105 CMR 451.123 Maintenance: Soap scum observed on walls in shower # 6, 8, and 9 105 CMR 451.123 Upper Cells Toilet and Handwashing Sink in Locked Cells: No hot running water in locked 105 CMR 451.113\* cell # 2-27 Plumbing: Plumbing not maintained in good repair, cold water continually running in 105 CMR 451.130 cell # 2-05 Plumbing: Plumbing not maintained in good repair, hot water continually running in 105 CMR 451.130 cell # 2-14 and 2-23 Plumbing: Plumbing not maintained in good repair, handwash sink not draining properly 105 CMR 451.130 in cell # 2-03 Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 2-20 105 CMR 451.140 Interior Maintenance: Floor paint damaged in cell # 2-17 105 CMR 451.353\* Interior Maintenance: Floor paint damaged in cell #2-11 and 2-12 105 CMR 451.353 Pod B Common Area No Violations Noted Counselor's Office No Violations Noted Storage Cage (Barber Shop) No Violations Noted Janitor's Closet Illumination in Habitable Areas: Inadequate lighting, light out 105 CMR 451.344 Storage Room (Small) 105 CMR 451.353\* Interior Maintenance: Wet mop stored in bucket Storage Room (Large) No Violations Noted Lower Level Shower Area Maintenance: Soap scum on walls in shower # 1 105 CMR 451.123 Maintenance: Mold observed on ceiling outside shower # 1 105 CMR 451.123 Lower Cells Plumbing: Plumbing not maintained in good repair, cold water continually running in 105 CMR 451.130\* cell # 1-16 105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, water continually running in cell # 1-01, 1-03, 1-05, 1-13, 1-14, 1-15, 1-26, 1-28, and 1-29 Maintenance: Black substance observed on handwash sink in cell # 1-03, 1-05, and 1-16 105 CMR 451.123 Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 1-31 105 CMR 451.140 Interior Maintenance: Floor paint damaged in cell # 1-13 and 1-15 105 CMR 451.353 105 CMR 451.353 Interior Maintenance: Floor surface cracked in cell # 1-07 Interior Maintenance: Wall paint damaged in cell # 1-26 105 CMR 451.353

Maintenance: Light out in shower # 6

451-18(1)-Middlesex-Billerica-Report 1-29-18

Upper Level Shower Area

105 CMR 451.123

Upper Cells Plumbing: Plumbing not maintained in good repair, hot water continually running in 105 CMR 451.130\* cell # 2-19 Plumbing: Plumbing not maintained in good repair, hot water continually running in 105 CMR 451.130 cell # 2-04 and 2-06 Plumbing: Plumbing not maintained in good repair, cold water continually running in 105 CMR 451.130 cell # 2-12 and 2-17 Plumbing: Plumbing not maintained in good repair, water continually running in 105 CMR 451.130

cell # 2-02, 2-22, and 2-24

Plumbing: Plumbing not maintained in good repair, handwash sink not draining properly 105 CMR 451.130

in cell # 2-02, 2-05, 2-12, and 2-24

Plumbing: Plumbing not maintained in good repair, handwash sink rusted in cell # 2-02 105 CMR 451.130

## Entrance Hallway for Pod C & D

Nurse's Station

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Office

No Violations Noted

Pod C

Common Area

Interior Maintenance: Floor paint damaged 105 CMR 451.353\*

Storage Cage (Barber Shop)

No Violations Noted

Janitor's Closet

No Violations Noted

Storage Room

Interior Maintenance: Ceiling vent dusty 105 CMR 451.353

Counselor/Interview Office

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 451.200

105 CMR 590.000, thermometer broken in refrigerator

Multi-Purpose Room

No Violations Noted

Lower Level Shower Area

Maintenance: Soap scum observed on walls in shower # 1, 3, 4, and 5 105 CMR 451.123

Maintenance: Floor dirty in shower # 5 105 CMR 451.123\*

Maintenance: Shower curtain dirty in shower # 5 105 CMR 451.123

Lower Cells	•
105 CMR 451.126*	

Hot Water: Hot water temperature recorded at 90°F in cell # 1-29

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, cold water continually running in

cell # 1-24

105 CMR 451,130 Plumbing: Plumbing not maintained in good repair, water continually running in

cell # 1-25

105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 1-21

Upper Level Shower Area # 6-10

105 CMR 451.123\* Maintenance: Shower # 7 out-of-order

105 CMR 451.130 Hot Water: Shower water temperature recorded at 90°F in shower # 6

105 CMR 451.123 Maintenance: Soap scum on walls in shower # 6

Upper Cells

105 CMR 451.353\* Interior Maintenance: Floor paint damaged in cell # 2-21, 2-25, and 2-26

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, cold water continually running in

cell # 2-14

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, hot water continually running in

cell # 2-31

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, handwash sink not draining properly

in cell # 2-31

#### Pod D

Common Area

No Violations Noted

Storage Cage (Barber Shop)

No Violations Noted

Janitor's Closet

105 CMR 451.130\* 105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, drain cover missing on slop sink Plumbing: Plumbing not maintained in good repair, backflow preventer leaking on slop

sink

Counselor/Interview Room

No Violations Noted

Multi-Purpose Room

No Violations Noted

Pod Storage Room

No Violations Noted

Lower Level Shower Area

105 CMR 451.123\* Maintenance: Shower # 3 out-of-order

105 CMR 451.124 Water Supply: Insufficient water supply in quantity and pressure in shower unit # 2

105 CMR 451.123 Maintenance: Ceiling paint damaged outside shower # 1

Lower Cells

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, cold water continually running in

cell # 1-09 and 1-15

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, hot water continually running in

cell # 1-28

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, water continually running in

cell # 1-02 and 1-14

Upper Level Shower Area

105 CMR 451.123 Maintenance: Handwash sink pulling away from wall 105 CMR 451.123 Maintenance: Pooling water outside shower # 1 105 CMR 451.123 Maintenance: Ceiling vents dusty outside all showers

Upper Cells

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, water continually running in

cell # 2-24 and 2-32

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, cold water continually running in

cell # 2-18, 2-23, and 2-27

105 CMR 451.353 Interior Maintenance: Floor paint damaged in cell # 2-21

Pod F

Administration Area

No Violations Noted

Female Staff Bathroom

No Violations Noted

Janitor's Closet

. 105 CMR 451.344\*

Illumination in Habitable Areas: Light not functioning properly, light not working

105 CMR 451.353\* Interior Maintenance: Ceiling vent dusty

Male Staff Bathroom

No Violations Noted

Medical Office

105 CMR 451.126 Hot Water: Hot water temperature recorded at 100°F

Block

Janitor's Closet

No Violations Noted

Barber Shop

No Violations Noted

Storage

No Violations Noted

Lower Showers

No Violations Noted

Lower Cells

No Violations Noted

Assessment Office

No Violations Noted

Library/Multi-Purpose Room

No Violations Noted

Case Worker's Office

Upper Cells

No Violations Noted

Upper Showers # 1-10

105 CMR 451.123

Maintenance: Soap scum on walls in shower #8

Common Area

No Violations Noted

Dorm #3 and 4 Landing

Male Bathroom

No Violations Noted

Female Bathroom

Unable to Inspect - Locked

Janitor's Closet

No Violations Noted

Storage/Med Pass

No Violations Noted

Medical Office

Unable to Inspect - Locked

Classroom # 2

No Violations Noted

Multi-Purpose Hallway

No Violations Noted

Storage Room # 1 and 2

No Violations Noted

Classroom A and B

No Violations Noted

**Dorm #3** 

Sleeping Area

No Violations Noted

Common Area

No Violations Noted

Toilet Area

105 CMR 451.124\* Water Supply: Insufficient cold water supply in quantity and pressure at handwash

sink # 5

105 CMR 451.124 Water Supply: Insufficient cold water supply in quantity and pressure at handwash

sink#6

105 CMR 451.124\* Water Supply: Insufficient hot water supply in quantity and pressure at handwash

sink # 6 and 7

Sink Area

105 CMR 451.124 Water Supply: Insufficient water supply in quantity and pressure at both water bubblers

105 CMR 451.123 Maintenance: Walls dirty around handwash sink

Shower Area

105 CMR 451.123 Maintenance: Drain flies observed in shower # 3

105 CMR 451.124 Water Supply: Insufficient water supply in quantity and pressure in shower unit # 3

Janitor's Closet

No Violations Noted

Case Worker's Office

Unable to Inspect – In Use

Barber Shop

No Violations Noted

Dorm # 4

Barber Shop

No Violations Noted

Case Worker's Office

Unable to Inspect - Locked

Janitor's Closet

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, backflow preventer leaking

105 CMR 451.353 Interior Maintenance: Unlabeled chemical bottle

Shower Area

105 CMR 451.123 Maintenance: Floor dirty in shower # 1 and 3

Toilet Area

105 CMR 451.123 Maintenance: Strong urine odor present

105 CMR 451.123 Maintenance: Floor dirty in toilet stall # 2, 4, and 5

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, toilet clogged in stall # 8

Sink Area

105 CMR 451.126\* Hot Water: Hot water temperature recorded at 92°F at handwash sink #3

105 CMR 451.126 Water Supply: No hot water supplied to handwash sink # 2

Common Area

No Violations Noted

Sleeping Area

No Violations Noted

Pod E

Administration Area

Female Staff Bathroom

Unable to Inspect – Locked

Janitor's Closet

Male Staff Bathroom

Unable to Inspect - Locked

Offices

No Violations Noted

Nurse's Station

Unable to Inspect - Locked

Block

Janitor's Closet

No Violations Noted

Barber Shop

No Violations Noted

Storage Room

No Violations Noted

Segregation Showers

105 CMR 451.123 Maintenance: Floor dirty in shower # 1, 3, 5, and 6

Segregation Cells

No Violations Noted

Classroom Assessment

No Violations Noted

Library

No Violations Noted

Caseworker's Office

No Violations Noted

Upper Cells

105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 2-02 and 2-11

Upper Showers

105 CMR 451.123 Maintenance: Soap scum observed on floor in shower # 1, 2, and 3

105 CMR 451.123 Maintenance: Debris in floor drain in shower # 2

Dorm # 1 and 2 Landing

Shift Administrator's Office

Unable to Inspect - Locked

Janitor's Closet

No Violations Noted

Male Staff Bathroom

No Violations Noted

Female Staff Bathroom

Unable to Inspect - Locked

Storage/Med Pass

No Violations Noted

Medical Office

Unable to Inspect - Locked

Classroom # 1

No Violations Noted

Dorm # 1

Sleeping Area

No Violations Noted

Common Area

No Violations Noted

Toilet Area

Water Supply: Insufficient cold water supply in quantity and pressure at handwash 105 CMR 451.124

sink #8

105 CMR 451.123

Maintenance: Door missing at toilet stall # 2

105 CMR 451.123

Maintenance: Floor dirty in toilet stall #7

Sink Area

105 CMR 451.126\*

Water Supply: No hot water supplied to handwash sink #3

105 CMR 451.126

Hot Water: Hot water temperature recorded at 100°F at handwash sink # 2

Shower Area

105 CMR 451.123\*

Maintenance: Mold observed on caulking around shower control in shower # 1

105 CMR 451.123

Maintenance: Floor drain clogged in shower #3

Janitor's Closet

105 CMR 451.353

Interior Maintenance: Unlabeled chemical bottle

Case Worker's Office

No Violations Noted

Barber Shop

No Violations Noted

**Dorm #2** 

Barber Shop

No Violations Noted

Case Worker's Office

No Violations Noted

Janitor's Closet

No Violations Noted

Shower Area

Maintenance: Mold observed on caulking in shower # 6 and 7 105 CMR 451.123\*

105 CMR 451.123

Maintenance: Mold observed on caulking in shower #8

105 CMR 451.123

Maintenance: Ceiling vent rusted in shower # 8

Toilet Area

105 CMR 451.126

Unable to Inspect Stall # 4-8 - In Use

Water Supply: No hot water supplied to handwash sink # 1

Sink Area

No Violations Noted

Common Area

No Violations Noted

Sleeping Area

No Violations Noted

**Intake and Discharge** 

Deputy's Office

No Violations Noted

Janitor's Closet

Unable to Inspect - Locked

Administrative Office

No Violations Noted

Holding Tank # 2

Unable to Inspect - In Use

Shake Room # 1 & 2

No Violations Noted

Holding Cell # 1

No Violations Noted

Institutional Property

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with

105 CMR 590.000, no functioning thermometer in refrigerator

Desk Area

No Violations Noted

Sally Port

No Violations Noted

Old Shower Room # 1

No Violations Noted

Holding Cell # 1-6

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, water continually running in cell #3

Break Room

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with

105 CMR 590.000, disposable silverware left uncovered

Male Bathroom

Female Bathroom 105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, sink not draining properly

Inmate Property Room

105 CMR 451.353

Interior Maintenance: Washer out-of-order

105 CMR 451.353 Interior Maintenance

Interior Maintenance: Pooling water on floor around washer

Change Room # 1 and 2

No Violations Noted

A & B Hall Entrance

Janitor's Closet

No Violations Noted

Teacher's Office

Unable to Inspect - Locked

Hall A

No Violations Noted

Hall B

No Violations Noted

Food Service Area

Staff Dining Room

FC 4-501.11(B)\* Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, gasket damaged on right side refrigerator

FC 3-501.16(A) Limitation of Growth of Organisms, Temperature and Time Control: Potentially

hazardous food not held at the proper hot holding temperature, soup temperature recorded

at 120°F

FC 4-903.11(B)(2) Protection of Clean Items, Storing: Single-service items not stored in an inverted position

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Supply Dock

Loading Dock

No Violations Noted

Surplus Storage Room

No Violations Noted

Storage Room

No Violations Noted

**Back of Kitchen** 

Supply Room # 2 (Dry Storage)

Culinary Arts Storage Cabinet

No Violations Noted

Chemical Supply Closet

No Violations Noted

Daily Cleaning Cabinet

No Violations Noted

Kitchen Staff Break Room

No Violations Noted

Supply Room # 1

No Violations Noted

Inmate Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Rack Spray Area

No Violations Noted

Main Kitchen Area

Cooler # 1

No Violations Noted

Warmer # 1 & 2

No Violations Noted

Serving Line

No Violations Noted

Handwash Sink – Near Pots and Pans Sink

FC 5-205.15(B) Plumbing System, Operations and Maintenance: Plumbing system not maintained in

good repair, handwash sink leaking

FC 6-501.11\* Maintenance and Operation; Repairing: Facility not in good repair, floor tiles damaged

around floor drain

Pots and Pan Sink

No Violations Noted

Mechanical Warewash Area

FC 6-501.11\* Maintenance and Operation; Repairing: Facility not in good repair, grease trap access

panel rusted

Warewash Machine

No Violations Noted

Handwash Sink after Warewash Machine

FC 6-301.11 Numbers and Capacity; Handwashing Facilities: No soap at handwash sink

Inmate Coffee Area

Diet Area/Serving Line # 2

No Violations Noted

Warmer # 3 & 4

No Violations Noted

Refrigerator # 2

No Violations Noted

McCall Proofer # 1

No Violations Noted

3 Warmers (under hoods)

FC 6-501.11\* Maintenance and Operation; Repairing: Facility not in good repair, light out under hood

Prep Tables and Sinks

FC 5-205.15(B)\* Plumbing System, Operations and Maintenance: Plumbing system not maintained in

good repair, uncovered floor drain under single bay prep sink

FC 5-205.15(B) Plumbing System, Operations and Maintenance: Plumbing system not maintained in

good repair, hot water continually running on prep sink near kettles

Ice Machine #4

No Violations Noted

Ice Machine #2

No Violations Noted

Handwash Sink (after ice machine # 2)

No Violations Noted

Kettle Area

No Violations Noted

Walk-in Refrigerator # 2

No Violations Noted

Spice Cabinet

No Violations Noted

Walk-in Refrigerator # 1

No Violations Noted

Hood Area with Warmers

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, lights not working

under hoods

Walk-in Freezer

No Violations Noted

Sallyport/Changing Area

No Violations Noted

Janitor's Closet

Officer's Area/Office

No Violations Noted

## Culinary Arts Program Kitchen

Classroom

No Violations Noted

McCall Refrigerator

No Violations Noted

**Proofers** 

No Violations Noted

Walk-in Freezer

No Violations Noted

Hood Area

No Violations Noted

Handwash Sink

No Violations Noted

3-Bay Sink

No Violations Noted

Prep Sink

No Violations Noted

Prep Tables

No Violations Noted

Walk-in Refrigerator

No Violations Noted

## **Health Service Unit**

ISO # 1 & 2

No Violations Noted

Nurse's Pantry

No Violations Noted

Janitor's Closet

No Violations Noted

Risk Cell # 1 & 2

Unable to Inspect Risk Cell # 1 - In Use

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, water continually running in risk

cell # 2

Private Rooms # 1-4

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, water continually running at

handwash sink in room #2

Ward A

Storage Room

No Violations Noted

Handicap Shower Room

105 CMR 451.123

Maintenance: Soap scum observed on walls in shower

Nurse's Station and Bathroom

No Violations Noted

Cleaning Utility Room

No Violations Noted

Storage Room # 1

No Violations Noted

Storage Room # 2

No Violations Noted

Holding

No Violations Noted

Ward B

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, water continually running at

handwash sink/toilet unit #2

105 CMR 451.123

Maintenance: Soap scum observed on walls in shower # 1

Pharmacy.

No Violations Noted

Janitor's Closet

No Violations Noted

Physical Therapy (Treatment Room # 4)

No Violations Noted

Treatment Room # 1

No Violations Noted

Inmate Bathroom

No Violations Noted

Treatment Room # 2

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, cold water continually running at

handwash sink

105 CMR 451.126 Hot Water: Hot water temperature recorded at 80°F at handwash sink

105 CMR 451.124 Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink

Medical Waste Storage

No Violations Noted

Treatment Room #3

No Violations Noted

Coordinator's Office

Lab

No Violations Noted

Dental Room

Unable to Inspect - In Use

Infectious Disease Office

No Violations Noted

Psychiatry Office

No Violations Noted

Exam Room # 2

No Violations Noted

Exam Room # 1

No Violations Noted

# **HSU Administration Hallway**

Male Bathroom

Unable to Inspect - In Use

Female Bathroom

No Violations Noted

Medical Records

No Violations Noted

Health Service Administrator's Office

No Violations Noted

# **Classifications Building**

#### Main Level

Lobby

105 CMR 451.350 Structural Maintenance: Window panes broken at entrance

Janitor's Closet

No Violations Noted

Female Bathroom

105 CMR 451.123\* Maintenance: Toilet # 2 out-of-order 105 CMR 451.123\* Maintenance: Window broken

Male Bathroom

105 CMR 451.130\* Plumbing: No backflow preventer on sink

105 CMR 451.130\* Plumbing: Plumbing not maintained in good repair, drain cover missing in slop sink
105 CMR 451.124 Water Supply: Insufficient hot and cold water supply in quantity and pressure at slop sink

105 CMR 451.123 Maintenance: Toilet paper holder broken

Control Area

105 CMR 451.350\* Structural Maintenance: Windows not weathertight and structurally sound

105 CMR 451.350\* Structural Maintenance: Several window panes broken

105 CMR 451.350\* Structural Maintenance: Window sills and wall near windows damaged

Roll Call Room

No Violations Noted

# Old Administration Wing

First Floor

Offices

No Violations Noted

Storage Closet

No Violations Noted

Female Bathroom

No Violations Noted

Tool Crib Area

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, backflow preventer missing on slop

sink

Tool Crib Bathroom

No Violations Noted

Mail Room

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles missing

105 CMR 451.200\*

Food Storage, Preparation and Service: Food storage not in compliance with

105 CMR 590.000, excessive ice buildup in freezer

Canteen Area

No Violations Noted

Second Floor

105 CMR 451.353

Interior Maintenance: Ceiling tiles missing

Male Bathroom # 2

105 CMR 451.123

Maintenance: Strong urine odor present

**New Male Locker Room** 

105 CMR 451.353

Interior Maintenance: Floor dirty throughout

Male Locker Room Bathroom

105 CMR 451.123\*

Maintenance: Window broken

105 CMR 451.123\*

Maintenance: Water stained ceiling tiles

105 CMR 451.123\*

Maintenance: Screen missing

Male Shower Room

No Violations Noted

Classifications & Old Infirmary Hallway

105 CMR 451.353

Interior Maintenance: Ceiling tiles missing

Offices

No Violations Noted

Female Bathroom

105 CMR 451.123\*

Maintenance: Wall damaged around window

451\_18(1)-Middlesex-Billerica-Report 1-29-18

Male Bathroom # 1

105 CMR 451.123\* Maintenance: Window broken

105 CMR 451.124\* Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink

105 CMR 451.123\* Maintenance: Wall paint damaged

Old Shower Room

No Violations Noted

Staff Break Room

105 CMR 451.353\* Interior Maintenance: Wall paint damaged

105 CMR 451.200 Food Storage, Preparation and Service: Food storage not in compliance with

105 CMR 590.000, disposable silverware left uncovered

Offices

105 CMR 451.353 Interior Maintenance: Ceiling tiles water stained in copy room

Third Floor

105 CMR 451.350\* Structural Maintenance: Several window panes broken throughout area

105 CMR 451.141\* Screens: Screens damaged throughout area

105 CMR 451.353 Interior Maintenance: Floor dirty throughout area

Male Locker Room

105 CMR 451.353 Interior Maintenance: Floor dirty

Male Locker Room Bathroom

105 CMR 451.123\* Maintenance: Wall paint damaged near soap dispenser # 3

105 CMR 451.123\* Maintenance: Floor paint damaged
105 CMR 451.123 Maintenance: Dead bugs in light shield
105 CMR 451.123 Maintenance: Light out in toilet stall # 2

105 CMR 451.123 Maintenance: Toilet fixtures dirty in stall # 2

105 CMR 451.123 Maintenance: Showers dirty

Female Locker Room

Unable to Inspect - Locked

Officer's Weight Room

105 CMR 451.350\* Structural Maintenance: Window panes broken

105 CMR 451.353 Interior Maintenance: Floor dirty

Lower Report

A & B Side Cells

Unable to Inspect – No longer in use due to lack of natural lighting

Training Center

First Floor

Barber Area

No Violations Noted

Library

No Violations Noted

Meeting Room

No Violations Noted

19(1) Notable---- Dillowing Demont 1 20 19 Page 20 of 27

Offices and Classroom

105 CMR 451.353 Interior Maintenance: Ceiling tiles water damaged in classroom after library

Bathroom

105 CMR 451.350 Structural Maintenance: Window broken 105 CMR 451.123 Maintenance: Ceiling tiles water stained

Storage Room

105 CMR 451.130\* Plumbing: No backflow preventer on slop sink

Chapel

105 CMR 451.350 Structural Maintenance: Window panes broken

Second Floor

Main Laundry

105 CMR 451.350\* Structural Maintenance: Window broken

105 CMR 451.353 Interior Maintenance: Light shield missing on lights near dryer units

Inmate Bathroom

105 CMR 451.350\* Structural Maintenance: Window broken

Officer's Bathroom

105 CMR 451.123\* Maintenance: Wall paint peeling on brick wall

105 CMR 451.123\* Maintenance: Window cracked

105 CMR 451.124\* Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink

Laundry Storage

No Violations Noted

Main Level

Old Wing Day Room

No Violations Noted

Side Entry Stairs

No Violations Noted

**HUMV Dorm Room** 

No Violations Noted

Dorm Bathroom

105 CMR 451.124\* Water Supply: Insufficient hot and cold water supply in quantity and pressure at

handwash sink # 1 and 2

105 CMR 451.123 Maintenance: Wall paint damaged outside handicap shower

105 CMR 451.123 Maintenance: Ceiling vent dusty near showers

First Tier

Control

No Violations Noted

Janitor's Closet

105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

A & B Side Cell Size: Inadequate floor space in all cells 105 CMR 451.320\* Interior Maintenance: Wall paint damaged in cell # B17 105 CMR 451.353 Interior Maintenance: Ceiling damaged in cell # A12 105 CMR 451.353\* Interior Maintenance: Ceiling damaged in cell # B5, B9, and B24 105 CMR 451.353 Bathroom and Shower Area Maintenance: Ceiling paint damaged in shower # 4 105 CMR 451.123 Water Supply: Insufficient water supply in quantity and pressure in shower unit # 11 105 CMR 451.124\* Water Supply: Insufficient hot and cold water supply in quantity and pressure at 105 CMR 451.124 handwash sink Maintenance: Soap scum observed on walls in shower # 4, 8, and 11 105 CMR 451.123 · C & D Side (Administrative Segregation and Segregation Unit) Unable to Inspect – Under Construction Shower Room # D23 Unable to Inspect - Under Construction **Second Tier** 105 CMR 451.353\* Interior Maintenance: Multiple cell windows painted Structural Maintenance: Window pane broken in stairway 105 CMR 451.350 Nurse's Room Unable to Inspect - Locked Control No Violations Noted E & F Side Cell Size: Inadequate floor space in all cells 105 CMR 451.320\* Interior Maintenance: Floor paint damaged in cell # 12 105 CMR 451.353 Interior Maintenance: Ceiling paint damaged in cell # E16 and outside cell # F19 105 CMR 451.353 Mattresses: Mattress damaged in cell # F13 105 CMR 451.103 Toilet Fixtures: Toilet fixtures dirty in cell # E16 105 CMR 451.117 Bathroom and Shower Area Maintenance: Floor drain not draining properly in shower #3 105 CMR 451.123\* Maintenance: Ceiling damaged in shower # 1 and 9 105 CMR 451.123 Water Supply: No hot water supplied to handwash sink 105 CMR 451.126 Plumbing: Plumbing not maintained in good repair, cold water handle leaking at slop sink 105 CMR 451.130 Janitorial Cage Interior Maintenance: Wet mop stored in bucket 105 CMR 451.353\* Interior Maintenance: Standing water left in bucket 105 CMR 451.353 G & H Side Cell Size: Inadequate floor space in all cells 105 CMR 451.320\* Interior Maintenance: Floor paint damaged in cell # H8 105 CMR 451.353 Interior Maintenance: Wall paint damaged in cell # G7, G23, and H16 105 CMR 451.353 Interior Maintenance: Ceiling paint damaged in cell # G5, H4, H11, and H25 105 CMR 451.353 Plumbing: Plumbing not maintained in good repair, discolored water observed coming

#### Gym

105 CMR 451.130

Structural Maintenance: Windows not weathertight and structurally sound 105 CMR 451.350\*

from handwash sink in cell # H17

Page 22 of 27

Gym Office

No Violations Noted

Staff Bathroom

105 CMR 451.110(A)\*

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

Stairway to Third Tier

No Violations Noted

Third Tier

105 CMR 451.353\*

Interior Maintenance: Multiple cell windows painted

Day Room

No Violations Noted

Control

No Violations Noted

Offices

No Violations Noted

I & J Side

Cell Size: Inadequate floor space in all cells 105 CMR 451.320\*

Hot Water: Hot water temperature recorded at 75°F in cell # J5 105 CMR 451.126\*

Mattresses: Mattress damaged in cell # J20 105 CMR 451.103

Interior Maintenance: Wall cracked in cell # J20 and J26 105 CMR 451.353

Water Supply: Insufficient water supply in quantity and pressure at handwash sink in 105 CMR 451.124

cell # J19

Bathroom and Shower Area

105 CMR 451.130\* Plumbing: Plumbing not maintained in good repair, hot water continually running at

handwash sink

Janitor's Closet

No Violations Noted

K & L Side

Cell Size: Inadequate floor space in all cells 105 CMR 451.320\*

Structural Maintenance: Window pane broken in cell # K1 105 CMR 451.350 Interior Maintenance: Floor paint damaged in cell # L9 105 CMR 451.353 Interior Maintenance: Ceiling paint damaged in cell # K5 105 CMR 451.353 Mattresses: Mattress damaged in cell # K2 and K7 105 CMR 451.103

105 CMR 451.353

Interior Maintenance: Debris on floor in cell # L25

**CWP Building** 

Unable to Inspect - Closed

## Work Release Building

## **House # 1**

First Floor

Hallway

*Infirmary* 

No Violations Noted

Control

No Violations Noted

Office

No Violations Noted

**Bathroom** 

No Violations Noted

**Bedrooms** 

105 CMR 451.353

Interior Maintenance: Wall paint damaged in room # 1

Food Service Area

Dining Room

FC 6-202.15(A)(3)\* Design, Construction, and Installation; Functionality: Outer door not weather and vermin

tight

Kitchen

FC 4-501.11(A) Maintenance and Operation, Equipment: Equipment not maintained in a state of good

repair, 3-temperature control knobs missing on stove

Second Floor

Stairway

No Violations Noted

Hallway

No Violations Noted

**Bedrooms** 

No Violations Noted

Bathroom

105 CMR 451.123

Maintenance: Screen missing

Stairway to Basement

No Violations Noted

**Basement** 

Laundry Room

105 CMR 451.353

Interior Maintenance: Dryer out-of-order

Boiler Room

Unable to Inspect - Locked

Chemical Storage Room

No Violations Noted

**Day Room Between Houses** 

# **House # 2**

#### First Floor

Hallway

No Violations Noted

Night Shift Office

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with

105 CMR 590.000, excessive ice buildup in freezer

Officer's Bathroom

No Violations Noted

Bedrooms

No Violations Noted

Administration Office

No Violations Noted

Second Floor

Hallway

No Violations Noted

Bathroom

105 CMR 451.123\* 105 CMR 451.123 Maintenance: Counter top cracked near sink # 2 Maintenance: Curtain missing for toilet stall # 1 and 2

105 CMR 451.123

Maintenance: Mop stored in bucket

Bedrooms

105 CMR 451.350

Structural Maintenance: Emergency exit door not weathertight, weather stripping

damaged

Third Floor

Bedrooms

105 CMR 451.141

Screens: Screen damaged in room #7

**Basement** 

Day Room

No Violations Noted

Property

Unable to Inspect - Locked

Bathroom

105 CMR 451.130

Hot Water: Shower water temperature recorded at 90°F in shower # 1

105 CMR 451.123

Maintenance: Shower curtain missing for shower # 1

105 CMR 451.123

Maintenance: Soap scum observed on shower curtain in shower # 2 and 4

105 CMR 451.123

Maintenance: Toilet # 1 removed

Storage Room

Unable to Inspect - Locked

WAREHOUSE

No Violations Noted

Office

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Old Walk-in Freezer

No Violations Noted

Back Freezer and Refrigerator

No Violations Noted

## Observations and Recommendations

1. The inmate population was 885 at the time of inspection.

2. During the inspection the Department recommended:

a. Re-numbering the bedrooms within the Work Release houses; and

b. Updating the list of individuals who have completed the Bloodborne Pathogen Training that is stored in the medical waste binder within HSU.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at <a href="www.mass.gov/dph/dcs">www.mass.gov/dph/dcs</a> and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at <a href="www.mass.gov/dph/fpp">www.mass.gov/dph/fpp</a> and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

To review the Labeling regulations please visit the Food Protection website at <a href="www.mass.gov/dph/fpp">www.mass.gov/dph/fpp</a> and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,

Kerry Wagner, MPH

Environmental Health Inspector, CSP, BEH

cc: Jana Ferguson, Director, BEH

Steven Hughes, Director, CSP, BEH

Marylou Sudders, Secretary, Executive Office of Health and Human Services

Thomas Turco, Commissioner, DOC

Shawn Jenkins, Special Sheriff

Osvaldo Vidal, Superintendent of Operations

Sergeant Shane Cassidy, EHSO

Captain William Buckley, EHSO

Richard Berube, Director, Billerica Board of Health

Clerk, Massachusetts House of Representatives

Clerk, Massachusetts Senate

Daniel Bennett, Secretary, EOPSS

Nelson Alves, Director, Policy Development and Compliance Unit

			et <sub>e,</sub>
·			