

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

August 3, 2026

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)
Kiame Mahaniah, MD, MBA, Secretary, Executive Office of Health and Human Services (electronic copy)
Clerk, Massachusetts House of Representatives (electronic copy)
Clerk, Massachusetts Senate (electronic copy)
Noe Bard, Environmental Health and Safety Officer (electronic copy)


Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Worcester County Jail and House of Correction, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Hannah LeBeau
Environmental Analyst, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)
Gina K. Kwon, Secretary, Executive Office of Public Safety and Security (electronic copy)
Kris Jansen, Administrative Assistant, West Boylston Board of Health (electronic copy)
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)
Jason Rives, Superintendent (electronic copy)



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
250 Washington Street, Boston, MA 02108-4619
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

May 4, 2026

Lew Evangelidis, Sheriff
Worcester County Jail and House of Correction
5 Paul X. Tivnan Drive
West Boylston, MA 01583 (electronic copy)

Re: Facility Inspection – Worcester County Jail and House of Correction, West Boylston

Dear Sheriff Evangelidis:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Worcester County Jail and House of Correction on April 21 and 22, 2026, accompanied by Captain Eric Locke and Lieutenant Devon Walker, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 371 total deficiencies: 235 new deficiencies under the Required Standards (.100 and .200 series), 20 repeat deficiencies under the Required Standards, 107 new deficiencies under the Recommended Standards (.300 series), 8 repeat deficiencies under the Recommended Standards, and 1 new deficiency under 105 CMR 451.402(B) (other conditions that may constitute a threat to health or safety).

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Main Building

Deficiencies under the Required Standards (.100 and .200 series)

108 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
1. Entrance	Control Room	Control Bathroom	105 CMR 451.123	Maintenance: Wet mop stored in bucket
2. Herman Building	Visiting Room	Female Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty
3. Herman Building	Visiting Room	Female Bathroom	105 CMR 451.123	Maintenance: Wall paint damaged in stall # 2
4. Herman Building	Visiting Room	Female Bathroom	105 CMR 451.123	Maintenance: Ceiling tiles water damaged
5. Herman Building	Visiting Room	Male Bathroom	105 CMR 451.123*	Maintenance: Wall paint damaged above urinal
6. Herman Building	Visiting Room	Male Bathroom	105 CMR 451.123	Maintenance: Strong urine odor present
7. Herman Building	Visiting Room	Male Bathroom	105 CMR 451.117	Toilet Fixtures: Urinal dirty
8. Old Receiving	Breakroom & Bathroom		105 CMR 451.123	Maintenance: Wall paint damaged near toilet
9. A1 Block	Control Booth	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty
10. A1 Block	Lower Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, table under microwave oven dirty
11. A1 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Access panel on ceiling rusted in shower # 2
12. A1 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Mold on ceiling in shower # 2
13. A1 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Ceiling vent dusty outside of showers
14. A1 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.102	Pillows and Linens: Insufficient pillow and linens available for inmates in cell # 28, no sheets available
15. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Wall paint damaged outside of showers
16. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Walls dirty in shower # 1
17. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # 1 and 2
18. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Floor drain dirty in shower # 2
19. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 2
20. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Floor dirty in shower # 2

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
21. A2 Block	Control Booth	Control Bathroom	105 CMR 451.117	Toilet Fixtures: Toilet fixture dirty
22. A2 Block	Lower Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
23. A2 Block	Lower Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, table under microwave oven dirty
24. A2 Block	Upper Tier	Slop Sink Room (Upstairs)	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, floor drain damaged
25. A2 Block	Upper Tier	Slop Sink Room (Upstairs)	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink clogged
26. A2 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Door frame rusted in shower # 1 and 2
27. A2 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Access panel rusted on ceiling in shower # 2
28. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Walls dirty in shower # 1 and 2
29. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Door frame rusted in shower # 1 and 2
30. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Dead drain flies observed on wall in shower # 1
31. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 2
32. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Ceiling dirty around light fixture outside of showers
33. MAXI B	Lower Right Tier	Slop Sink	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, sink leaking
34. MAXI B	Lower Right Tier	Showers	105 CMR 451.123	Maintenance: Caulking along floor dirty in shower # 1 and 2
35. MAXI B	Lower Right Tier	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1 and 2
36. MAXI B	Lower Right Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged at entrance in shower # 2
37. MAXI B	Lower Left Tier	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1 and 2
38. MAXI B	Upper Right Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
39. MAXI B	Upper Right Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, table under microwave oven dirty
40. MAXI B	Upper Left Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
41. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged in shower # 1
42. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 1
43. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Rodent droppings observed in door guide outside of showers
44. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged outside of shower # 1 and 2
45. MAXI B	Upper Right Tier	Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 1 leaking
46. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1 and 2
47. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 1
48. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Wall vent dusty in shower # 1
49. Food Service	Staff Dining & Culinary	Staff Dining Room	105 CMR 451.200	Cleaning of Equipment and Utensils, Objective: Food contact surface dirty (Pf), coffee machine dirty. Standard found in 105 CMR 590.00, FC 4-601.11(A). ** Corrected On-Site **
50. Food Service	Staff Dining & Culinary	Staff Dining Room	105 CMR 451.200	Design, Construction, and Installation; Cleanability: Ceiling not smooth and easily cleanable, ceiling water damaged near smoke detector. Standard found in 105 CMR 590; FC 6-201.11.
51. Food Service	Staff Dining & Culinary	Staff Dining Room	105 CMR 451.200	Design, Construction, and Installation; Cleanability: Ceiling not smooth and easily cleanable, paint damaged on duct work. Standard found in 105 CMR 590; FC 6-201.11.

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
52. Food Service	Staff Dining & Culinary	Staff Serving Line & Prep Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Premises not maintained free of rodents, rodent droppings observed behind warmer. Standard found in 105 CMR 590; FC 6-501.111. ** Corrected On-Site **
53. Food Service	Staff Dining & Culinary	Pots & Pans Culinary Closet	105 CMR 451.200	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, refrigerator gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C). ** Corrected On-Site **
54. Food Service	Staff Dining & Culinary	Pots & Pans Culinary Closet	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B).
55. Food Service	Staff Dining & Culinary	Pots & Pans Culinary Closet	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food, several items not labeled. Standard found in 105 CMR 590; FC 3-302.12. ** Corrected On-Site **
56. Food Service	Staff Dining & Culinary	Pots & Pans Culinary Closet	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Refrigerated time/temperature control for safety food prepared on site not clearly marked indicating the date or day by which the food shall be consumed or discarded (Pf), several items not dated. Standard found in 105 CMR 590; FC 3-501.17(A). ** Corrected On-Site **

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
57. Food Service	Staff Dining & Culinary	Staff Serving Line & Prep Area	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, shelf under single compartment sink rusted. Standard found in 105 CMR 590; FC 4-501.11(B).
58. Food Service	Main Kitchen		105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling leaking near buffalo chopper. Standard found in 105 CMR 590; FC 6-501.11.
59. Food Service	Main Kitchen	Handwash Sink	105 CMR 451.127	Numbers and Capacity; Handwashing Sinks: No soap at handwash sink(Pf), soap not dispensing properly. Standard found in 105 CMR 50; FC 6-301.12. ** Corrected On-Site **
60. Food Service	Main Kitchen	Food Prep Area	105 CMR 451.200	Protection of Clean Items, Storing: Pots and trays not stored in a self-draining position. Standard found in 105 CMR 590; FC 4-903.11(B)(1).
61. Food Service	Main Kitchen	Food Prep Area	105 CMR 451.200	Protection of Clean Items; Drying: Cleaned, sanitized equipment and utensils dried with a cloth. Standard found in 105 CMR 590; FC 4-901.11(B).
62. Food Service	Main Kitchen	Food Prep Area	105 CMR 451.200	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil/mold observed on interior surfaces of ice machine. Standard found in 105 CMR 590; FC 4-602.11(E)(4)(b). ** Corrected On-Site **
63. Food Service	Main Kitchen	Prep Cooler # 3	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food, food items improperly labeled. Standard found in 105 CMR 590; FC 3-302.12. ** Corrected On-Site **

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
64. Food Service	Main Kitchen	Freezer # 4	105 CMR 451.200	Preventing Contamination from the Premises; Food Storage: Food stored beneath condensation where ceiling. Standard found in 105 CMR 590; FC 3-305.12(I). ** Corrected On-Site **
65. Food Service	Main Kitchen	Freezer # 4	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, excessive ice buildup observed. Standard found in 105 CMR 590; FC 6-501.12(A). ** Corrected On-Site **
66. Food Service	Main Kitchen	Receiving Area	105 CMR 451.200	Design, Construction, and Installation; Functionality: Outer openings not protected against the entry of insects and rodents, door not rodent and weathertight. Standard found in 105 CMR 590; FC 6-202.15(A)(3).
67. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises, warewash machine out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A). ** Corrected On-Site **
68. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, hoses leaking at 3-compartment sink. Standard found in 105 CMR 590; FC 5-205.15(B).
69. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, sprayer head dirty. Standard found in 105 CMR 590; FC 6-501.12(A).

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
70. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Wet cloth not stored in sanitizer solution. Standard found in 105 CMR 590; FC 3-304.14(B)(1). ** Corrected On-Site **
71. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Plumbing System; Design, Construction, and Installation: Air gap missing between water supply inlet and the flood level rim of the sink, chemical dispensing tube in sink (Pf). Standard found in 105 CMR 590; FC 5-202.13.
72. Food Service	Main Kitchen	Culinary Dry Goods	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Premises not maintained free of rodents, rodent droppings observed. Standard found in 105 CMR 590; FC 6-501.111. ** Corrected On-Site **
73. Food Service	Main Kitchen	Inmate Serving Area	105 CMR 451.200*	Numbers and Capacities, Equipment: Insufficient hot holding equipment in number and capacity (Pf). Standard found in 105 CMR 590; FC 4-301.11.
74. Main Gymnasium	Bathroom without Showers		105 CMR 451.123	Maintenance: Dead insects observed throughout bathroom
75. Main Gymnasium	Bathroom without Showers		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet clogged
76. Main Gymnasium	Bathroom without Showers		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, plumbing not appropriately disconnected
77. MAXI C	Upper Tier	Left-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
78. MAXI C	Upper Tier	Right-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
79. MAXI C	Upper Tier	Right-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, table under microwave oven dirty
80. MAXI C	Upper Tier	Showers	105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower # 2
81. MAXI C	Upper Tier	Showers	105 CMR 451.123*	Maintenance: Wall paint damaged in shower # 1 and 2
82. MAXI C	Upper Tier	Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 1 and 2
83. MAXI C	Upper Tier	Showers	105 CMR 451.123	Maintenance: Wall surface damaged in shower # 1 and 2
84. MAXI C	Upper Tier	Showers	105 CMR 451.123	Maintenance: Pipes rusted above shower # 1 and 2
85. MAXI C	Lower Tier	Left-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
86. MAXI C	Lower Tier	Left-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, table under microwave oven dirty
87. MAXI C	Lower Tier	Right-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
88. MAXI C	Lower Tier	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # 246
89. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Ceiling paint damaged outside of showers
90. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 3
91. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged in shower # 1, 2, and 3
92. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 2
93. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Pipes rusted above shower # 2 and 3
94. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 3
95. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Paint damaged on beam outside of shower
96. Programs	Male Staff Bathroom		105 CMR 451.123	Maintenance: Ceiling vent dusty
97. Programs	Male Staff Bathroom		105 CMR 451.117	Toilet Fixtures: Toilet fixture dirty in stall # 1
98. Programs	Female Staff Bathroom		105 CMR 451.123	Maintenance: Ceiling vent dusty

Deficiencies under the Recommended Standards (.300 series)

57 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
1. A1 Block	Lower Tier	Day Room	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty near microwave oven
2. A1 Block	Lower Tier	Day Room	105 CMR 451.353	Interior Maintenance: Metal grate leading to lower cells dusty
3. A1 Block	Lower Tier	Room # 3	105 CMR 451.360	Protective Measures: Rodent droppings observed
4. A1 Block	Lower Tier	Room # 3	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
5. A1 Block	Lower Tier	Shakedown Room # 6	105 CMR 451.353	Interior Maintenance: Wall mounted fan dusty
6. A1 Block	Upper Tier	Slop Sink (Upstairs)	105 CMR 451.353	Interior Maintenance: Floor dirty
7. A1 Block	Upper Tier	Slop Sink (Upstairs)	105 CMR 451.353	Interior Maintenance: Walls dirty
8. A1 Block	Upper Tier	Cells (Upstairs)	105 CMR 451.353	Interior Maintenance: Debris in door guide leading to cells
9. A1 Block	Upper Tier	Cells (Upstairs)	105 CMR 451.360	Protective Measures: Rodent droppings observed in door guide leading to cells
10. A1 Block	Lower Tier	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Walls dirty
11. A1 Block	Lower Tier	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Floor dirty
12. A1 Block	Lower Tier	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
13. A1 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Floor dirty in cell # 32
14. A1 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 21, 26, 27, and 32
15. A1 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 25 and 30
16. A1 Block			105 CMR 451.320	Cell Size: Inadequate floor space in all cells
17. A2 Block			105 CMR 451.320	Cell Size: Inadequate floor space in all cells
18. A2 Block	Lower Tier	Day Room	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty near microwave oven
19. A2 Block	Lower Tier	Chemical Storage Room	105 CMR 451.360	Protective Measures: Rodent droppings observed
20. A2 Block	Lower Tier	Paper Good Storage	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
21. A2 Block	Upper Tier	Cells (Upstairs)	105 CMR 451.360	Protective Measures: Rodent droppings observed in door guide leading to cells
22. A2 Block	Upper Tier	Cells (Upstairs)	105 CMR 451.360	Protective Measures: Rodent droppings observed in door guide of cell # 41
23. A2 Block	Lower Tier	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Slop sink dirty
24. A2 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 52 and 60

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
25. A2 Block	Hallway	Storage Closets	105 CMR 451.360	Protective Measures: Rodent droppings observed
26. MAXI B	Lower Right Tier	Day Room	105 CMR 451.353	Interior Maintenance: Debris between metal grate and window of Day Room
27. MAXI B	Lower Left Tier	Day Room	105 CMR 451.353	Interior Maintenance: Debris between metal grate and window to Day Room
28. MAXI B	Lower Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 135 and 141
29. MAXI B	Upper Right Tier	Day Room	105 CMR 451.353	Interior Maintenance: Debris between metal grate and window to Day Room
30. MAXI B	Upper Right Tier	Day Room	105 CMR 451.353	Interior Maintenance: Window to Day Room dirty
31. MAXI B	Upper Right Tier	Day Room	105 CMR 451.353	Interior Maintenance: Standing fan dusty
32. MAXI B	Upper Right Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 304
33. MAXI B	Upper Left Tier	Day Room	105 CMR 451.353	Interior Maintenance: Debris between metal grate and window to Day Room
34. MAXI B	Upper Left Tier	Day Room	105 CMR 451.353	Interior Maintenance: Metal grate dirty inside Day Room near trash can
35. MAXI B	Upper Left Tier	Day Room	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged outside of Day Room
36. MAXI B	Upper Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 307 and 329
37. MAXI B	Upper Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Baseboard paint damaged near toilet in cell # 337
38. Main Gymnasium	Basketball Court		105 CMR 451.353*	Interior Maintenance: Wall paint damaged
39. Main Gymnasium	Basketball Court		105 CMR 451.353	Interior Maintenance: Ceiling water damaged
40. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 418, 428, 430, 432, 434, 440, and 448
41. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 420
42. MAXI C	Lower Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 229
43. MAXI C	Lower Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 247
44. Maintenance Corridor	Welding Area		105 CMR 451.350	Structural Maintenance: Exterior door not rodent and weathertight
45. MAXI C			105 CMR 451.320	Cell Size: Inadequate floor space in all cells

Deficiencies under 105 CMR 451.402(B) (other conditions that may constitute a threat to health or safety)

1 new deficiency was found during the inspection:

Area	Sub Area # 1	Regulation	Description of Deficiency
1. Maintenance Corridor	EHSO Office (Waste Log)	105 CMR 451.425(A)	Tracking Medical or Biological Waste for Treatment: Generator did not confirm the shipment was received by the treatment facility within 30 days on an approved tracking form Standard found in 105 CMR 480.425(A). ** Corrected On-Site **

Deignan Building**Deficiencies under the Required Standards (.100 and .200 series)**

13 new deficiencies were found during the inspection:

Area	Sub Area # 1	Regulation	Description of Deficiency
1. Control Booth Bathroom		105 CMR 451.123	Maintenance: Wall vent dusty
2. Upper West	Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 2 leaking
3. Upper West	Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 2
4. Upper West	Showers	105 CMR 451.123	Maintenance: Mold on walls in shower # 2
5. Upper West	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 2
6. Upper West	Showers	105 CMR 451.123	Maintenance: Door frame damaged in shower # 2
7. Upper West	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink out-of-order
8. Upper West	Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water control leaking at handwash sink # 2
9. Lower West	Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 1 out-of-order
10. Lower West	Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink # 1 out-of-order
11. Lower East	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1
12. Lower East	Showers	105 CMR 451.123	Maintenance: Wall epoxy damaged in shower # 1
13. Upper East	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover missing at slop sink

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies were found during the inspection:

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
1. Deignan Building			105 CMR 451.320	Cell Size: Inadequate floor space in all cells
2. Deignan Building	Dry Storage		105 CMR 451.360	Protective Measures: Rodents observed, rodent droppings observed
3. Deignan Building	Upper West	Cells	105 CMR 451.353	Interior Maintenance: Ceiling water damaged in cell # 56

Mini 5

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies were found during the inspection:

Area	Sub Area # 1	Regulation	Description of Deficiency
1. Bathroom	Left Side	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 1 and 2
2. Bathroom	Left Side	105 CMR 451.123	Maintenance: Walls dirty in shower # 2
3. Bathroom	Right Side	105 CMR 451.123	Maintenance: Caulking dirty in shower # 1
4. Bathroom	Right Side	105 CMR 451.123	Maintenance: Walls dirty outside shower # 1
5. Bathroom	Right Side	105 CMR 451.123	Maintenance: Floor dirty outside shower # 1

Medical Building

Deficiencies under the Required Standards (.100 and .200 series)

14 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
1. MIU	Receiving	Staff Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty
2. MIU	Receiving	Staff Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 101°F at handwash sink
3. Medical Entrance	Right Wing	Inmate WC # 166	105 CMR 451.123	Maintenance: Toilet bowl rusted
4. Medical Entrance	Right Wing	Nurse's Station	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 68°F at right side handwash sink
5. Medical Entrance	Left Wing	Breakroom # 175	105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of ice machine dirty
6. Medical Entrance	Left Wing	Inmate WC # 169	105 CMR 451.123	Maintenance: Toilet bowl rusted
7. Medical Entrance	2nd Floor	Showers	105 CMR 451.130*	Hot Water: Shower water temperature 74°F at shower # 1
8. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Mat outside of shower dirty in shower # 2 and 3
9. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 3
10. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 2 and 3
11. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty outside of shower # 1, 2, and 3

Deficiencies under the Recommended Standards (.300 series)

8 new deficiencies were found during the inspection:

Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
1. MIU	Receiving	Holding Cells	105 CMR 451.353	Interior Maintenance: Ceiling dirty in cell # 121
2. MIU	Receiving	Holding Cells	105 CMR 451.353	Interior Maintenance: Walls dirty in cell # 114
3. MIU	Receiving	Receiving Trap	105 CMR 451.350	Structural Maintenance: Exterior door not rodent and weathertight
4. MIU	Receiving	Janitor's Closet # 154	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged outside of closet

	Area	Sub Area # 1	Sub Area # 2	Regulation	Description of Deficiency
5.	Medical Entrance	Right Wing	Nurse's Station	105 CMR 451.353	Interior Maintenance: Right side bubbler dirty
6.	Medical Entrance	Left Wing	Soil Storage # 170 (Medical Waste)	105 CMR 451.353	Interior Maintenance: Objectionable odor observed
7.	Medical Entrance	2nd Floor	Single Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 219
8.	Medical Entrance	2nd Floor	Single Cells	105 CMR 451.353	Interior Maintenance: Walls dirty in cell # 217

Modular Administration

Deficiencies under the Required Standards (.100 and .200 series)

16 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

	Area	Sub Area # 1	Sub Area # 2	Description of Deficiency
1.	Lobby	Female Bathroom	105 CMR 451.123	Maintenance: Floor tile damaged
2.	Lobby	Female Bathroom	105 CMR 451.123	Maintenance: Wall tile damaged
3.	Lobby	Female Bathroom	105 CMR 451.123	Maintenance: Wall tiles missing
4.	Lobby	Female Bathroom	105 CMR 451.123	Maintenance: Floor dirty
5.	Special Services Corridor	Female Bathroom	105 CMR 451.123	Maintenance: Wall tile missing
6.	Special Services Corridor	Male Bathroom	105 CMR 451.123	Maintenance: Wall dirty under soap dispenser
7.	Special Services Corridor	Female Locker Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 3 out-of-order
8.	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123*	Maintenance: Floor damaged in locker room area
9.	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handicapped shower out-of-order
10.	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Curtain dirty in shower # 2, 3, and 4
11.	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Floor dirty in shower # 3 and 4
12.	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Floor dirty outside of showers
13.	2nd Floor	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover not secure
14.	Trap	Bathroom in Pedestrian Trap	105 CMR 451.123	Maintenance: Ceiling water damaged

Deficiencies under the Recommended Standards (.300 series)

4 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

Area	Sub Area # 1	Regulation	Description of Deficiency
1. Building Exterior		105 CMR 451.350*	Structural Maintenance: Exterior wall damaged
2. Control 3		105 CMR 451.344	Illumination in Habitable Areas: Light(s) not functioning properly, light out in break area
3. 2nd Floor	Copy Room	105 CMR 451.353	Interior Maintenance: Floor damaged
4. 2nd Floor	Copy Room	105 CMR 451.353	Interior Maintenance: Wall paint damaged
5. 2nd Floor	Slop Sink Room	105 CMR 451.353	Interior Maintenance: Wet mop stored in sink

Mods Gym**Deficiencies under the Required Standards (.100 and .200 series)**

3 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

Area	Regulation	Description of Deficiency
1. Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Floor tile missing
2. Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Ceiling vent cover missing
3. Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Wall damaged behind toilet
4. Inmate Bathroom # 104	105 CMR 451.123	Maintenance: Baseboard damaged
5. Inmate Bathroom # 104	105 CMR 451.123	Maintenance: Wall paint damaged
6. Staff Bathroom	105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 3 repeat deficiencies (indicated by an *) were found during the inspection:

Area	Regulation	Description of Deficiency
1. Gym	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
2. Gym	105 CMR 451.360*	Protective Measures: Bird nest observed in window above entrance
3. Gym	105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight
4. Gym	105 CMR 451.353	Interior Maintenance: Baseboard around gym dirty

H Building**Deficiencies under the Required Standards (.100 and .200 series)**

3 new deficiencies were found during the inspection:

Area	Regulation	Description of Deficiency
1. Showers	105 CMR 451.123	Maintenance: Curtain dirty in shower # 1, 7, and 8

Deficiencies under the Recommended Standards (.300 series)

7 new deficiencies were found during the inspection:

Area	Regulation	Description of Deficiency
1. Cells	105 CMR 451.320	Cell Size: Inadequate floor space in all cells
2. Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 119 and 131
3. Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 128
4. Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 138 and 143

5. Cells	105 CMR 451.353	Interior Maintenance: Light fixture missing in cell # 132
----------	-----------------	---

I Building

Deficiencies under the Required Standards (.100 and .200 series)

21 new deficiencies were found during the inspection:

Area	Regulation	Description of Deficiency
1. Control Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control leaking
2. Control Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 103°F at handwash sink
3. Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
4. Showers	105 CMR 451.123	Maintenance: Dead drain flies observed on ceiling in shower # 1, 2, 3, 4, 5, 6, 8, 9, and 10
5. Showers	105 CMR 451.123	Maintenance: Drain flies observed in shower # 2 and 8
6. Showers	105 CMR 451.123	Maintenance: Wall vent dusty in shower # 3 and 8
7. Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 4, 8, and 10
8. Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 6 and 9

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

Area	Regulation	Description of Deficiency
1. Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles missing
2. Cells	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 200

J Building

Deficiencies under the Required Standards (.100 and .200 series)

7 new deficiencies were found during the inspection:

Area	Regulation	Description Of Deficiency
1. Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 10 leaking
2. Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # 3
3. Showers	105 CMR 451.123	Maintenance: Curtain dirty in shower # 4
4. Showers	105 CMR 451.123	Maintenance: Dead drain flies observed on ceiling in shower # 5, 8, and 10
5. Cells	105 CMR 451.101	Blankets: Blanket damaged in cell # 239

Deficiencies under the Recommended Standards (.300 series)

8 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

Area	Regulation	Description of Deficiency
1. Common Area	105 CMR 451.353	Interior Maintenance: Seat damaged at table
2. Common Area	105 CMR 451.353	Interior Maintenance: Wall fan dusty
3. Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 264
4. Cells	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 251

5. Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 234, 246, 255, 256, 273, and 276
----------	-----------------	--

K Building

Deficiencies under the Required Standards (.100 and .200 series)

7 new deficiencies were found during the inspection:

Area	Regulation	Description of Deficiency
1. Control Booth	105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of refrigerator dirty
2. Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, table under microwave oven dirty
3. Showers	105 CMR 451.123	Maintenance: Debris on floor in shower # 2
4. Showers	105 CMR 451.123	Maintenance: Dead drain flies on ceiling in shower # 6, 7, 8, and 9

Deficiencies under the Recommended Standards (.300 series)

7 new deficiencies were found during the inspection:

Area	Regulation	Description of Deficiency
1. Cells	105 CMR 451.320	Cell Size: Inadequate floor space in all cells
2. Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles damaged
3. Common Area	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged outside of cell # 326
4. Common Area	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged throughout
5. Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 281, 290, and 324

L Building

Deficiencies under the Required Standards (.100 and .200 series)

30 new deficiencies and 7 repeat deficiencies (indicated by an *) were found during the inspection:

Area	Regulation	Description of Deficiency
1. Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, table under microwave oven dirty
2. Showers	105 CMR 451.123*	Maintenance: Mold where floor and wall meet in shower # 2, 3, 4, 5, 6, 7, and 8
3. Showers	105 CMR 451.123	Maintenance: Mold where floor and wall meet in shower # 9 and 10
4. Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 10 leaking
5. Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 1, 2, 3, 4, 5, 6, 7, 8, 9, and 10
6. Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1, 2, 3, 4, 5, 6, 7, 8, 9, and 10
7. Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 3
8. Showers	105 CMR 451.123	Maintenance: Mold on light shield in shower # 5 and 10
9. Showers	105 CMR 451.123	Maintenance: Dead drain flies observed on ceiling in shower # 6, 8, and 9

Deficiencies under the Recommended Standards (.300 series)

10 new deficiencies were found during the inspection:

Area	Regulation	Description of Deficiency
1. Common Area	105 CMR 451.350	Structural Maintenance: Ceiling water damaged near control booth
2. Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 243, 350, 371, 381, and 388
3. Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged outside of cell # 383
4. Cells	105 CMR 451.353	Interior Maintenance: Ceiling water damaged outside of cell # 387
5. Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 357
6. Chemical Room	105 CMR 451.353	Interior Maintenance: Floor paint damaged

Warehouse**Deficiencies under the Required Standards (.100 and .200 series)**

6 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

Area	Sub Area # 1	Regulation	Description of Deficiency
1. Staff Gym	Female Bathroom/ Locker Room	105 CMR 451.123*	Maintenance: Wall paint damaged
2. Staff Gym	Female Bathroom/ Locker Room	105 CMR 451.123*	Maintenance: Floor tiles not secure near toilet
3. Staff Gym	Female Bathroom/ Locker Room	105 CMR 451.123	Maintenance: Mold on walls
4. Staff Gym	Female Bathroom/Locker Room	105 CMR 451.123	Maintenance: Grab bar rusted in shower
5. Staff Gym	Female Bathroom/ Locker Room	105 CMR 451.123	Maintenance: Dead drain flies observed on floor in shower
6. Warehouse	Staff Bathroom # 2	105 CMR 451.123	Maintenance: Wall paint damaged
7. Warehouse	Staff Bathroom # 2	105 CMR 451.123	Maintenance: Floor tile damaged
8. Warehouse	Staff Bathroom # 2	105 CMR 451.123	Maintenance: Wall water damaged

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

Area	Regulation	Description of Deficiency
1. Warehouse	105 CMR 451.353	Interior Maintenance: Hole in floor in back corner near exit door

Garage/Transportation**Deficiencies under the Required Standards (.100 and .200 series)**

1 new deficiency was found during the inspection:

Area	Regulation	Description of Deficiency
1. Garage Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

SECTION 2: Areas Found to be in Compliance

EHRS inspected 133 additional areas of the facility which were found to be in compliance.

SECTION 3: Areas EHRS did not Inspect

EHRS did not inspect 7 areas of the facility because they were either in use, locked, or under construction.

Area	Sub Area # 1	Sub Area # 2	Description of Deficiency
1. Entrance	Control Room	Key Room	Unable to Inspect – Locked
2. MAXI B	Lower Disciplinary Unit		Unable to Inspect – Not in Use
3. MAXI B	Upper Disciplinary Unit		Unable to Inspect – Not in Use
4. Modular Administration Building	Special Services Corridor	Slop Sink Room	Unable to Inspect – Locked
5. Work Release			Unable to Inspect – Not in Use
6. Tower			Unable to Inspect – Not in Use
7. Annex			Unable to Inspect – Under Construction

SECTION 4: Plan of Correction

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. A signature by the Superintendent or Administrator responsible for the plan. The signed plan should be submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 660 at the time of inspection.
2. During the facility inspection, the EHRS noted numerous deficiencies related to cleanliness. The conditions noted throughout the facility can lead to bacterial growth and pest infestation, increasing the risk of illness for staff and inmates. The EHRS suggests a routine cleaning schedule be developed and implemented to ensure all areas of the facility are cleaned at a higher frequency.

To review the specific regulatory requirements, please visit the [Massachusetts Department of Public Health Regulatory and Compliance Unit](#) and [read the minimum health and sanitation standards for correctional facilities](#) available in both PDF and RTF formats. For more specific information about the food standards, you can [download the merged food code](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000: Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities](#)
- [105 CMR 480.000: Minimum requirements for the Management of Medical or Biological Waste](#)
- [105 CMR 500.000: Good Manufacturing Practices for Food](#)

This inspection report is true and accurate to the best of my knowledge.

Sincerely,

A handwritten signature in blue ink that reads "Hannah LeBeau". The signature is written in a cursive, flowing style.

Hannah LeBeau
Environmental Health Officer, EHRS, BCEH



Commonwealth of Massachusetts

OFFICE OF THE SHERIFF

COUNTY OF WORCESTER
JAIL AND HOUSE OF CORRECTION
5 PAUL X. TIVNAN DRIVE
WEST BOYLSTON, MASSACHUSETTS 01583
TELEPHONE: 508 854-1800

LEWIS G. EVANGELIDIS
SHERIFF

FAX: 508 856-0465
TTY: 508 854-1888

May 14, 2026

Hannah Lebeau
Environmental Health Officer
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street Suite 100
Marlborough, MA 01752

Re: Plan of Correction – Worcester County House of Corrections and Jail

Dear Ms. Lebeau:

Pursuant to the Department of Public Health (DPH) Regulations 105 CMR 451.000 – Minimum Health and Sanitations Standards and Inspection Procedures for Correctional Facilities, attached please find a corrected response to the inspection conducted on April 21st & 22nd, 2026.

If you require additional information, please feel free to contact me.

Sincerely,



Jason Rives
Superintendent

cc: AS Jason Butland
Capt. Eric Locke
Lt. Devon Walker
Anna Laukaitis – Compliance Analyst

Area	Sub Area	Room	Code	Description	Plan of Action	Deadline Date	Responsible Staff
------	----------	------	------	-------------	----------------	---------------	-------------------

Required Standards (.100 & .200 Series)

1. Entrance	Control Room	Control Bathroom	105 CMR 451.123	Maintenance: Wet mop stored in bucket	Mop Removed	4/21/2026	
2. Herman Building	Visiting Room	Female Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty	Vent to be cleaned	5/29/2026	Hubacz
3. Herman Building	Visiting Room	Female Bathroom	105 CMR 451.123	Maintenance: Wall paint damaged in stall # 2	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
4. Herman Building	Visiting Room	Female Bathroom	105 CMR 451.123	Maintenance: Ceiling tiles water damaged	Damaged tiles to be replaced	9/4/2026	Hubacz
5. Herman Building	Visiting Room	Male Bathroom	105 CMR 451.123*	Maintenance: Wall paint damaged above urinal	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
6. Herman Building	Visiting Room	Male Bathroom	105 CMR 451.123	Maintenance: Strong urine odor present	Bathroom cleaned	4/21/2026	
7. Herman Building	Visiting Room	Male Bathroom	105 CMR 451.117	Toilet Fixtures: Urinal dirty	Bathroom cleaned	4/21/2026	
8. Old Receiving	Breakroom & Bathroom		105 CMR 451.123	Maintenance: Wall paint damaged near toilet	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
9. A1 Block	Control Booth	Control Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty	Vent to be cleaned	5/29/2026	Hubacz

10. A1 Block	Lower Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Table to be cleaned	5/29/2026	Hubacz
				105 CMR 590.000, table under microwave oven dirty			
11. A1 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Access panel on ceiling rusted in shower # 2	Maintenance to inspect and repair	9/4/2026	Hubacz
12. A1 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Mold on ceiling in shower # 2	Showers cleaned	4/21/2026	
13. A1 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Ceiling vent dusty outside of showers	Vent to be cleaned	5/29/2026	Hubacz
14. A1 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.102	Pillows and Linens: Insufficient pillow and linens available for inmates in cell # 28, no sheets available	Sheets available regardless of inmate's decision to use	4/21/2026	
15. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Wall paint damaged outside of showers	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
16. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Walls dirty in shower # 1	Showers cleaned	4/21/2026	
17. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # 1 and 2	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
18. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Floor drain dirty in shower # 2	Showers cleaned	4/21/2026	
19. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 2	Showers cleaned	4/21/2026	

20. A1 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Floor dirty in shower # 2	Showers cleaned	4/21/2026	
21. A2 Block	Control Booth	Control Bathroom	105 CMR 451.117	Toilet Fixtures: Toilet fixture dirty	Bathroom cleaned	4/21/2026	
22. A2 Block	Lower Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Microwave cleaned	4/21/2026	
				105 CMR 590.000, interior of microwave oven dirty			
23. A2 Block	Lower Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Table to be cleaned	5/29/2026	Hubacz
				105 CMR 590.000, table under microwave oven dirty			
24. A2 Block	Upper Tier	Slop Sink Room (Upstairs)	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, floor drain damaged	Maintenance to inspect and repair	6/30/2026	Hubacz
25. A2 Block	Upper Tier	Slop Sink Room (Upstairs)	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink clogged	Maintenance to inspect and repair	5/29/2026	Hubacz
26. A2 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Door frame rusted in shower # 1 and 2	Maintenance to inspect and repair	9/4/2026	Hubacz
27. A2 Block	Upper Tier	Showers (Upstairs)	105 CMR 451.123	Maintenance: Access panel rusted on ceiling in shower # 2	Maintenance to inspect and repair	9/4/2026	Hubacz
28. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Walls dirty in shower # 1 and 2	Showers cleaned	4/21/2026	
29. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Door frame rusted in shower # 1 and 2	Maintenance to inspect and repair	9/4/2026	Hubacz

30. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Dead drain flies observed on wall in shower # 1	Showers cleaned	4/21/2026	
31. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 2	Showers cleaned	4/21/2026	
32. A2 Block	Lower Tier	Showers (Downstairs)	105 CMR 451.123	Maintenance: Ceiling dirty around light fixture outside of showers	Ceiling to be cleaned	5/29/2026	Hubacz
33. MAXI B	Lower Right Tier	Slop Sink	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, sink leaking	Maintenance to inspect and repair	5/29/2026	Hubacz
34. MAXI B	Lower Right Tier	Showers	105 CMR 451.123	Maintenance: Caulking along floor dirty in shower # 1 and 2	Showers cleaned	4/21/2026	
35. MAXI B	Lower Right Tier	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1 and 2	Showers cleaned	4/21/2026	
36. MAXI B	Lower Right Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged at entrance in shower # 2	Maintenance to inspect and repair	9/4/2026	Hubacz
37. MAXI B	Lower Left Tier	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1 and 2	Showers cleaned	4/21/2026	
38. MAXI B	Upper Right Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Microwave cleaned	4/21/2026	
				105 CMR 590.000, interior of microwave oven dirty			
39. MAXI B	Upper Right Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Table to be cleaned	5/29/2026	Hubacz
				105 CMR 590.000, table under microwave oven dirty			

40. MAXI B	Upper Left Tier	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Microwave cleaned	4/21/2026	
				105 CMR 590.000, interior of microwave oven dirty			
41. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged in shower # 1	Maintenance to inspect and repair	9/4/2026	Hubacz
42. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 1	Showers cleaned	4/21/2026	
43. MAXI B	Upper Left Tier	Showers	105 CMR 451.123	Maintenance: Rodent droppings observed in door guide outside of showers	Door guide cleaned	4/21/2026	
44. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Wall paint damaged outside of shower # 1 and 2	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
45. MAXI B	Upper Right Tier	Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 1 leaking	Maintenance to inspect and repair	5/29/2026	Hubacz
46. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1 and 2	Showers cleaned	4/21/2026	
47. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 1	Showers cleaned	4/21/2026	
48. MAXI B	Upper Right Tier	Showers	105 CMR 451.123	Maintenance: Wall vent dusty in shower # 1	Vent to be cleaned	5/29/2026	Hubacz
49. Food Service	Staff Dining & Culinary	Staff Dining Room	105 CMR 451.200	Cleaning of Equipment and Utensils, Objective: Food contact surface dirty (Pf), coffee machine dirty. Standard found in			
				105 CMR 590.00, FC 4-601.11(A).			

				** Corrected On-Site **			
50. Food Service	Staff Dining & Culinary	Staff Dining Room	105 CMR 451.200	Design, Construction, and Installation; Cleanability: Ceiling not smooth and easily cleanable, ceiling water damaged near smoke detector. Standard found in 105 CMR 590; FC 6-201.11.	Maintenance to inspect and repair	9/4/2026	Hubacz
51. Food Service	Staff Dining & Culinary	Staff Dining Room	105 CMR 451.200	Design, Construction, and Installation; Cleanability: Ceiling not smooth and easily cleanable, paint damaged on duct work. Standard found in 105 CMR 590; FC 6-201.11.	Maintenance to inspect and repair	9/4/2026	Hubacz
52. Food Service	Staff Dining & Culinary	Staff Serving Line & Prep Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Premises not maintained free of rodents, rodent droppings observed behind warmer. Standard found in 105 CMR 590; FC 6-501.111.			
				** Corrected On-Site **			
53. Food Service	Staff Dining & Culinary	Pots & Pans Culinary Closet	105 CMR 451.200	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, refrigerator gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C).			
				** Corrected On-Site **			
54. Food Service	Staff Dining & Culinary	Pots & Pans Culinary Closet	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B).	Gaskets to be replaced	6/30/2026	Hubacz

55. Food Service	Staff Dining & Culinary	Pots & Pans Culinary Closet	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food, several items not labeled. Standard found in 105 CMR 590;			
				FC 3-302.12.			
				** Corrected On-Site **			
56. Food Service	Staff Dining & Culinary	Pots & Pans Culinary Closet	105 CMR 451.200	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Refrigerated time/temperature control for safety food prepared on site not clearly marked indicating the date or day by which the food shall be consumed or discarded (Pf), several items not dated. Standard found in 105 CMR			
				590; FC 3-501.17(A).			
				** Corrected On-Site **			
57. Food Service	Staff Dining & Culinary	Staff Serving Line & Prep Area	105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, shelf under single compartment sink rusted. Standard found in 105 CMR 590; FC 4-501.11(B).	Maintenance to inspect and repair	9/4/2026	Hubacz
58. Food Service	Main Kitchen		105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling leaking near buffalo chopper. Standard found in	Maintenance to inspect and repair	5/29/2026	Hubacz
				105 CMR 590; FC 6-501.11.			

59. Food Service	Main Kitchen	Handwash Sink	105 CMR 451.127	Numbers and Capacity; Handwashing Sinks: No soap at handwash sink(Pf), soap not dispensing properly. Standard found in 105 CMR 50;			
				FC 6-301.12.			
				** Corrected On-Site **			
60. Food Service	Main Kitchen	Food Prep Area	105 CMR 451.200	Protection of Clean Items, Storing: Pots and trays not stored in a self-draining position. Standard found in 105 CMR 590; FC 4-903.11(B)(1).	Pots and trays to be stored properly	5/29/2026	Stone
61. Food Service	Main Kitchen	Food Prep Area	105 CMR 451.200	Protection of Clean Items; Drying: Cleaned, sanitized equipment and utensils dried with a cloth. Standard found in 105 CMR 590; FC 4-901.11(B).	Equipment and utensils to be dried properly	5/29/2026	Stone
62. Food Service	Main Kitchen	Food Prep Area	105 CMR 451.200	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil/mold observed on interior surfaces of ice machine. Standard found in 105 CMR 590;			
				FC 4-602.11(E)(4)(b).			
				** Corrected On-Site **			
63. Food Service	Main Kitchen	Prep Cooler # 3	105 CMR 451.200	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food, food items improperly labeled. Standard found in 105 CMR 590; FC 3-302.12.			
				** Corrected On-Site **			

64. Food Service	Main Kitchen	Freezer # 4	105 CMR 451.200	Preventing Contamination from the Premises; Food Storage: Food stored beneath condensation where ceiling. Standard found in 105 CMR 590; FC 3-305.12(I).			
				** Corrected On-Site **			
65. Food Service	Main Kitchen	Freezer # 4	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, excessive ice buildup observed. Standard found in 105 CMR 590;			
				FC 6-501.12(A).			
				** Corrected On-Site **			
66. Food Service	Main Kitchen	Receiving Area	105 CMR 451.200	Design, Construction, and Installation; Functionality: Outer openings not protected against the entry of insects and rodents, door not rodent and weathertight. Standard found in 105 CMR 590; FC 6-202.15(A)(3).	Maintenance to inspect and repair	9/4/2026	Hubacz
67. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired or removed from premises, warewash machine out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A).			
				** Corrected On-Site **			
68. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, hoses leaking at 3-compartment sink. Standard found in	Maintenance to inspect and repair	5/29/2026	Hubacz
				105 CMR 590; FC 5-205.15(B).			

69. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, sprayer head dirty. Standard found in	Sprayer to be replaced	5/29/2026	Stone
				105 CMR 590; FC 6-501.12(A).			
70. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Wet cloth not stored in sanitizer solution. Standard found in 105 CMR 590; FC 3-304.14(B)(1).			
				** Corrected On-Site **			
71. Food Service	Main Kitchen	Dishwasher Area	105 CMR 451.200	Plumbing System; Design, Construction, and Installation: Air gap missing between water supply inlet and the flood level rim of the sink, chemical dispensing tube in sink (Pf). Standard found in 105 CMR 590; FC 5-202.13.	Outside vendor installation verified	4/22/2026	
72. Food Service	Main Kitchen	Culinary Dry Goods	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Premises not maintained free of rodents, rodent droppings observed. Standard found in 105 CMR 590; FC 6-501.111.			
				** Corrected On-Site **			
73. Food Service	Main Kitchen	Inmate Serving Area	105 CMR 451.200*	Numbers and Capacities, Equipment: Insufficient hot holding equipment in number and capacity (Pf). Standard found in 105 CMR 590; FC 4-301.11.	Warmers to be requested through Finance	9/4/2026	Stone
74. Main Gymnasium	Bathroom without Showers		105 CMR 451.123	Maintenance: Dead insects observed throughout bathroom	Bathroom to be cleaned	5/29/2026	Hubacz

75. Main Gymnasium	Bathroom without Showers		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet clogged	Maintenance to inspect and repair	5/29/2026	Hubacz
76. Main Gymnasium	Bathroom without Showers		105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, plumbing not appropriately disconnected	Maintenance to inspect and repair	9/4/2026	Hubacz
77. MAXI C	Upper Tier	Left-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Microwave cleaned	4/21/2026	
				105 CMR 590.000, interior of microwave oven dirty			
78. MAXI C	Upper Tier	Right-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Microwave cleaned	4/21/2026	
				105 CMR 590.000, interior of microwave oven dirty			
79. MAXI C	Upper Tier	Right-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with			
				105 CMR 590.000, table under microwave oven dirty	Table to be cleaned	5/29/2026	Hubacz
80. MAXI C	Upper Tier	Showers	105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower # 2	Maintenance to inspect and repair	9/4/2026	Hubacz
81. MAXI C	Upper Tier	Showers	105 CMR 451.123*	Maintenance: Wall paint damaged in shower # 1 and 2	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
82. MAXI C	Upper Tier	Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 1 and 2	Showers cleaned	4/21/2026	

83. MAXI C	Upper Tier	Showers	105 CMR 451.123	Maintenance: Wall surface damaged in shower # 1 and 2	Maintenance to inspect and repair	9/4/2026	Hubacz
84. MAXI C	Upper Tier	Showers	105 CMR 451.123	Maintenance: Pipes rusted above shower # 1 and 2	Maintenance to inspect and repair	9/4/2026	Hubacz
85. MAXI C	Lower Tier	Left-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Microwave cleaned	4/21/2026	
				105 CMR 590.000, interior of microwave oven dirty			
86. MAXI C	Lower Tier	Left-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Table to be cleaned	5/29/2026	Hubacz
				105 CMR 590.000, table under microwave oven dirty			
87. MAXI C	Lower Tier	Right-Side Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Microwave cleaned	4/21/2026	
				105 CMR 590.000, interior of microwave oven dirty			
88. MAXI C	Lower Tier	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # 246	Mattress to be replaced	5/29/2026	Dickhaut
89. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Ceiling paint damaged outside of showers	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
90. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 3	Showers cleaned	4/21/2026	
91. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Wall damaged in shower # 1, 2, and 3	Maintenance to inspect and repair	9/4/2026	Hubacz

92. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 2	Showers cleaned	4/21/2026	
93. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Pipes rusted above shower # 2 and 3	Maintenance to inspect and repair	9/4/2026	Hubacz
94. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Floor paint damaged in shower # 3	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
95. MAXI C	Lower Tier	Showers	105 CMR 451.123	Maintenance: Paint damaged on beam outside of shower	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
96. Programs	Male Staff Bathroom		105 CMR 451.123	Maintenance: Ceiling vent dusty	Vent to be cleaned	5/29/2026	Hubacz
97. Programs	Male Staff Bathroom		105 CMR 451.117	Toilet Fixtures: Toilet fixture dirty in stall # 1	Fixture cleaned	4/21/2026	
98. Programs	Female Staff Bathroom		105 CMR 451.123	Maintenance: Ceiling vent dusty	Vent to be cleaned	5/29/2026	Hubacz
Deignan	1. Control Booth Bathroom		105 CMR 451.123	Maintenance: Wall vent dusty	Vent to be cleaned	5/29/2026	Hubacz
	2. Upper West	Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 2 leaking	Maintenance to inspect and repair	5/29/2026	Hubacz
	3. Upper West	Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 2	Showers cleaned	4/21/2026	
	4. Upper West	Showers	105 CMR 451.123	Maintenance: Mold on walls in shower # 2	Showers cleaned	4/21/2026	

	5. Upper West	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 2	Showers cleaned	4/21/2026	
	6. Upper West	Showers	105 CMR 451.123	Maintenance: Door frame damaged in shower # 2	Maintenance to inspect and repair	9/4/2026	Hubacz
	7. Upper West	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink out-of-order	Maintenance to inspect and repair	5/29/2026	Hubacz
	8. Upper West	Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water control leaking at handwash sink # 2	Maintenance to inspect and repair	5/29/2026	Hubacz
	9. Lower West	Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 1 out-of-order	Maintenance to inspect and repair	5/29/2026	Hubacz
	10. Lower West	Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink # 1 out-of-order	Maintenance to inspect and repair	5/29/2026	Hubacz
	11. Lower East	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1	Showers cleaned	4/21/2026	
	12. Lower East	Showers	105 CMR 451.123	Maintenance: Wall epoxy damaged in shower # 1	Maintenance to inspect and repair	9/4/2026	Hubacz
	13. Upper East	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover missing at slop sink	Maintenance to inspect and repair	5/29/2026	Hubacz
Mini-5	1. Bathroom	Left Side	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 1 and 2	Showers cleaned	4/21/2026	
	2. Bathroom	Left Side	105 CMR 451.123	Maintenance: Walls dirty in shower # 2	Showers cleaned	4/21/2026	

	3. Bathroom	Right Side	105 CMR 451.123	Maintenance: Caulking dirty in shower # 1	Showers cleaned	4/21/2026	
	4. Bathroom	Right Side	105 CMR 451.123	Maintenance: Walls dirty outside shower # 1	Walls cleaned	4/21/2026	
	5. Bathroom	Right Side	105 CMR 451.123	Maintenance: Floor dirty outside shower # 1	Floor cleaned	4/21/2026	
1. MIU	Receiving	Staff Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty	Vent to be cleaned	5/29/2026	Hubacz
2. MIU	Receiving	Staff Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 101°F at handwash sink	Maintenance to inspect and repair	9/4/2026	Hubacz
3. Medical Entrance	Right Wing	Inmate WC # 166	105 CMR 451.123	Maintenance: Toilet bowl rusted	Maintenance to inspect and repair	9/4/2026	Hubacz
4. Medical Entrance	Right Wing	Nurse's Station	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 68°F at right side handwash sink	Maintenance to inspect and repair	9/4/2026	Hubacz
5. Medical Entrance	Left Wing	Breakroom # 175	105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with	Ice Machine to be cleaned	5/29/2026	Richard
				105 CMR 590.000, interior of ice machine dirty			
6. Medical Entrance	Left Wing	Inmate WC # 169	105 CMR 451.123	Maintenance: Toilet bowl rusted	Maintenance to inspect and repair	9/4/2026	Hubacz
7. Medical Entrance	2nd Floor	Showers	105 CMR 451.130*	Hot Water: Shower water temperature 74°F at shower # 1	Maintenance to inspect and repair	9/4/2026	Hubacz

8. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Mat outside of shower dirty in shower # 2 and 3	Showers cleaned	4/22/2026	
9. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 3	Showers cleaned	4/22/2026	
10. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 2 and 3	Showers cleaned	4/22/2026	
11. Medical Entrance	2nd Floor	Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty outside of shower # 1, 2, and 3	Vents to be cleaned	5/29/2026	Hubacz
Mods Admin	1. Lobby	Female Bathroom	105 CMR 451.123	Maintenance: Floor tile damaged	Damaged tile to be replaced	9/4/2026	Hubacz
	2. Lobby	Female Bathroom	105 CMR 451.123	Maintenance: Wall tile damaged	Damaged tile to be replaced	9/4/2026	Hubacz
	3. Lobby	Female Bathroom	105 CMR 451.123	Maintenance: Wall tiles missing	Damaged tile to be replaced	9/4/2026	Hubacz
	4. Lobby	Female Bathroom	105 CMR 451.123	Maintenance: Floor dirty	Floor cleaned	4/22/2026	
	5. Special Services Corridor	Female Bathroom	105 CMR 451.123	Maintenance: Wall tile missing	Missing tile to be replaced	9/4/2026	Hubacz
	6. Special Services Corridor	Male Bathroom	105 CMR 451.123	Maintenance: Wall dirty under soap dispenser	Wall to be cleaned	5/29/2026	Hubacz

	7. Special Services Corridor	Female Locker Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 3 out-of-order	Maintenance to inspect and repair	6/30/2026	Hubacz
	8. Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123*	Maintenance: Floor damaged in locker room area	Maintenance to inspect and repair	9/4/2026	Hubacz
	9. Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handicapped shower out-of-order	Maintenance to inspect and repair	6/30/2026	Hubacz
	10. Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Curtain dirty in shower # 2, 3, and 4	Curtains to be replaced	5/29/2026	Hubacz
	11. Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Floor dirty in shower # 3 and 4	Showers to be cleaned	5/29/2026	Hubacz
	12. Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123	Maintenance: Floor dirty outside of showers	Floors to be cleaned	5/29/2026	Hubacz
	13. 2nd Floor	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, drain cover not secure	Maintenance to inspect and repair	5/29/2026	Hubacz
	14. Trap	Bathroom in Pedestrian Trap	105 CMR 451.123	Maintenance: Ceiling water damaged	Maintenance to inspect and repair	9/4/2026	Hubacz

Mods Gym		1. Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Floor tile missing	Missing tile to be replaced	9/4/2026	Hubacz
		2. Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Ceiling vent cover missing	Missing cover to be replaced	6/30/2026	Hubacz
		3. Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Wall damaged behind toilet	Maintenance to inspect and repair	9/4/2026	Hubacz
		4. Inmate Bathroom # 104	105 CMR 451.123	Maintenance: Baseboard damaged	Maintenance to inspect and repair	9/4/2026	Hubacz
		5. Inmate Bathroom # 104	105 CMR 451.123	Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
		6. Staff Bathroom	105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink	Paper Towels replaced	4/22/2026	
H Building		1. Showers	105 CMR 451.123	Maintenance: Curtain dirty in shower # 1, 7, and 8	Curtains to be replaced	5/29/2026	Hubacz
I Building		1. Control Bathroom	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water control leaking	Maintenance to inspect and repair	5/29/2026	Hubacz

		2. Control Bathroom	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 103°F at handwash sink	Maintenance to inspect and repair	9/4/2026	Hubacz
		3. Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty	Microwave cleaned	4/22/2026	
		4. Showers	105 CMR 451.123	Maintenance: Dead drain flies observed on ceiling in shower # 1, 2, 3, 4, 5, 6, 8, 9, and 10	Showers to be treated for drain flies	5/29/2026	Hubacz
		5. Showers	105 CMR 451.123	Maintenance: Drain flies observed in shower # 2 and 8	Showers to be treated for drain flies	5/29/2026	Hubacz
		6. Showers	105 CMR 451.123	Maintenance: Wall vent dusty in shower # 3 and 8	Vents to be cleaned	5/29/2026	Hubacz
		7. Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 4, 8, and 10	Showers cleaned	4/22/2026	
		8. Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 6 and 9	Showers cleaned	4/22/2026	
J Building		1. Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 10 leaking	Maintenance to inspect and repair	5/29/2026	Hubacz
		2. Showers	105 CMR 451.123	Maintenance: Door frame rusted in shower # 3	Maintenance to inspect and repair	9/4/2026	Hubacz
		3. Showers	105 CMR 451.123	Maintenance: Curtain dirty in shower # 4	Curtain to be replaced	5/29/2026	Dowd

		4. Showers	105 CMR 451.123	Maintenance: Dead drain flies observed on ceiling in shower # 5, 8, and 10	Showers cleaned; drain flies to be treated	5/29/2026	Hubacz
		5. Cells	105 CMR 451.101	Blankets: Blanket damaged in cell # 239	Blanket to be replaced	5/29/2026	Dowd
K Building		1. Control Booth	105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of refrigerator dirty	Fridge to be cleaned	5/29/2026	Dowd
		2. Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, table under microwave oven dirty	Table to be cleaned	5/29/2026	Hubacz
		3. Showers	105 CMR 451.123	Maintenance: Debris on floor in shower # 2	Shower cleaned	4/22/2026	
		4. Showers	105 CMR 451.123	Maintenance: Dead drain flies on ceiling in shower # 6, 7, 8, and 9	Showers cleaned; drain flies to be treated	5/29/2026	Hubacz
L Building		1. Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, table under microwave oven dirty	Table to be cleaned	5/29/2026	Hubacz
		2. Showers	105 CMR 451.123*	Maintenance: Mold where floor and wall meet in shower # 2, 3, 4, 5, 6, 7, and 8	Showers cleaned	4/22/2026	
		3. Showers	105 CMR 451.123	Maintenance: Mold where floor and wall meet in shower # 9 and 10	Showers cleaned	4/22/2026	
		4. Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 10 leaking	Maintenance to inspect and repair	5/29/2026	Hubacz

		5. Showers	105 CMR 451.123	Maintenance: Floor dirty in shower # 1, 2, 3, 4, 5, 6, 7, 8, 9, and 10	Showers cleaned	4/22/2026	
		6. Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1, 2, 3, 4, 5, 6, 7, 8, 9, and 10	Showers cleaned	4/22/2026	
		7. Showers	105 CMR 451.123	Maintenance: Ceiling dirty in shower # 3	Shower cleaned	4/22/2026	
		8. Showers	105 CMR 451.123	Maintenance: Mold on light shield in shower # 5 and 10	Light shields to be cleaned	5/29/2026	Hubacz
		9. Showers	105 CMR 451.123	Maintenance: Dead drain flies observed on ceiling in shower # 6, 8, and 9	Showers cleaned; drain flies to be treated	5/29/2026	Hubacz
Warehouse	1. Staff Gym	Female Bathroom/ Locker Room	105 CMR 451.123*	Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
	2. Staff Gym	Female Bathroom/ Locker Room	105 CMR 451.123*	Maintenance: Floor tiles not secure near toilet	Maintenance to inspect and repair	9/4/2026	Hubacz
	3. Staff Gym	Female Bathroom/ Locker Room	105 CMR 451.123	Maintenance: Mold on walls	Walls to be cleaned	5/29/2026	Hubacz
	4. Staff Gym	Female Bathroom/ Locker Room	105 CMR 451.123	Maintenance: Grab bar rusted in shower	Maintenance to inspect and repair	9/4/2026	Hubacz
	5. Staff	Female Bathroom/	105 CMR	Maintenance: Dead drain flies observed on	Showers cleaned; drain flies to be treated	5/29/2026	Hubacz

	Gym	Locker Room	451.123	floor in shower			
	6. Warehouse	Staff Bathroom # 2	105 CMR 451.123	Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
	7. Warehouse	Staff Bathroom # 2	105 CMR 451.123	Maintenance: Floor tile damaged	Damaged tile to be replaced	9/4/2026	Hubacz
	8. Warehouse	Staff Bathroom # 2	105 CMR 451.123	Maintenance: Wall water damaged	Maintenance to inspect and repair	9/4/2026	Hubacz
Garage		1. Garage Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty	Microwave cleaned	4/22/2026	

Recommended Standards (.300 & .400 series)

1. A1 Block	Lower Tier	Day Room	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty near microwave oven	Vent to be cleaned	5/29/2026	Hubacz
2. A1 Block	Lower Tier	Day Room	105 CMR 451.353	Interior Maintenance: Metal grate leading to lower cells dusty	Grate to be cleaned	5/29/2026	Dickhaut
3. A1 Block	Lower Tier	Room # 3	105 CMR 451.360	Protective Measures: Rodent droppings observed	Room cleaned	4/21/2026	
4. A1 Block	Lower Tier	Room # 3	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	Vent to be cleaned	5/29/2026	Hubacz
5. A1 Block	Lower Tier	Shakedown Room # 6	105 CMR 451.353	Interior Maintenance: Wall mounted fan dusty	Fan to be cleaned	5/29/2026	Hubacz

6. A1 Block	Upper Tier	Slop Sink (Upstairs)	105 CMR 451.353	Interior Maintenance: Floor dirty	Floor cleaned	4/21/2026	
7. A1 Block	Upper Tier	Slop Sink (Upstairs)	105 CMR 451.353	Interior Maintenance: Walls dirty	Walls to be cleaned	5/29/2026	Dickhaut
8. A1 Block	Upper Tier	Cells (Upstairs)	105 CMR 451.353	Interior Maintenance: Debris in door guide leading to cells	Door guides to be cleaned	5/29/2026	Dickhaut
9. A1 Block	Upper Tier	Cells (Upstairs)	105 CMR 451.360	Protective Measures: Rodent droppings observed in door guide leading to cells	Door guides cleaned	4/22/2026	
10. A1 Block	Lower Tier	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Walls dirty	Walls to be cleaned	5/29/2026	Dickhaut
11. A1 Block	Lower Tier	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Floor dirty	Floor cleaned	4/21/2026	
12. A1 Block	Lower Tier	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	Vent to be cleaned	5/29/2026	Hubacz
13. A1 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Floor dirty in cell # 32	Floor cleaned	4/21/2026	
14. A1 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 21, 26, 27, and 32	Damaged paint to be scraped and repainted	9/4/2026	Dickhaut
15. A1 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 25 and 30	Obstructions removed	4/21/2026	

16. A1 Block			105 CMR 451.320	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
17. A2 Block			105 CMR 451.320	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
18. A2 Block	Lower Tier	Day Room	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty near microwave oven	Vent to be cleaned	5/29/2026	Hubacz
19. A2 Block	Lower Tier	Chemical Storage Room	105 CMR 451.360	Protective Measures: Rodent droppings observed	Floor cleaned	4/21/2026	
20. A2 Block	Lower Tier	Paper Good Storage	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	Vent to be cleaned	5/29/2026	Hubacz
21. A2 Block	Upper Tier	Cells (Upstairs)	105 CMR 451.360	Protective Measures: Rodent droppings observed in door guide leading to cells	Door guides cleaned	4/22/2026	
22. A2 Block	Upper Tier	Cells (Upstairs)	105 CMR 451.360	Protective Measures: Rodent droppings observed in door guide of cell # 41	Door guides cleaned	4/22/2026	

23. A2 Block	Lower Tier	Slop Sink (Downstairs)	105 CMR 451.353	Interior Maintenance: Slop sink dirty	Sink to be cleaned	5/29/2026	Dickhaut
24. A2 Block	Lower Tier	Cells (Downstairs)	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 52 and 60	Obstructions removed	4/21/2026	
25. A2 Block	Hallway	Storage Closets	105 CMR 451.360	Protective Measures: Rodent droppings observed	Floor cleaned	4/21/2026	
26. MAXI B	Lower Right Tier	Day Room	105 CMR 451.353	Interior Maintenance: Debris between metal grate and window of Day Room	Debris cleaned	4/22/2026	
27. MAXI B	Lower Left Tier	Day Room	105 CMR 451.353	Interior Maintenance: Debris between metal grate and window to Day Room	Debris cleaned	4/22/2026	
28. MAXI B	Lower Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 135 and 141	Obstructions removed	4/21/2026	
29. MAXI B	Upper Right Tier	Day Room	105 CMR 451.353	Interior Maintenance: Debris between metal grate and window to Day Room	Debris cleaned	4/22/2026	
30. MAXI B	Upper Right Tier	Day Room	105 CMR 451.353	Interior Maintenance: Window to Day Room dirty	Window to be cleaned	5/29/2026	Dickhaut
31. MAXI B	Upper Right Tier	Day Room	105 CMR 451.353	Interior Maintenance: Standing fan dusty	Fan to be cleaned	5/29/2026	Dickhaut
32. MAXI B	Upper Right Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 304	Damaged paint to be scraped and repainted	9/4/2026	Dickhaut
33. MAXI B	Upper Left Tier	Day Room	105 CMR 451.353	Interior Maintenance: Debris between metal grate and window to Day Room	Debris cleaned	4/22/2026	

34. MAXI B	Upper Left Tier	Day Room	105 CMR 451.353	Interior Maintenance: Metal grate dirty inside Day Room near trash can	Grate to be cleaned	5/29/2026	Dickhaut
35. MAXI B	Upper Left Tier	Day Room	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged outside of Day Room	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
36. MAXI B	Upper Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 307 and 329	Obstructions removed	4/21/2026	
37. MAXI B	Upper Left Tier	Cells	105 CMR 451.353	Interior Maintenance: Baseboard paint damaged near toilet in cell # 337	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
38. Main Gymnasium	Basketball Court		105 CMR 451.353*	Interior Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
39. Main Gymnasium	Basketball Court		105 CMR 451.353	Interior Maintenance: Ceiling water damaged	Maintenance to inspect and repair	9/4/2026	Hubacz
40. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 418, 428, 430, 432, 434, 440, and 448	Damaged paint to be scraped and repainted	9/4/2026	Dickhaut
41. MAXI C	Upper Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 420	Damaged paint to be scraped and repainted	9/4/2026	Dickhaut
42. MAXI C	Lower Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 229	Obstruction removed	4/21/2026	
43. MAXI C	Lower Tier	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 247	Damaged paint to be scraped and repainted	9/4/2026	Dickhaut
44. Maintenance Corridor	Welding Area		105 CMR 451.350	Structural Maintenance: Exterior door not rodent and weathertight	Maintenance to inspect and repair	9/4/2026	Hubacz

45. MAXI C			105 CMR 451.320	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
1. Deignan Building			105 CMR 451.320	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
2. Deignan Building	Dry Storage		105 CMR 451.360	Protective Measures: Rodents observed, rodent droppings observed	Floor cleaned	4/21/2026	
3. Deignan Building	Upper West	Cells	105 CMR 451.353	Interior Maintenance: Ceiling water damaged in cell # 56	Maintenance to inspect and repair	9/4/2026	Hubacz
1. MIU	Receiving	Holding Cells	105 CMR 451.353	Interior Maintenance: Ceiling dirty in cell # 121	Ceiling to be cleaned	5/29/2026	Hubacz
2. MIU	Receiving	Holding Cells	105 CMR 451.353	Interior Maintenance: Walls dirty in cell # 114	Walls to be cleaned	5/29/2026	Daignault
3. MIU	Receiving	Receiving Trap	105 CMR 451.350	Structural Maintenance: Exterior door not rodent and weathertight	Maintenance to inspect and repair	9/4/2026	Hubacz

4. MIU	Receiving	Janitor's Closet # 154	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged outside of closet	Damaged tiles to be replaced	9/4/2026	Hubacz
5. Medical Entrance	Right Wing	Nurse's Station	105 CMR 451.353	Interior Maintenance: Right side bubbler dirty	Bubbler cleaned	4/22/2026	
6. Medical Entrance	Left Wing	Soil Storage # 170 (Medical Waste)	105 CMR 451.353	Interior Maintenance: Objectionable odor observed	Medical to assess & remediate	5/29/2026	Richard
7. Medical Entrance	2nd Floor	Single Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 219	Obstruction removed	4/22/2026	
8. Medical Entrance	2nd Floor	Single Cells	105 CMR 451.353	Interior Maintenance: Walls dirty in cell # 217	Walls to be cleaned	5/29/2026	Daignault
Mods Admin	1. Building Exterior		105 CMR 451.350*	Structural Maintenance: Exterior wall damaged	Maintenance to inspect and repair	9/4/2026	Hubacz
	2. Control 3		105 CMR 451.344	Illumination in Habitable Areas: Light(s) not functioning properly, light out in break area	Lightbulb to be replaced	5/29/2026	Hubacz
	3. 2nd Floor	Copy Room	105 CMR 451.353	Interior Maintenance: Floor damaged	Maintenance to inspect and repair	9/4/2026	Hubacz
	4. 2nd Floor	Copy Room	105 CMR 451.353	Interior Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
	5. 2nd Floor	Slop Sink Room	105 CMR 451.353	Interior Maintenance: Wet mop stored in sink	Mop removed	4/22/2026	

Mods Gym		1. Gym	105 CMR 451.353*	Interior Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	9/4/2026	Hubacz
		2. Gym	105 CMR 451.360*	Protective Measures: Bird nest observed in window above entrance	Birds nest to be removed	5/29/2026	Hubacz
		3. Gym	105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight	Maintenance to inspect and repair	9/4/2026	Hubacz
		4. Gym	105 CMR 451.353	Interior Maintenance: Baseboard around gym dirty	Baseboard to be cleaned	5/29/2026	Dowd
H Building		1. Cells	105 CMR 451.320	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
		2. Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 119 and 131	Damaged paint to be scraped and repainted	9/4/2026	Dowd
		3. Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 128	Damaged paint to be scraped and repainted	9/4/2026	Dowd
		4. Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 138 and 143	Obstructions removed	4/22/2026	


		5. Cells	105 CMR 451.353	Interior Maintenance: Light fixture missing in cell # 132	Missing fixture to be replaced	5/29/2026	Hubacz
I Building		1. Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles missing	Missing tiles to be replaced	9/4/2026	Hubacz
		2. Cells	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 200	Damaged paint to be scraped and repainted	9/4/2026	Dowd
J Building		1. Common Area	105 CMR 451.353	Interior Maintenance: Seat damaged at table	Damaged seat to be replaced	9/4/2026	Hubacz
		2. Common Area	105 CMR 451.353	Interior Maintenance: Wall fan dusty	Fan to be cleaned	5/29/2026	Hubacz
		3. Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 264	Obstruction removed	4/22/2026	
		4. Cells	105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 251	Damaged paint to be scraped and repainted	9/4/2026	Dowd
		5. Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 234, 246, 255, 256, 273, and 276	Obstructions removed	4/22/2026	

K Building		1. Cells	105 CMR 451.320	Cell Size: Inadequate floor space in all cells	This is a recommended DPH standard. The facility acknowledges that due to facility design and separation of inmates some cells do not have the recommended floor space.		
		2. Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles damaged	Damaged tiles to be replaced	9/4/2026	Hubacz
		3. Common Area	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged outside of cell # 326	Damaged paint to be scraped and repainted	9/4/2026	Dowd
		4. Common Area	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged throughout	Damaged tiles to be replaced	9/4/2026	Hubacz
		5. Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 281, 290, and 324	Damaged paint to be scraped and repainted	9/4/2026	Dowd
L Building		1. Common Area	105 CMR 451.350	Structural Maintenance: Ceiling water damaged near control booth	Maintenance to inspect and repair	9/4/2026	Hubacz
		2. Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 243, 350, 371, 381, and 388	Obstructions removed	4/22/2026	
		3. Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged outside of cell # 383	Damaged paint to be scraped and repainted	9/4/2026	Dowd
		4. Cells	105 CMR 451.353	Interior Maintenance: Ceiling water damaged outside of cell # 387	Maintenance to inspect and repair	9/4/2026	Hubacz

		5. Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 357	Damaged paint to be scraped and repainted	9/4/2026	Dowd
		6. Chemical Room	105 CMR 451.353	Interior Maintenance: Floor paint damaged	Damaged paint to be scraped and repainted	9/4/2026	Dowd
Warehouse		1. Warehouse	105 CMR 451.353	Interior Maintenance: Hole in floor in back corner near exit door	Maintenance to inspect and repair	9/4/2026	Hubacz

Deficiencies under 105 CMR 451.402(B) (other conditions that may constitute a threat to health or safety)

	1. Maintenance Corridor	EHSO Office (Waste Log)	105 CMR 451.425(A)	Tracking Medical or Biological Waste for Treatment: Generator did not confirm the shipment was received by the treatment facility within 30 days on an approved tracking form Standard found in 105 CMR 480.425(A). ** Corrected On-Site **			
--	-------------------------	-------------------------	--------------------	--	--	--	--



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

May 29, 2026

Sheriff Lewis Evangelidis
Worcester County Jail and House of Correction
5 Paul X. Tivnan Drive
West Boylston, MA 01583 (electronic copy)

Re: Plan of Correction – Worcester County Jail and HOC, West Boylston

Dear Sheriff Evangelidis:

The Massachusetts Department of Public Health, Division of Environmental Regulations and Standards (EHRS) has received your Plan of Correction in response to my inspection conducted on April 21 and 22, 2026. After review, the EHRS finds the plan addresses all the deficiencies noted with the following exceptions:

1. In regards to the issue of overcrowding, the EHRS appreciates the limitations of correctional facilities and the need to accommodate the ever-increasing population; however we remain concerned with the overcrowded conditions; and
2. Please provide the specific corrective steps to be taken and an estimated date of completion for the following items:
 - a. Chemical dispensing tube in sink in the Dishwasher Area in the Main Kitchen; and
 - b. Insufficient hot holding equipment in number and capacity in the Inmate Serving Area in the Main Kitchen.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Hannah LeBeau
Environmental Health Officer, EHRS, BCEH

cc: Noe Bard, EHSO
Captain Eric Locke, Policy, Procedure, Accreditation and Compliance
Lieutenant Devon Walker, Policy, Procedure, Accreditation and Compliance
Superintendent Jason Rives

(electronic copy)
(electronic copy)
(electronic copy)



Commonwealth of Massachusetts

OFFICE OF THE SHERIFF

COUNTY OF WORCESTER
JAIL AND HOUSE OF CORRECTION
5 PAUL X. TIVNAN DRIVE
WEST BOYLSTON, MASSACHUSETTS 01583
TELEPHONE: 508 854-1800

LEWIS G. EVANGELIDIS
SHERIFF

FAX: 508 856-0465
TTY: 508 854-1888

June 3, 2026

Hannah Lebeau
Environmental Health Officer
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street Suite 100
Marlborough, MA 01752

Re: Plan of Correction – Worcester County House of Corrections and Jail


Dear Ms. Lebeau:

In response to your letter dated May 29, 2026, please find our detailed corrective steps below.

- 2.a. The chemical dispensing tube is being removed from the sink and installed directly to the grease trap. The estimated date of completion for this is July 1, 2026.
- 2.b. Four new hot holding warmers are on order and expected to be delivered the first week of July.


If you require additional information, please feel free to contact me.

Sincerely,



Jason Rives
Superintendent

cc: AS Jason Butland
Capt. Eric Locke
Lt. Devon Walker
Anna Laukaitis – Compliance Analyst



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

June 5, 2026

Lewis Evangelidis, Sheriff
Worcester County Jail and House of Correction
5 Paul X. Tivnan Drive
West Boylston, MA 01583 (electronic copy)

Re: Plan of Correction – Worcester County Jail and House of Correction, West Boylston

Dear Sheriff Evangelidis:

The Massachusetts Department of Public Health, Division of Environmental Regulations and Standards (EHRS) has received your Plan of Correction dated June 3, 2026. After review, the EHRS finds the plan addresses all the deficiencies noted.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Hannah LeBeau
Environmental Health Officer, EHRS, BCEH

cc:	Noe Bard, EHSO	(electronic copy)
	Captain Eric Locke, Policy, Procedure, Accreditation and Compliance	(electronic copy)
	Lieutenant Devon Walker, Policy, Procedure, Accreditation and Compliance	(electronic copy)
	Superintendent Jason Rives	(electronic copy)