



The Commonwealth of Massachusetts
 Executive Office of Health and Human Services
 Department of Public Health
 Bureau of Environmental Health
 Community Sanitation Program
 5 Randolph Street, Canton, MA 02021
 Phone: 781-828-7700
 Fax: 781-828-7703

CHARLES D. BAKER
 Governor

KARYN E. POLITO
 Lieutenant Governor

MARYLOU SUDDERS
 Secretary

MARGRET R. COOKE
 Acting Commissioner

Tel: 617-624-6000
www.mass.gov/dph

October 12, 2021

Joseph D. McDonald, Jr., Sheriff
 Plymouth County Correctional Facility
 26 Long Pond Road
 Plymouth, MA 02360 (electronic copy)

Re: Facility Inspection - Plymouth County Correctional Facility

Dear Sheriff McDonald:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 2013 Food Code; 105 CMR 500.000 Good Manufacturing Practices for Food; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; the Department's Community Sanitation Program (CSP) conducted an inspection of the Plymouth County Correctional Facility on September 30 and October 1, 2021 accompanied by Kevin DiMarzio, ADS of Operations, and Ronald Ehnes, Accreditation Specialist. Violations noted during the inspection are listed below including 64 repeat violations:

Should you have any questions, please don't hesitate to contact me.

Sincerely,

Nicholas Gale
 Environmental Analyst, CSP, BEH

cc: Margret R. Cooke, Acting Commissioner, DPH (electronic copy)
 Jan Sullivan, Acting Director, BEH (electronic copy)
 Steven Hughes, Director, CSP, BEH (electronic copy)
 Marylou Sudders, Secretary, Executive Office of Health and Human Services (electronic copy)
 Carol A. Mici, Commissioner, DOC (electronic copy)
 Terrence Reidy, Acting Secretary, EOPSS (electronic copy)
 Timothy Gotovich, Acting Director, Policy Development and Compliance Unit (electronic copy)
 Antone Moniz, Superintendent (electronic copy)
 Ronald Ehnes, Accreditation Specialist (electronic copy)
 Karen Keane, Acting Director, Plymouth Board of Health (electronic copy)
 Clerk, Massachusetts House of Representatives (electronic copy)
 Clerk, Massachusetts Senate (electronic copy)

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

Front Lobby

Main Area

105 CMR 451.353 Interior Maintenance: Ceiling tiles water damaged near vending machines

Janitor's Closet

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Administration Area

Break Room # 1014

No Violations Noted

Male Bathroom # 1013

No Violations Noted

Female Bathroom # 1015

No Violations Noted

Mail Room # 1016

No Violations Noted

Administration - Main Hallway

Janitor's Closet # 1027

No Violations Noted

PREA Manager # 1021

No Violations Noted

Immigration Office # 1020

Unable to Inspect – Locked

Female Locker Room

105 CMR 451.353 Interior Maintenance: Ceiling vent dusty

Showers

No Violations Noted

Male Locker Room

105 CMR 451.353* Interior Maintenance: Ceiling vents dusty

Showers

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, handicapped shower leaking

Staff Gym

No Violations Noted

IPS Office

No Violations Noted

Food Service Area

The following Food Code violations listed in **BOLD** were observed to be corrected on-site.

Staff Dining

Staff Dining Area

FC 6-501.12(A)*

Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, interior of microwave oven dirty

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, interior of microwave oven surface damaged

Staff Serving Line

FC 6-501.12(A)

Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, ceiling vent dusty

FC 4-601.11(A)

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty^{Pf}, coffee machine dirty

FC 4-501.114(C)(2)

Maintenance and Operation; Equipment: Quaternary ammonium compound (QAC) solution lower than the manufacturers recommended concentration

Kitchen Area

Continental Warming Units

FC 4-501.11(B)

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged in warming unit # 3, 4, and 5

FC 4-202.11(A)(2)

Design and Construction; Cleanability: Multiuse food contact surface not free of breaks, open seams, cracks, chips, inclusions, pits, and similar imperfections^{Pf}, bottom interior surface damaged in warming unit # 3

Bakery Area

No Violations Noted

Office

FC 6-501.12(A)

Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, ice build-up in small refrigerator

FC 4-501.11(B)

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged

Office Bathroom

No Violations Noted

Dry Storage

No Violations Noted

Tool Closet

No Violations Noted

Cooler # 2

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, refrigerator temperature recorded 60°F

Inmate Break Area

No Violations Noted

Inmate Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Freezer # 1

FC 3-202.15

Sources, Specifications; Specifications for Receiving: Food packages not in good condition^{Pf}, damaged ice cream container observed

Cooler # 3

FC 6-501.11

Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, 1 cooler fan not working

Cooler # 4

No Violations Noted

Cooler # 5

No Violations Noted

Freezer # 6

No Violations Noted

Prep Area

4-Compartment Sink Area

No Violations Noted

Stove and Kettle Area

FC 6-501.12(A)

Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, ventilation hood dusty

FC 6-501.11

Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, exterior metal grates not appropriately attached to ventilation hood

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, 2 kettle hinges damaged

Manual Rinse Station

3-Compartment Sink

FC 4-901.11(A)*

Protection of Clean Items; Drying: Cleaned, sanitized equipment and utensils not allowed to fully air dry

Dishwashing Machine Area

FC 6-501.12(A)

Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, standing water observed around floor drain in warewash machine area

Laundry

Janitor's Closet

No Violations Noted

Office

No Violations Noted

Chemical Closet

No Violations Noted

Inmate Bathroom # 1058

No Violations Noted

Loading Dock

105 CMR 451.350

Structural Maintenance: Large rolling door # K4 not rodent and weathertight

Maintenance # 1053

Small Tool Room

No Violations Noted

Bathroom

Unable to Inspect – In Use

Office

No Violations Noted

Office Bathroom

No Violations Noted

Attorney Visits

No Violations Noted

Chapel

105 CMR 451.353*

Interior Maintenance: Carpet dirty

105 CMR 451.353*

Interior Maintenance: Ceiling vent rusted

Medical Corridor

No Violations Noted

HSU

Waiting Room # M103

No Violations Noted

Stock # M110

No Violations Noted

Staff Break Room

105 CMR 451.200

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Nurse's Station # M106

No Violations Noted

Storage # M133

No Violations Noted

Room # M132

No Violations Noted

Autoclave # M131

No Violations Noted

<i>Staff Bathroom # M130</i>	No Violations Noted
<i>Supervisor's Office # M129</i>	No Violations Noted
<i>Pharmacy # M128</i> 105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink
<i>Janitor's Closet # M127</i>	No Violations Noted
<i>Laboratory # M126</i>	No Violations Noted
<i>Dentist # M124</i>	No Violations Noted
<i>X-Ray Room # M123</i>	No Violations Noted
<i>Inmate Bathroom # M122</i> 105 CMR 451.123*	Maintenance: Ceiling vent dusty
<i>Exam Room # M121</i>	No Violations Noted
<i>Room # M119</i>	No Violations Noted
<i>Handicapped Bathroom</i>	No Violations Noted
<i>Office # M112</i>	No Violations Noted
<i>Cell # M113 - M116</i>	No Violations Noted
<i>Office # M117</i>	No Violations Noted
<i>Office # M118</i>	No Violations Noted
<u>Property</u>	No Violations Noted
<u>Booking</u>	
<i>Main Area</i> 105 CMR 451.350*	Structural Maintenance: Exit door not rodent and weathertight in Bail Lobby
<i>Office # R112</i>	No Violations Noted

<i>Records # R106</i>	No Violations Noted
<i>Inmate Toilet # R105</i>	No Violations Noted
<i>Inmate Bathroom # R118</i>	No Violations Noted
<i>Janitor's Closet # R126</i>	No Violations Noted
<i>Watch Cells</i>	No Violations Noted
<i>Holding Cells</i>	No Violations Noted
<i>Staff Bathroom # R127</i>	No Violations Noted
<i>Showers</i>	No Violations Noted
<i>Officer's Landing</i>	No Violations Noted
<i>Kitchenette</i>	No Violations Noted
<u>Library</u> 105 CMR 451.353*	Interior Maintenance: Ceiling vents dusty
<i>Library Bathroom</i>	No Violations Noted
<u>Human Services # 1079</u>	
<i>Break Room</i>	No Violations Noted
<i>Offices</i>	No Violations Noted
<i>Staff Bathroom # 1069</i>	No Violations Noted
<i>Janitor's Closet # 1064</i>	No Violations Noted
<u>Gymnasium</u>	No Violations Noted
<i>Toilet Area</i>	No Violations Noted

Main Hallway

Female Staff Bathroom # 1039

No Violations Noted

Male Staff Bathroom # 1040

No Violations Noted

Janitor's Closet # 1084
105 CMR 451.344

Illumination in Habitable Areas: Light not functioning properly, light out

Staff Bathroom # 1090

No Violations Noted

Room # 1094

No Violations Noted

Janitor's Closet # 1095

No Violations Noted

Staff Bathroom # 1098
105 CMR 451.123

Maintenance: Sink faucet rusted

Staff Bathroom # 1099

No Violations Noted

Unit Manager # 1100

No Violations Noted

Classroom # 1102

No Violations Noted

Staff Bathroom # 1102

No Violations Noted

Office # 1103

No Violations Noted

Staff Bathroom # 1107

No Violations Noted

Janitor's Closet # 1108

No Violations Noted

Classroom # 1110

No Violations Noted

Unit Manager's Office # 1112

No Violations Noted

Cell Blocks/Pods

A1

Classroom

No Violations Noted

<i>Slop Sink</i>	No Violations Noted
<i>Bathroom</i>	No Violations Noted
<i>Showers</i>	No Violations Noted
<i>Cell # A107 - A110</i>	No Violations Noted
<i>Main Area – Dorm Bunks</i> 105 CMR 451.322*	Cell Size: Inadequate floor space in dorm area
BS101	
<i>Trap – First Floor</i>	No Violations Noted
<i>Slop Sink</i>	No Violations Noted
<i>Bathroom</i>	No Violations Noted
<i>Showers</i> 105 CMR 451.123	Maintenance: Soap scum on walls in shower # 5
<i>Main Area – Dorm Bunks</i> 105 CMR 451.322* 105 CMR 451.353*	Cell Size: Inadequate floor space in dorm area Interior Maintenance: Ceiling vents dusty
BN101	
<i>Slop Sink</i>	No Violations Noted
<i>Bathroom</i>	No Violations Noted
<i>Showers</i> 105 CMR 451.123	Maintenance: Soap scum on walls in shower # 5 and 7
<i>Main Area – Dorm Bunks</i> 105 CMR 451.322* 105 CMR 451.353*	Cell Size: Inadequate floor space in dorm area Interior Maintenance: Ceiling vents dusty
BS201	
<i>Slop Sink</i>	No Violations Noted
<i>Bathroom</i>	No Violations Noted

Showers

No Violations Noted

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

BN201

Slop Sink

No Violations Noted

Bathroom

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, sink # 3 leaking

Showers

No Violations Noted

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

C1

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 6 leaking

105 CMR 451.123

Maintenance: Mold on ceiling outside showers

Recreation Deck

105 CMR 451.360*

Protective Measures: Bird's nests observed

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space, cells double bunked

105 CMR 451.353*

Interior Maintenance: Wall vent blocked in cell # 104, 105, 112, 120, 205, 224, and 231

105 CMR 451.353

Interior Maintenance: Wall vent blocked in cell # 114, 115, 125, 126, 128, 131, 222, 223, 225, and 227

105 CMR 451.103

Mattresses: Mattress damaged in cell # 106, 207, and 208

DN1

Main Area

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Slop Sink

No Violations Noted

<i>Showers – 1st Floor</i>	No Violations Noted
<i>Showers – 2nd Floor</i> 105 CMR 451.123	Maintenance: Soap scum on walls in shower # 6
<i>Recreation Deck</i>	No Violations Noted
<i>Second Floor – Rooms</i>	No Violations Noted
<i>Cells</i> 105 CMR 451.322*	Cell Size: Inadequate floor space in dorm cells
DS1	
<i>Main Area</i> 105 CMR 451.353*	Interior Maintenance: Ceiling vents dusty
<i>Slop Sink</i>	No Violations Noted
<i>Showers – 1st Floor</i>	No Violations Noted
<i>Showers – 2nd Floor</i>	No Violations Noted
<i>Recreation Deck</i>	No Violations Noted
<i>Second Floor – Rooms</i>	No Violations Noted
<i>Cells</i> 105 CMR 451.322*	Cell Size: Inadequate floor space in dorm cells
E1	
<i>Main Area</i> 105 CMR 451.353*	Interior Maintenance: Ceiling tiles water stained above entrance to Recreation Deck
<i>Slop Sink</i>	No Violations Noted
<i>Showers</i> 105 CMR 451.123* 105 CMR 451.123*	Maintenance: Mold on ceiling outside showers Maintenance: Soap scum on walls in shower # 6, 8, and 9
<i>Recreation Deck</i>	No Violations Noted
<i>Second Floor – Rooms</i>	No Violations Noted

Cells
105 CMR 451.321* Cell Size: Inadequate floor space, cells double bunked
105 CMR 451.353 Interior Maintenance: Ceiling dirty in cell # 236
105 CMR 451.353 Interior Maintenance: Wall vent blocked in cell # 215 and 219
105 CMR 451.353* Interior Maintenance: Wall vent blocked in cell # 235

FN1

Main Area
No Violations Noted

Slop Sink
No Violations Noted

Recreation Deck
No Violations Noted

Showers – 1st Floor
No Violations Noted

Showers – 2nd Floor
No Violations Noted

Second Floor – Rooms
No Violations Noted

Cells
105 CMR 451.322* Cell Size: Inadequate floor space in dorm cells
105 CMR 451.353 Interior Maintenance: Wall vent blocked in cell # 204

FS1

Main Area
No Violations Noted

Slop Sink
No Violations Noted

Showers – 1st Floor
No Violations Noted

Showers – 2nd Floor
No Violations Noted

Recreation Deck
No Violations Noted

Second Floor – Rooms
No Violations Noted

Cells
105 CMR 451.322* Cell Size: Inadequate floor space in dorm cells

H1

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 9

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space, cells double bunked

105 CMR 451.103

Mattresses: Mattress damaged in cell # 231

G Block

Main Area

No Violations Noted

GE South

105 CMR 451.353

Interior Maintenance: Ceiling dirty around ceiling vent

Slop Sink

No Violations Noted

Showers

No Violations Noted

Chemical Storage

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space, cells double bunked

105 CMR 451.353*

Interior Maintenance: Wall vent blocked in cell # 105

105 CMR 451.353

Interior Maintenance: Ceiling dirty in cell # 208

GE North

105 CMR 451.353

Interior Maintenance: Ceiling tiles water damaged

105 CMR 451.353

Interior Maintenance: Ceiling dirty around ceiling vents

Slop Sink

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Floor dirty outside showers

105 CMR 451.123

Maintenance: Floor dirty in shower # 1, 2, and 3

105 CMR 451.123

Maintenance: Soap scum on metal door in shower # 2

Cells

105 CMR 451.321*
105 CMR 451.353*
105 CMR 451.353

Cell Size: Inadequate floor space, cells double bunked
Interior Maintenance: Wall vent blocked in cell # 117
Interior Maintenance: Wall vent blocked in cell # 110

GW North

Slop Sink

No Violations Noted

Showers

105 CMR 451.123

Maintenance: Ceiling vents dusty outside showers

Cells

105 CMR 451.321*
105 CMR 451.353*
105 CMR 451.353

Cell Size: Inadequate floor space, cells double bunked
Interior Maintenance: Wall vent blocked in cell # 115
Interior Maintenance: Wall vent blocked in cell # 215

GW South

Slop Sink

No Violations Noted

Showers

105 CMR 451.123

Maintenance: Ceiling vents dusty outside showers

Cells

105 CMR 451.353*
105 CMR 451.353

Interior Maintenance: Wall vent blocked in cell # 108
Interior Maintenance: Wall vent blocked in cell # 104 and 105

3rd Floor

Main Hallway

Attorney Visit Room # 3024

No Violations Noted

Janitor's Closet # 3022

No Violations Noted

Staff Bathroom # 3021

No Violations Noted

Storage # 3020

No Violations Noted

Janitor's Closet # 3018

No Violations Noted

Discovery Room # 3015

No Violations Noted

Unit Manager # 3012

No Violations Noted

Chaplin's Office # 3011

No Violations Noted

Janitor's Closet # 3010
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Staff Bathroom # 3009

No Violations Noted

Break Room # 3008
105 CMR 451.200

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Janitor's Closet # 3006

No Violations Noted

Classroom # 3005

No Violations Noted

I.C.E. Video Courtroom # 3004

No Violations Noted

Staff Bathroom # 3003

No Violations Noted

3rd Floor - Cell Blocks/Pods

C3

Main Area
105 CMR 451.353

Interior Maintenance: Wall vent dusty under hot water dispenser

Slop Sink

No Violations Noted

Showers
105 CMR 451.123*
105 CMR 451.130
105 CMR 451.123

Maintenance: Soap scum on walls in shower # 9
Plumbing: Plumbing not maintained in good repair, shower # 2 leaking
Maintenance: Staircase rusted outside showers

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells
105 CMR 451.321*
105 CMR 451.353

Cell Size: Inadequate floor space, cells double bunked
Interior Maintenance: Wall vent blocked in cell # 324, 326, 327, 407, and 422

DN3

Main Area
105 CMR 451.353

Interior Maintenance: Ceiling tiles water damaged

Slop Sink

No Violations Noted

Showers – 1st Floor

105 CMR 451.123

105 CMR 451.123

Maintenance: Excessive moisture on ceiling in shower # 1

Maintenance: Drain flies observed in shower # 3

Showers – 2nd Floor

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 7 leaking

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.322*

105 CMR 451.353*

105 CMR 451.353

Cell Size: Inadequate floor space in dorm cells

Interior Maintenance: Ceiling surface damaged in cell # 305 and 306

Interior Maintenance: Wall vent blocked in cell # 405

DS3

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers – 1st Floor

105 CMR 451.123

Maintenance: Drain flies observed in shower # 2

Showers – 2nd Floor

105 CMR 451.123

Maintenance: Mold on ceiling outside showers

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.322*

105 CMR 451.353*

Cell Size: Inadequate floor space in dorm cells

Interior Maintenance: Wall vent blocked in cell # 307

E3

Main Area

105 CMR 451.353

Interior Maintenance: Wall vent dusty in hot water dispenser area

Slop Sink

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Showers

105 CMR 451.123

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 9

Maintenance: Mold on ceiling outside showers

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space, cells double bunked

105 CMR 451.353

Interior Maintenance: Wall vent blocked in cell # 320 and 331

FS3

Main Area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

105 CMR 451.353

Interior Maintenance: Ceiling tiles water damaged

Slop Sink

No Violations Noted

Medical Room

No Violations Noted

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor

No Violations Noted

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm cells

105 CMR 451.353

Interior Maintenance: Ceiling vent blocked in cell # 406

FN3

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers – 1st Floor

105 CMR 451.123*

Maintenance: Excessive moisture on ceiling in shower # 1

Showers – 2nd Floor

No Violations Noted

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm cells

105 CMR 451.353*

Interior Maintenance: Ceiling paint damaged in cell # 307

H3

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers

No Violations Noted

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space, cells double bunked

Garage

Bathroom # W124

No Violations Noted

Janitor's Closet # W123

No Violations Noted

Print Shop

No Violations Noted

Office Bathroom

No Violations Noted

Inmate Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Silkscreen Janitor's Closet

105 CMR 451.353

Interior Maintenance: Wet mop stored in sink

Print Warehouse

105 CMR 451.350*

Structural Maintenance: Exit door not rodent and weathertight

Janitor's Closet No Violations Noted

Male Bathroom No Violations Noted

Female Bathroom No Violations Noted

Warehouse – Support Building

Canteen Storage No Violations Noted

Freezer # 1
105 CMR 451.353 Interior Maintenance: One fan not working properly

Freezer # 2 No Violations Noted

Fridge # 1 No Violations Noted

Fridge # 2 No Violations Noted

Male Bathroom No Violations Noted

Female Bathroom No Violations Noted

Inmate Bathroom No Violations Noted

Janitor's Closet No Violations Noted

K9 Training Room

Bathroom No Violations Noted

Break Area
105 CMR 451.200* Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Record Storage No Violations Noted

K9 Unit

Female Bathroom No Violations Noted

Bathroom # 2

No Violations Noted

Janitor's Closet

No Violations Noted

Laundry

No Violations Noted

Observations and Recommendations

1. The inmate population was 650 at the time of inspection.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment Regulations or download a copy, please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Retail food". Then under DPH Regulations and FDA Code click "Merged Food Code" or "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments".

To review the Labeling regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Program regulations". Then under Food Processing click "105 CMR 500.000: Good Manufacturing Practices for Food".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Nicholas Gale
Environmental Analyst, CSP, BEH