

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
Phone: 617-624-6000

MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

KATHLEEN E. WALSH
Secretary

ROBERT GOLDSTEIN, MD, PhD
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

June 30, 2025

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)
Kathleen E. Walsh, Secretary, Executive Office of Health and Human Services (electronic copy)
Clerk, Massachusetts House of Representatives (electronic copy)
Clerk, Massachusetts Senate (electronic copy)
Michael Aiken Jr., Special Operations Officer (electronic copy)


Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Franklin County Jail and House of Correction, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Thomas Murphy
Environmental Analyst, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)
Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)
Michael Theroux, Health Director, Greenfield Health Department (electronic copy)
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)
Jason Kilgour, Superintendent (electronic copy)
Christopher Pelletier, Assistant Superintendent of Support Services (electronic copy)



MAURA T. HEALEY
Governor

KIMBERLEY L. DRISCOLL
Lieutenant Governor

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
Phone: 617-624-5757

KATHLEEN E. WALSH
Secretary

ROBERT GOLDSTEIN, MD,
PhD Commissioner

Tel: 617-624-6000
www.mass.gov/dph

June 6, 2025

Lori M. Streeter, Sheriff
Franklin County Jail and House of Correction
160 Elm Street
Greenfield, MA 01301 (electronic copy)

Re: Facility Inspection – Franklin County Jail and House of Correction, Greenfield

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Franklin County Jail and House of Correction on May 29, 2025 accompanied by Special Operations Officers Michael Aiken Jr. and Justin Chapin in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 48 total deficiencies: 18 deficiencies under the Required Standards (.100 and .200 series), 22 repeat deficiencies under the Required Standards, 5 deficiencies under the Recommended Standards (.300 series), and 3 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Deficiencies under the Required Standards (.100 and .200 series)

18 new deficiencies and 22 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Intake	Cells A-C		105 CMR 451.123*	Maintenance: Handwash sink dirty in cell B
2.	Intake	Medical Exam Room		105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 72°F at handwash sink
3.	Medical	Break Room and Records		105 CMR 451.200*	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
4.	Housing	A Pod	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # 18
5.	Housing	A Pod	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven damaged
6.	Housing	A Pod	Lower Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 2
7.	Housing	A Pod	Lower Showers	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # 1 and 2
8.	Housing	A Pod	Lower Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 2
9.	Housing	A Pod	Upper Showers	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1 and 3
10.	Housing	A Pod	Upper Showers	105 CMR 451.123*	Maintenance: Soap scum on floors in shower # 1 and 2
11.	Housing	B Pod	Lower Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 1
12.	Housing	B Pod	Upper Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 1, 2, and 3
13.	Housing	B Pod	Sub Day Room Shower	105 CMR 451.123	Maintenance: Rust on ceiling
14.	Housing	B Pod	Sub Day Room Shower	105 CMR 451.123	Maintenance: Rust on sprinkler shroud
15.	Housing	C Pod	Lower Showers	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1 and 2
16.	Housing	C Pod	Upper Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 2
17.	Housing	C Pod	Upper Showers	105 CMR 451.123*	Maintenance: Ceiling vent dusty in shower # 3
18.	Housing	C Pod	Upper Showers	105 CMR 451.123*	Maintenance: Mold on ceiling in shower # 3
19.	Housing	D Pod	Staff Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty
20.	Housing	D Pod	Lower Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 2
21.	Housing	D Pod	Juice Bar	105 CMR 451.200*	Food Storage, Preparation and Service: Food service not in compliance with 105 CMR 590.000, sponge observed on juice bar. ** Corrected On-Site **
22.	Housing	D Pod	Upper Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 2
23.	Housing	D Pod	Upper Showers	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 3
24.	Kitchen	2-Door Refrigerator		105 CMR 451.200*	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets moldy. Standard found in 105 CMR 590; FC 4-601.11(C).
25.	Kitchen	Ice Machine		105 CMR 451.200	Food Storage, Preparation and Service: Food storage/preparation/service not in compliance with 105 CMR 590.000, interior of ice machine dirty

26. Maintenance Shop			105 CMR 451.200*	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
27. Administration - Outer	Male Locker Room		105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 106°F at handwash sink
28. Kimble House	2nd Floor	Kitchen	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, raw eggs stored over ready to eat food
29. Kimble House	2nd Floor	Kitchen	105 CMR 451.200*	Food Storage, Preparation and Service: Food service not in compliance with 105 CMR 590.000, sponges observed on kitchen counter
30. Kimble House	3rd Floor	Rooms	105 CMR 451.103*	Mattresses: Mattresses damaged in room # 2
31. Kimble House	3rd Floor	Rooms	105 CMR 451.103*	Mattresses: Mattresses damaged in room # 1
32. Kimble House	3rd Floor	Bathroom	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1
33. Kimble House	3rd Floor	Bathroom	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # 2
34. Vehicle Maintenance	Office		105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, coffee maker dirty

Deficiencies under the Recommended Standards (.300 series)

5 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Housing	A Pod	Staff Office	105 CMR 451. 353	Interior Maintenance: Water damaged ceiling tile
2. Housing	A Pod	Day Room	105 CMR 451.353	Interior Maintenance: Water damaged ceiling tile
3. Housing	B Pod	Day Room	105 CMR 451.353	Interior Maintenance: Water damaged ceiling tile
4. Housing	C Pod	Day Room	105 CMR 451.353*	Interior Maintenance: Water damaged ceiling tile
5. Housing	C Pod	Upper Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Wet mop stored in bucket
6. Minimum Security	1st Floor	Day Room	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
7. Minimum Security	Downstairs	Laundry	105 CMR 451.353*	Interior Maintenance: Wet mop stored in bucket
8. Minimum Security	3rd Floor	Gymnasium	105 CMR 451.353	Interior Maintenance: Ripped padding on exercise equipment

SECTION 2: Areas Found to be in Compliance

EHRS inspected 150 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 3 areas of the facility because they were either in use, locked, or under construction.

1. Medical		Dental Office	Unable to Inspect – In Use
2. Minimum Security	Downstairs	Storage Closet # 1	Unable to Inspect – Locked

3. Minimum Security	Downstairs	Storage Closet # 2	Unable to Inspect – Locked
---------------------	------------	--------------------	----------------------------

SECTION 4: Plan of Correction

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 125 at the time of inspection.
2. At the time of inspection, female inmates were being housed in B Pod.
3. ERHS recommends numbering all showers throughout the institution. This will assist EHRS and staff to better recognize where issues exist.
4. The required temperature for handwash sinks is between 110°F and 130°F.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#) available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Thomas Murphy
Environmental Analyst, EHRS, BCEH

Commonwealth of Massachusetts

Office of the Sheriff

FRANKLIN COUNTY

LORI M. STREETER
SHERIFF



JASON B. KILGOUR
SUPERINTENDENT/SPECIAL SHERIFF

June 17th, 2025

Thomas Murphy
Division of Environmental Health, Regulations and Standards
Massachusetts Department of Public Health
Bureau of Climate and Environmental Health
DPH Marlborough Office
67 Forest Street
Marlborough, MA 01752

Dear Thomas,

Enclosed you will find the plan of correction in response to your sanitation inspection conducted on May 29th, 2025. Please feel free to contact me in regards to any questions and/or concerns that you might have.

Sincerely,

Christopher Pelletier
AS of Support Services

Michael Aiken Jr.
Special Operations Officer



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
Phone: 617-624-5757

MAURA T. HEALEY
Governor

KIMBERLEY L. DRISCOLL
Lieutenant Governor

KATHLEEN E. WALSH
Secretary

ROBERT GOLDSTEIN, MD,
PhD Commissioner

Tel: 617-624-6000
www.mass.gov/dph

June 6, 2025

Lori M. Streeter, Sheriff
Franklin County Jail and House of Correction
160 Elm Street
Greenfield, MA 01301 (electronic copy)

Re: Facility Inspection – Franklin County Jail and House of Correction, Greenfield

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Franklin County Jail and House of Correction on May 29, 2025 accompanied by Special Operations Officers Michael Aiken Jr. and Justin Chapin in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 48 total deficiencies: 18 deficiencies under the Required Standards (.100 and .200 series), 22 repeat deficiencies under the Required Standards, 5 deficiencies under the Recommended Standards (.300 series), and 3 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Deficiencies under the Required Standards (.100 and .200 series)

18 new deficiencies and 22 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Intake	Cells A-C		105 CMR 451.123*	Maintenance: Handwash sink dirty in cell B Hand wash Sinks cleaned by inmate workers on 6-10-25.
2.	Intake	Medical Exam Room		105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 72°F at handwash sink Electronic work order placed with maintenance. Water temp will be adjusted to reach 110-130 °F. Estimated completion 6-25-25.
3.	Medical	Break Room and Records		105 CMR 451.200*	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty Medical staff cleaned the interior of the microwave on 6-11-25.
4.	Housing	A Pod	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # 18 Mattress removed, disposed of, and replaced on 6-12-25.
5.	Housing	A Pod	Day Room	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven damaged Electronic work order placed with maintenance. Microwave will be removed and replaced after July 1 st by Maintenance.
6.	Housing	A Pod	Lower Showers	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 2 Inmate workers cleaned all showers on 6-17-25.
7.	Housing	A Pod	Lower Showers	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # 1 and 2 Inmate workers cleaned all showers on 6-17-25.
8.	Housing	A Pod	Lower Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 2 Electronic work order placed with maintenance. Maintenance will vacuum and clean vents. Estimated completion 6-26-25.
9.	Housing	A Pod	Upper Showers	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1 and 3 Inmate workers cleaned all showers on 6-17-25.
10.	Housing	A Pod	Upper Showers	105 CMR 451.123*	Maintenance: Soap scum on floors in shower # 1 and 2 Inmate workers cleaned all showers on 6-17-25.
11.	Housing	B Pod	Lower Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 1 Electronic work order placed with maintenance. Maintenance will vacuum and clean vents. Estimated completion 6-26-25.
12.	Housing	B Pod	Upper Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 1, 2, and 3 Electronic work order placed with maintenance. Maintenance will vacuum and clean vents. Estimated completion 6-26-25.
13.	Housing	B Pod	Sub Day Showe	105 CMR 451.123	Maintenance: Rust on ceiling

		Room			Electronic work order placed with maintenance. Maintenance will clean rust off ceiling. Estimated completion 6-26-25.
14. Housing	B Pod	Sub Day Room	Showers	105 CMR 451.123	Maintenance: Rust on sprinkler shroud Electronic work order placed with maintenance. Maintenance will replace sprinkler shroud and inspect sprinkler head. Estimated completion 6-26-25.
15. Housing	C Pod	Lower Showers		105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1 and 2 Inmate workers cleaned all showers on 6-17-25.
16. Housing	C Pod	Upper Showers		105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 2 Electronic work order placed with maintenance. Maintenance will vacuum and clean vents. Estimated completion 6-26-25.
17. Housing	C Pod	Upper Showers		105 CMR 451.123*	Maintenance: Ceiling vent dusty in shower # 3 Electronic work order placed with maintenance. Maintenance will vacuum and clean vents. Estimated completion 6-26-25.
18. Housing	C Pod	Upper Showers		105 CMR 451.123*	Maintenance: Mold on ceiling in shower # 3 Electronic work order placed with maintenance. Maintenance will clean mold or replace ceiling tiles. Estimated completion 6-26-25.
19. Housing	D Pod	Staff Bathroom		105 CMR 451.123	Maintenance: Ceiling vent dusty Electronic work order placed with maintenance. Maintenance will vacuum and clean vents. Estimated completion 6-26-25.
20. Housing	D Pod	Lower Showers		105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 2 Electronic work order placed with maintenance. Maintenance will vacuum and clean vents. Estimated completion 6-26-25.
21. Housing	D Pod	Juice Bar		105 CMR 451.200*	Food Storage, Preparation and Service: Food service not in compliance with 105 CMR 590.000, sponge observed on juice bar. **Corrected On-Site **
22. Housing	D Pod	Upper Showers		105 CMR 451.123	Maintenance: Soap scum on walls in shower # 2 Inmate workers cleaned all showers on 6-17-25.
23. Housing	D Pod	Upper Showers		105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 3 Inmate workers cleaned all showers on 6-17-25.
24. Kitchen		2-Door Refrigerator		105 CMR 451.200*	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets moldy. Standard found in 105 CMR 590; FC 4-601.11(C). Electronic work order placed with maintenance. Maintenance will remove and replace gaskets. Estimated completion 7-4-25.
25. Kitchen		Ice Machine		105 CMR 451.200	Food Storage, Preparation and Service: Food storage/preparation/service not in compliance with 105 CMR 590.000, interior of ice machine dirty Ice machine emptied and cleaned by inmate kitchen worker on 6-11-25.

26. Maintenance Shop			105 CMR 451.200*	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty Maintenance worker cleaned microwave on 6-12-25.
27. Administration - Outer	Male Locker Room		105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 106°F at handwash sink Checked temperature on both male locker room hand wash sinks hot water temperature reached 114°F on 6-12-25.
28. Kimble House	2nd Floor	Kitchen	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, raw eggs stored over ready to eat food Minimum supervisors and Inmates were informed that eggs need to be stored below ready to eat food. Eggs were moved under ready to eat food on 6-16-25.
29. Kimble House	2nd Floor	Kitchen	105 CMR 451.200*	Food Storage, Preparation and Service: Food service not in compliance with 105 CMR 590.000, sponges observed on kitchen counter Sponges removed and disposed of on 6-12-25.
30. Kimble House	3rd Floor	Rooms	105 CMR 451.103*	Mattresses: Mattresses damaged in room # 2 Damaged mattresses removed and disposed of on 6-12-25.
31. Kimble House	3rd Floor	Rooms	105 CMR 451.103*	Mattresses: Mattresses damaged in room # 1 Damaged mattresses removed and disposed of on 6-12-25.
32. Kimble House	3rd Floor	Bathroom	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1 Inmate workers cleaned shower all showers on 6-17-25.
33. Kimble House	3rd Floor	Bathroom	105 CMR 451.123*	Maintenance: Soap scum on floor in shower # 2 Inmate workers cleaned shower all showers on 6-17-25.
34. Vehicle Maintenance	Office		105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, coffee maker dirty Inmate workers cleaned dirty coffee maker on 7-12-25.

Deficiencies under the Recommended Standards (.300 series)

5 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Housing	A Pod	Staff Office	105 CMR 451. 353	Interior Maintenance: Water damaged ceiling tile Titles will be replaced at the completion of the roof replacement project. Estimated Completion 7-15-25.
2. Housing	A Pod	Day Room	105 CMR 451.353	Interior Maintenance: Water damaged ceiling tile Titles will be replaced at the completion of the roof replacement project. Estimated Completion

					7-15-25.
3.	Housing	B Pod	Day Room	105 CMR 451.353	Interior Maintenance: Water damaged ceiling tile Titles will be replaced at the completion of the roof replacement project. Estimated Completion 7-15-25.
4.	Housing	C Pod	Day Room	105 CMR 451.353*	Interior Maintenance: Water damaged ceiling tile Titles will be replaced at the completion of the roof replacement project. Estimated Completion 7-15-25.
5.	Housing	C Pod	Upper Janitor's Closet	105 CMR 451.353*	Interior Maintenance: Wet mop stored in bucket Mop removed from bucket and stored properly 6-12-25.
6.	Minimum Security	1st Floor	Day Room	105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket Mop removed from bucket and stored properly 6-12-25.
7.	Minimum Security	Downstairs	Laundry	105 CMR 451.353*	Interior Maintenance: Wet mop stored in bucket Mop removed from bucket and stored properly 6-12-25.
8.	Minimum Security	3rd Floor	Gymnasium	105 CMR 451.353	Interior Maintenance: Ripped padding on exercise equipment Electronic work order placed with maintenance. Damaged exercise equipment padding will be replaced by Maintenance. Estimated completion 6-27-25.

SECTION 2: Areas Found to be in Compliance

EHRIS inspected 150 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRIS did not inspect

EHRIS did not inspect 3 areas of the facility because they were either in use, locked, or under construction.

1.	Medical		Dental Office	Unable to Inspect – In Use
2.	Minimum Security	Downstairs	Storage Closet # 1	Unable to Inspect – Locked
3.	Minimum Security	Downstairs	Storage Closet # 2	Unable to Inspect – Locked

SECTION 4: Plan of Correction

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff

5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 125 at the time of inspection.
2. At the time of inspection, female inmates were being housed in B Pod.
3. ERHS recommends numbering all showers throughout the institution. This will assist EHRS and staff to better recognize where issues exist.
4. The required temperature for handwash sinks is between 110°F and 130°F.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#) available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).


An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,

Thomas Murphy
Environmental Analyst, EHRS, BCEH



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards

MAURA T. HEALEY
Governor

KIMBERLEY DRISCOLL
Lieutenant Governor

67 Forest Street, Suite # 100
Marlborough, MA 01752
Phone: 617-624-5454

KATHLEEN E. WALSH
Secretary

ROBERT GOLDSTEIN, MD, PhD
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

June 18, 2025

Lori M. Streeter, Sheriff
Franklin County Jail and House of Correction
160 Elm Street
Greenfield, MA 01301 (electronic copy)

Re: Plan of Correction - Franklin County Jail and House of Correction, Greenfield

Dear Sheriff Streeter:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction (POC) in response to my inspection on May 29, 2025. After review, the EHRS finds the plan addresses all the deficiencies noted in the report.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Thomas Murphy
Environmental Analyst, EHRS, BCEH

cc: Jason Kilgour, Superintendent (electronic copy)
Christopher Pelletier, Assistant Superintendent of Support Services (electronic copy)
Officer Michael K. Aiken Jr., Special Operations Officer (electronic copy)